


Northeast Ohio Regional Sewer District

Daily Precipitation Report Monday, May 3, 2021

Accumulation in Inches



Northeast Ohio Regional Sewer District**Daily Precipitation Report****Monday, May 3, 2021**

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	n/a	n/a	n/a	n/a	n/a
Brecksville	0.52	0.42	0.35	0.18	0.07
Brook Park	0.26	0.23	0.19	0.08	0.03
Cleveland Industrial Pkwy	0.21	0.19	0.16	0.07	0.02
Dille Ave PS	0.21	0.19	0.18	0.08	0.01
Division Ave PS	0.29	0.26	0.23	0.10	0.02
Easterly WWTP	0.24	0.19	0.15	0.08	0.02
Independence	0.40	0.34	0.28	0.15	0.05
James Rhodes HS	0.27	0.25	0.21	0.09	0.02
Jennings PS	0.33	0.30	0.26	0.11	0.05
Macedonia	0.61	0.45	0.34	0.15	0.06
Maple Heights	0.46	0.39	0.28	0.14	0.06
Mary Street PS	0.29	0.26	0.24	0.10	0.04
Mayfield Heights	0.40	0.35	0.27	0.11	0.05
Moreland Hills	0.56	0.47	0.37	0.16	0.08
North Olmsted	0.33	0.26	0.19	0.10	0.05
North Royalton	0.56	0.50	0.41	0.21	0.09
Oakwood	0.64	0.52	0.40	0.18	0.07
Olmsted Falls	0.28	0.23	0.18	0.09	0.04
Parma	0.31	0.28	0.24	0.10	0.04
Richfield	0.45	0.33	0.23	0.10	0.06
Shaker Heights	0.38	0.33	0.24	0.12	0.06
South Euclid	0.35	0.32	0.24	0.10	0.06
Southerly WWTC	0.28	0.26	0.23	0.11	0.04
Strongsville C WWTP	0.32	0.29	0.25	0.11	0.05
Strongsville Falls	0.31	0.29	0.24	0.12	0.05
University Heights	0.36	0.33	0.25	0.11	0.08
Wade Park	0.28	0.22	0.19	0.09	0.05
Westlake	0.27	0.23	0.16	0.09	0.03

Work Order Detail Report

5/7/2021

SSO INSPECTION 5-3-2021 0.36 INCHES ON RAIN

9:05 AM

WO Number:	210506-0004	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	5/7/2021 9:03 am	Main Task:	Inspection
Asset: SSO 431			
Location:	FAIRFAX AT NORTH PARK	Assigned By:	
Cause:	Weather	Assigned Date:	
Assigned Crew:		Start Date:	5/6/2021 8:00 AM
Supervisor:	Jackson, Jeff	End Date:	5/6/2021
Lead Worker:	DelZoppo, Michael	Override Notifications:	
Priority:	High	<input type="checkbox"/> Problem	<input type="checkbox"/> Overdue
Account #:		<input type="checkbox"/> Lead Worker	<input type="checkbox"/> Task
Proj No - Acct:		<input type="checkbox"/> Supervisor	<input type="checkbox"/> Supervisor
Project:		<input type="checkbox"/> Hard Lock WO	<input type="checkbox"/> Hard Lock WO
Reason:			
Received By:			
Inspected By:			

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection

Comments for Crew
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339		Doan Brook
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210506-0004

Work Order Detail Report

5/7/2021

SSO INSPECTION 5-3-2021 0.36 INCHES ON RAIN

9:05 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)
2,223,111.44143730 664,794.46048072 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO
2,221,638.88762389 665,726.15513962 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON
2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)
2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY
2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON
2,221,598.28993607 666,996.61322863
MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423 665,499.19660404 DOAN BROOK
BRADFORD AND LEE
2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH
EDDINGTON
2,221,299.08384156 674,932.84604380
HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL
2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")
2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD

HAMPSHIRE AT EUCLID HTS. BLVD.
2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON
2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY
2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD
2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd
2,227,113.30810548 671,276.67684697
LEE RD. & SUPERIOR AVE.
2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE
2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND
2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND
2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON
2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD

2225 NOBLE ROAD
2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF
2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE
2,228,126.76638040 684,188.23206055

2,220,777.89623564 666,181.72575080

2,218,501.67473823 671,997.54581206

2,216,759.55453481 670,474.59347738

Work Order Detail Report

5/7/2021

SSO INSPECTION 5-3-2021 0.36 INCHES ON RAIN

9:05 AM

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

Work Order Detail Report

5/7/2021

SSO INSPECTION 5-3-2021 0.36 INCHES ON RAIN

9:05 AM

Work Order Assets							
<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>Description 2</u>
							<u>PM Description</u>
Sewer Control Valve							FAIRFAX AT NORTH PARK
SSO 431							26
Sewer Control Valve							NORTH PARK AND COVENTRY
SSO 114							16
Sewer Control Valve							FAIRMOUNT SOUTH OF SCARBOROUGH
SSO 121							35
Sewer Structure							3094
SA16AAWBO							
Sewer Control Valve							FAIRMOUNT AT FAIRFAX
SSO 112							7
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (S. SIDE)
SSO 99							6
Sewer Control Valve							3012 NORTH WOODLAND
SSO 432							14
Sewer Control Valve							55
DB-03							
Sewer Control Valve							56
DB-01							
Sewer Control Valve							57
DB-02							
Sewer Control Valve							FAIRMOUNT AT DARTMOOR
CH-04							5
Sewer Control Valve							FAIRMOUNT AT WELLINGTON
SSO 110							44
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (N. SIDE)
SSO 87							33
Sewer Control Valve							FAIRMOUNT AT MARLBORO
SSO 116							4
Sewer Control Valve							FAIRMOUNT AT ARLINGTON
SSO 111							46
Sewer Control Valve							FAIRMOUNT & COVENTRY (SCARBOROUGH)
SSO 113							37
Sewer Control Valve							FAIRMOUNT AND COVENTRY
SSO 124							47
Sewer Control Valve							SCARBOROUGH AT LAMBERTON
CH-50							53
Sewer Control Valve							BRADFORD AND LEE
SSO 129							11
Sewer Control Valve							EDDINGTON
CH-52							2
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (18")
SSO 88							42
Sewer Control Valve							EAST OVERLOOK AT EDGEHILL
SSO 122							36
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (36")
SSO 89							34
Sewer Structure							1536
SA16ADZB0							
Sewer Control Valve							HAMPSHIRE AT EUCLID HTS. BLVD.
SSO 91							20
Sewer Structure							4446
SA16ADPH0							
Sewer Control Valve							CEDAR BTW. FAIRMOUNT/DEMINGTON
SSO 120							8
Sewer Control Valve							2828 BERKSHIRE, EAST OF COVENTRY

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210506-0004

Work Order Detail Report

5/7/2021

SSO INSPECTION 5-3-2021 0.36 INCHES ON RAIN

9:05 AM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQCO	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTON
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

5/7/2021

SSO INSPECTION 5-3-2021 0.36 INCHES ON RAIN

9:05 AM

Check List		<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	5/6/2021/ 7:51 am	
	No overflow				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	5/6/2021/ 7:54 am	
	No overflow				
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	5/6/2021/ 7:58 am	
	No overflow				
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	5/6/2021/ 8:00 am	
	No overflow				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	5/6/2021/ 8:02 am	
	No overflow				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	5/6/2021/ 8:07 am	
	No overflow				
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	5/6/2021/ 8:10 am	
	No overflow				
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	5/6/2021/ 8:15 am	
	No overflow				
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	5/6/2021/ 8:19 am	
	Overflow				
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	5/6/2021/ 8:21 am	
	No overflow				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	5/6/2021/ 8:24 am	
	No overflow				
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	5/6/2021/ 8:28 am	
	No overflow				
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	5/6/2021/ 8:33 am	
	No overflow				
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	5/6/2021/ 8:36 am	
	No overflow				
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	5/6/2021/ 8:38 am	
	No overflow				
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	5/6/2021/ 8:42 am	
	No overflow				
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	5/6/2021/ 8:45 am	
	No overflow				
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	5/6/2021/ 8:49 am	
	No overflow				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210506-0004

Work Order Detail Report

5/7/2021

SSO INSPECTION 5-3-2021 0.36 INCHES ON RAIN

9:05 AM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/> Sound	5/6/2021/ 8:53 am
	No overflow		
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/> Sound	5/6/2021/ 8:56 am
	No overflow		
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/> Sound	5/6/2021/ 8:58 am
	No overflow		
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/> Sound	5/6/2021/ 9:06 am
	Overflow. Block fell off. Replaced block.		
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/> Sound	5/6/2021/ 9:20 am
	No overflow		
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/> Sound	5/6/2021/ 9:24 am
	No overflow		
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/> Sound	5/6/2021/ 9:25 am
	No overflow		
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/> Sound	5/6/2021/ 9:28 am
	No overflow		
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/> Sound	5/6/2021/ 9:31 am
	No overflow		
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/> Sound	5/6/2021/ 9:33 am
	No overflow		
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/> Sound	5/6/2021/ 9:38 am
	No overflow		
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/> Sound	5/6/2021/ 9:42 am
	No overflow		
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/> Sound	5/6/2021/ 9:46 am
	No overflow		
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/> Sound	5/6/2021/ 9:50 am
	No overflow		
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/> Sound	5/6/2021/ 9:57 am
	Overflow		
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/> Sound	5/6/2021/12:22 pm
	No overflow		
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/> Sound	5/6/2021/12:25 pm
	No overflow		
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/> Sound	5/6/2021/12:28 pm
	No overflow		
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/> Sound	5/6/2021/12:31 pm
	No overflow		
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/> Sound	5/6/2021/12:33 pm
	No overflow		
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/> Sound	5/6/2021/12:36 pm
	No overflow		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210506-0004

Work Order Detail Report

5/7/2021

SSO INSPECTION 5-3-2021 0.36 INCHES ON RAIN

9:05 AM

40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Sound	5/6/2021/12:43 pm
No overflow				
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	5/6/2021/12:46 pm
No overflow				
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	5/6/2021/12:51 pm
No overflow				
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	5/6/2021/12:57 pm
No overflow				
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	5/6/2021/12:58 pm
Tangled				
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	5/6/2021/ 1:03 pm
No overflow				

Tasks/Resources	
SWCT26 Inspection	
Crew:	Status:
Supervisor:	UOM: Each
Task Comment: SSO INSPECTION	

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
			0.00	0.00	0.00
Repair Type:		Labor Hours	0.00	0.00	0.00
Subcontractor:		Labor Costs	\$0.00	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity:	0.00	Equipment Costs	0.00	0.00	0.00
Unit of Measure:	Each	Contractor Costs	0.00	0.00	0.00
*Unit Cost:	\$0.00	Misc. Costs	0.00	0.00	0.00
WO Hours:	0.00	Total Costs	\$0.00	\$0.00	\$0.00
Use Task Info:		True	True	True	

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	Cell #:
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	Billing Required: <input type="checkbox"/>
Invoice Number:		Date Bill Sent:	Billing Processed: <input type="checkbox"/>
Incoming Account #:		Payment Received:	Imported to Financials: <input type="checkbox"/>
		Payment Method:	

Associated PMs		PM Code and Description	Closed
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>
Item	Tracking	Description	By
Work Order Creation		From Routine Work SSO-02 - SSO INSPECTION	jjackson
Supervisor Notification		Email Queued Successfully!	jjackson
Status Change		From New Work Order to Complete	aferrone
Date	Time		
5/6/2021	7:49 AM		
5/6/2021	7:49 AM		
5/7/2021	9:03 AM		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210506-0004

Work Order Detail Report

5/7/2021

SSO INSPECTION 5-3-2021 0.36 INCHES ON RAIN

9:05 AM

Rates:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned,	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:	Appointment Date: 5/6/2021	7:30 AM	
Dye Test Results:			
WO User 51:			
Measurement:	E Mail:		
History:	WO User 22:		
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sles		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 5/6/2021	PM Trigger:	Rec #: 7656

Northeast Ohio Regional Sewer District

Daily Precipitation Report Sunday, May 9, 2021

Accumulation in inches

Eastern
WWTP

0.96

South
Euclid

1.20

University
Heights

1.09

Beachwood

1.01

Shaker
Heights

1.09

Moreland
Hills

1.06

Oakwood

1.08

Macedonia

1.38

Richfield

1.58

Dille PS

0.95

Mary
Street PS

0.97

Division PS

1.16

Jennings PS

1.09

Southerly
WWTC

1.12

James
Rhodes HS

1.09

Cleveland
Industrial Pkwy

1.00

Brook Park

1.22

Parma

1.26

Independence

1.19

Brecksville

1.31

North
Royalton

1.41

Strongsville
"C" WWTP

1.34

Olmsted
Falls

1.17

Strongsville
Foltz

1.29



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Sunday, May 9, 2021

<u>Site Location</u>	<u>Peak Accumulation (inches)</u>					
	<u>24-Hour</u>	<u>6-Hour</u>	<u>3-Hour</u>	<u>1-Hour</u>	<u>15-Minute</u>	<u>5-Minute</u>
Beachwood	1.01	0.85	0.50	0.24	0.08	0.04
Brecksville	1.31	0.98	0.58	0.24	0.08	0.03
Brook Park	1.22	0.92	0.52	0.22	0.07	0.03
Cleveland Industrial Pkwy	1.00	0.81	0.51	0.26	0.11	0.05
Dille Ave PS	0.95	0.77	0.47	0.23	0.07	0.03
Division Ave PS	1.16	0.94	0.57	0.25	0.07	0.03
Easterly WWTP	0.96	0.82	0.55	0.27	0.08	0.03
Independence	1.19	0.92	0.55	0.22	0.07	0.03
James Rhodes HS	1.09	0.89	0.53	0.25	0.09	0.04
Jennings PS	1.09	0.85	0.52	0.23	0.07	0.03
Macedonia	1.38	1.04	0.60	0.24	0.09	0.04
Maple Heights	1.23	0.94	0.56	0.27	0.11	0.05
Mary Street PS	0.97	0.78	0.49	0.21	0.07	0.03
Mayfield Heights	0.90	0.76	0.46	0.19	0.07	0.03
Moreland Hills	1.06	0.78	0.41	0.16	0.06	0.02
North Olmsted	n/a	n/a	n/a	n/a	n/a	n/a
North Royalton	1.41	1.06	0.62	0.27	0.12	0.05
Oakwood	1.08	0.82	0.48	0.21	0.07	0.03
Olmsted Falls	1.17	0.88	0.50	0.21	0.07	0.03
Parma	1.26	0.97	0.56	0.24	0.08	0.03
Richfield	1.58	1.20	0.63	0.28	0.10	0.04
Shaker Heights	1.09	0.86	0.52	0.24	0.09	0.04
South Euclid	1.20	0.99	0.62	0.29	0.08	0.03
Southerly WWTC	1.12	0.87	0.52	0.25	0.08	0.04
Strongsville C WWTP	1.34	1.01	0.59	0.25	0.09	0.04
Strongsville Foltz	1.29	0.97	0.57	0.26	0.08	0.03
University Heights	1.09	0.90	0.57	0.26	0.08	0.03
Wade Park	1.02	0.86	0.54	0.25	0.08	0.03
Westlake	1.36	1.06	0.67	0.31	0.10	0.04

Work Order Detail Report

5/13/2021

SSO INSPECTION 5-9-2021 1.09" OF RAIN

9:26 AM

WO Number:	210511-0002	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	5/13/2021 9:22 am	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	5/11/2021 8:00 AM
Lead Worker:	DelZoppo, Michael	End Date:	5/11/2021
Priority:	High	Override Notifications	<input type="checkbox"/>
Account #:		Problem	<input type="checkbox"/>
Proj No - Act:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection

Comments for Crew
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:

Area:
Sub-Area:
Owner:
Location:
Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
Address	X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK	2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY	2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH	2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX	2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND	2,222,845.06631389	664,689.08536339	Doan Brook
	2,226,440.21168265	664,329.55524255	
	2,226,354.79813956	664,409.89202413	
	2,226,389.92077273	664,379.07548472	
	2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
	2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210511-0002

Work Order Detail Report

5/13/2021

SSO INSPECTION 5-9-2021 1.09" OF RAIN

9:26 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

5/13/2021

SSO INSPECTION 5-9-2021 1.09" OF RAIN

9:26 AM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

5/13/2021

SSO INSPECTION 5-9-2021 1.09" OF RAIN

9:26 AM

Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Description 2</u>	<u>Asset ID</u>	<u>Completed</u>
			<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>
Sewer Control Valve						FAIRFAX AT NORTH PARK
SSO 431						26
Sewer Control Valve						NORTH PARK AND COVENTRY
SSO 114						16
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH
SSO 121						35
Sewer Structure						
SA16AAWB0						3094
Sewer Control Valve						FAIRMOUNT AT FAIRFAX
SSO 112						7
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)
SSO 99						6
Sewer Control Valve						3012 NORTH WOODLAND
SSO 432						14
Sewer Control Valve						
DB-03						55
Sewer Control Valve						
DB-01						56
Sewer Control Valve						
DB-02						57
Sewer Control Valve						FAIRMOUNT AT DARTMOOR
CH-04						5
Sewer Control Valve						FAIRMOUNT AT WELLINGTON
SSO 110						44
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)
SSO 87						33
Sewer Control Valve						FAIRMOUNT AT MARLBORO
SSO 116						4
Sewer Control Valve						FAIRMOUNT AT ARLINGTON
SSO 111						46
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)
SSO 113						37
Sewer Control Valve						FAIRMOUNT AND COVENTRY
SSO 124						47
Sewer Control Valve						SCARBOROUGH AT LAMBERTON
CH-50						53
Sewer Control Valve						BRADFORD AND LEE
SSO 129						11
Sewer Control Valve						EDDINGTON
CH-52						2
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")
SSO 88						42
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL
SSO 122						36
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")
SSO 89						34
Sewer Structure						
SA16ADZB0						1536
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.
SSO 91						20
Sewer Structure						
SA16ADPH0						4446
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON
SSO 120						8
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210511-0002

Work Order Detail Report

5/13/2021

SSO INSPECTION 5-9-2021 1.09" OF RAIN

9:26 AM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONNE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

5/13/2021

SSO INSPECTION 5-9-2021 1.09" OF RAIN

9:26 AM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	5/11/2021/ 8:12 am	
	No overflow				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	5/11/2021/ 8:15 am	
	No overflow				
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	5/11/2021/ 8:20 am	
	Overflow				
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	5/11/2021/ 8:23 am	
	No overflow				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	5/11/2021/ 8:55 am	
	No overflow				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	5/11/2021/	
	No overflow				
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	5/11/2021/ 8:58 am	
	No overflow				
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	5/11/2021/ 9:00 am	
	No overflow				
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	5/11/2021/ 9:10 am	
	No overflow				
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	5/11/2021/ 9:13 am	
	No overflow				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	5/11/2021/ 9:15 am	
	No overflow				
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	5/11/2021/ 9:18 am	
	No overflow				
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	5/11/2021/ 9:21 am	
	No overflow				
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	5/11/2021/ 9:24 am	
	No overflow				
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	5/11/2021/ 9:26 am	
	No overflow				
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	5/11/2021/ 9:28 am	
	No overflow				
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	5/11/2021/ 9:31 am	
	Overflow				
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	5/11/2021/ 9:34 am	
	No overflow				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210511-0002

Work Order Detail Report

5/13/2021

SSO INSPECTION 5-9-2021 1.09" OF RAIN

9:26 AM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	5/11/2021/ 9:38 am
	No overflow			
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	5/11/2021/ 9:43 am
	No overflow			
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	5/11/2021/ 9:46 am
	No overflow			
22	A-9 BRADFORD AT LEE SA16AFL0 (INTERSECTION)	<input type="checkbox"/>	Sound	5/11/2021/ 9:50 am
	No overflow			
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	5/11/2021/10:04 am
	No overflow			
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	5/11/2021/10:10 am
	No overflow			
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	5/11/2021/10:10 am
	No overflow			
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	5/11/2021/10:12 am
	No overflow			
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	5/11/2021/10:15 am
	No overflow			
28	B-46 EDGEHILL AT E OVERLOOK SA16AEFP0	<input type="checkbox"/>	Sound	5/11/2021/10:17 am
	No overflow			
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	5/11/2021/10:20 am
	No overflow			
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	5/11/2021/10:23 am
	No overflow			
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	5/11/2021/10:26 am
	No overflow			
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	5/11/2021/12:20 pm
	No overflow			
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	5/11/2021/12:28 pm
	Overflow			
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	5/11/2021/12:36 pm
	Overflow			
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	5/11/2021/12:43 pm
	Overflow			
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	5/11/2021/12:45 pm
	No overflow			
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	5/11/2021/12:47 pm
	No overflow			
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	5/11/2021/12:49 pm
	No overflow			
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	5/11/2021/12:51 pm
	No overflow			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210511-0002

Work Order Detail Report

5/13/2021

SSO INSPECTION 5-9-2021 1.09" OF RAIN

9:26 AM

40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Sound	5/11/2021/ 1:04 pm
No overflow				
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	5/11/2021/ 1:07 pm
No overflow				
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	5/11/2021/ 1:14 pm
No overflow				
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	5/11/2021/ 1:19 pm
No overflow				
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	5/11/2021/ 1:25 pm
Tangled				
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	5/11/2021/ 1:25 pm
No overflow				

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:		*Cal'c UC: \$10.24	*Task Cost: \$460.64	Start Dt: 5/11/2021	
Supervisor:	UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:	
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
9512 DelZoppo, Michael	Hours	8.00	\$172.32		5/11/2021	
11213 Owens, Will	Hours	8.00	\$181.12		5/11/2021	
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB	Hours	8.00	\$107.20		5/11/2021	
5						

Task Comment: SSO INSPECTION 5-9-2021 1.09" OF RAIN

				*Actual	*Estimated	*Difference
Projected Complete:		Lock: <input type="checkbox"/>	WO Duration	0.00	0.00	0.00
Repair Type:			Labor Hours	16.00	0.00	0.00
Subcontractor:			Labor Costs	\$353.44	\$0.00	\$0.00
Profit Center:			Material Costs	0.00	0.00	0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each		Equipment Costs	107.20	0.00	0.00
*Unit Cost:	\$0.00		Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00		Misc. Costs	0.00	0.00	0.00
			Total Costs	\$460.64	\$0.00	\$0.00
			Use Task Info:	True	True	

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:				
City:		Phone:		
State:		Fax #:		
Zip:		Cell #: E-mail:		
Billing Data				
Contact Name:		*Billing Amount:		
Invoice Number:		Billing Required: <input type="checkbox"/>		
Incoming Account #:		Date Bill Sent:		
		Payment Received:		
		Imported to Financials: <input type="checkbox"/>		
		Payment Method:		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210511-0002

Work Order Detail Report

5/13/2021

SSO INSPECTION 5-9-2021 1.09" OF RAIN

9:26 AM

Associated PMs		PM Code and Description	Closed
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>
Tracking			
Item	Description	By	Date
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jackson	5/11/2021
Supervisor Notification	Email Queued Successfully!	jackson	5/11/2021
Status Change	From New Work Order to Complete	aferrone	5/13/2021
Time			7:27 AM
			9:22 AM
Rates:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned:	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:	Appointment Date:	5/11/2021	7:30 AM
Dye Test Results:			
WO User 51:	E Mail:		
Measurement:	WO User 22:		
History:			
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Slat		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re:			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		

Work Order Detail Report

5/13/2021

SSO INSPECTION 5-9-2021 1.09" OF RAIN

9:26 AM


WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 5/11/2021	PM Trigger:	Rec #: 7669



Daily Precipitation Report

Friday, May 28, 2021

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report
Friday, May 28, 2021

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	1.27	0.97	0.67	0.36	0.11
Brecksville	1.18	0.93	0.65	0.39	0.12
Brook Park	1.03	0.78	0.54	0.33	0.12
Cleveland Industrial Pkwy	1.29	0.95	0.63	0.39	0.16
Dillie Ave PS	1.34	1.07	0.74	0.38	0.15
Division Ave PS	1.27	0.97	0.59	0.32	0.11
Easterly WWTP	1.47	1.07	0.68	0.33	0.14
Independence	1.11	0.86	0.59	0.33	0.10
James Rhodes HS	n/a	n/a	n/a	n/a	n/a
Jennings PS	1.39	1.10	0.78	0.37	0.16
Macedonia	n/a	n/a	n/a	n/a	n/a
Maple Heights	1.27	0.98	0.69	0.40	0.12
Mary Street PS	1.26	0.98	0.65	0.32	0.12
Mayfield Heights	1.40	1.02	0.65	0.32	0.11
Moreland Hills	1.15	0.88	0.57	0.31	0.11
North Olmsted	n/a	n/a	n/a	n/a	n/a
North Royalton	1.06	0.83	0.62	0.39	0.13
Oakwood	n/a	n/a	n/a	n/a	n/a
Olmsted Falls	0.98	0.73	0.54	0.35	0.13
Parma	n/a	n/a	n/a	n/a	n/a
Richfield	0.99	0.76	0.52	0.35	0.11
Shaker Heights	1.25	0.95	0.66	0.36	0.12
South Euclid	1.50	1.14	0.75	0.42	0.14
Southerly WWTC	1.23	0.95	0.66	0.36	0.12
Strongsville C WWTP	1.14	0.85	0.57	0.36	0.12
Strongsville Foltz	1.03	0.81	0.60	0.39	0.13
University Heights	1.25	0.95	0.64	0.35	0.11
Wade Park	1.39	1.10	0.74	0.35	0.14
Westlake	1.12	0.80	0.47	0.28	0.09

Work Order Detail Report

6/3/2021

SSO INSPECTION 5-28-2021 1.25 INCHES OF RAIN

1:17 PM

WO Number: 210602-0001	Category:	SSOs
Status: Complete	Problem:	Storm Response
Status Date: 6/3/2021 1:16 pm	Main Task:	Inspection

Asset: SSO 431

Location: FAIRFAX AT NORTH PARK

Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	6/2/2021 8:00 AM
Lead Worker:	Cardarella, Joe	End Date:	6/3/2021
Priority:	High	Override Notifications	<input type="checkbox"/>
Account #:		Problem	<input type="checkbox"/>
Proj No - Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection

Comments for Crew
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations		
<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210602-0001

Work Order Detail Report

6/3/2021

SSO INSPECTION 5-28-2021 1.25 INCHES OF RAIN

1:17 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481	672,922.02624655	EAST OVERLOOK AT EDGEHILL
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	LEE RD. & SUPERIOR AVE.
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

6/3/2021

SSO INSPECTION 5-28-2021 1.25 INCHES OF RAIN

1:17 PM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

6/3/2021

SSO INSPECTION 5-28-2021 1.25 INCHES OF RAIN

1:17 PM

Work Order Assets								
Object Type	System ID 1	Description 1			Description 2		Asset ID	Completed
	System ID 2	Odometer	Hourmeter	Othermeter	PM Description			
Sewer Control Valve	SSO 431				FAIRFAX AT NORTH PARK		26	
Sewer Control Valve	SSO 114				NORTH PARK AND COVENTRY		16	
Sewer Control Valve	SSO 121				FAIRMOUNT SOUTH OF SCARBOROUGH		35	
Sewer Structure	SA16AAWBO						3094	
Sewer Control Valve	SSO 112				FAIRMOUNT AT FAIRFAX		7	
Sewer Control Valve	SSO 99				FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		6	
Sewer Control Valve	SSO 432				3012 NORTH WOODLAND		14	
Sewer Control Valve	DB-03						55	
Sewer Control Valve	DB-01						56	
Sewer Control Valve	DB-02						57	
Sewer Control Valve	CH-04				FAIRMOUNT AT DARTMOOR		5	
Sewer Control Valve	SSO 110				FAIRMOUNT AT WELLINGTON		44	
Sewer Control Valve	SSO 87				FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		33	
Sewer Control Valve	SSO 116				FAIRMOUNT AT MARLBORO		4	
Sewer Control Valve	SSO 111				FAIRMOUNT AT ARLINGTON		46	
Sewer Control Valve	SSO 113				FAIRMOUNT & COVENTRY (SCARBOROUGH)		37	
Sewer Control Valve	SSO 124				FAIRMOUNT AND COVENTRY		47	
Sewer Control Valve	CH-50				SCARBOROUGH AT LAMBERTON		53	
Sewer Control Valve	SSO 129				BRADFORD AND LEE		11	
Sewer Control Valve	CH-52				EDDINGTON		2	
Sewer Control Valve	SSO 88				HAMPSHIRE LANE AT MAYFIELD (18")		42	
Sewer Control Valve	SSO 122				EAST OVERLOOK AT EDGEHILL		36	
Sewer Control Valve	SSO 89				HAMPSHIRE LANE AT MAYFIELD (36")		34	
Sewer Structure	SA16ADZBO						1536	
Sewer Control Valve	SSO 91				HAMPSHIRE AT EUCLID HTS. BLVD.		20	
Sewer Structure	SA16ADPH0						4446	
Sewer Control Valve	SSO 120				CEDAR BTW. FAIRMOUNT/DEMINGTON		8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210602-0001

Work Order Detail Report

6/3/2021

SSO INSPECTION 5-28-2021 1.25 INCHES OF RAIN

1:17 PM

SSO 103	19
Sewer Control Valve SSO 104	3003 EUCLID HEIGHTS BLVD 15
Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior R 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQQD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

Work Order Detail Report

6/3/2021

SSO INSPECTION 5-28-2021 1.25 INCHES OF RAIN

1:17 PM

Check List					
	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	6/3/2021/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	6/3/2021/	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	6/2/2021/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	6/2/2021/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	6/3/2021/	
Reset block					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	6/3/2021/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	6/3/2021/	
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	6/3/2021/	
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	6/3/2021/	
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Not Sound	6/3/2021/	
Reset block					
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	6/3/2021/	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	6/3/2021/	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	6/3/2021/	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	6/3/2021/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	6/3/2021/	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	6/3/2021/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	/	
Reset					
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	6/3/2021/	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	6/3/2021/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	6/3/2021/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	6/3/2021/	
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	6/3/2021/	
Board came off replaced					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	6/2/2021/	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	6/2/2021/	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	6/2/2021/	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210602-0001

Work Order Detail Report

6/3/2021

SSO INSPECTION 5-28-2021 1.25 INCHES OF RAIN

1:17 PM

26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	6/2/2021/
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	6/2/2021/
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	6/2/2021/
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	6/2/2021/
30	B-15 COVENTRY AND CEDAR SA16ADB0	<input type="checkbox"/>	Sound	6/2/2021/
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	6/2/2021/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	6/3/2021/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	6/2/2021/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	6/3/2021/
Block came off put new block and reset				
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	6/2/2021/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	6/2/2021/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	6/2/2021/
39	C-17 1685 CUMBERLAND RD SA16AQIB0	<input type="checkbox"/>	Sound	6/2/2021/
40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Sound	6/2/2021/
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	6/2/2021/
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	6/2/2021/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	6/2/2021/
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Not Sound	6/2/2021/
No string or block				
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	6/2/2021/

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:		*Cal'c UC: \$10.14	*Task Cost: \$456.24	Start Dt:	6/2/2021
Supervisor:	UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:	
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
9512 DelZoppo, Michael	Hours	4.00	\$86.16		6/2/2021	
11213 Owens, Will	Hours	4.00	\$90.56		6/2/2021	
22394 Cardarella, Joe	Hours	8.00	\$172.32		6/2/2021	
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB	Hours	8.00	\$107.20		6/2/2021	
5						
Task Comment: SSO INSPECTIONS 5-28-2021 1.25 INCHES OF RAIN						

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210602-0001

Work Order Detail Report

6/3/2021

SSO INSPECTION 5-28-2021 1.25 INCHES OF RAIN

1:17 PM

			*Actual	*Estimated	*Difference
Projected Complete:		Lock: <input type="checkbox"/>	WO Duration	8.00	0.00
Repair Type:			Labor Hours	16.00	0.00
Subcontractor:			Labor Costs	\$349.04	\$0.00
Profit Center:			Material Costs	0.00	0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Fluids Costs	0.00	0.00
Unit of Measure:	Each		Equipment Costs	107.20	0.00
*Unit Cost:	\$0.00		Contractor Costs	0.00	0.00
WO Hours:	0.00		Misc. Costs	0.00	0.00
			Total Costs	\$456.24	\$0.00
			Use Task Info:	True	True

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	<input type="checkbox"/>
Invoice Number:		Date Bill Sent:	<input type="checkbox"/>
Incoming Account #:		Payment Received:	<input type="checkbox"/>
		Payment Method:	<input type="checkbox"/>
Imported to Financials: <input type="checkbox"/>			

Associated PMs		PM Code and Description	Closed
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>

Tracking					
<u>Item</u>	<u>Description</u>	<u>By</u>	<u>Date</u>	<u>Time</u>	
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	6/2/2021	8:51 AM	
Supervisor Notification	Email Queued Successfully!	jjackson	6/2/2021	8:51 AM	
Email Successfully Sent	jjackson@clvhts.com Lucy Work Order	BackgroundTaskUser	6/3/2021	12:43 PM	
Status Change	Update - Supervisor	aferrone	6/3/2021	1:16 PM	
From New Work Order to Complete					

Rates:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned ,	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>
Test Performed Through:	Appointment Date: 6/2/2021	7:30 AM
Dye Test Results:		
WO User 51:	E Mail:	
Measurement:	WO User 22:	
History:		

Work Order Detail Report

6/3/2021

SSO INSPECTION 5-28-2021 1.25 INCHES OF RAIN

1:17 PM

Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sled		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 6/2/2021	PM Trigger:	Rec #: 7735