


# Northeast Ohio Regional Sewer District

## Daily Precipitation Report Sunday, June 20, 2021

Accumulation in Inches



**Northeast Ohio Regional Sewer District****Daily Precipitation Report****Sunday, June 20, 2021**

<u>Site Location</u>	<u>Peak Accumulation (inches)</u>				
	<u>24-Hour</u>	<u>6-Hour</u>	<u>3-Hour</u>	<u>1-Hour</u>	<u>15-Minute</u>
Beachwood	0.72	0.72	0.72	0.70	0.36
Brecksville	0.11	0.08	0.08	0.07	0.07
Brook Park	0.77	0.77	0.77	0.77	0.53
Cleveland Industrial Pkwy	0.54	0.54	0.54	0.54	0.39
Dille Ave PS	0.27	0.27	0.27	0.27	0.11
Division Ave PS	0.94	0.94	0.94	0.94	0.52
Easterly WWTP	0.28	0.28	0.28	0.15	0.13
Independence	0.23	0.23	0.23	0.23	0.19
James Rhodes HS	0.86	0.86	0.86	0.86	0.54
Jennings PS	0.71	0.71	0.71	0.71	0.46
Macedonia	0.05	0.02	0.02	0.01	0.01
Maple Heights	0.69	0.69	0.69	0.68	0.43
Mary Street PS	0.35	0.35	0.35	0.35	0.18
Mayfield Heights	0.41	0.41	0.41	0.41	0.30
Moreland Hills	1.02	1.02	1.02	0.99	0.37
North Olmsted	0.36	0.36	0.36	0.36	0.25
North Royalton	0.07	0.07	0.07	0.07	0.07
Oakwood	0.04	0.04	0.04	0.04	0.03
Olmsted Falls	0.11	0.11	0.11	0.11	0.11
Parma	0.28	0.28	0.28	0.28	0.18
Richfield	0.00	0.00	0.00	0.00	0.00
Shaker Heights	1.44	1.44	1.44	1.34	0.55
South Euclid	0.23	0.23	0.23	0.23	0.13
Southerly WWTC	n/a	n/a	n/a	n/a	n/a
Strongsville C WWTP	0.20	0.20	0.20	0.20	0.19
Strongsville Foltz	0.00	0.00	0.00	0.00	0.00
University Heights	0.89	0.89	0.89	0.89	0.52
Wade Park	0.72	0.72	0.72	0.71	0.42
Westlake	0.40	0.40	0.40	0.40	0.35

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-20-2021 0.89 INCHES OF RAIN

1:32 PM

WO Number: 210622-0001	Category:	SSOs
Status: Complete	Problem:	Storm Response
Status Date: 6/30/2021 1:31 pm	Main Task:	Inspection

Asset: SSO 431	
Location: FAIRFAX AT NORTH PARK	

Cause: Weather	Assigned By:
Assigned Crew:	Assigned Date:
Supervisor: Jackson, Jeff	Start Date: 6/20/2021 8:00 AM
Lead Worker: Cardarella, Joe	End Date: 6/23/2021
Priority: High	<u>Override Notifications</u>
Account #:	Problem <input type="checkbox"/>
Proj No - Acct:	Overdue <input type="checkbox"/>
Project:	Lead Worker <input type="checkbox"/>
Reason:	Task <input type="checkbox"/>
Received By:	Supervisor <input type="checkbox"/>
Inspected By:	Hard Lock WO <input type="checkbox"/>

### Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

### Location

Department: Sewer Collection  
Division: Sewer Collection

Comments for Crew  
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:  
Area:  
Sub-Area:  
Owner:  
Location:  
Classification:

### Maintenance Zone:

### Alternate Zone:

Work Order Locations		
<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH

**Work Order Detail Report**

6/30/2021

SSO INSPECTION 6-20-2021 0.89 INCHES OF RAIN

1:32 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-20-2021 0.89 INCHES OF RAIN

1:32 PM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-20-2021 0.89 INCHES OF RAIN

1:32 PM

### Work Order Assets

Object Type	System ID 1	System ID 2	Description 1	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve						FAIRFAX AT NORTH PARK		
SSO 431							26	
Sewer Control Valve						NORTH PARK AND COVENTRY		
SSO 114							16	
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121							35	
Sewer Structure							3094	
SA16AAWB0								
Sewer Control Valve						FAIRMOUNT AT FAIRFAX		
SSO 112							7	
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99							6	
Sewer Control Valve						3012 NORTH WOODLAND		
SSO 432							14	
Sewer Control Valve							55	
DB-03								
Sewer Control Valve							56	
DB-01								
Sewer Control Valve							57	
DB-02								
Sewer Control Valve						FAIRMOUNT AT DARTMOOR		
CH-04							5	
Sewer Control Valve						FAIRMOUNT AT WELLINGTON		
SSO 110							44	
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87							33	
Sewer Control Valve						FAIRMOUNT AT MARLBORO		
SSO 116							4	
Sewer Control Valve						FAIRMOUNT AT ARLINGTON		
SSO 111							46	
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113							37	
Sewer Control Valve						FAIRMOUNT AND COVENTRY		
SSO 124							47	
Sewer Control Valve						SCARBOROUGH AT LAMBERTON		
CH-50							53	
Sewer Control Valve						BRADFORD AND LEE		
SSO 129							11	
Sewer Control Valve						EDDINGTON		
CH-52							2	
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88							42	
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL		
SSO 122							36	
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89							34	
Sewer Structure							1536	
SA16ADZB0								
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91							20	
Sewer Structure							4446	
SA16ADPH0								
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120							8	
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY		

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210622-0001

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-20-2021 0.89 INCHES OF RAIN

1:32 PM

SSO 103	19
Sewer Control Valve SSO 104	3003 EUCLID HEIGHTS BLVD 15
Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior R 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQD0	4987
Sewer Structure SA16AQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-20-2021 0.89 INCHES OF RAIN

1:32 PM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	6/23/2021/	
Reset					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	6/23/2021/	
3	A-45-FAIRMOUNT ( IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	6/23/2021/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	6/23/2021/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	6/23/2021/	
Reset					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	6/23/2021/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	6/23/2021/	
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	/	6/23/2021
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	6/23/2021/	
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	6/23/2021/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	6/22/2021/	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	6/23/2021/	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	6/23/2021/	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	6/23/2021/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	6/23/2021/	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	6/23/2021/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	6/23/2021/	
Reset					
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	6/22/2021/	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	6/22/2021/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	6/22/2021/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Not Sound	6/22/2021/	
Reset					
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	6/22/2021/	
Reset					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	6/22/2021/	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	6/22/2021/	

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210622-0001

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-20-2021 0.89 INCHES OF RAIN

1:32 PM

25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	6/22/2021/
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	/
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO	<input type="checkbox"/>	Sound	6/22/2021/
28	B-46 EDGEHILL AT E OVERLOOK SA16AEFP0	<input type="checkbox"/>	Not Sound	6/22/2021/
Reset				
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	6/22/2021/
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	6/22/2021/
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	6/22/2021/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	6/22/2021/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	6/22/2021/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	6/23/2021/
Reset				
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	6/22/2021/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Not Sound	6/22/2021/
Reset				
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Not Sound	6/22/2021/
Reset				
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	/
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	6/22/2021/
40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	6/22/2021/
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	6/22/2021/
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	6/22/2021/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	6/22/2021/
44	C-51 AATHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Not Sound	6/22/2021/
String is twisted				
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	6/22/2021/

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:		*Cal'c UC: \$6.21	*Task Cost: \$279.52	Start Dt: 6/20/2021	
Supervisor:	UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:	
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	8.00	\$172.32		6/20/2021	
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB	Hours	8.00	\$107.20		6/20/2021	

Task Comment: SSO INSPECTION 6-20-2021 0.89 INCHES OF RAIN

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-20-2021 0.89 INCHES OF RAIN

1:32 PM

			*Actual	*Estimated	*Difference
Projected Complete:		Lock: <input type="checkbox"/>	WO Duration	24.00	0.00
Repair Type:			Labor Hours	8.00	0.00
Subcontractor:			Labor Costs	\$172.32	\$0.00
Profit Center:			Material Costs	0.00	0.00
			Fluids Costs	0.00	0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Equipment Costs	107.20	0.00
Unit of Measure:	Each		Contractor Costs	0.00	0.00
*Unit Cost:	\$0.00		Misc. Costs	0.00	0.00
WO Hours:	0.00		Total Costs	\$279.52	\$0.00
			Use Task Info:	True	True

Billed Party		Billing	
Customer ID:	Customer Number:		
Customer Name:	Last Name:		
Address:			
City:	Phone:	Cell #:	
State:	Fax #:		
Zip:	E-mail:		
Billing Data			
Contact Name:	*Billing Amount:		Billing Required: <input type="checkbox"/>
Invoice Number:	Date Bill Sent:		Billing Processed: <input type="checkbox"/>
Incoming Account #:	Payment Received:		Imported to Financials: <input type="checkbox"/>
	Payment Method:		

Associated PMs		PM Code and Description		
		SSO-02 SSO INSPECTION		

Tracking		Closed		
<b>Item</b>	<b>Description</b>	<b>By</b>	<b>Date</b>	<b>Time</b>
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	6/22/2021	8:34 AM
Supervisor Notification	Email Queued Successfully!	jjackson	6/22/2021	8:34 AM
Email Successfully Sent	jjackson@clvhts.com Lucity Work Order	BackgroundTaskUser	6/22/2021	8:35 AM
Status Change	Update - Supervisor From New Work Order to Complete	aferrone	6/30/2021	1:31 PM

Rates:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned ,	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>
Test Performed Through:	Appointment Date: 6/22/2021	7:30 AM
Dye Test Results:		
WO User 51:	E Mail:	
Measurement:	WO User 22:	
History:		

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-20-2021 0.89 INCHES OF RAIN


1:32 PM

Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sled		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:			
WO User 40:	OUPS #:		
WO User 41:	WO User 48:		
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 6/22/2021	PM Trigger:	Rec #: 7771

# Northeast Ohio Regional Sewer District

Daily Precipitation Report  
Friday, June 25, 2021

Accumulation in Inches



**Northeast Ohio Regional Sewer District****Daily Precipitation Report****Friday, June 25, 2021**

<u>Site Location</u>	<u>Peak Accumulation (inches)</u>				
	<u>24-Hour</u>	<u>6-Hour</u>	<u>3-Hour</u>	<u>1-Hour</u>	<u>15-Minute</u>
Beachwood	0.24	0.24	0.15	0.10	0.10
Brecksville	0.15	0.15	0.10	0.07	0.07
Brook Park	0.73	0.73	0.43	0.33	0.21
Cleveland Industrial Pkwy	0.53	0.52	0.34	0.27	0.12
Dille Ave PS	n/a	n/a	n/a	n/a	n/a
Division Ave PS	0.43	0.42	0.32	0.28	0.12
Easterly WWTP	n/a	n/a	n/a	n/a	n/a
Independence	0.39	0.36	0.26	0.23	0.13
James Rhodes HS	0.45	0.45	0.24	0.21	0.16
Jennings PS	0.42	0.42	0.25	0.17	0.13
Macedonia	0.09	0.09	0.06	0.06	0.03
Maple Heights	0.40	0.39	0.32	0.26	0.21
Mary Street PS	0.51	0.47	0.32	0.25	0.13
Mayfield Heights	0.32	0.30	0.21	0.19	0.18
Moreland Hills	0.28	0.28	0.26	0.23	0.18
North Olmsted	0.49	0.49	0.39	0.32	0.13
North Royalton	0.33	0.32	0.21	0.11	0.10
Oakwood	0.16	0.16	0.14	0.13	0.12
Olmsted Falls	0.71	0.70	0.47	0.36	0.20
Parma	0.32	0.31	0.19	0.16	0.06
Richfield	0.16	0.16	0.14	0.14	0.05
Shaker Heights	0.24	0.23	0.15	0.11	0.06
South Euclid	0.38	0.34	0.22	0.18	0.08
Southerly WWTC	0.23	0.22	0.15	0.12	0.05
Strongsville C WWTP	0.39	0.38	0.25	0.21	0.08
Strongsville Foltz	0.39	0.37	0.22	0.19	0.07
University Heights	0.35	0.34	0.19	0.15	0.14
Wade Park	0.46	0.44	0.29	0.24	0.13
Westlake	0.43	0.37	0.33	0.26	0.09

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-25-2021 0.35 INCHES OF RAIN

12:19 PM

WO Number: 210629-0009	Category:	SSOs
Status: Complete	Problem:	Storm Response
Status Date: 6/30/2021 12:18 pm	Main Task:	Inspection

Asset: SSO 431

Location: FAIRFAX AT NORTH PARK

Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	6/29/2021 8:00 AM
Lead Worker:	DelZoppo, Michael	End Date:	6/29/2021
Priority:	High	Override Notifications	<input type="checkbox"/>
Account #:		Problem	<input type="checkbox"/>
Proj No - Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

### Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

#### Location

Department: Sewer Collection  
Division: Sewer Collection

Comments for Crew  
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations		
<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-25-2021 0.35 INCHES OF RAIN

12:19 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210629-0009

**Work Order Detail Report**

SSO INSPECTION 6-25-2021 0.35 INCHES OF RAIN

6/30/2021

12:19 PM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-25-2021 0.35 INCHES OF RAIN

12:19 PM

Work Order Assets								
Object Type	System ID 1	System ID 2	Description 1	Hourmeter	Othermeter	PM Description	Asset ID	Completed
			Odometer					
Sewer Control Valve						FAIRFAX AT NORTH PARK		
SSO 431							26	
Sewer Control Valve						NORTH PARK AND COVENTRY		
SSO 114							16	
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121							35	
Sewer Structure								
SA16AAWB0							3094	
Sewer Control Valve						FAIRMOUNT AT FAIRFAX		
SSO 112							7	
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99							6	
Sewer Control Valve						3012 NORTH WOODLAND		
SSO 432							14	
Sewer Control Valve								
DB-03							55	
Sewer Control Valve								
DB-01							56	
Sewer Control Valve								
DB-02							57	
Sewer Control Valve						FAIRMOUNT AT DARTMOOR		
CH-04							5	
Sewer Control Valve						FAIRMOUNT AT WELLINGTON		
SSO 110							44	
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87							33	
Sewer Control Valve						FAIRMOUNT AT MARLBORO		
SSO 116							4	
Sewer Control Valve						FAIRMOUNT AT ARLINGTON		
SSO 111							46	
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113							37	
Sewer Control Valve						FAIRMOUNT AND COVENTRY		
SSO 124							47	
Sewer Control Valve						SCARBOROUGH AT LAMBERTON		
CH-50							53	
Sewer Control Valve						BRADFORD AND LEE		
SSO 129							11	
Sewer Control Valve						EDDINGTON		
CH-52							2	
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88							42	
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL		
SSO 122							36	
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89							34	
Sewer Structure								
SA16ADZB0							1536	
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91							20	
Sewer Structure								
SA16ADPH0							4446	
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120							8	
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY		

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210629-0009

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-25-2021 0.35 INCHES OF RAIN

12:19 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-25-2021 0.35 INCHES OF RAIN

12:19 PM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	6/29/2021/ 8:30 am	
	No overflow				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	6/29/2021/ 8:34 am	
	No overflow				
3	A-45-FAIRMOUNT ( IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	6/29/2021/ 8:39 am	
	No overflow				
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	6/29/2021/ 8:47 am	
	No overflow				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	6/29/2021/ 8:51 am	
	No overflow				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	6/29/2021/ 8:55 am	
	No overflow				
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	6/29/2021/ 8:57 am	
	No overflow				
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	6/29/2021/ 9:00 am	
	No overflow				
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	6/29/2021/ 9:03 am	
	No overflow				
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	6/29/2021/ 9:06 am	
	No overflow				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	6/29/2021/ 9:08 am	
	No overflow				
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	6/29/2021/ 9:11 am	
	No overflow				
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	6/29/2021/ 9:15 am	
	No overflow				
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	6/29/2021/ 9:18 am	
	No overflow				
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	6/29/2021/ 9:20 am	
	No overflow				
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	6/29/2021/ 9:23 am	
	No overflow				
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	6/29/2021/ 9:25 am	
	No overflow				
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	6/29/2021/ 9:31 am	
	Overflow				

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210629-0009

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-25-2021 0.35 INCHES OF RAIN

12:19 PM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	6/29/2021/ 9:37 am
	No overflow			
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	6/29/2021/ 9:42 am
	No overflow			
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	6/29/2021/ 9:45 am
	No overflow			
22	A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	<input type="checkbox"/>	Sound	6/29/2021/ 9:49 am
	Block missing			
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	6/29/2021/12:18 pm
	No overflow			
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	6/29/2021/12:21 pm
	No overflow			
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	6/29/2021/12:22 pm
	No overflow			
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	6/29/2021/12:26 pm
	Overflow. Rope. Broken needs replacing.			
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO	<input type="checkbox"/>	Sound	6/29/2021/12:29 pm
	No overflow			
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	6/29/2021/12:31 pm
	No overflow			
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	6/29/2021/12:35 pm
	Overflow			
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	6/29/2021/12:40 pm
	No overflow			
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	6/29/2021/12:42 pm
	No overflow			
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	6/29/2021/12:46 pm
	No overflow			
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	6/29/2021/12:51 pm
	No overflow			
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	6/29/2021/12:57 pm
	Overflow			
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	6/29/2021/ 1:00 pm
	No overflow			
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	6/29/2021/ 1:04 pm
	Overflow			
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	6/29/2021/ 1:06 pm
	No overflow			
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	6/29/2021/ 1:08 pm
	No overflow			
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	6/29/2021/ 1:09 pm
	No overflow			

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210629-0009

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-25-2021 0.35 INCHES OF RAIN

12:19 PM

40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Sound	6/29/2021/ 1:47 pm
No overflow				
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	6/29/2021/ 1:48 pm
No overflow				
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	6/29/2021/ 1:55 pm
No overflow				
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	6/29/2021/ 1:59 pm
No overflow				
44	C-51 AATHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	6/29/2021/ 2:02 pm
Tangled				
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	6/29/2021/ 2:03 pm
No overflow				

### Tasks/Resources

#### SWCT26 Inspection

Crew:	Status:	*Cal'c UC: \$10.24	*Task Cost: \$460.64	Start Dt: 6/29/2021
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:
<b>Employee</b>				
<b>Resource</b>	<b>UOM</b>	<b>Units</b>	<b>*Total Cost</b>	<b>Alt Description</b>
11213 Owens, Will	Hours	8.00	\$181.12	6/29/2021
9512 DelZoppo, Michael	Hours	8.00	\$172.32	6/29/2021
<b>Equipment</b>				
<b>Resource</b>	<b>UOM</b>	<b>Units</b>	<b>*Total Cost</b>	<b>Alt Description</b>
CHFLT50 FORD F250 CREW CAB	Hours	8.00	\$107.20	6/29/2021
5				

Task Comment: SSO INSPECTION 6-25-2021 0.35 INCHES OF RAIN

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	0.00	0.00	0.00
Subcontractor:		Labor Costs	16.00	0.00	0.00
Profit Center:		Material Costs	\$353.44	\$0.00	\$0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Lock: <input type="checkbox"/>	Equipment Costs	0.00	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	107.20	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$460.64	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:		Cell #:
City:		Fax #:		
State:		E-mail:		
Zip:				
Billing Data		*Billing Amount:	Billing Required: <input type="checkbox"/>	
Contact Name:		Date Bill Sent:	Billing Processed: <input type="checkbox"/>	
Invoice Number:		Payment Received:	Imported to Financials: <input type="checkbox"/>	
Incoming Account #:		Payment Method:		

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-25-2021 0.35 INCHES OF RAIN

12:19 PM

Associated PMs		PM Code and Description	Closed	
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>	
Item	Tracking	Description	By	Date Time
Work Order Creation		From Routine Work SSO-02 - SSO INSPECTION	jjackson	6/29/2021 7:17 AM
Supervisor Notification		Email Queued Successfully!	jjackson	6/29/2021 7:17 AM
Email Successfully Sent		jjackson@clvhts.com Lucity Work Order	BackgroundTaskUser	6/29/2021 7:17 AM
Status Change		Update - Supervisor	aferrone	6/30/2021 12:18 PM
Rates:		Opened At:		Televised: <input type="checkbox"/>
Received By:		Pipe Footage Cleaned.		Power Rooter: <input type="checkbox"/>
Work From:		Gallons Used:		Jet: <input type="checkbox"/>
Pipe Size:		WO User 23:		Gap Vac: <input type="checkbox"/>
Pipe Condition:		WO User 24:		Dye Test: <input type="checkbox"/>
Could Not Open:		WO User 9:		Gap Root Cut: <input type="checkbox"/>
Additional Repair:		User 10:		GIS Correction?: <input type="checkbox"/>
Dye Test Reason:		Appointment Date DNL		Test Tee Correction: <input type="checkbox"/>
Test Performed Through:		Appointment Date:	6/29/2021	7:30 AM
Dye Test Results:				
WO User 51:		E Mail:		
Measurement:		WO User 22:		
History:				
Manhole Basin Repair:		Pipe Size:		
Material Used:		PVC Tees, Angles, Sled		
Pipe Repair:		WO User 44:		
Street Repair:		WO User 45:		
Grass Repair:		WO User 46:		
Curb Repair:				
Driveway- Sidewalk Repair:				
Construction Crew:				
WO User 39:		OUPS #:		
WO User 40:		WO User 48:		
WO User 41:				
WO User 52:		WO User 62:		
WO User 53:		WO User 63:		
WO User 54:		WO User 64:		
WO User 55:		WO User 65:		
WO User 56:		WO User 66:		
WO User 57:		WO User 67:		
WO User 58:		WO User 68:		
WO User 59:		WO User 69:		
WO User 60:		WO User 70:		
WO User 61:		WO User 71:		
WO User 72:		WO User 82:		Televised: <input type="checkbox"/>
WO User 73:		Quantity:		Paid: <input type="checkbox"/>
WO User 74:		WO User 84:		WO User 104: <input type="checkbox"/>
WO User 75:		WO User 85:		WO User 105: <input type="checkbox"/>
WO User 76:		WO User 86:		WO User 106: <input type="checkbox"/>
WO User 92 Date:		WO User 97 Date:		
WO User 93 Date:		WO User 98 Date:		
WO User 94 Date:		WO User 99 Date:		
WO User 95 Date:		WO User 100 Date:		
WO User 96 Date:		WO User 101 Date:		

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210629-0009

## Work Order Detail Report

6/30/2021

SSO INSPECTION 6-25-2021 0.35 INCHES OF RAIN

12:19 PM

WO User 77:

WO User 87:

WO User 107:

WO User 78:

WO User 88:

WO User 108:

WO User 79:

WO User 89:

WO User 109:

WO User 80:

WO User 90:

WO User 110:

WO User 81:

WO User 91:

WO User 111:

WO Creator: jjackson

WO Creation Date: 6/29/2021

PM Trigger:

Rec #: 7780