


Daily Precipitation Report
Thursday, July 8, 2021
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report


Thursday, July 8, 2021

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	1.06	1.03	0.92	0.61	0.54
Brecksville	1.01	0.98	0.79	0.78	0.66
Brook Park	2.01	1.25	1.21	0.83	0.56
Cleveland Industrial Pkwy	0.92	0.68	0.67	0.45	0.35
Dille Ave PS	n/a	n/a	n/a	n/a	n/a
Division Ave PS	0.80	0.75	0.71	0.43	0.32
Easterly WWTP	0.79	0.79	0.75	0.61	0.43
Independence	0.80	0.72	0.72	0.41	0.29
James Rhodes HS	0.81	0.69	0.68	0.35	0.25
Jennings PS	0.65	0.62	0.61	0.38	0.26
Macedonia	0.34	0.30	0.25	0.25	0.19
Maple Heights	0.53	0.51	0.51	0.28	0.24
Mary Street PS	1.01	0.99	0.99	0.80	0.68
Mayfield Heights	0.89	0.86	0.77	0.61	0.36
Moreland Hills	0.45	0.43	0.42	0.21	0.17
North Olmsted	0.99	0.63	0.50	0.50	0.36
North Royalton	1.14	1.10	0.90	0.89	0.73
Oakwood	0.48	0.47	0.47	0.46	0.38
Olmsted Falls	2.07	1.52	1.48	1.01	0.95
Parma	0.39	0.36	0.22	0.22	0.20
Richfield	0.67	0.64	0.49	0.46	0.46
Shaker Heights	0.59	0.57	0.56	0.55	0.49
South Euclid	0.41	0.39	0.35	0.20	0.13
Southerly WWTC	0.38	0.35	0.33	0.31	0.28
Strongsville CWWTP	0.81	0.69	0.68	0.60	0.40
Strongsville Foltz	0.30	0.24	0.21	0.21	0.15
University Heights	0.50	0.48	0.47	0.43	0.35
Wade Park	0.92	0.89	0.89	0.46	0.38
Westerly WWTP	0.80	0.75	0.70	0.49	0.34
Westlake	0.54	0.39	0.31	0.21	0.16



Sunday, July 11, 2021

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report


Sunday, July 11, 2021

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	1.08	1.07	0.57	0.47	0.22	0.12
Brecksville	1.25	1.24	0.81	0.49	0.31	0.20
Brook Park	0.90	0.90	0.57	0.55	0.24	0.11
Cleveland Industrial Pkwy	0.85	0.85	0.51	0.48	0.22	0.09
Dille Ave PS	n/a	n/a	n/a	n/a	n/a	n/a
Division Ave PS	0.86	0.86	0.54	0.49	0.21	0.09
Easterly WWTP	0.81	0.81	0.55	0.47	0.19	0.09
Independence	1.00	0.98	0.55	0.41	0.20	0.12
James Rhodes HS	1.00	1.00	0.71	0.63	0.23	0.09
Jennings PS	1.01	1.01	0.69	0.65	0.31	0.14
Macedonia	1.30	1.26	1.15	0.80	0.37	0.20
Maple Heights	1.23	1.21	0.62	0.57	0.32	0.16
Mary Street PS	0.90	0.90	0.61	0.52	0.20	0.08
Mayfield Heights	0.96	0.95	0.51	0.36	0.15	0.07
Moreland Hills	1.04	1.03	0.72	0.49	0.20	0.11
North Olmsted	0.77	0.77	0.49	0.49	0.26	0.10
North Royalton	0.99	0.97	0.68	0.38	0.18	0.12
Oakwood	0.98	0.96	0.82	0.57	0.25	0.10
Olmsted Falls	0.81	0.81	0.46	0.45	0.27	0.10
Parma	0.85	0.85	0.50	0.48	0.25	0.10
Richfield	1.30	1.25	1.08	0.65	0.27	0.11
Shaker Heights	1.10	1.10	0.62	0.54	0.20	0.10
South Euclid	0.99	0.98	0.57	0.50	0.15	0.08
Southerly WWTC	0.80	0.80	0.41	0.37	0.17	0.08
Strongsville C WWTP	0.93	0.93	0.57	0.56	0.23	0.09
Strongsville Foltz	1.04	1.04	0.69	0.69	0.38	0.17
University Heights	1.21	1.21	0.77	0.69	0.28	0.11
Wade Park	0.82	0.82	0.55	0.51	0.22	0.09
Westerly WWTP	0.81	0.81	0.54	0.49	0.23	0.09
Westlake	0.61	0.61	0.39	0.38	0.19	0.08

Daily Precipitation Report

Monday, July 12, 2021

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report


Monday, July 12, 2021

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.48	0.47	0.25	0.25	0.11
Brecksville	1.91	1.66	1.46	1.41	0.61
Brook Park	1.37	1.28	0.94	0.89	0.63
Cleveland Industrial Pkwy	1.10	1.03	0.59	0.55	0.44
Dille Ave PS	n/a	n/a	n/a	n/a	n/a
Division Ave PS	0.66	0.61	0.33	0.29	0.19
Easterly WWTP	0.53	0.51	0.46	0.42	0.30
Independence	1.53	1.49	1.04	0.75	0.38
James Rhodes HS	n/a	n/a	n/a	n/a	n/a
Jennings PS	0.94	0.88	0.47	0.42	0.30
Macedonia	1.34	1.19	1.10	0.90	0.62
Maple Heights	1.50	1.46	0.91	0.91	0.54
Mary Street PS	0.79	0.75	0.41	0.39	0.32
Mayfield Heights	0.51	0.51	0.34	0.33	0.19
Moreland Hills	1.46	1.43	0.87	0.70	0.52
North Olmsted	0.94	0.81	0.56	0.56	0.34
North Royalton	1.14	1.10	0.65	0.47	0.33
Oakwood	1.15	1.10	0.94	0.66	0.38
Olmsted Falls	2.11	1.97	1.57	1.55	0.96
Parma	1.25	1.21	0.88	0.66	0.39
Richfield	1.18	1.15	0.61	0.54	0.36
Shaker Heights	1.08	1.06	0.56	0.56	0.32
South Euclid	0.61	0.58	0.46	0.42	0.19
Southerly WWTC	1.19	1.16	0.77	0.76	0.47
Strongsville C WWTP	1.85	1.76	1.50	1.21	0.51
Strongsville Foltz	2.47	2.40	1.97	1.81	0.61
University Heights	0.77	0.75	0.50	0.49	0.31
Wade Park	1.54	1.50	1.37	1.34	0.82
Westerly WWTP	0.54	0.48	0.35	0.29	0.20
Westlake	0.34	0.31	0.21	0.21	0.12

0.06



Daily Precipitation Report
Tuesday, July 13, 2021
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Tuesday, July 13, 2021

Peak Accumulation (inches)						
Site Location	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.41	0.41	0.41	0.39	0.29	0.17
Brecksville	0.20	0.19	0.19	0.19	0.16	0.09
Brook Park	0.32	0.25	0.25	0.25	0.23	0.16
Cleveland Industrial Pkwy	0.42	0.37	0.37	0.37	0.19	0.13
Dille Ave PS	0.56	0.47	0.47	0.47	0.43	0.28
Division Ave PS	0.29	0.22	0.22	0.22	0.14	0.08
Easterly WWTP	0.40	0.39	0.39	0.39	0.18	0.12
Independence	0.54	0.53	0.53	0.51	0.40	0.18
James Rhodes HS	n/a	n/a	n/a	n/a	n/a	n/a
Jennings PS	n/a	n/a	n/a	n/a	n/a	n/a
Macedonia	0.30	0.29	0.29	0.29	0.22	0.11
Maple Heights	0.38	0.37	0.37	0.35	0.27	0.15
Mary Street PS	0.59	0.55	0.55	0.55	0.36	0.22
Mayfield Heights	0.80	0.79	0.79	0.76	0.50	0.34
Moreland Hills	0.40	0.39	0.39	0.39	0.30	0.20
North Olmsted	0.28	0.28	0.28	0.28	0.15	0.09
North Royalton	0.52	0.52	0.52	0.51	0.43	0.19
Oakwood	0.25	0.25	0.25	0.25	0.23	0.14
Olmsted Falls	0.51	0.51	0.51	0.48	0.26	0.15
Parma	0.41	0.31	0.31	0.30	0.24	0.16
Richfield	0.41	0.40	0.40	0.40	0.31	0.15
Shaker Heights	0.44	0.44	0.44	0.42	0.32	0.15
South Euclid	0.78	0.75	0.70	0.69	0.57	0.38
Southerly WWTC	0.22	0.22	0.22	0.21	0.19	0.12
Strongsville C WWTP	0.57	0.35	0.35	0.35	0.31	0.26
Strongsville Foltz	0.47	0.25	0.25	0.25	0.22	0.10
University Heights	0.73	0.73	0.73	0.70	0.50	0.33
Wade Park	0.73	0.62	0.62	0.62	0.45	0.27
Westerly WWTP	0.29	0.28	0.28	0.27	0.18	0.14
Westlake	0.20	0.20	0.20	0.20	0.12	0.06

Work Order Detail Report

7/16/2021

SSO INSPECTION-SEVERAL DAYS OF RAIN JULY 2021

11:26 AM

WO Number: 210713-0001		Category:	SSOs	
Status: Complete		Problem:	Storm Response	
Status Date: 7/16/2021 11:26 am		Main Task:	Inspection	
Asset: SSO 431				
Location: FAIRFAX AT NORTH PARK				
Cause: Weather		Assigned By:		
Assigned Crew:		Assigned Date:		
Supervisor: Jackson, Jeff		Start Date: 7/13/2021 7:17 AM	Override	
Lead Worker: Cardarella, Joe		End Date: 7/14/2021 11:16 AM	Notifications	
Priority: High				
Account #:				
Proj No - Acct:		Project ID:		
Project:		Project Name:		
Reason:				
Received By:				
Inspected By:				

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection
Sub-Division:
Area:
Sub-Area:
Owner:
Location:
Classification:
Maintenance Zone:

Alternate Zone:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Locations

<u>Address</u>		<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

7/16/2021

SSO INSPECTION-SEVERAL DAYS OF RAIN JULY 2021

11:26 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

* A 'Hidden' field indicates permission to view the secured field is turned off.

Work Order Detail Report

7/16/2021

SSO INSPECTION-SEVERAL DAYS OF RAIN JULY 2021

11:26 AM

2,224,536.21778722	668,887.44048372
2,226,741.35609348	679,432.95121680
2,226,591.76420106	679,420.92761880
2,227,825.14395215	684,881.15948047

Work Order Detail Report

7/16/2021

SSO INSPECTION-SEVERAL DAYS OF RAIN JULY 2021

11:26 AM

Work Order Assets							
Object Type	Description 1		Description 2				
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve					FAIRFAX AT NORTH PARK		
SSO 431						26	
Sewer Control Valve					NORTH PARK AND COVENTRY		
SSO 114						16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Control Valve					3012 NORTH WOODLAND		
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO		
SSO 116						4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY		
SSO 124						47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON		
CH-50						53	
Sewer Control Valve					BRADFORD AND LEE		
SSO 129						11	
Sewer Control Valve					EDDINGTON		
CH-52						2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL		
SSO 122						36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		

Work Order Detail Report

7/16/2021

SSO INSPECTION-SEVERAL DAYS OF RAIN JULY 2021

11:26 AM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

7/16/2021

SSO INSPECTION-SEVERAL DAYS OF RAIN JULY 2021

11:26 AM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Not Sound	7/14/2021/	
Reset					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	7/14/2021/	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	7/14/2021/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	7/14/2021/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Not Sound	7/14/2021/	
Reset					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	7/14/2021/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	7/14/2021/	
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	7/14/2021/	
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	7/14/2021/	
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	7/14/2021/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	7/14/2021/	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	7/14/2021/	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	7/14/2021/	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	7/14/2021/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	7/14/2021/	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	7/14/2021/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Not Sound	7/13/2021/	
Reset					
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Not Sound	7/13/2021/	
Reset					
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	7/13/2021/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	7/14/2021/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	7/14/2021/	
22	A-9 BRADFORD AT LEE SA16AFL0 (INTERSECTION)	☐	Not Sound	7/13/2021/	
Reset					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	7/13/2021/	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	7/13/2021/	

Work Order Detail Report

7/16/2021

SSO INSPECTION-SEVERAL DAYS OF RAIN JULY 2021

11:26 AM

25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	7/13/2021/
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	7/13/2021/
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Not Sound	7/13/2021/
Reset				
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Not Sound	7/13/2021/
Reset				
29	B-42 12537 CEDAR SA16ACZA0	☐	Sound	7/13/2021/
30	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	7/13/2021/
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	7/13/2021/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	7/13/2021/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	7/13/2021/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Not Sound	7/14/2021/
Reset				
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Not Sound	7/13/2021/
Reset				
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Not Sound	7/13/2021/
Reset				
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Not Sound	7/13/2021/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Sound	7/13/2021/
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Sound	7/13/2021/
40	C-59 3427 THORNE RD SA16AQQD0	☐	Sound	7/13/2021/
41	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	7/13/2021/
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	7/13/2021/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	7/13/2021/ 8:03 am
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Not Sound	7/13/2021/
Reset				
45	C-50 3593 FENLEY SA16APEH0	☐	Sound	7/13/2021/

Tasks/Resources

SWCT26 Inspection

Crew:

Status:

*Cal'c UC: \$14.67

*Task Cost: \$660.00

Start Dt: 7/13/2021

Supervisor:

UOM: Each

of Units: 45.00

*Unit Cost: \$0.00

End Dt: 7/14/2021

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	12.00	\$258.48		7/13/2021	7/14/2021
28056 Palmisano, Anthony	Hours	12.00	\$240.72		7/13/2021	7/14/2021

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	12.00	\$160.80		7/13/2021	7/14/2021

Task Comment: SSO INSPECTIONS 7-8-2021 .50"/ 7-12-2021 0.77"/7-11-2021 1.21"/7-13-2021 0.73"

Work Order Detail Report

7/16/2021

SSO INSPECTION-SEVERAL DAYS OF RAIN JULY 2021

11:26 AM

			*Actual	*Estimated	*Difference
Projected Complete:	Lock: ☐	WO Duration	11.98	0.00	0.00
Repair Type:		Labor Hours	24.00	0.00	0.00
Subcontractor:		Labor Costs	\$499.20	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity:	0.00	Equipment Costs	160.80	0.00	0.00
Unit of Measure:	Each	Contractor Costs	0.00	0.00	0.00
*Unit Cost:	\$0.00	Misc. Costs	0.00	0.00	0.00
WO Hours:	0.00	Total Costs	\$660.00	\$0.00	\$0.00
Use Task Info:			True	True	

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:			
City:		Phone:	Cell #:
State:		Fax #:	
Zip:		E-mail:	
Billing Data			
Contact Name:		*Billing Amount:	Billing Required: ☐
Invoice Number:		Date Bill Sent:	Billing Processed: ☐
Incoming Account #:		Payment Received:	Imported to Financials: ☐
		Payment Method:	

Associated PMs	
PM Code and Description	Closed
SSO-02 SSO INSPECTION	☒

Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	7/13/2021	7:21 AM
Supervisor Notification	Email Queued Successfully!	jjackson	7/13/2021	7:21 AM
Email Successfully Sent	jjackson@clvhts.com Lucity Work Order	BackgroundTaskUser	7/13/2021	7:22 AM
Status Change	Update - Supervisor From New Work Order to Complete	aferrone	7/16/2021	11:26 AM

Rates:	Opened At:	Televised:	☐
Recieved By:	Pipe Footage Cleaned	Power Rooter:	☐
Work From:	Gallons Used:	Jet:	☐
Pipe Size:	WO User 23:	Gap Vac:	☐
Pipe Condition:	WO User 24:	Dye Test:	☐
Could Not Open:	WO User 9:	Gap Root Cut:	☐
Additional Repair:	User 10:	GIS Correction?:	☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	☐
Test Performed Throug	Appointment Date: 7/13/2021 7:30 AM		
Dye Test Results:			
WO User 51:			
Measurement:	E Mail:		
History:	WO User 22:		

Work Order Detail Report

7/16/2021

SSO INSPECTION-SEVERAL DAYS OF RAIN JULY 2021


11:26 AM

Manhole Basin Repair:	Pipe Size:	
Material Used:	PVC Tees, Angles, Slec	
Pipe Repair:	WO User 44:	
Street Repair:	WO User 45:	
Grass Repair:	WO User 46:	
Curb Repair:		
Driveway- Sidewalk Re		
Construction Crew:		
WO User 39:		
WO User 40:	OUPS #:	
WO User 41:	WO User 48:	
WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	
WO User 72:	WO User 82:	Televised: ☐
WO User 73:	Quantity:	Paid: ☐
WO User 74:	WO User 84:	WO User 104: ☐
WO User 75:	WO User 85:	WO User 105: ☐
WO User 76:	WO User 86:	WO User 106: ☐
WO User 92 Date:	WO User 97 Date:	
WO User 93 Date:	WO User 98 Date:	
WO User 94 Date:	WO User 99 Date:	
WO User 95 Date:	WO User 100 Date:	
WO User 96 Date:	WO User 101 Date:	
WO User 77:	WO User 87:	WO User 107: ☐
WO User 78:	WO User 88:	WO User 108: ☐
WO User 79:	WO User 89:	WO User 109: ☐
WO User 80:	WO User 90:	WO User 110: ☐
WO User 81:	WO User 91:	WO User 111: ☐
WO Creator: jjackson	WO Creation Date: 7/13/2021	PM Trigger: Rec #: 7840

Daily Precipitation Report

Saturday, July 17, 2021

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Saturday, July 17, 2021

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	1.03	0.59	0.44	0.26	0.17	0.07
Brecksville	1.43	0.95	0.76	0.71	0.58	0.28
Brook Park	1.18	0.91	0.58	0.50	0.22	0.13
Cleveland Industrial Pkwy	1.05	0.77	0.45	0.38	0.15	0.06
Dille Ave PS	0.99	0.70	0.43	0.36	0.13	0.07
Division Ave PS	n/a	n/a	n/a	n/a	n/a	n/a
Easterly WWTP	0.96	0.70	0.45	0.35	0.21	0.09
Independence	1.11	0.76	0.59	0.46	0.30	0.12
James Rhodes HS	1.11	0.83	0.49	0.41	0.16	0.09
Jennings PS	1.14	0.78	0.48	0.40	0.15	0.07
Macedonia	1.97	1.28	1.07	1.00	0.72	0.39
Maple Heights	1.03	0.64	0.48	0.39	0.28	0.15
Mary Street PS	0.97	0.66	0.42	0.34	0.13	0.06
Mayfield Heights	0.93	0.57	0.40	0.29	0.17	0.08
Moreland Hills	1.42	0.93	0.76	0.47	0.39	0.22
North Olmsted	1.07	0.77	0.52	0.38	0.22	0.16
North Royalton	1.34	0.99	0.79	0.70	0.51	0.22
Oakwood	1.77	1.13	0.88	0.69	0.52	0.30
Olmsted Falls	1.28	0.95	0.66	0.53	0.29	0.13
Parma	1.13	0.72	0.53	0.37	0.22	0.10
Richfield	2.25	1.28	1.23	0.83	0.53	0.31
Shaker Heights	1.08	0.68	0.50	0.30	0.13	0.07
South Euclid	1.05	0.67	0.44	0.32	0.15	0.06
Southerly WWTC	1.00	0.61	0.40	0.27	0.15	0.09
Strongsville C WWTP	1.40	1.07	0.76	0.43	0.28	0.16
Strongsville Foltz	1.53	1.18	1.02	0.72	0.50	0.20
University Heights	0.89	0.54	0.31	0.22	0.09	0.05
Wade Park	0.95	0.68	0.43	0.36	0.13	0.07
Westerly WWTP	0.90	0.59	0.36	0.26	0.13	0.07
Westlake	1.35	1.03	0.70	0.54	0.42	0.23

Work Order Detail Report

7/20/2021

SSO INSPECTION 7-17-2021 0.89 INCHES OF RAIN

1:49 PM

WO Number: 210719-0003		Category:	SSOs	
Status:	Complete	Problem:	Storm Response	
Status Date:	7/20/2021 1:48 pm	Main Task:	Inspection	
Asset: SSO 431				
Location: FAIRFAX AT NORTH PARK				
Cause:	Weather		Assigned By:	
Assigned Crew:			Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	7/19/2021 7:43 AM	<u>Override</u>
Lead Worker:	DelZoppo, Michael	End Date:	7/19/2021 2:43 PM	<u>Notifications</u>
Priority:	High			
Account #:				Problem ☐
Proj No - Acct:				Overdue ☐
Project:	Project ID:			Lead Worker ☐
Reason:	Project Name:			Task ☐
Received By:				Supervisor ☐
Inspected By:				Hard Lock WO ☐

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection
Sub-Division:
Area:
Sub-Area:
Owner:
Location:
Classification:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Maintenance Zone:**Alternate Zone:**

Work Order Locations

<u>Address</u>	<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>
<u>General Location</u>	
FAIRFAX AT NORTH PARK	
2,220,655.65435414	665,517.24643672
NORTH PARK AND COVENTRY	Doan Brook
2,219,873.16674590	666,048.82312946
FAIRMOUNT SOUTH OF SCARBOROUGH	DOAN BROOK - MAIN BRANCH
2,220,364.86097248	666,446.72325230
FAIRMOUNT AT FAIRFAX	DOAN BROOK - MAIN BRANCH
2,220,920.81917815	666,080.57995571
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	DOAN BROOK - MAIN BRANCH
2,223,053.81655256	664,693.25202172
3012 NORTH WOODLAND	DOAN BROOK - MAIN BRANCH
2,222,845.06631389	664,689.08536339
	Doan Brook
2,226,440.21168265	664,329.55524255
2,226,354.79813956	664,409.89202413
2,226,389.92077273	664,379.07548472
FAIRMOUNT AT DARTMOOR	
2,225,149.97508989	664,453.31024438
FAIRMOUNT AT WELLINGTON	DOAN BROOK - MAIN BRANCH
2,223,969.26550905	664,532.08075613
	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

7/20/2021

SSO INSPECTION 7-17-2021 0.89 INCHES OF RAIN

1:49 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564 666,181.72575080		
2,218,501.67473823 671,997.54581206		
2,216,759.55453481 670,474.59347738		

Work Order Detail Report

7/20/2021

SSO INSPECTION 7-17-2021 0.89 INCHES OF RAIN

1:49 PM

2,224,536.21778722	668,887.44048372
2,226,741.35609348	679,432.95121680
2,226,591.76420106	679,420.92761880
2,227,825.14395215	684,881.15948047

Work Order Detail Report

7/20/2021

SSO INSPECTION 7-17-2021 0.89 INCHES OF RAIN

1:49 PM

Work Order Assets							
Object Type	Description 1		Description 2				
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve SSO 431					FAIRFAX AT NORTH PARK	26	
Sewer Control Valve SSO 114					NORTH PARK AND COVENTRY	16	
Sewer Control Valve SSO 121					FAIRMOUNT SOUTH OF SCARBOROUGH	35	
Sewer Structure SA16AAWB0						3094	
Sewer Control Valve SSO 112					FAIRMOUNT AT FAIRFAX	7	
Sewer Control Valve SSO 99					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	6	
Sewer Control Valve SSO 432					3012 NORTH WOODLAND	14	
Sewer Control Valve DB-03						55	
Sewer Control Valve DB-01						56	
Sewer Control Valve DB-02						57	
Sewer Control Valve CH-04					FAIRMOUNT AT DARTMOOR	5	
Sewer Control Valve SSO 110					FAIRMOUNT AT WELLINGTON	44	
Sewer Control Valve SSO 87					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	33	
Sewer Control Valve SSO 116					FAIRMOUNT AT MARLBORO	4	
Sewer Control Valve SSO 111					FAIRMOUNT AT ARLINGTON	46	
Sewer Control Valve SSO 113					FAIRMOUNT & COVENTRY (SCARBOROUGH)	37	
Sewer Control Valve SSO 124					FAIRMOUNT AND COVENTRY	47	
Sewer Control Valve CH-50					SCARBOROUGH AT LAMBERTON	53	
Sewer Control Valve SSO 129					BRADFORD AND LEE	11	
Sewer Control Valve CH-52					EDDINGTON	2	
Sewer Control Valve SSO 88					HAMPSHIRE LANE AT MAYFIELD (18")	42	
Sewer Control Valve SSO 122					EAST OVERLOOK AT EDGEHILL	36	
Sewer Control Valve SSO 89					HAMPSHIRE LANE AT MAYFIELD (36")	34	
Sewer Structure SA16ADZB0						1536	
Sewer Control Valve SSO 91					HAMPSHIRE AT EUCLID HTS. BLVD.	20	
Sewer Structure SA16ADPH0						4446	
Sewer Control Valve SSO 120					CEDAR BTW. FAIRMOUNT/DEMINGTON	8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210719-0003

Work Order Detail Report

7/20/2021

SSO INSPECTION 7-17-2021 0.89 INCHES OF RAIN

1:49 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

7/20/2021

SSO INSPECTION 7-17-2021 0.89 INCHES OF RAIN

1:49 PM

Check List				
Item	Completed	Condition	Completion Date/Time	Est Completion Date
1 A-37-FAIRFAX AT NORTH PARK SA16ACPG0 Overflowed	☐	Sound	7/19/2021/ 8:08 am	
2 A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT) No overflow	☐	Sound	7/19/2021/ 8:14 am	
3 A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0 No overflow	☐	Sound	7/19/2021/ 8:23 am	
4 A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK) No overflow	☐	Sound	7/19/2021/ 8:28 am	
5 A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK) Overflowed	☐	Sound	7/19/2021/ 8:35 am	
6 A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN) No overflow	☐	Sound	7/19/2021/ 8:43 am	
7 A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD) No overflow	☐	Sound	7/19/2021/ 8:47 am	
8 A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE) No overflow	☐	Sound	7/19/2021/ 8:54 am	
9 A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK) No overflow	☐	Sound	7/19/2021/ 8:58 am	
10 A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND) No overflow	☐	Sound	7/19/2021/ 9:02 am	
11 A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN) No overflow	☐	Sound	7/19/2021/ 9:07 am	
12 A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION) No overflow	☐	Sound	7/19/2021/ 9:15 am	
13 A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK) No overflow	☐	Sound	7/19/2021/ 9:19 am	
14 A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION) No overflow	☐	Sound	7/19/2021/ 9:26 am	
15 A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION) No overflow	☐	Sound	7/19/2021/ 9:31 am	
16 A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN) No overflow	☐	Sound	7/19/2021/ 9:38 am	
17 A-35 2393 COVENTRY SA16AASK0 (INTERSECTION) No overflow	☐	Sound	7/19/2021/ 9:44 am	
18 A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION) Overflowed	☐	Sound	7/19/2021/ 9:49 am	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210719-0003

Work Order Detail Report

7/20/2021

SSO INSPECTION 7-17-2021 0.89 INCHES OF RAIN

1:49 PM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	7/19/2021/ 9:54 am
No overflow				
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	7/19/2021/ 9:58 am
No overflow				
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	7/19/2021/10:01 am
No overflow				
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Sound	7/19/2021/10:06 am
Block missing				
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	7/19/2021/12:14 pm
No overflow				
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	7/19/2021/12:18 pm
No overflow				
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	7/19/2021/12:19 pm
No overflow				
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	7/19/2021/12:23 pm
Block missing				
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	7/19/2021/12:27 pm
No overflow				
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	7/19/2021/12:30 pm
Overflowed				
29	B-42 12537 CEDAR SA16ACZA0	☐	Sound	7/19/2021/12:37 pm
No overflow				
30	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	7/19/2021/12:41 pm
No overflow				
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	7/19/2021/12:46 pm
No overflow				
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	7/19/2021/12:51 pm
No overflow				
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	7/19/2021/12:58 pm
Overflowed				
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	7/19/2021/ 1:05 pm
Overflowed				
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Sound	7/19/2021/ 1:11 pm
Overflowed				
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Sound	7/19/2021/ 1:14 pm
Overflowed				
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Sound	7/19/2021/ 1:17 pm
Overflowed				
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Sound	7/19/2021/ 1:20 pm
No overflow				
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Sound	7/19/2021/ 1:23 pm
No overflow				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210719-0003

Work Order Detail Report

7/20/2021

SSO INSPECTION 7-17-2021 0.89 INCHES OF RAIN

1:49 PM

40	C-59 3427 THORNE RD SA16AQD0	☐	Sound	7/19/2021/ 1:31 pm
No overflow				
41	C-60 3415 THORNE RD SA16AQD0	☐	Sound	7/19/2021/ 1:33 pm
No overflow				
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	7/19/2021/ 1:39 pm
No overflow				
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	7/19/2021/ 1:43 pm
No overflow				
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	7/19/2021/ 1:44 pm
Tangled				
45	C-50 3593 FENLEY SA16APEH0	☐	Sound	7/19/2021/ 1:49 pm
No overflow				

Tasks/Resources

SWCT26 Inspection

Crew:

Status:

*Cal'c UC: \$6.21

*Task Cost: \$279.52

Start Dt: 7/19/2021

Supervisor:

UOM: Each

of Units: 45.00

*Unit Cost: \$0.00

End Dt: 7/19/2021

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
9512 DelZoppo, Michael	Hours	8.00	\$172.32		7/19/2021	7/19/2021

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	8.00	\$107.20		7/19/2021	7/19/2021

Task Comment: SSO INSPECTION 7-17-2021 0.89 INCHES OF RAIN

Projected Complete:

Lock: ☐

Repair Type:

Subcontractor:

Profit Center:

Quantity: 0.00

Unit of Measure: Each

*Unit Cost: \$0.00

WO Hours: 0.00

	*Actual	*Estimated	*Difference
WO Duration	7.00	0.00	0.00
Labor Hours	8.00	0.00	0.00
Labor Costs	\$172.32	\$0.00	\$0.00
Material Costs	0.00	0.00	0.00
Fluids Costs	0.00	0.00	0.00
Equipment Costs	107.20	0.00	0.00
Contractor Costs	0.00	0.00	0.00
Misc. Costs	0.00	0.00	0.00
Total Costs	\$279.52	\$0.00	\$0.00
Use Task Info:	True	True	

Billing

Billed Party

Customer ID:

Customer Name:

Address:

City:

State:

Zip:

Customer Number:

Last Name:

Phone:

Cell #:

Fax #:

E-mail:

Billing Data

Contact Name:

Invoice Number:

Incoming Account #:

*Billing Amount:

Date Bill Sent:

Payment Received:

Payment Method:

Billing Required: ☐

Billing Processed: ☐

Imported to Financials: ☐

Associated PMs

PM Code and Description
SSO-02 SSO INSPECTION

Closed
☒

Work Order Detail Report

7/20/2021

SSO INSPECTION 7-17-2021 0.89 INCHES OF RAIN

1:49 PM

Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	7/19/2021	6:54 AM
Supervisor Notification	Email Queued Successfully!	jjackson	7/19/2021	6:54 AM
Email Successfully Sent	jjackson@clvhts.com Lucity Work Order	BackgroundTaskUser	7/19/2021	7:02 AM
Status Change	Update - Supervisor From New Work Order to Complete	aferrone	7/20/2021	1:48 PM

Rate:	Opened At:	Televised:	☐
Recieved By:	Pipe Footage Cleaned :	Power Rooter:	☐
Work From:	Gallons Used:	Jet:	☐
Pipe Size:	WO User 23:	Gap Vac:	☐
Pipe Condition:	WO User 24:	Dye Test:	☐
Could Not Open:	WO User 9:	Gap Root Cut:	☐
Additional Repair:	User 10:	GIS Correction?:	☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	☐
Test Performed Throug	Appointment Date: 7/19/2021 7:30 AM		

Dye Test Results:	
WO User 51:	
Measurement:	E Mail:
History:	WO User 22:

Manhole Basin Repair:	Pipe Size:
Material Used:	PVC Tees, Angles, Slec
Pipe Repair:	WO User 44:
Street Repair:	WO User 45:
Grass Repair:	WO User 46:
Curb Repair:	

Driveway- Sidewalk Re	
Construction Crew:	
WO User 39:	
WO User 40:	OUPS #:
WO User 41:	WO User 48:

WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	
WO User 72:	WO User 82:	Televised: ☐
WO User 73:	Quantity:	Paid: ☐
WO User 74:	WO User 84:	WO User 104: ☐
WO User 75:	WO User 85:	WO User 105: ☐
WO User 76:	WO User 86:	WO User 106: ☐

WO User 92 Date:	WO User 97 Date:
WO User 93 Date:	WO User 98 Date:
WO User 94 Date:	WO User 99 Date:
WO User 95 Date:	WO User 100 Date:
WO User 96 Date:	WO User 101 Date:

Work Order Detail Report

7/20/2021


SSO INSPECTION 7-17-2021 0.89 INCHES OF RAIN

1:49 PM

WO User 77:	WO User 87:	WO User 107:	☐
WO User 78:	WO User 88:	WO User 108:	☐
WO User 79:	WO User 89:	WO User 109:	☐
WO User 80:	WO User 90:	WO User 110:	☐
WO User 81:	WO User 91:	WO User 111:	☐
WO Creator: jjackson	WO Creation Date: 7/19/2021	PM Trigger:	Rec #: 7860



Daily Precipitation Report
Saturday, July 24, 2021
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Saturday, July 24, 2021

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.47	0.44	0.41	0.41	0.25
Brecksville	0.13	0.13	0.13	0.08	0.06
Brook Park	0.28	0.24	0.21	0.15	0.07
Cleveland Industrial Pkwy	0.61	0.52	0.40	0.40	0.20
Dille Ave PS	0.08	0.06	0.06	0.04	0.03
Division Ave PS	0.11	0.07	0.06	0.05	0.04
Easterly WWTP	0.08	0.06	0.06	0.04	0.04
Independence	0.14	0.10	0.10	0.09	0.06
James Rhodes HS	0.53	0.47	0.38	0.38	0.19
Jennings PS	0.33	0.28	0.22	0.22	0.10
Macedonia	0.07	0.06	0.06	0.04	0.02
Maple Heights	0.16	0.13	0.09	0.09	0.06
Mary Street PS	0.11	0.08	0.07	0.04	0.03
Mayfield Heights	0.20	0.16	0.13	0.10	0.09
Moreland Hills	0.36	0.34	0.29	0.28	0.13
North Olmsted	0.29	0.25	0.24	0.12	0.11
North Royalton	0.23	0.23	0.20	0.17	0.08
Oakwood	0.14	0.13	0.12	0.12	0.07
Olmsted Falls	0.36	0.35	0.28	0.23	0.13
Parma	0.17	0.16	0.14	0.11	0.05
Richfield	n/a	n/a	n/a	n/a	n/a
Shaker Heights	0.30	0.29	0.26	0.26	0.20
South Euclid	0.11	0.09	0.06	0.03	0.03
Southerly WWTC	0.35	0.32	0.25	0.25	0.18
Strongsville C WWTP	0.23	0.22	0.17	0.14	0.05
Strongsville Foltz	0.49	0.49	0.36	0.23	0.18
University Heights	0.34	0.33	0.30	0.30	0.28
Wade Park	0.27	0.26	0.25	0.23	0.23
Westerly WWTP	0.10	0.06	0.06	0.04	0.03
Westlake	0.38	0.35	0.19	0.17	0.15

Work Order Detail Report

8/2/2021

SSO INSPECTION 7-24-2021 0.34 INCHES OF RAIN

1:18 PM

WO Number: 210727-0001	Category: SSOs
Status: Complete	Problem: Storm Response
Status Date: 8/2/2021 1:16 pm	Main Task: Inspection
Asset: SSO 431	
Location: FAIRFAX AT NORTH PARK	
Cause: Weather	Assigned By:
Assigned Crew:	Assigned Date:
Supervisor: Jackson, Jeff	Start Date: 7/27/2021 7:10 AM Override
Lead Worker: DelZoppo, Michael	End Date: 7/28/2021 1:09 PM Notifications
Priority: High	Problem ☐
Account #:	Overdue ☐
Proj No - Acct:	Lead Worker ☐
Project:	Task ☐
Reason:	Supervisor ☐
Received By:	Hard Lock WO ☐
Inspected By:	

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection
Sub-Division:
Area:
Sub-Area:
Owner:
Location:
Classification:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Maintenance Zone:**Alternate Zone:**

Work Order Locations

<u>Address</u>	<u>Address 2</u>
<u>X Coord</u> <u>Y Coord</u> <u>General Location</u>	
FAIRFAX AT NORTH PARK	
2,220,655.65435414 665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY	
2,219,873.16674590 666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH	
2,220,364.86097248 666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX	
2,220,920.81917815 666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	
2,223,053.81655256 664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND	
2,222,845.06631389 664,689.08536339	Doan Brook
2,226,440.21168265 664,329.55524255	
2,226,354.79813956 664,409.89202413	
2,226,389.92077273 664,379.07548472	
FAIRMOUNT AT DARTMOOR	
2,225,149.97508989 664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON	
2,223,969.26550905 664,532.08075613	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

8/2/2021

SSO INSPECTION 7-24-2021 0.34 INCHES OF RAIN

1:18 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564		
666,181.72575080		
2,218,501.67473823		
671,997.54581206		
2,216,759.55453481		
670,474.59347738		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210727-0001

Work Order Detail Report

8/2/2021

SSO INSPECTION 7-24-2021 0.34 INCHES OF RAIN

1:18 PM

2,224,536.21778722	668,887.44048372
2,226,741.35609348	679,432.95121680
2,226,591.76420106	679,420.92761880
2,227,825.14395215	684,881.15948047

Work Order Detail Report

SSO INSPECTION 7-24-2021 0.34 INCHES OF RAIN

8/2/2021

1:18 PM

Work Order Assets								
Object Type	Description 1		Description 2					
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed	
Sewer Control Valve					FAIRFAX AT NORTH PARK			
SSO 431						26		
Sewer Control Valve					NORTH PARK AND COVENTRY			
SSO 114						16		
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH			
SSO 121						35		
Sewer Structure								
SA16AAWB0						3094		
Sewer Control Valve					FAIRMOUNT AT FAIRFAX			
SSO 112						7		
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
SSO 99						6		
Sewer Control Valve					3012 NORTH WOODLAND			
SSO 432						14		
Sewer Control Valve								
DB-03						55		
Sewer Control Valve								
DB-01						56		
Sewer Control Valve								
DB-02						57		
Sewer Control Valve					FAIRMOUNT AT DARTMOOR			
CH-04						5		
Sewer Control Valve					FAIRMOUNT AT WELLINGTON			
SSO 110						44		
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
SSO 87						33		
Sewer Control Valve					FAIRMOUNT AT MARLBORO			
SSO 116						4		
Sewer Control Valve					FAIRMOUNT AT ARLINGTON			
SSO 111						46		
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)			
SSO 113						37		
Sewer Control Valve					FAIRMOUNT AND COVENTRY			
SSO 124						47		
Sewer Control Valve					SCARBOROUGH AT LAMBERTON			
CH-50						53		
Sewer Control Valve					BRADFORD AND LEE			
SSO 129						11		
Sewer Control Valve					EDDINGTON			
CH-52						2		
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")			
SSO 88						42		
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL			
SSO 122						36		
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")			
SSO 89						34		
Sewer Structure								
SA16ADZB0						1536		
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.			
SSO 91						20		
Sewer Structure								
SA16ADPH0						4446		
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON			
SSO 120						8		
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210727-0001

Work Order Detail Report

8/2/2021

SSO INSPECTION 7-24-2021 0.34 INCHES OF RAIN

1:18 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

8/2/2021

SSO INSPECTION 7-24-2021 0.34 INCHES OF RAIN

1:18 PM

Check List				
Item	Completed	Condition	Completion Date/Time	Est Completion Date
1 A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	7/27/2021/ 8:11 am	
No overflow				
2 A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	7/27/2021/ 8:15 am	
No overflow				
3 A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	7/27/2021/ 8:24 am	
No overflow				
4 A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	7/27/2021/ 8:34 am	
No overflow				
5 A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Sound	7/27/2021/ 8:38 am	
No overflow				
6 A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	7/27/2021/ 8:45 am	
No overflow				
7 A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	7/27/2021/ 8:48 am	
No overflow				
8 A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	7/27/2021/ 8:56 am	
No overflow				
9 A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	7/27/2021/ 8:58 am	
No overflow				
10 A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	7/27/2021/ 9:04 am	
No overflow				
11 A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	7/27/2021/ 9:07 am	
No overflow				
12 A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	7/27/2021/ 9:16 am	
No overflow				
13 A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	7/27/2021/ 9:21 am	
No overflow				
14 A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	7/27/2021/ 9:25 am	
No overflow				
15 A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	7/27/2021/ 9:30 am	
No overflow				
16 A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	7/27/2021/ 9:36 am	
No overflow				
17 A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	7/27/2021/ 9:41 am	
No overflow				
18 A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	7/27/2021/ 9:47 am	
No overflow				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210727-0001

Work Order Detail Report

8/2/2021

SSO INSPECTION 7-24-2021 0.34 INCHES OF RAIN

1:18 PM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	7/27/2021/ 9:57 am
	Overflowed			
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	7/27/2021/10:03 am
	No overflow			
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	7/27/2021/10:06 am
	No overflow			
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Sound	7/27/2021/12:43 pm
	Overflowed..Replaced block.			
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	7/27/2021/12:56 pm
	No overflow			
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	7/27/2021/ 1:08 pm
	No overflow			
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	7/27/2021/ 1:09 pm
	No overflow			
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	7/27/2021/ 1:13 pm
	No overflow			
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	7/27/2021/ 1:19 pm
	Overflowed			
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	7/27/2021/ 1:20 pm
	No overflow			
29	B-42 12537 CEDAR SA16ACZA0	☐	Sound	7/27/2021/ 1:35 pm
	No overflow.			
30	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	7/27/2021/ 1:39 pm
	No overflow			
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	7/27/2021/ 1:43 pm
	No overflow.			
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	7/27/2021/ 1:49 pm
	No overflow			
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	7/27/2021/ 2:00 pm
	Overflowed. Replaced block.			
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	7/28/2021/ 7:45 am
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Sound	7/28/2021/ 8:00 am
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Sound	7/28/2021/ 8:00 am
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Sound	7/28/2021/ 8:30 am
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Sound	7/28/2021/ 8:45 am
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Sound	7/28/2021/ 9:00 am
40	C-59 3427 THORNE RD SA16AQD0	☐	Sound	7/28/2021/ 9:15 am
41	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	7/28/2021/ 9:30 am
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	7/28/2021/ 9:45 am
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	7/28/2021/10:00 am

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210727-0001

Work Order Detail Report

8/2/2021

SSO INSPECTION 7-24-2021 0.34 INCHES OF RAIN

1:18 PM

44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	7/28/2021/10:15 am
45	C-50 3593 FENLEY SA16APEH0	☐	Sound	7/28/2021/10:30 am

Tasks/Resources

SWCT26 Inspection

Crew: Status: *Cal'c UC: \$9.32 *Task Cost: \$419.28 Start Dt: 7/27/2021
Supervisor: UOM: Each # of Units: 45.00 *Unit Cost: \$0.00 End Dt: 7/28/2021

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
9512 DelZoppo, Michael	Hours	12.00	\$258.48		7/27/2021	7/28/2021

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD F250 PICK UP 0	Hours	12.00	\$160.80		7/27/2021	7/28/2021

Task Comment: SSO INSPECTIONS 0.34" OF RAIN

Projected Complete:	Lock: ☐	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	12.00	0.00	0.00
Subcontractor:		Labor Costs	\$258.48	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity: 0.00	Lock: ☐	Equipment Costs	160.80	0.00	0.00
Unit of Measure: Each		Contractor Costs	0.00	0.00	0.00
*Unit Cost: \$0.00		Misc. Costs	0.00	0.00	0.00
WO Hours: 0.00		Total Costs	\$419.28	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing	
Customer ID:	Customer Number:		
Customer Name:	Last Name:		
Address:	Phone:	Cell #:	
City:	Fax #:		
State:	E-mail:		
Zip:			

Billing Data		
Contact Name:	*Billing Amount:	Billing Required: ☐
Invoice Number:	Date Bill Sent:	Billing Processed: ☐
Incoming Account #:	Payment Received:	Imported to Financials: ☐
	Payment Method:	

Associated PMs

PM Code and Description
SSO-02 SSO INSPECTION

Closed
☒

Tracking

Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	7/27/2021	7:24 AM
Supervisor Notification	Email Queued Successfully!	jjackson	7/27/2021	7:24 AM
Email Successfully Sent	jjackson@clvhts.com Lucity Work Order	BackgroundTaskUser	7/27/2021	7:24 AM
Status Change	Update - Supervisor From New Work Order to Complete	aferrone	8/2/2021	1:16 PM

Work Order Detail Report

8/2/2021

SSO INSPECTION 7-24-2021 0.34 INCHES OF RAIN

1:18 PM

Rate:	Opened At:	Televised:	☐
Received By:	Pipe Footage Cleaned :	Power Rooter:	☐
Work From:	Gallons Used:	Jet:	☐
Pipe Size:	WO User 23:	Gap Vac:	☐
Pipe Condition:	WO User 24:	Dye Test:	☐
Could Not Open:	WO User 9:	Gap Root Cut:	☐
Additional Repair:	User 10:	GIS Correction?:	☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	☐
Test Performed Throug	Appointment Date:	7/27/2021	7:30 AM
Dye Test Results:			

WO User 51:

Measurement:

History:

E Mail:

Measurement Line 2:

Manhole Basin Repair:

Material Used:

Pipe Repair:

Street Repair:

Grass Repair:

Curb Repair:

Driveway- Sidewalk Re

Construction Crew:

WO User 39:

WO User 40:

WO User 41:

Pipe Size:

PVC Tees, Angles, Slec

WO User 44:

WO User 45:

WO User 46:

OUPS #:

WO User 48:

WO User 52:

WO User 53:

WO User 54:

WO User 55:

WO User 56:

WO User 57:

WO User 58:

WO User 59:

WO User 60:

WO User 61:

WO User 72:

WO User 73:

WO User 74:

WO User 75:

WO User 76:

WO User 62:

WO User 63:

WO User 64:

WO User 65:

WO User 66:

WO User 67:

WO User 68:

WO User 69:

WO User 70:

WO User 71:

WO User 82:

Quantity:

WO User 84:

WO User 85:

WO User 86:

Televised: ☐Paid: ☐WO User 104: ☐WO User 105: ☐WO User 106: ☐

WO User 92 Date:

WO User 93 Date:

WO User 94 Date:

WO User 95 Date:

WO User 96 Date:

WO User 97 Date:

WO User 98 Date:

WO User 99 Date:

WO User 100 Date:

WO User 101 Date:

WO User 77:

WO User 78:

WO User 79:

WO User 80:

WO User 81:

WO User 87:

WO User 88:

WO User 89:

WO User 90:

WO User 91:

WO User 107: ☐WO User 108: ☐WO User 109: ☐WO User 110: ☐WO User 111: ☐

WO Creator: jjackson

WO Creation Date: 7/27/2021

PM Trigger:

Rec #: 7908