


Daily Precipitation Report
Wednesday, September 15, 2021
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Wednesday, September 15, 2021

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.48	0.47	0.47	0.43	0.23
Brecksville	0.49	0.45	0.45	0.44	0.41
Brook Park	0.61	0.55	0.54	0.53	0.24
Cleveland Industrial Pkwy	0.96	0.91	0.90	0.88	0.37
Dille Ave PS	n/a	n/a	n/a	n/a	n/a
Division Ave PS	0.94	0.91	0.82	0.77	0.29
Easterly WWTP	0.64	0.60	0.58	0.52	0.25
Independence	0.69	0.64	0.64	0.62	0.25
James Rhodes HS	0.84	0.78	0.77	0.77	0.35
Jennings PS	0.83	0.81	0.80	0.79	0.42
Macedonia	0.73	0.67	0.67	0.66	0.32
Maple Heights	0.74	0.71	0.70	0.65	0.52
Mary Street PS	0.61	0.57	0.55	0.53	0.31
Mayfield Heights	0.52	0.51	0.51	0.29	0.18
Moreland Hills	0.46	0.45	0.44	0.34	0.18
North Olmsted	0.57	0.49	0.46	0.45	0.25
North Royalton	0.78	0.71	0.70	0.70	0.48
Oakwood	0.63	0.54	0.54	0.53	0.45
Olmsted Falls	0.20	0.17	0.15	0.15	0.12
Parma	0.75	0.68	0.68	0.67	0.42
Richfield	0.41	0.39	0.38	0.37	0.36
Shaker Heights	0.60	0.59	0.58	0.46	0.28
South Euclid	0.94	0.90	0.89	0.63	0.32
Southerly WWTC	0.77	0.72	0.71	0.70	0.37
Strongsville CWWTP	0.43	0.37	0.36	0.35	0.30
Strongsville Foltz	0.27	0.23	0.21	0.20	0.17
University Heights	0.71	0.71	0.70	0.51	0.25
Wade Park	0.64	0.63	0.60	0.55	0.35
Westerly WWTP	0.66	0.64	0.62	0.59	0.23
Westlake	0.67	0.58	0.54	0.51	0.34

Work Order Detail Report

9/17/2021

SSO INSPECTION 9-15-2021 0.71 INCHES OF RAIN

2:41 PM

WO Number: 210917-0001	Category:	SSOs
Status: Complete	Problem:	Storm Response
Status Date: 9/17/2021 2:40 pm	Main Task:	Inspection

Asset: SSO 431

Location: FAIRFAX AT NORTH PARK

Cause: Weather

Assigned By:

Assigned Crew:

Assigned Date:

Supervisor: Jackson, Jeff

Start Date: 9/17/2021 7:39 AM

Override

Lead Worker: DelZoppo, Michael

End Date: 9/17/2021 1:39 PM

Notifications

Priority: High

Problem

Account #:

Overdue

Proj No - Acct:

Project ID:

Lead Worker

Project:

Project Name:

Task

Reason:

Supervisor

Received By:

Hard Lock WO

Inspected By:

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer Collection

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations		
<u>Address</u>		<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

9/17/2021

SSO INSPECTION 9-15-2021 0.71 INCHES OF RAIN

2:41 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

9/17/2021

SSO INSPECTION 9-15-2021 0.71 INCHES OF RAIN

2:41 PM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

9/17/2021

SSO INSPECTION 9-15-2021 0.71 INCHES OF RAIN

2:41 PM

Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Description 2</u>	<u>Asset ID</u>	<u>Completed</u>
			<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>
Sewer Control Valve	SSO 431					FAIRFAX AT NORTH PARK
Sewer Control Valve	SSO 114					NORTH PARK AND COVENTRY
Sewer Control Valve	SSO 121					FAIRMOUNT SOUTH OF SCARBOROUGH
Sewer Structure	SA16AAWB0					3094
Sewer Control Valve	SSO 112					FAIRMOUNT AT FAIRFAX
Sewer Control Valve	SSO 99					7
Sewer Control Valve	SSO 432					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)
Sewer Control Valve	DB-03					6
Sewer Control Valve	DB-01					3012 NORTH WOODLAND
Sewer Control Valve	DB-02					14
Sewer Control Valve	CH-04					55
Sewer Control Valve	SSO 110					FAIRMOUNT AT DARTMOOR
Sewer Control Valve	SSO 87					5
Sewer Control Valve	SSO 116					FAIRMOUNT AT WELLINGTON
Sewer Control Valve	SSO 111					44
Sewer Control Valve	SSO 113					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)
Sewer Control Valve	SSO 124					33
Sewer Control Valve	CH-50					FAIRMOUNT AT MARLBORO
Sewer Control Valve	SSO 129					4
Sewer Control Valve	CH-52					FAIRMOUNT AT ARLINGTON
Sewer Control Valve	SSO 88					46
Sewer Control Valve	SSO 122					FAIRMOUNT & COVENTRY (SCARBOROUGH)
Sewer Control Valve	SSO 89					37
Sewer Structure	SA16ADZB0					FAIRMOUNT AND COVENTRY
Sewer Control Valve	SSO 91					53
Sewer Structure	SA16ADPH0					SCARBOROUGH AT LAMBERTON
Sewer Control Valve	SSO 120					2
Sewer Control Valve	SSO 128					HAMPSHIRE LANE AT MAYFIELD (18")
Sewer Control Valve	SSO 121					42
Sewer Control Valve	SSO 123					EAST OVERLOOK AT EDGEHILL
Sewer Control Valve	SSO 125					HAMPSHIRE LANE AT MAYFIELD (36")
Sewer Control Valve	SSO 126					36
Sewer Control Valve	SSO 127					34
Sewer Control Valve	SSO 128					1536
Sewer Control Valve	SSO 129					HAMPSHIRE AT EUCLID HTS. BLVD.
Sewer Control Valve	SSO 130					20
Sewer Control Valve	SSO 131					4446
Sewer Control Valve	SSO 132					CEDAR BTW. FAIRMOUNT/DEMINGTON
Sewer Control Valve	SSO 133					8
Sewer Control Valve	SSO 134					2828 BERKSHIRE, EAST OF COVENTRY

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210917-0001

Work Order Detail Report

9/17/2021

SSO INSPECTION 9-15-2021 0.71 INCHES OF RAIN

2:41 PM

SSO 103	19
Sewer Control Valve	
SSO 104	3003 EUCLID HEIGHTS BLVD
Sewer Structure	15
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQCO	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

9/17/2021

SSO INSPECTION 9-15-2021 0.71 INCHES OF RAIN

2:41 PM

Check List		<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	9/17/2021/ 7:23 am	
	Overflowed				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	9/17/2021/ 7:31 am	
	Overflowed				
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	9/17/2021/ 7:36 am	
	No overflow				
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	9/17/2021/ 7:39 am	
	No overflow				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	9/17/2021/ 7:45 am	
	Overflowed				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	9/17/2021/ 7:50 am	
	No overflow				
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	9/17/2021/ 7:55 am	
	No overflow				
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	9/17/2021/ 8:01 am	
	No overflow				
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	9/17/2021/ 8:05 am	9/17/2021
	No overflow				
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	9/17/2021/ 8:09 am	
	No overflow				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	9/17/2021/ 8:13 am	
	No overflow				
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/17/2021/ 8:18 am	
	No overflow				
13	A-1 3041 FAIRMOUNT SA16AAUTO (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	9/17/2021/ 8:24 am	
	No overflow				
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/17/2021/ 8:29 am	
	No overflow				
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/17/2021/ 8:33 am	
	No overflow				
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	9/17/2021/ 8:54 am	
	No overflow				
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/17/2021/ 9:00 am	
	Overflowed				
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	9/17/2021/ 9:05 am	
	Overflowed				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210917-0001

Work Order Detail Report

9/17/2021

SSO INSPECTION 9-15-2021 0.71 INCHES OF RAIN

2:41 PM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	9/17/2021/ 9:16 am
	No overflow			
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	9/17/2021/ 9:24 am
	No overflow			
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	9/17/2021/ 9:30 am
	No overflow			
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/17/2021/ 9:40 am
	Overflowed			
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	9/17/2021/11:13 am
	No overflow			
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	9/17/2021/11:18 am
	No overflow			
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	9/17/2021/11:19 am
	No overflow			
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	9/17/2021/11:23 am
	No overflow			
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO0	<input type="checkbox"/>	Sound	9/17/2021/11:27 am
	Rope and block removed. Overflow meter installed.			
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	9/17/2021/11:30 am
	No overflow			
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	9/17/2021/11:36 am
	No overflow			
30	B-15 COVENTRY AND CEDAR SA16ADBHO	<input type="checkbox"/>	Sound	9/17/2021/11:40 am
	No overflow			
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	9/17/2021/11:45 am
	No overflow			
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	9/17/2021/11:52 am
	No overflow			
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	9/17/2021/12:00 pm
	No overflow			
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	9/17/2021/12:07 pm
	Overflowed			
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	9/17/2021/12:12 pm
	No overflow			
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	9/17/2021/12:14 pm
	No overflow			
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	9/17/2021/12:18 pm
	No overflow			
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	9/17/2021/12:22 pm
	No overflow			
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	9/17/2021/12:24 pm
	No overflow			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210917-0001

Work Order Detail Report

9/17/2021

SSO INSPECTION 9-15-2021 0.71 INCHES OF RAIN

2:41 PM

40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	9/17/2021/12:48 pm
No overflow				
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	9/17/2021/12:50 pm
No overflow				
42	C-22 2225 NOBLE RD ST16ZLHBO	<input type="checkbox"/>	Sound	9/17/2021/12:57 pm
No overflow				
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	9/17/2021/ 1:03 pm
No overflow				
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	9/17/2021/ 1:05 pm
Tangled line.				
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	9/17/2021/ 1:10 pm
No overflow				

Tasks/Resources

SWCT26 Inspection

Crew:	Status:	*Cal'c UC: \$6.21	*Task Cost: \$279.52	Start Dt: 9/17/2021
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 9/17/2021

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
9512 DelZoppo, Michael	Hours	8.00	\$172.32		9/17/2021	9/17/2021

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD F250 PICK UP	Hours	8.00	\$107.20		9/17/2021	9/17/2021
0						

Task Comment: SSO INSPECTION 0.71 INCHES OF RAIN

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	6.00	0.00	0.00
Subcontractor:		Labor Costs	8.00	0.00	0.00
Profit Center:		Material Costs	\$172.32	\$0.00	\$0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	0.00	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$279.52	\$0.00	\$0.00
		Use Task Info:	True	True	

Billing

Billed Party

Customer ID:	Customer Number:
Customer Name:	Last Name:
Address:	
City:	Phone:
State:	Fax #:
Zip:	E-mail:

Billing Data

Contact Name:	*Billing Amount:	Billing Required: <input type="checkbox"/>
Invoice Number:	Date Bill Sent:	Billing Processed: <input type="checkbox"/>
Incoming Account #:	Payment Received:	Imported to Financials: <input type="checkbox"/>
	Payment Method:	

Associated PMs

PM Code and Description
SSO-02 SSO INSPECTION

Closed

Work Order Detail Report

9/17/2021

SSO INSPECTION 9-15-2021 0.71 INCHES OF RAIN

2:41 PM

Tracking		Item	Description	By	Date	Time
Work Order Creation			From Routine Work SSO-02 - SSO INSPECTION	jjackson	9/17/2021	7:03 AM
Supervisor Notification			Email Queued Successfully!	jjackson	9/17/2021	7:03 AM
Email Successfully Sent			jjackson@clvhts.com Lacity Work Order	BackgroundTaskUser	9/17/2021	7:04 AM
Status Change			Update - Supervisor	aferrone	9/17/2021	2:40 PM

Rate:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned,	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:	Appointment Date: 9/17/2021	7:30 AM	

Dye Test Results:	E Mail:
WO User 51:	Measurement Line 2:
Measurement:	

History:	Measurement Line 2:
Manhole Basin Repair:	Pipe Size:
Material Used:	PVC Tees, Angles, Sleeves
Pipe Repair:	WO User 44:
Street Repair:	WO User 45:
Grass Repair:	WO User 46:
Curb Repair:	
Driveway- Sidewalk Repair:	
Construction Crew:	
WO User 39:	OUPS #:
WO User 40:	WO User 48:
WO User 41:	

WO User 52:	WO User 62:	Televised:	<input type="checkbox"/>
WO User 53:	WO User 63:	Paid:	<input type="checkbox"/>
WO User 54:	WO User 64:		
WO User 55:	WO User 65:	WO User 104:	<input type="checkbox"/>
WO User 56:	WO User 66:	WO User 105:	<input type="checkbox"/>
WO User 57:	WO User 67:	WO User 106:	<input type="checkbox"/>
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:		
WO User 73:	Quantity:		
WO User 74:	WO User 84:		
WO User 75:	WO User 85:		
WO User 76:	WO User 86:		

WO User 92 Date:	WO User 97 Date:
WO User 93 Date:	WO User 98 Date:
WO User 94 Date:	WO User 99 Date:
WO User 95 Date:	WO User 100 Date:
WO User 96 Date:	WO User 101 Date:

Work Order Detail Report

9/17/2021


SSO INSPECTION 9-15-2021 0.71 INCHES OF RAIN

2:41 PM

WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 9/17/2021	PM Trigger:	Rec #: 8047



Daily Precipitation Report
Wednesday, September 22, 2021
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Wednesday, September 22, 2021

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	1.49	1.42	1.36	0.91	0.34
Brecksville	1.18	1.06	0.88	0.37	0.25
Brook Park	2.18	1.39	1.08	0.67	0.25
Cleveland Industrial Pkwy	2.02	1.25	0.99	0.59	0.22
Dille Ave PS	n/a	n/a	n/a	n/a	n/a
Division Ave PS	1.98	1.32	1.08	0.62	0.25
Easterly WWTP	2.70	2.03	1.60	0.67	0.32
Independence	1.54	1.40	1.20	0.63	0.30
James Rhodes HS	1.87	1.27	1.08	0.62	0.26
Jennings PS	2.32	1.71	1.41	0.74	0.40
Macedonia	1.03	0.91	0.86	0.59	0.28
Maple Heights	1.41	1.35	1.25	0.65	0.35
Mary Street PS	2.14	1.49	1.28	0.69	0.39
Mayfield Heights	1.78	1.69	1.65	1.23	0.57
Moreland Hills	0.93	0.83	0.79	0.49	0.25
North Olmsted	n/a	n/a	n/a	n/a	n/a
North Royalton	1.72	1.50	1.37	0.90	0.43
Oakwood	1.16	1.09	1.04	0.73	0.30
Olmsted Falls	2.52	1.75	1.39	0.69	0.26
Parma	1.84	1.33	1.15	0.67	0.29
Richfield	0.92	0.78	0.64	0.32	0.22
Shaker Heights	n/a	n/a	n/a	n/a	n/a
South Euclid	2.05	1.86	1.74	1.05	0.41
Southerly WWTC	1.68	1.52	1.36	0.78	0.48
Strongsville C WWTP	2.27	1.41	1.13	0.72	0.29
Strongsville Foltz	2.08	1.47	1.13	0.68	0.28
University Heights	2.02	1.91	1.82	1.13	0.58
Wade Park	2.50	2.05	1.86	0.92	0.57
Westerly WWTP	1.81	1.16	1.01	0.52	0.21
Westlake	3.03	1.72	1.32	0.56	0.20

Work Order Detail Report

9/24/2021

SSO INSPECTION 9-22-2021 2.02 INCHES OF RAIN

2:49 PM

WO Number:	210922-0002	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	9/24/2021 2:48 pm	Main Task:	Inspection
Asset: SSO 431			
Location: FAIRFAX AT NORTH PARK			
Cause:	Weather	Assigned By:	
Assigned Crew:			
Supervisor:	Jackson, Jeff	Start Date:	9/23/2021 7:46 AM
Lead Worker:	DelZoppo, Michael	End Date:	9/23/2021 2:45 PM
Priority:	High	Override Notifications	<input type="checkbox"/>
Account #:		Problem	<input type="checkbox"/>
Proj No - Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department:	Sewer Collection
Division:	Sewer Collection
Sub-Division:	
Area:	
Sub-Area:	
Owner:	
Location:	
Classification:	

Maintenance Zone:

Alternate Zone:

Work Order Locations		
<u>Address</u>		<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210922-0002

Work Order Detail Report

9/24/2021

SSO INSPECTION 9-22-2021 2.02 INCHES OF RAIN

2:49 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

9/24/2021

SSO INSPECTION 9-22-2021 2.02 INCHES OF RAIN

2:49 PM

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

Work Order Detail Report

9/24/2021

SSO INSPECTION 9-22-2021 2.02 INCHES OF RAIN

2:49 PM

Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Description 2</u>	<u>Asset ID</u>	<u>Completed</u>
			<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>
Sewer Control Valve					FAIRFAX AT NORTH PARK	
SSO 431					26	
Sewer Control Valve					NORTH PARK AND COVENTRY	
SSO 114					16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH	
SSO 121					35	
Sewer Structure					3094	
SA16AAWB0						
Sewer Control Valve					FAIRMOUNT AT FAIRFAX	
SSO 112					7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	
SSO 99					6	
Sewer Control Valve					3012 NORTH WOODLAND	
SSO 432					14	
Sewer Control Valve					55	
DB-03						
Sewer Control Valve					56	
Sewer Control Valve					57	
DB-02						
Sewer Control Valve					FAIRMOUNT AT DARTMOOR	
CH-04					5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON	
SSO 110					44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	
SSO 87					33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO	
SSO 116					4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON	
SSO 111					46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)	
SSO 113					37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY	
SSO 124					47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON	
CH-50					53	
Sewer Control Valve					BRADFORD AND LEE	
SSO 129					11	
Sewer Control Valve					EDDINGTON	
CH-52					2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")	
SSO 88					42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL	
SSO 122					36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")	
SSO 89					34	
Sewer Structure					1536	
SA16ADZB0						
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.	
SSO 91					20	
Sewer Structure					4446	
SA16ADPH0						
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON	
SSO 120					8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY	
SSO 115						

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210922-0002

Work Order Detail Report

9/24/2021

SSO INSPECTION 9-22-2021 2.02 INCHES OF RAIN

2:49 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQCO	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

9/24/2021

SSO INSPECTION 9-22-2021 2.02 INCHES OF RAIN

2:49 PM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	9/24/2021/ 7:22 am	
	Overflowed				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	9/24/2021/ 7:27 am	
	No overflow				
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	9/24/2021/ 7:09 am	
	No overflow				
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	9/24/2021/ 7:11 am	
	No overflow				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	9/24/2021/ 7:17 am	
	Overflowed				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	9/24/2021/ 7:34 am	
	No overflow				
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	9/24/2021/ 7:36 am	
	No overflow				
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	9/24/2021/ 7:46 am	
	No overflow				
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	9/24/2021/ 7:49 am	
	No overflow				
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	9/24/2021/ 7:53 am	
	Overflowed				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	9/24/2021/ 7:57 am	
	No overflow				
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/24/2021/ 8:45 am	
	No overflow				
13	A-1 3041 FAIRMOUNT SA16AAUTO (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	9/24/2021/ 8:50 am	
	No overflow				
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUPO (INTERSECTION)	<input type="checkbox"/>	Sound	9/24/2021/ 8:23 am	
	No overflow				
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/24/2021/ 8:25 am	
	No overflow				
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	9/24/2021/ 8:29 am	
	No overflow				
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/24/2021/ 8:33 am	
	Overflowed				
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	9/24/2021/ 8:38 am	
	Overflowed				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210922-0002

Work Order Detail Report

9/24/2021

SSO INSPECTION 9-22-2021 2.02 INCHES OF RAIN

2:49 PM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	9/24/2021/ 8:20 am
	No overflow			
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	9/24/2021/ 8:05 am
	No overflow			
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	9/24/2021/ 8:02 am
	No overflow			
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Sound	9/23/2021/ 2:24 pm
	Overflowed			
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	9/23/2021/ 9:56 am
	No overflow			
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	9/23/2021/10:04 am
	No overflow			
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	9/23/2021/10:05 am
	No overflow			
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	9/23/2021/10:16 am
	No overflow			
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO	<input type="checkbox"/>	Sound	9/23/2021/10:20 am
	Block and rope missing. Flow meter in.			
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	9/23/2021/10:25 am
	No overflow			
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	9/23/2021/12:34 pm
	No overflow			
30	B-15 COVENTRY AND CEDAR SA16ADBHO	<input type="checkbox"/>	Sound	9/23/2021/12:39 pm
	No overflow			
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	9/23/2021/12:45 pm
	No overflow			
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	9/23/2021/ 1:00 pm
	No overflow			
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	9/23/2021/ 7:00 am
	No overflow . Done on 9/23. Forgot to put in. Put in today.			
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	9/23/2021/ 1:59 pm
	Overflowed			
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	9/23/2021/ 1:44 pm
	No overflow			
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	9/23/2021/ 1:40 pm
	Overflowed			
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	9/23/2021/ 1:13 pm
	No overflow			9/23/2021
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	9/23/2021/ 1:18 pm
	No overflow			
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	9/23/2021/ 1:22 pm
	No overflow			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210922-0002

Work Order Detail Report

9/24/2021

SSO INSPECTION 9-22-2021 2.02 INCHES OF RAIN

2:49 PM

40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	9/23/2021/ 9:30 am
No overflow				
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	9/23/2021/ 9:28 am
No overflow				
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	9/23/2021/ 9:15 am
No overflow				
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOQU0	<input type="checkbox"/>	Sound	9/23/2021/ 8:36 am
No overflow				
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	9/23/2021/ 8:42 am
Tangled				
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	9/23/2021/ 9:00 am
Overflowed				

Tasks/Resources					
SWCT26 Inspection					
Crew:	Status:		*Cal'c UC: \$10.04	*Task Cost: \$451.84	Start Dt: 9/23/2021
Supervisor:	UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 9/23/2021
Employee					
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt
22394 Cardarella, Joe	Hours	8.00	\$172.32		9/23/2021 9/23/2021
9512 DelZoppo, Michael	Hours	8.00	\$172.32		9/23/2021 9/23/2021
Equipment					
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt
CHFLT50 FORD F250 CREW CAB	Hours	8.00	\$107.20		9/23/2021 9/23/2021
5					
Task Comment: SSO INSPECTIONS 2.02" OF RAIN					

Projected Complete:		Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:			Labor Hours	6.98	0.00	0.00
Subcontractor:			Labor Costs	16.00	0.00	0.00
Profit Center:			Material Costs	\$344.64	\$0.00	\$0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each		Equipment Costs	107.20	0.00	0.00
*Unit Cost:	\$0.00		Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00		Misc. Costs	0.00	0.00	0.00
			Total Costs	\$451.84	\$0.00	\$0.00
			Use Task Info:	True	True	

Billing					
Billed Party			Billing		
Customer ID:			Customer Number:		
Customer Name:			Last Name:		
Address:			Phone:		Cell #:
City:			Fax #:		
State:			E-mail:		
Zip:					
Billing Data			Billing		
Contact Name:			*Billing Amount:		Billing Required: <input type="checkbox"/>
Invoice Number:			Date Bill Sent:		Billing Processed: <input type="checkbox"/>
Incoming Account #:			Payment Received:		Imported to Financials: <input type="checkbox"/>
			Payment Method:		

Work Order Detail Report

9/24/2021

SSO INSPECTION 9-22-2021 2.02 INCHES OF RAIN

2:49 PM

Associated PMs		PM Code and Description	Closed	
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>	
Item	Tracking			
Work Order Creation	Description	From Routine Work SSO-02 - SSO INSPECTION	By	Date 9/22/2021 Time 4:12 PM
Supervisor Notification		Email Queued Successfully!		
Email Successfully Sent		jackson@clvhts.com Lucity Work Order		
		Update - Supervisor		
Status Change		From New Work Order to Complete		
Rate:	Opened At:		Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned,		Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:		Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:		Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:		Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:		Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:		GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL		Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:	Appointment Date: 9/23/2021			
Dye Test Results:				
WO User 51:				
Measurement:	E Mail:			
History:	Measurement Line 2:			
Manhole Basin Repair:	Pipe Size:			
Material Used:	PVC Tees, Angles, Sled			
Pipe Repair:	WO User 44:			
Street Repair:	WO User 45:			
Grass Repair:	WO User 46:			
Curb Repair:				
Driveway- Sidewalk Re:				
Construction Crew:				
WO User 39:	OUPS #:			
WO User 40:	WO User 48:			
WO User 41:				
WO User 52:	WO User 62:			
WO User 53:	WO User 63:			
WO User 54:	WO User 64:			
WO User 55:	WO User 65:			
WO User 56:	WO User 66:			
WO User 57:	WO User 67:			
WO User 58:	WO User 68:			
WO User 59:	WO User 69:			
WO User 60:	WO User 70:			
WO User 61:	WO User 71:			
WO User 72:	WO User 82:		Televised:	<input type="checkbox"/>
WO User 73:	Quantity:		Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:		WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:		WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:		WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:			
WO User 93 Date:	WO User 98 Date:			
WO User 94 Date:	WO User 99 Date:			
WO User 95 Date:	WO User 100 Date:			
WO User 96 Date:	WO User 101 Date:			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 210922-0002

Work Order Detail Report

9/24/2021

SSO INSPECTION 9-22-2021 2.02 INCHES OF RAIN

2:49 PM

WO User 77:

WO User 78:

WO User 79:

WO User 80:

WO User 81:

WO Creator: aferrone

WO Creation Date:

9/22/2021

WO User 87:

WO User 88:

WO User 89:

WO User 90:

WO User 91:

PM Trigger:

WO User 107:

WO User 108:

WO User 109:

WO User 110:

WO User 111:

Rec #: 8054