




Northeast Ohio Regional Sewer District

Daily Precipitation Report Thursday, November 11, 2021

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Thursday, November 11, 2021

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.52	0.52	0.45	0.19	0.06
Brecksville	0.44	0.44	0.39	0.20	0.09
Brook Park	0.40	0.40	0.33	0.13	0.05
Cleveland Industrial Pkwy	0.38	0.38	0.31	0.13	0.05
Dille Ave PS	n/a	n/a	n/a	n/a	n/a
Division Ave PS	0.34	0.34	0.30	0.13	0.04
Easterly WWTP	0.48	0.48	0.42	0.20	0.07
Independence	0.35	0.35	0.31	0.14	0.05
James Rhodes HS	0.35	0.35	0.31	0.13	0.04
Jennings PS	0.37	0.37	0.32	0.14	0.05
Macedonia	0.46	0.46	0.39	0.18	0.07
Maple Heights	0.38	0.38	0.35	0.16	0.06
Mary Street PS	0.33	0.33	0.29	0.14	0.04
Mayfield Heights	0.61	0.61	0.52	0.23	0.07
Moreland Hills	n/a	n/a	n/a	n/a	n/a
North Olmsted	0.39	0.39	0.32	0.13	0.04
North Royalton	0.35	0.35	0.31	0.15	0.06
Oakwood	0.50	0.50	0.44	0.19	0.07
Olmsted Falls	0.40	0.40	0.33	0.15	0.05
Parma	0.37	0.37	0.33	0.16	0.07
Richfield	0.40	0.40	0.34	0.16	0.05
Shaker Heights	0.44	0.44	0.40	0.18	0.06
South Euclid	0.49	0.49	0.43	0.20	0.07
Southerly WWTC	0.32	0.32	0.29	0.13	0.05
Strongsville C WWTP	0.42	0.42	0.36	0.14	0.06
Strongsville Foltz	0.44	0.44	0.36	0.15	0.06
University Heights	0.45	0.45	0.40	0.17	0.06
Wade Park	0.37	0.37	0.34	0.17	0.07
Westerly WWTP	0.30	0.30	0.26	0.10	0.03
Westlake	0.42	0.42	0.34	0.13	0.04

Work Order Detail Report

11/19/2021

SSO INSPECTIONS 11-11-2021 0.45"

2:00 PM

WO Number: 211119-0003	Category: SSOs
Status: Complete	Problem: Storm Response
Status Date: 11/19/2021 1:59 pm	Main Task: Inspection
Asset: SSO 431	
Location: FAIRFAX AT NORTH PARK	
Cause: Weather	Assigned By: 15854 Ferrone, Anthony
Assigned Crew:	Assigned Date: 11/15/2021
Supervisor: Jackson, Jeff	Start Date: 11/16/2021 7:51 AM Override
Lead Worker: Eathridge, David	End Date: 11/16/2021 2:51 PM Notifications
Priority: High	Problem ☐
Account #:	Overdue ☐
Proj No - Acct:	Lead Worker ☐
Project:	Task ☐
Reason:	Supervisor ☐
Received By:	Hard Lock WO ☐
Inspected By:	

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection
Sub-Division:
Area:
Sub-Area:
Owner:
Location:
Classification:

Maintenance Zone:**Alternate Zone:**

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Locations

<u>Address</u>	<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>
<u>General Location</u>	
FAIRFAX AT NORTH PARK	
2,220,655.65435414	665,517.24643672
NORTH PARK AND COVENTRY	
2,219,873.16674590	666,048.82312946
FAIRMOUNT SOUTH OF SCARBOROUGH	
2,220,364.86097248	666,446.72325230
FAIRMOUNT AT FAIRFAX	
2,220,920.81917815	666,080.57995571
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	
2,223,053.81655256	664,693.25202172
3012 NORTH WOODLAND	
2,222,845.06631389	664,689.08536339
2,226,440.21168265	664,329.55524255
2,226,354.79813956	664,409.89202413
2,226,389.92077273	664,379.07548472
FAIRMOUNT AT DARTMOOR	
2,225,149.97508989	664,453.31024438
FAIRMOUNT AT WELLINGTON	
2,223,969.26550905	664,532.08075613

Work Order Detail Report

11/19/2021

SSO INSPECTIONS 11-11-2021 0.45"

2:00 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

11/19/2021

SSO INSPECTIONS 11-11-2021 0.45"

2:00 PM

2,224,536.21778722	668,887.44048372
2,226,741.35609348	679,432.95121680
2,226,591.76420106	679,420.92761880
2,227,825.14395215	684,881.15948047

Work Order Detail Report

11/19/2021

SSO INSPECTIONS 11-11-2021 0.45"

2:00 PM

Work Order Assets							
Object Type	Description 1		Description 2				
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve					FAIRFAX AT NORTH PARK		
SSO 431						26	
Sewer Control Valve					NORTH PARK AND COVENTRY		
SSO 114						16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Control Valve					3012 NORTH WOODLAND		
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO		
SSO 116						4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY		
SSO 124						47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON		
CH-50						53	
Sewer Control Valve					BRADFORD AND LEE		
SSO 129						11	
Sewer Control Valve					EDDINGTON		
CH-52						2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL		
SSO 122						36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		

Work Order Detail Report

11/19/2021

SSO INSPECTIONS 11-11-2021 0.45"

2:00 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

11/19/2021

SSO INSPECTIONS 11-11-2021 0.45"

2:00 PM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	11/16/2021/ 7:00 am	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Not Sound	11/16/2021/ 7:15 am	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Not Sound	11/16/2021/ 7:30 am	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	11/16/2021/ 7:00 am	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Sound	11/16/2021/ 7:00 am	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	11/16/2021/ 7:00 am	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	11/16/2021/ 7:00 am	
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	11/16/2021/ 7:00 am	
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	11/16/2021/ 7:00 am	
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Not Sound	11/16/2021/ 7:00 am	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	11/16/2021/ 7:00 am	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	11/16/2021/ 7:00 am	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	11/16/2021/ 7:00 am	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	11/16/2021/ 7:00 am	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	11/16/2021/ 7:00 am	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	11/16/2021/ 7:00 am	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	11/16/2021/ 7:00 am	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Not Sound	11/16/2021/ 7:00 am	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	11/16/2021/ 7:00 am	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	11/16/2021/ 7:00 am	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	11/16/2021/ 7:00 am	
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Sound	11/16/2021/ 7:00 am	
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	11/16/2021/ 7:00 am	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	11/16/2021/ 7:00 am	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	11/16/2021/ 7:00 am	
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	11/16/2021/ 7:00 am	
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	11/16/2021/ 7:00 am	

Work Order Detail Report

11/19/2021

SSO INSPECTIONS 11-11-2021 0.45"

2:00 PM

28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Not Sound	11/16/2021/ 7:00 am
29	B-42 12537 CEDAR SA16ACZA0	☐		11/16/2021/ 7:00 am
30	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	11/16/2021/ 7:00 am
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	11/16/2021/ 7:00 am
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	11/16/2021/ 7:00 am
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	11/16/2021/ 7:00 am
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	11/16/2021/ 7:00 am
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Sound	11/16/2021/ 7:00 am
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Sound	11/16/2021/ 7:00 am
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Sound	11/16/2021/ 7:00 am
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Not Sound	11/16/2021/ 7:00 am
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Not Sound	11/16/2021/ 7:00 am
40	C-59 3427 THORNE RD SA16AQQD0	☐	Not Sound	11/16/2021/ 7:00 am
41	C-60 3415 THORNE RD SA16AQQC0	☐	Not Sound	11/16/2021/ 7:00 am
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	11/16/2021/ 7:00 am
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	11/16/2021/ 7:00 am
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	11/16/2021/ 7:00 am
45	C-50 3593 FENLEY SA16APEH0	☐	Sound	11/16/2021/ 7:00 am

Tasks/Resources**SWCT26 Inspection****Crew:****Status:** Complete***Cal'c UC:** \$17.24***Task Cost:** \$775.92**Start Dt:** 11/16/2021**Supervisor:** Jackson, Jeff**UOM:** Each**# of Units:** 45.00***Unit Cost:** \$0.00**End Dt:** 11/16/2021**Employee**

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
12459 Eathridge, David	Hours	8.00	\$181.12		11/16/2021	11/16/2021
11213 Owens, Will	Hours	8.00	\$181.12		11/16/2021	11/16/2021
39986 OBrien, Dominick	Hours	8.00	\$165.28		11/16/2021	11/16/2021

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	8.00	\$107.20		11/16/2021	11/16/2021
CHFLT55 FORD 350 CREW CAB 9	Hours	8.00	\$141.20		11/16/2021	11/16/2021

Task Comment: SSO INSPECTION 11-11-2021

Work Order Detail Report

11/19/2021

SSO INSPECTIONS 11-11-2021 0.45"

2:00 PM

			<u>*Actual</u>	<u>*Estimated</u>	<u>*Difference</u>
Projected Complete:	Lock: ☐	WO Duration	7.00	0.00	0.00
Repair Type:		Labor Hours	24.00	0.00	0.00
Subcontractor:		Labor Costs	\$527.52	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity: 0.00	Lock: ☐	Equipment Costs	248.40	0.00	0.00
Unit of Measure: Each		Contractor Costs	0.00	0.00	0.00
*Unit Cost: \$0.00		Misc. Costs	0.00	0.00	0.00
WO Hours: 0.00		Total Costs	\$775.92	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	Cell #:
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	Billing Required: ☐
Invoice Number:		Date Bill Sent:	Billing Processed: ☐
Incoming Account #:		Payment Received:	Imported to Financials: ☐
		Payment Method:	

Associated PMs	
<u>PM Code and Description</u>	<u>Closed</u>
SSO-02 SSO INSPECTION	☒

Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	aferrone	11/19/2021	1:37 PM
Supervisor Notification	Email Queued Successfully!	aferrone	11/19/2021	1:37 PM
Email Successfully Sent	jjackson@clvhts.com Lucity Work Order	BackgroundTaskUser	11/19/2021	1:38 PM
Status Change	Update - Supervisor			
	From New Work Order to Complete	aferrone	11/19/2021	1:59 PM

Rate:	Opened At:	Televised: ☐
Recieved By:	Pipe Footage Cleaned :	Power Rooter: ☐
Work From:	Gallons Used:	Jet: ☐
Pipe Size:	WO User 23:	Gap Vac: ☐
Pipe Condition:	WO User 24:	Dye Test: ☐
Could Not Open:	WO User 9:	Gap Root Cut: ☐
Additional Repair:	User 10:	GIS Correction?: ☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: ☐
Test Performed Throug	Appointment Date:	
Dye Test Results:		
WO User 51:		
Measurement:	E Mail:	
History:	Measurement Line 2:	

Work Order Detail Report

11/19/2021

SSO INSPECTIONS 11-11-2021 0.45"

2:00 PM

Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sleeves		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Reconstruction:			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	☐
WO User 73:	Quantity:	Paid:	☐
WO User 74:	WO User 84:	WO User 104:	☐
WO User 75:	WO User 85:	WO User 105:	☐
WO User 76:	WO User 86:	WO User 106:	☐
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	☐
WO User 78:	WO User 88:	WO User 108:	☐
WO User 79:	WO User 89:	WO User 109:	☐
WO User 80:	WO User 90:	WO User 110:	☐
WO User 81:	WO User 91:	WO User 111:	☐
WO Creator: aferrone	WO Creation Date: 11/19/2021	PM Trigger:	Rec #: 9206