




Daily Precipitation Report
Saturday, December 11, 2021
Accumulation in inches

Lake Erie



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Saturday, December 11, 2021

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.66	0.61	0.37	0.22	0.11
Brecksville	0.94	0.72	0.52	0.34	0.23
Brook Park	0.60	0.57	0.41	0.21	0.10
Cleveland Industrial Pkwy	0.61	0.60	0.45	0.25	0.16
Dille Ave PS	n/a	n/a	n/a	n/a	n/a
Division Ave PS	0.62	0.60	0.47	0.28	0.19
Eastely WWTP	0.65	0.64	0.51	0.34	0.27
Independence	0.90	0.84	0.57	0.35	0.28
James Rhodes HS	0.57	0.55	0.42	0.24	0.16
Jennings PS	0.70	0.66	0.50	0.27	0.18
Macedonia	0.98	0.62	0.39	0.34	0.29
Maple Heights	0.80	0.74	0.48	0.28	0.23
Mary Street PS	0.55	0.53	0.38	0.22	0.15
Mayfield Heights	0.78	0.73	0.50	0.29	0.23
Moreland Hills	0.77	0.57	0.39	0.25	0.19
North Olmsted	0.64	0.62	0.46	0.29	0.22
North Royalton	0.88	0.78	0.50	0.30	0.20
Oakwood	0.83	0.59	0.41	0.26	0.19
Olmsted Falls	0.66	0.63	0.46	0.26	0.16
Parma	0.61	0.58	0.42	0.24	0.08
Richfield	1.24	0.89	0.66	0.46	0.28
Shaker Heights	0.64	0.59	0.39	0.23	0.10
South Euclid	0.67	0.64	0.48	0.30	0.23
Southerly WWTC	0.51	0.49	0.38	0.21	0.10
Strongsville CWWTP	0.65	0.60	0.44	0.23	0.09
Strongsville Foltz	0.77	0.70	0.52	0.29	0.15
University Heights	0.55	0.52	0.39	0.21	0.14
Wade Park	0.66	0.63	0.47	0.28	0.20
Westely WWTP	0.56	0.54	0.42	0.25	0.19
Westlake	0.71	0.71	0.56	0.31	0.26

Work Order Detail Report

12/23/2021

SSO INSPECTION 12-11-2021 0.55 INCHES OF RAIN

9:39 AM

WO Number: 211223-0001	Category:	SSOs
Status: Complete	Problem:	Storm Response
Status Date: 12/23/2021 9:21 am	Main Task:	Inspection

Asset: SSO 431	
Location: FAIRFAX AT NORTH PARK	

Cause:	Weather	Assigned By:
Assigned Crew:		Assigned Date: 12/11/2021
Supervisor:	Jackson, Jeff	Start Date: 12/15/2021 8:00 AM
Lead Worker:	Mc Coy, Sam	End Date: 12/15/2021
Priority:	High	Override Notifications
Account #:		Problem <input type="checkbox"/>
Proj No - Act:		Overdue <input type="checkbox"/>
Project:		Lead Worker <input type="checkbox"/>
Reason:		Task <input type="checkbox"/>
Received By:		Supervisor <input type="checkbox"/>
Inspected By:		Hard Lock WO <input type="checkbox"/>

Request Comments for Work Order
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location	Comments for Crew
Department: Sewer Collection	Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.
Division: Sewer Collection	
Sub-Division:	
Area:	
Sub-Area:	
Owner:	
Location:	
Classification:	

Maintenance Zone:	Alternate Zone:
-------------------	-----------------

Work Order Locations			Address 2
<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339		Doan Brook
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH

Work Order Detail Report

12/23/2021

SSO INSPECTION 12-11-2021 0.55 INCHES OF RAIN

9:39 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

12/23/2021

SSO INSPECTION 12-11-2021 0.55 INCHES OF RAIN

9:39 AM

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

Work Order Detail Report

12/23/2021

SSO INSPECTION 12-11-2021 0.55 INCHES OF RAIN

9:39 AM

Work Order Assets							
Object Type	System ID 1	System ID 2	Description 1	Description 2	PM Description	Asset ID	Completed
Sewer Control Valve	SSO 431			FAIRFAX AT NORTH PARK			26
Sewer Control Valve	SSO 114			NORTH PARK AND COVENTRY			16
Sewer Control Valve	SSO 121			FAIRMOUNT SOUTH OF SCARBOROUGH			35
Sewer Structure	SA16AAWB0					3094	
Sewer Control Valve	SSO 112			FAIRMOUNT AT FAIRFAX			7
Sewer Control Valve	SSO 99			FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			6
Sewer Control Valve	SSO 432			3012 NORTH WOODLAND			14
Sewer Control Valve	DB-03					55	
Sewer Control Valve	DB-01					56	
Sewer Control Valve	DB-02					57	
Sewer Control Valve	CH-04			FAIRMOUNT AT DARTMOOR			5
Sewer Control Valve	SSO 110			FAIRMOUNT AT WELLINGTON			44
Sewer Control Valve	SSO 87			FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			33
Sewer Control Valve	SSO 116			FAIRMOUNT AT MARLBORO			4
Sewer Control Valve	SSO 111			FAIRMOUNT AT ARLINGTON			46
Sewer Control Valve	SSO 113			FAIRMOUNT & COVENTRY (SCARBOROUGH)			37
Sewer Control Valve	SSO 124			FAIRMOUNT AND COVENTRY			47
Sewer Control Valve	CH-50			SCARBOROUGH AT LAMBERTON			53
Sewer Control Valve	SSO 129			BRADFORD AND LEE			11
Sewer Control Valve	CH-52			EDDINGTON			2
Sewer Control Valve	SSO 88			HAMPSHIRE LANE AT MAYFIELD (18")			42
Sewer Control Valve	SSO 122			EAST OVERLOOK AT EDGEHILL			36
Sewer Control Valve	SSO 89			HAMPSHIRE LANE AT MAYFIELD (36")			34
Sewer Structure	SA16ADZB0					1536	
Sewer Control Valve	SSO 91			HAMPSHIRE AT EUCLID HTS. BLVD.			20
Sewer Structure	SA16ADPH0					4446	
Sewer Control Valve	SSO 120			CEDAR BTW. FAIRMOUNT/DEMINGTON			8
Sewer Control Valve				2828 BERKSHIRE, EAST OF COVENTRY			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 211223-0001

Work Order Detail Report

12/23/2021

SSO INSPECTION 12-11-2021 0.55 INCHES OF RAIN

9:39 AM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQCO	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

12/23/2021

SSO INSPECTION 12-11-2021 0.55 INCHES OF RAIN

9:39 AM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Not Sound	12/15/2021/ 7:00 am	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	12/15/2021/ 7:00 am	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Not Sound	12/15/2021/ 7:00 am	
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	12/15/2021/ 7:00 am	
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Not Sound	12/15/2021/ 7:00 am	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
17	A-35 2393 COVENTRY SA16AAASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
22	B-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Not Sound	12/15/2021/ 7:00 am	
no block					
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am	
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO0	<input type="checkbox"/>	Not Sound	12/15/2021/ 7:00 am	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 211223-0001

Work Order Detail Report

12/23/2021

SSO INSPECTION 12-11-2021 0.55 INCHES OF RAIN

9:39 AM

28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Not Sound	12/15/2021/ 7:00 am
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am
30	B-15 COVENTRY AND CEDAR SA16ADBHQ0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	12/15/2021/ 7:00 am
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am
40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Not Sound	12/15/2021/ 7:00 am
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	12/15/2021/ 7:00 am

Tasks/Resources						
SWCT26 Inspection						
Crew: Supervisor: Jackson, Jeff	Status: Complete	UOM: Each	*Cal'd UC: \$5.39 # of Units: 45.00	*Task Cost: \$242.72 *Unit Cost: \$0.00	Start Dt: 12/15/2021	End Dt: 12/15/2021
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
40151 Mc Coy, Sam	Hours	8.00	\$135.52		12/15/2021	12/15/2021
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	8.00	\$107.20		12/15/2021	12/15/2021

Task Comment: SSO INSPECTIONS 0.55 INCHES OF RAIN

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	8.00	0.00	0.00
Subcontractor:		Labor Costs	\$135.52	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	107.20	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$242.72	\$0.00	\$0.00
		Use Task Info:	True	True	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO #: 211223-0001

Work Order Detail Report

12/23/2021

SSO INSPECTION 12-11-2021 0.55 INCHES OF RAIN

9:39 AM

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:	Cell #:	
City:		Fax #:		
State:		E-mail:		
Zip:				
Billing Data				
Contact Name:		*Billing Amount:	<input type="checkbox"/> Billing Required: <input type="checkbox"/>	
Invoice Number:		Date Bill Sent:	<input type="checkbox"/> Billing Processed: <input type="checkbox"/>	
Incoming Account #:		Payment Received:	<input type="checkbox"/> Imported to Financials: <input type="checkbox"/>	
		Payment Method:		
Associated PMs				
PM Code and Description		Closed <input checked="" type="checkbox"/>		
SSO-02 SSO INSPECTION				
Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	aferrone	12/23/2021	9:06 AM
Supervisor Notification	Email Queued Successfully!	aferrone	12/23/2021	9:06 AM
Email Successfully Sent	jackson@clvhts.com Lucity Work Order	BackgroundTaskUser	12/23/2021	9:06 AM
Status Change	Update - Supervisor From New Work Order to Complete	aferrone	12/23/2021	9:21 AM
Rate:	Opened At:		Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned .		Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:		Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:		Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:		Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:		Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:		GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL		Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:	Appointment Date:			
Dye Test Results:	E Mail:			
WO User 51:	Measurement Line 2:			
Measurement:	Pipe Size:			
History:	PVC Tees, Angles, Sles			
Manhole Basin Repair:	WO User 44:			
Material Used:	WO User 45:			
Pipe Repair:	WO User 46:			
Street Repair:	OUPS #:			
Grass Repair:	WO User 48:			
Curb Repair:				
Driveway- Sidewalk Re				
Construction Crew:				
WO User 39:				
WO User 40:				
WO User 41:				

Work Order Detail Report

12/23/2021


SSO INSPECTION 12-11-2021 0.55 INCHES OF RAIN

9:39 AM

WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	
WO User 72:	WO User 82:	Televised: <input type="checkbox"/>
WO User 73:	Quantity:	Paid: <input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104: <input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105: <input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106: <input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:	
WO User 93 Date:	WO User 98 Date:	
WO User 94 Date:	WO User 99 Date:	
WO User 95 Date:	WO User 100 Date:	
WO User 96 Date:	WO User 101 Date:	
WO User 77:	WO User 87:	WO User 107: <input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108: <input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109: <input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110: <input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111: <input type="checkbox"/>
WO Creator: aferrone	WO Creation Date: 12/23/2021	PM Trigger: Rec #: 10257



Daily Precipitation Report
Saturday, December 18, 2021
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report
Saturday, December 18, 2021

<u>Site Location</u>	<u>Peak Accumulation (Inches)</u>				
	<u>24-Hour</u>	<u>6-Hour</u>	<u>3-Hour</u>	<u>1-Hour</u>	<u>15-Minute</u>
Beachwood	0.48	0.28	0.20	0.08	0.04
Brecksville	0.37	0.22	0.14	0.06	0.03
Brook Park	0.44	0.25	0.16	0.08	0.04
Cleveland Industrial Pkwy	0.48	0.28	0.19	0.08	0.04
Dille Ave PS	n/a	n/a	n/a	n/a	n/a
Division Ave PS	0.50	0.29	0.19	0.08	0.03
Easterly WWTP	n/a	n/a	n/a	n/a	n/a
Independence	0.43	0.27	0.16	0.06	0.03
James Rhodes HS	0.41	0.23	0.16	0.07	0.03
Jennings PS	0.47	0.26	0.18	0.08	0.04
Macedonia	0.45	0.26	0.16	0.07	0.03
Maple Heights	0.44	0.28	0.17	0.07	0.04
Mary Street PS	n/a	n/a	n/a	n/a	n/a
Mayfield Heights	0.51	0.29	0.22	0.09	0.04
Moreland Hills	0.40	0.26	0.16	0.07	0.04
North Olmsted	0.46	0.26	0.17	0.07	0.03
North Royalton	0.35	0.21	0.13	0.06	0.02
Oakwood	0.43	0.27	0.16	0.06	0.03
Olmsted Falls	0.42	0.23	0.14	0.07	0.03
Parma	0.47	0.29	0.18	0.08	0.04
Richfield	0.46	0.26	0.18	0.08	0.04
Shaker Heights	0.46	0.28	0.20	0.08	0.04
South Euclid	0.45	0.26	0.18	0.07	0.03
Southerly WWTC	0.44	0.28	0.19	0.08	0.03
Strongsville C WWTP	0.51	0.29	0.17	0.08	0.04
Strongsville Foltz	0.44	0.25	0.17	0.07	0.03
University Heights	0.50	0.28	0.20	0.08	0.04
Wade Park	0.43	0.26	0.17	0.07	0.03
Westerly WWTP	0.38	0.24	0.16	0.07	0.03
Westlake	0.49	0.27	0.20	0.10	0.03

Work Order Detail Report

12/23/2021

SSO INSPECTION 12-18-2021 .50 INCHES OF RAIN

9:36 AM

WO Number: 211221-0003	Category:	SSOs
Status: Complete	Problem:	Storm Response
Status Date: 12/23/2021 9:35 am	Main Task:	Inspection

Asset: SSO 431

Location: FAIRFAX AT NORTH PARK

Cause:	Weather	Assigned By:
Assigned Crew:		Assigned Date: 12/18/2021
Supervisor:	Jackson, Jeff	Start Date: 12/21/2021 9:32 AM
Lead Worker:	Manco, Angelo	End Date: 12/21/2021 9:34 AM
Priority:	High	<u>Override Notifications</u>
Account #:		Problem <input type="checkbox"/>
Proj No - Acct:		Overdue <input type="checkbox"/>
Project:		Lead Worker <input type="checkbox"/>
Reason:		Task <input type="checkbox"/>
Received By:		Supervisor <input type="checkbox"/>
Inspected By:		Hard Lock WO <input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer Collection

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations		
<u>Address</u>		<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 211221-0003

Work Order Detail Report

12/23/2021

SSO INSPECTION 12-18-2021 .50 INCHES OF RAIN

9:36 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

12/23/2021

SSO INSPECTION 12-18-2021 .50 INCHES OF RAIN

9:36 AM

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

Work Order Detail Report

SSO INSPECTION 12-18-2021 .50 INCHES OF RAIN

12/23/2021

9:36 AM

Work Order Assets

Object Type	System ID 1	System ID 2	Description 1	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve							FAIRFAX AT NORTH PARK		
SSO 431								26	
Sewer Control Valve							NORTH PARK AND COVENTRY		
SSO 114								16	
Sewer Control Valve							FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121								35	
Sewer Structure									
SA16AAWB0								3094	
Sewer Control Valve							FAIRMOUNT AT FAIRFAX		
SSO 112								7	
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99								6	
Sewer Control Valve							3012 NORTH WOODLAND		
SSO 432								14	
Sewer Control Valve									
DB-03								55	
Sewer Control Valve									
DB-01								56	
Sewer Control Valve									
DB-02								57	
Sewer Control Valve							FAIRMOUNT AT DARTMOOR		
CH-04								5	
Sewer Control Valve							FAIRMOUNT AT WELLINGTON		
SSO 110								44	
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87								33	
Sewer Control Valve							FAIRMOUNT AT MARLBORO		
SSO 116								4	
Sewer Control Valve							FAIRMOUNT AT ARLINGTON		
SSO 111								46	
Sewer Control Valve							FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113								37	
Sewer Control Valve							FAIRMOUNT AND COVENTRY		
SSO 124								47	
Sewer Control Valve							SCARBOROUGH AT LAMBERTON		
CH-50								53	
Sewer Control Valve							BRADFORD AND LEE		
SSO 129								11	
Sewer Control Valve							EDDINGTON		
CH-52								2	
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88								42	
Sewer Control Valve							EAST OVERLOOK AT EDGEHILL		
SSO 122								36	
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89								34	
Sewer Structure									
SA16ADZB0								1536	
Sewer Control Valve							HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91								20	
Sewer Structure									
SA16ADPH0								4446	
Sewer Control Valve							CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120								8	
Sewer Control Valve								2828 BERKSHIRE, EAST OF COVENTRY	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 211221-0003

Work Order Detail Report

12/23/2021

SSO INSPECTION 12-18-2021 .50 INCHES OF RAIN

9:36 AM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

12/23/2021

SSO INSPECTION 12-18-2021 .50 INCHES OF RAIN

9:36 AM

Check List		<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Not Sound	12/21/2021/ 7:00 am	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	12/21/2021/ 7:00 am	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Not Sound	12/21/2021/ 7:00 am	
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Not Sound	12/21/2021/ 7:00 am	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	12/21/2021/ 7:00 am	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am	

Work Order Detail Report

12/23/2021

SSO INSPECTION 12-18-2021 .50 INCHES OF RAIN

9:36 AM

28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	12/21/2021/ 7:00 am
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am
40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Not Sound	12/21/2021/ 7:00 am
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	12/21/2021/ 7:00 am

Tasks/Resources						
SWCT26 Inspection						
Crew: Supervisor:	Status: UOM: Each	*Cal'd UC: \$10.65 # of Units: 45.00	*Task Cost: \$479.44 *Unit Cost: \$0.00	Start Dt: 12/21/2021 End Dt: 12/21/2021		
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
12459 Eathridge, David	Hours	8.00	\$181.12		12/21/2021	12/21/2021
19356 Manco, Angelo	Hours	8.00	\$191.12		12/21/2021	12/21/2021
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD F250 PICK UP 0	Hours	8.00	\$107.20		12/21/2021	12/21/2021

Task Comment: SSO INSPECTIONS .50 INCHES OF RAIN

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	0.03	0.00	0.00
Subcontractor:		Labor Costs	16.00	0.00	0.00
Profit Center:		Material Costs	\$372.24	\$0.00	\$0.00
Quantity: 0.00	Lock: <input type="checkbox"/>	Fluids Costs	0.00	0.00	0.00
Unit of Measure: Each		Equipment Costs	107.20	0.00	0.00
*Unit Cost: \$0.00		Contractor Costs	0.00	0.00	0.00
WO Hours: 0.00		Misc. Costs	0.00	0.00	0.00
		Total Costs	\$479.44	\$0.00	\$0.00
		Use Task Info:	True	True	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 211221-0003

Work Order Detail Report

12/23/2021

SSO INSPECTION 12-18-2021 .50 INCHES OF RAIN

9:36 AM

Billing				
Billed Party				
Customer ID:	Customer Number:			
Customer Name:	Last Name:			
Address:				
City:	Phone:	Cell #:		
State:	Fax #:			
Zip:	E-mail:			
Billing Data				
Contact Name:	*Billing Amount:		Billing Required: <input type="checkbox"/>	
Invoice Number:	Date Bill Sent:		Billing Processed: <input type="checkbox"/>	
Incoming Account #:	Payment Received:		Imported to Financials: <input type="checkbox"/>	
Payment Method:				
Associated PMs				
PM Code and Description			Closed <input checked="" type="checkbox"/>	
SSO-02 SSO INSPECTION				
Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	12/21/2021	8:24 AM
Supervisor Notification	Email Queued Successfully!	jjackson	12/21/2021	8:24 AM
Leadworker Notification	Email Queued Successfully!	jjackson	12/21/2021	8:25 AM
Email Successfully Sent	jjackson@clvhts.com Lucy Work Order	BackgroundTaskUser	12/21/2021	8:25 AM
Email Successfully Sent	Update - Supervisor	BackgroundTaskUser	12/21/2021	8:25 AM
Email Successfully Sent	amanco@clvhts.com Lucy Work Order Status	BackgroundTaskUser	12/21/2021	8:25 AM
Status Change	Update - Leadworker	aferrone	12/23/2021	9:35 AM
Rate:	Opened At:	Televised: <input type="checkbox"/>		
Received By:	Pipe Footage Cleaned,	Power Rooter: <input type="checkbox"/>		
Work From:	Gallons Used:	Jet: <input type="checkbox"/>		
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>		
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>		
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>		
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>		
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>		
Test Performed Through:	Appointment Date: 12/21/2021 8:00 AM			
Dye Test Results:				
WO User 51:	E Mail:			
Measurement:	Measurement Line 2:			
History:				
Manhole Basin Repair:	Pipe Size:			
Material Used:	PVC Tees, Angles, Sles			
Pipe Repair:	WO User 44:			
Street Repair:	WO User 45:			
Grass Repair:	WO User 46:			
Curb Repair:				
Driveway- Sidewalk Re				
Construction Crew:				
WO User 39:	OUPS #:			
WO User 40:	WO User 48:			
WO User 41:				

Work Order Detail Report

12/23/2021

SSO INSPECTION 12-18-2021 .50 INCHES OF RAIN

9:36 AM

WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	
WO User 72:	WO User 82:	Televised: <input type="checkbox"/>
WO User 73:	Quantity:	Paid: <input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104: <input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105: <input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106: <input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:	
WO User 93 Date:	WO User 98 Date:	
WO User 94 Date:	WO User 99 Date:	
WO User 95 Date:	WO User 100 Date:	
WO User 96 Date:	WO User 101 Date:	
WO User 77:	WO User 87:	WO User 107: <input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108: <input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109: <input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110: <input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111: <input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 12/21/2021	PM Trigger:
		Rec #: 10253