




Daily Precipitation Report
Saturday, January 1, 2022
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Saturday, January 1, 2022

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.43	0.26	0.17	0.07	0.03
Brecksville	0.37	0.26	0.17	0.07	0.03
Brook Park	0.38	0.24	0.17	0.07	0.03
Cleveland Industrial Pkwy	0.52	0.31	0.21	0.09	0.03
Dille Ave PS	n/a	n/a	n/a	n/a	n/a
Division Ave PS	0.50	0.31	0.21	0.09	0.03
Easterly WWTP	0.39	0.26	0.18	0.08	0.03
Independence	0.46	0.32	0.23	0.13	0.05
James Rhodes HS	0.43	0.26	0.18	0.08	0.03
Jennings PS	0.48	0.31	0.20	0.08	0.03
Macedonia	0.37	0.25	0.17	0.07	0.03
Maple Heights	0.44	0.29	0.21	0.10	0.04
Mary Street PS	0.44	0.28	0.20	0.08	0.03
Mayfield Heights	0.48	0.31	0.21	0.09	0.03
Moreland Hills	0.45	0.32	0.23	0.13	0.05
North Olmsted	0.46	0.29	0.20	0.09	0.03
North Royalton	0.30	0.21	0.14	0.06	0.03
Oakwood	0.40	0.28	0.19	0.10	0.03
Olmsted Falls	0.36	0.22	0.14	0.06	0.02
Parma	0.40	0.24	0.16	0.07	0.03
Richfield	0.37	0.24	0.16	0.07	0.03
Shaker Heights	0.43	0.27	0.19	0.08	0.03
South Euclid	0.47	0.32	0.23	0.09	0.04
Southerly WWTC	0.39	0.26	0.17	0.08	0.03
Strongsville CWWTP	0.46	0.27	0.17	0.07	0.03
Strongsville Foltz	0.43	0.28	0.19	0.09	0.05
University Heights	0.49	0.31	0.22	0.09	0.03
Wade Park	0.45	0.30	0.21	0.09	0.03
Westerly WWTP	0.49	0.29	0.20	0.09	0.03
Westlake	n/a	n/a	n/a	n/a	n/a

Work Order Detail Report

1/4/2022

SSO INSPECTION 1-1-2022 0.49 INCHES OF RAIN

8:55 AM

WO Number:	220103-0001	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	1/4/2022 8:54 am	Main Task:	Inspection
Asset: SSO 431			
Location: FAIRFAX AT NORTH PARK			
Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	1/3/2022 7:53 AM
Lead Worker:	DelZoppo, Michael	End Date:	1/3/2022 2:53 PM
Priority:	High	Override Notifications	
Account #:		Problem	<input type="checkbox"/>
Proj No - Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection

Comments for Crew
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations		
<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

1/4/2022

SSO INSPECTION 1-1-2022 0.49 INCHES OF RAIN

8:55 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

1/4/2022

SSO INSPECTION 1-1-2022 0.49 INCHES OF RAIN

8:55 AM

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

Work Order Detail Report

1/4/2022

SSO INSPECTION 1-1-2022 0.49 INCHES OF RAIN

8:55 AM

Work Order Assets									
<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>	<u>Asset ID</u>	<u>Completed</u>
Sewer Control Valve	SSO 431						FAIRFAX AT NORTH PARK		26
Sewer Control Valve	SSO 114						NORTH PARK AND COVENTRY		16
Sewer Control Valve	SSO 121						FAIRMOUNT SOUTH OF SCARBOROUGH		35
Sewer Structure	SA16AAWB0								3094
Sewer Control Valve	SSO 112						FAIRMOUNT AT FAIRFAX		7
Sewer Control Valve	SSO 99						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		6
Sewer Control Valve	SSO 432						3012 NORTH WOODLAND		14
Sewer Control Valve	DB-03								55
Sewer Control Valve	DB-01								56
Sewer Control Valve	DB-02								57
Sewer Control Valve	CH-04						FAIRMOUNT AT DARTMOOR		5
Sewer Control Valve	SSO 110						FAIRMOUNT AT WELLINGTON		44
Sewer Control Valve	SSO 87						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		33
Sewer Control Valve	SSO 116						FAIRMOUNT AT MARLBORO		4
Sewer Control Valve	SSO 111						FAIRMOUNT AT ARLINGTON		46
Sewer Control Valve	SSO 113						FAIRMOUNT & COVENTRY (SCARBOROUGH)		37
Sewer Control Valve	SSO 124						FAIRMOUNT AND COVENTRY		47
Sewer Control Valve	CH-50						SCARBOROUGH AT LAMBERTON		53
Sewer Control Valve	SSO 129						BRADFORD AND LEE		11
Sewer Control Valve	CH-52						EDDINGTON		2
Sewer Control Valve	SSO 88						HAMPSHIRE LANE AT MAYFIELD (18")		42
Sewer Control Valve	SSO 122						EAST OVERLOOK AT EDGEHILL		36
Sewer Control Valve	SSO 89						HAMPSHIRE LANE AT MAYFIELD (36")		34
Sewer Structure	SA16ADZB0								1536
Sewer Control Valve	SSO 91						HAMPSHIRE AT EUCLID HTS. BLVD.		20
Sewer Structure	SA16ADPH0								4446
Sewer Control Valve	SSO 120						CEDAR BTW. FAIRMOUNT/DEMINGTON		8
Sewer Control Valve							2828 BERKSHIRE, EAST OF COVENTRY		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220103-0001

Work Order Detail Report

1/4/2022

SSO INSPECTION 1-1-2022 0.49 INCHES OF RAIN

8:55 AM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQCO	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

1/4/2022

SSO INSPECTION 1-1-2022 0.49 INCHES OF RAIN

8:55 AM

Check List		<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	1/3/2022/ 8:42 am	
	No overflow				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	1/3/2022/ 8:45 am	
	No overflow				
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	1/3/2022/ 8:49 am	
	No overflow				
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	1/3/2022/ 8:52 am	
	No overflow				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	1/3/2022/ 8:55 am	
	Overflow. Reset. Still overflowing.				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	1/3/2022/ 8:59 am	
	No overflow				
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	1/3/2022/ 9:01 am	
	No overflow				
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	1/3/2022/ 9:06 am	
	Overflow				
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	1/3/2022/ 9:09 am	
	No overflow.				
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	1/3/2022/ 9:11 am	
	No overflow				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	1/3/2022/ 9:15 am	
	No overflow				
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	1/3/2022/ 9:18 am	
	No overflow				
13	A-1 3041 FAIRMOUNT SA16AAUTO (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	1/3/2022/ 9:21 am	
	No overflow				
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	1/3/2022/ 9:24 am	
	No overflow				
15	A-38 FAIRMOUNT AT MARLBORO SA16AAU0 (INTERSECTION)	<input type="checkbox"/>	Sound	1/3/2022/ 9:26 am	
	No overflow				
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	1/3/2022/ 9:30 am	
	No overflow				
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	1/3/2022/ 9:33 am	
	No overflow				
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	1/3/2022/ 9:36 am	
	No overflow				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220103-0001

Work Order Detail Report

1/4/2022

SSO INSPECTION 1-1-2022 0.49 INCHES OF RAIN

8:55 AM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	1/3/2022/ 9:40 am
	No overflow			
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	1/3/2022/ 9:43 am
	No overflow			
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	1/3/2022/ 9:45 am
	No overflow			
22	A-9 BRADFORD AT LEE SA16AFL0 (INTERSECTION)	<input type="checkbox"/>	Sound	1/3/2022/ 9:50 am
	Overflow			
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	1/3/2022/10:13 am
	No overflow			1/3/2022
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	1/3/2022/10:17 am
	No overflow			
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	1/3/2022/10:17 am
	No overflow			
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	1/3/2022/10:20 am
	No overflow			
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	1/3/2022/10:23 am
	Overflow			
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	1/3/2022/10:26 am
	Overflow			
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	1/3/2022/10:29 am
	No overflow			
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	1/3/2022/10:32 am
	No overflow			
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	1/3/2022/10:36 am
	No overflow			
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	1/3/2022/10:40 am
	No overflow			
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	1/3/2022/10:46 am
	No overflow			
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	1/3/2022/12:13 pm
	No overflow			
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	1/3/2022/12:17 pm
	No overflow			
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	1/3/2022/12:18 pm
	No overflow			
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	1/3/2022/12:20 pm
	No overflow			
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	1/3/2022/12:23 pm
	No overflow			
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	1/3/2022/12:26 pm
	No overflow			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220103-0001

Work Order Detail Report

1/4/2022

SSO INSPECTION 1-1-2022 0.49 INCHES OF RAIN

8:55 AM

40	C-59 3427 THORNE RD SA16AQJD0	<input type="checkbox"/>	Sound	1/3/2022/12:33 pm
No overflow				
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	1/3/2022/12:35 pm
Overflow				
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	1/3/2022/12:40 pm
No overflow				
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	1/3/2022/12:44 pm
No overflow				
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	1/3/2022/12:47 pm
Overflow. Still overflowing. Can't reset. This was tangled up in flow detector. Flow detector is now removed.				
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	1/3/2022/12:54 pm
No overflow				

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:		*Cal'c UC: \$6.21	*Task Cost: \$279.52	Start Dt:	1/3/2022
Supervisor:	UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:	1/3/2022
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
9512 DelZoppo, Michael	Hours	8.00	\$172.32		1/3/2022	1/3/2022
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB	Hours	8.00	\$107.20		1/3/2022	1/3/2022
5						
Task Comment: SSO INSPECTION 0.49 INCHES OF RAIN						

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	7.00	0.00	0.00
Subcontractor:		Labor Costs	\$172.32	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	107.20	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$279.52	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:		Cell #:
City:		Fax #:		
State:		E-mail:		
Zip:				
Billing Data				
Contact Name:		*Billing Amount:		Billing Required: <input type="checkbox"/>
Invoice Number:		Date Bill Sent:		Billing Processed: <input type="checkbox"/>
Incoming Account #:		Payment Received:		Imported to Financials: <input type="checkbox"/>
		Payment Method:		

Associated PMs		Closed
PM Code	and Description	<input checked="" type="checkbox"/>
SSO-02	SSO INSPECTION	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220103-0001

Work Order Detail Report

1/4/2022

SSO INSPECTION 1-1-2022 0.49 INCHES OF RAIN

8:55 AM

Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	1/3/2022	8:19 AM
Supervisor Notification	Email Queued Successfully!	jjackson	1/3/2022	8:19 AM
Email Successfully Sent	jjackson@clvhts.com Lucity Work Order	BackgroundTaskUser	1/3/2022	8:20 AM
Status Change	Update - Supervisor From New Work Order to Complete	aferrone	1/4/2022	8:54 AM

Rate:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned .	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:	Appointment Date: 1/3/2022	7:30 AM	
Dye Test Results:			
WO User 51:			
Measurement:	E Mail:		
History:	Measurement Line 2:		
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Slee		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		

Work Order Detail Report

1/4/2022

SSO INSPECTION 1-1-2022 0.49 INCHES OF RAIN

8:55 AM

WO User 77:

WO User 87:

WO User 107:

WO User 78:

WO User 88:

WO User 108:

WO User 79:

WO User 89:

WO User 109:

WO User 80:

WO User 90:

WO User 110:

WO User 81:

WO User 91:

WO User 111:

WO Creator: jjackson


WO Creation Date: 1/3/2022

PM Trigger:

Rec #: 10267



Daily Precipitation Report
Sunday, January 9, 2022
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Sunday, January 9, 2022

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.39	0.35	0.31	0.18	0.06
Brecksville	0.24	0.22	0.19	0.09	0.04
Brook Park	0.35	0.34	0.31	0.15	0.06
Cleveland Industrial Pkwy	0.38	0.37	0.33	0.16	0.07
Dille Ave PS	n/a	n/a	n/a	n/a	n/a
Division Ave PS	0.41	0.40	0.34	0.20	0.08
Easterly WWTP	0.37	0.35	0.26	0.14	0.06
Independence	0.25	0.23	0.21	0.14	0.07
James Rhodes HS	0.27	0.26	0.25	0.13	0.05
Jennings PS	0.33	0.32	0.30	0.15	0.06
Macedonia	0.29	0.27	0.23	0.12	0.06
Maple Heights	0.26	0.22	0.21	0.13	0.06
Mary Street PS	0.40	0.39	0.34	0.18	0.08
Mayfield Heights	0.48	0.44	0.39	0.24	0.11
Moreland Hills	0.29	0.22	0.21	0.13	0.06
North Olmsted	n/a	n/a	n/a	n/a	n/a
North Royalton	n/a	n/a	n/a	n/a	n/a
Oakwood	0.26	0.24	0.21	0.12	0.06
Olmsted Falls	0.40	0.39	0.35	0.16	0.06
Parma	0.27	0.26	0.24	0.12	0.05
Richfield	0.33	0.31	0.27	0.14	0.07
Shaker Heights	0.34	0.32	0.30	0.16	0.05
South Euclid	0.40	0.39	0.32	0.20	0.09
Southerly WWTC	0.24	0.23	0.22	0.12	0.04
Strongsville C WWTP	0.31	0.29	0.26	0.13	0.05
Strongsville Foltz	0.31	0.30	0.28	0.16	0.08
University Heights	0.41	0.38	0.33	0.19	0.08
Wade Park	0.40	0.40	0.34	0.19	0.08
Westerly WWTP	0.36	0.36	0.31	0.18	0.08
Westlake	0.49	0.48	0.40	0.23	0.09

Work Order Detail Report

1/18/2022

SSO INSPECTION 1-9-2022 0.41 INCHES OF RAIN

10:55 AM

WO Number: 220118-0001	Category:	SSOs
Status: Complete	Problem:	Storm Response
Status Date: 1/18/2022 10:53 am	Main Task:	Inspection

Asset: SSO 431

Location: FAIRFAX AT NORTH PARK

Cause:	Weather	Assigned By:	29960	Jackson, Jeff
Assigned Crew:		Assigned Date:	1/9/2022	
Supervisor:	Jackson, Jeff	Start Date:	1/10/2022 8:00 AM	Override
Lead Worker:	Eathridge, David	End Date:	1/10/2022	Notifications
Priority:	High			Problem <input type="checkbox"/>
Account #:				Overdue <input type="checkbox"/>
Proj No - Acct:		Project ID:		Lead Worker <input type="checkbox"/>
Project:		Project Name:		Task <input type="checkbox"/>
Reason:				Supervisor <input type="checkbox"/>
Received By:				Hard Lock WO <input type="checkbox"/>
Inspected By:				

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection

Comments for Crew
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations		
<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

1/18/2022

SSO INSPECTION 1-9-2022 0.41 INCHES OF RAIN

10:55 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)
2,223,111.44143730 664,794.46048072 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO
2,221,638.88762389 665,726.15513962 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON
2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)
2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY
2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON
2,221,598.28993607 666,996.61322863
MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423 665,499.19660404 DOAN BROOK
BRADFORD AND LEE
2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH
EDDINGTON
2,221,299.08384156 674,932.84604380
HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL
2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")
2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD

HAMPSHIRE AT EUCLID HTS. BLVD.
2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON
2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY
2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD
2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd
2,227,113.30810548 671,276.67684697
LEE RD. & SUPERIOR AVE.
2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE
2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND
2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND
2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON
2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD

2225 NOBLE ROAD
2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF
2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE
2,228,126.76638040 684,188.23206055

2,220,777.89623564 666,181.72575080

2,218,501.67473823 671,997.54581206

2,216,759.55453481 670,474.59347738

Work Order Detail Report

1/18/2022

SSO INSPECTION 1-9-2022 0.41 INCHES OF RAIN

10:55 AM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

1/18/2022

SSO INSPECTION 1-9-2022 0.41 INCHES OF RAIN

10:55 AM

Work Order Assets							
<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>Description 2</u>
							<u>PM Description</u>
Sewer Control Valve	SSO 431						FAIRFAX AT NORTH PARK
Sewer Control Valve	SSO 114						NORTH PARK AND COVENTRY
Sewer Control Valve	SSO 121						FAIRMOUNT SOUTH OF SCARBOROUGH
Sewer Structure	SA16AAWB0						3094
Sewer Control Valve	SSO 112						FAIRMOUNT AT FAIRFAX
Sewer Control Valve	SSO 99						7
Sewer Control Valve	SSO 432						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)
Sewer Control Valve	DB-03						6
Sewer Control Valve	DB-01						3012 NORTH WOODLAND
Sewer Control Valve	DB-02						14
Sewer Control Valve	CH-04						55
Sewer Control Valve	SSO 110						FAIRMOUNT AT WELLINGTON
Sewer Control Valve	SSO 87						44
Sewer Control Valve	SSO 116						FAIRMOUNT AT MARLBORO
Sewer Control Valve	SSO 111						4
Sewer Control Valve	SSO 113						FAIRMOUNT AT ARLINGTON
Sewer Control Valve	SSO 124						46
Sewer Control Valve	CH-50						FAIRMOUNT & COVENTRY (SCARBOROUGH)
Sewer Control Valve	SSO 129						37
Sewer Control Valve	CH-52						SCARBOROUGH AT LAMBERTON
Sewer Control Valve	SSO 88						53
Sewer Control Valve	SSO 122						BRADFORD AND LEE
Sewer Control Valve	SSO 89						11
Sewer Structure	SA16ADZB0						EDDINGTON
Sewer Control Valve	SSO 91						2
Sewer Structure	SA16ADPH0						HAMPSHIRE LANE AT MAYFIELD (18")
Sewer Control Valve	SSO 120						42
Sewer Control Valve	SSO 120						EAST OVERLOOK AT EDGEHILL
Sewer Control Valve	SSO 99						36
Sewer Control Valve	SSO 88						HAMPSHIRE LANE AT MAYFIELD (36")
Sewer Control Valve	SSO 122						34
Sewer Control Valve	SSO 91						1536
Sewer Control Valve	SSO 91						HAMPSHIRE AT EUCLID HTS. BLVD.
Sewer Control Valve	SSO 120						20
Sewer Control Valve	SSO 120						4446
Sewer Control Valve	SSO 120						CEDAR BTW. FAIRMOUNT/DEMINGTON
Sewer Control Valve	SSO 120						8
Sewer Control Valve	SSO 120						2828 BERKSHIRE, EAST OF COVENTRY

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220118-0001

Work Order Detail Report

1/18/2022

SSO INSPECTION 1-9-2022 0.41 INCHES OF RAIN

10:55 AM

SSO 103	19
Sewer Control Valve SSO 104	3003 EUCLID HEIGHTS BLVD 15
Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior R 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQD0	4987
Sewer Structure SA16AQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

Work Order Detail Report

1/18/2022

SSO INSPECTION 1-9-2022 0.41 INCHES OF RAIN

10:55 AM

Check List		<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>		1/10/2022/ 7:00 am	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>		1/10/2022/ 7:00 am	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
8	A-6 FAIRMOUNT AT SHELBOURNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
9	A-5 FAIRMOUNT AT SHELBOURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
10	A-7 FAIRMOUNT AT SHELBOURNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAU0 (INTERSECTION)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>		1/10/2022/ 7:00 am	
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>		1/10/2022/ 7:00 am	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>		1/10/2022/ 7:00 am	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>		1/10/2022/ 7:00 am	
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>		1/10/2022/ 7:00 am	
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>		1/10/2022/ 7:00 am	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220118-0001

Work Order Detail Report

1/18/2022

SSO INSPECTION 1-9-2022 0.41 INCHES OF RAIN

10:55 AM

28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	1/10/2022/ 7:00 am
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	1/10/2022/ 7:00 am
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	1/10/2022/ 7:00 am
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	1/10/2022/ 7:00 am
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	1/10/2022/ 7:00 am
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	1/10/2022/ 7:00 am
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	1/10/2022/ 7:00 am
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	1/10/2022/ 7:00 am
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	1/10/2022/ 7:00 am
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	1/10/2022/ 7:00 am
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	1/10/2022/ 7:00 am
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	1/10/2022/ 7:00 am
40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	1/10/2022/ 7:00 am
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	1/10/2022/ 7:00 am
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	1/10/2022/ 7:00 am
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	1/10/2022/ 7:00 am
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	1/10/2022/ 7:00 am
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	1/10/2022/ 7:00 am

Tasks/Resources						
SWCT26 Inspection						
Crew:		Status: Complete	*Cal'd UC: \$0.00	*Task Cost: \$453.60	Start Dt: 1/10/2022	
Supervisor: Jackson, Jeff		UOM: Each	# of Units: 0.00	*Unit Cost: \$45.00	End Dt: 1/10/2022	
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
12459 Eathridge, David	Hours	8.00	\$181.12		1/10/2022	1/10/2022
39986 OBrien, Dominick	Hours	8.00	\$165.28		1/10/2022	1/10/2022
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB	Hours	8.00	\$107.20		1/10/2022	1/10/2022
5						
Task Comment: SSO INSPECTION 0.41 INCHES OF RAIN						

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	0.00	0.00	0.00
Subcontractor:		Labor Costs	16.00	0.00	0.00
Profit Center:		Material Costs	\$346.40	\$0.00	\$0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	107.20	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$453.60	\$0.00	\$0.00
		Use Task Info:	True	True	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220118-0001

Work Order Detail Report

1/18/2022

SSO INSPECTION 1-9-2022 0.41 INCHES OF RAIN

10:55 AM

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:	Cell #:	
City:		Fax #:		
State:		E-mail:		
Zip:				
Billing Data				
Contact Name:		*Billing Amount:	Billing Required: <input type="checkbox"/>	
Invoice Number:		Date Bill Sent:	Billing Processed: <input type="checkbox"/>	
Incoming Account #:		Payment Received:	Imported to Financials: <input type="checkbox"/>	
		Payment Method:		
Associated PMs				
PM Code and Description				
SSO-02 SSO INSPECTION		<u>Closed</u> <input checked="" type="checkbox"/>		
Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	aferrone	1/18/2022	8:53 AM
Supervisor Notification	Email Queued Successfully!	aferrone	1/18/2022	8:53 AM
Email Successfully Sent	jjackson@clvhts.com Lucy Work Order	BackgroundTaskUser	1/18/2022	8:54 AM
Status Change	Update - Supervisor	aferrone	1/18/2022	10:53 AM
From New Work Order to Complete				
Rate:	Opened At:	Televised: <input type="checkbox"/>		
Received By:	Pipe Footage Cleaned,	Power Rooter: <input type="checkbox"/>		
Work From:	Gallons Used:	Jet: <input type="checkbox"/>		
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>		
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>		
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>		
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>		
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>		
Test Performed Through:	Appointment Date:			
Dye Test Results:				
WO User 51:	E Mail:			
Measurement:	Measurement Line 2:			
History:				
Manhole Basin Repair:	Pipe Size:			
Material Used:	PVC Tees, Angles, Sleds			
Pipe Repair:	WO User 44:			
Street Repair:	WO User 45:			
Grass Repair:	WO User 46:			
Curb Repair:				
Driveway- Sidewalk Repair:				
Construction Crew:				
WO User 39:	OUPS #:			
WO User 40:	WO User 48:			
WO User 41:				

* A 'Hidden' field indicates permission to view the secured field is turned off.

Work Order Detail Report

1/18/2022

SSO INSPECTION 1-9-2022 0.41 INCHES OF RAIN

10:55 AM

WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	
WO User 72:	WO User 82:	Televised: <input type="checkbox"/>
WO User 73:	Quantity:	Paid: <input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104: <input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105: <input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106: <input type="checkbox"/>

WO User 92 Date:	WO User 97 Date:	
WO User 93 Date:	WO User 98 Date:	
WO User 94 Date:	WO User 99 Date:	
WO User 95 Date:	WO User 100 Date:	
WO User 96 Date:	WO User 101 Date:	
WO User 77:	WO User 87:	WO User 107: <input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108: <input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109: <input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110: <input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111: <input type="checkbox"/>

WO Creator: aferrone WO Creation Date: 1/18/2022 PM Trigger: Rec #: 10300