


**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Friday, May 6, 2022

Accumulation in Inches



Northeast Ohio Regional Sewer District


Daily Precipitation Report

Friday, May 6, 2022

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.62	0.48	0.30	0.13	0.05
Brecksville	0.88	0.56	0.33	0.15	0.06
Brook Park	1.13	0.59	0.31	0.17	0.05
Cleveland Industrial Pkwy	1.24	0.63	0.33	0.14	0.06
Dille Ave PS	0.60	0.44	0.24	0.10	0.04
Division Ave PS	0.73	0.55	0.31	0.15	0.08
Easterly WWTP	0.50	0.40	0.21	0.09	0.03
Independence	0.86	0.57	0.35	0.16	0.07
James Rhodes HS	0.91	0.50	0.26	0.12	0.04
Jennings PS	0.81	0.53	0.28	0.12	0.05
Macedonia	0.76	0.49	0.26	0.14	0.04
Maple Heights	0.82	0.55	0.35	0.16	0.06
Mary Street PS	0.71	0.53	0.30	0.13	0.06
Mayfield Heights	0.60	0.46	0.25	0.13	0.05
Moreland Hills	0.67	0.47	0.27	0.14	0.05
North Olmsted	1.22	0.71	0.42	0.18	0.07
North Royalton	1.18	0.69	0.45	0.21	0.07
Oakwood	0.69	0.43	0.23	0.11	0.04
Olmsted Falls	1.20	0.68	0.37	0.16	0.09
Parma	1.07	0.56	0.33	0.12	0.04
Richfield	1.29	0.62	0.38	0.22	0.11
Shaker Heights	0.60	0.47	0.29	0.13	0.05
South Euclid	0.53	0.40	0.21	0.09	0.04
Southerly WWTC	0.76	0.54	0.29	0.13	0.06
Strongsville CWWTP	1.13	0.61	0.34	0.15	0.05
Strongsville Foltz	1.05	0.61	0.35	0.18	0.07
University Heights	0.62	0.43	0.25	0.12	0.06
Wade Park	0.57	0.42	0.24	0.11	0.04
Westerly WWTP	0.66	0.50	0.28	0.14	0.06
Westlake	1.16	0.65	0.39	0.20	0.06



Daily Precipitation Report
Tuesday, May 3, 2022
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Tuesday, May 3, 2022

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.43	0.33	0.22	0.13	0.11	0.07
Brecksville	0.34	0.23	0.22	0.16	0.07	0.03
Brook Park	0.53	0.34	0.29	0.18	0.14	0.10
Cleveland Industrial Pkwy	0.47	0.27	0.25	0.16	0.13	0.09
Dille Ave PS	0.38	0.24	0.18	0.09	0.08	0.06
Division Ave PS	0.42	0.23	0.23	0.15	0.13	0.09
Easterly WWTP	0.36	0.19	0.18	0.15	0.14	0.10
Independence	0.41	0.29	0.27	0.17	0.07	0.04
James Rhodes HS	0.39	0.24	0.20	0.11	0.07	0.04
Jennings PS	0.46	0.32	0.26	0.16	0.13	0.10
Macedonia	0.35	0.22	0.19	0.16	0.07	0.03
Maple Heights	0.36	0.26	0.22	0.15	0.06	0.03
Mary Street PS	0.42	0.25	0.21	0.13	0.11	0.08
Mayfield Heights	0.38	0.28	0.23	0.11	0.08	0.07
Moreland Hills	0.37	0.25	0.25	0.14	0.09	0.07
North Olmsted	0.53	0.28	0.27	0.18	0.15	0.11
North Royalton	0.55	0.41	0.40	0.23	0.11	0.05
Oakwood	0.25	0.15	0.14	0.13	0.07	0.03
Olmsted Falls	0.56	0.34	0.33	0.23	0.18	0.11
Parma	0.49	0.35	0.27	0.13	0.08	0.05
Richfield	0.30	0.17	0.16	0.15	0.07	0.03
Shaker Heights	0.40	0.28	0.21	0.11	0.07	0.04
South Euclid	0.38	0.26	0.20	0.13	0.11	0.09
Southerly WWTC	0.42	0.29	0.23	0.12	0.08	0.06
Strongsville C WWTP	0.64	0.43	0.36	0.20	0.14	0.10
Strongsville Foltz	0.72	0.55	0.54	0.25	0.14	0.07
University Heights	0.32	0.22	0.18	0.09	0.06	0.05
Wade Park	0.32	0.17	0.17	0.10	0.08	0.07
Westerly WWTP	0.29	0.16	0.16	0.11	0.05	0.03
Westlake	0.69	0.45	0.44	0.35	0.31	0.15

Work Order Detail Report

5/11/2022

SSO INSPECTION 5-6-2022 0.62 INCHES OF RAIN

12:37 PM

WO Number: 220509-0002		Category:	SSOs	
Status:	Complete	Problem:	Storm Response	
Status Date:	5/11/2022 12:36 pm	Main Task:	Inspection	
Asset: SSO 431				
Location: FAIRFAX AT NORTH PARK				
Cause:	Weather	Assigned By:	29960	Jackson, Jeff
Assigned Crew:		Assigned Date:	5/6/2022	
Supervisor:	Jackson, Jeff	Start Date:	5/9/2022 7:34 AM	<u>Override</u>
Lead Worker:	Eathridge, David	End Date:	5/9/2022 12:33 PM	<u>Notifications</u>
Priority:	High			Problem ☐
Account #:				Overdue ☐
Proj No - Acct:		Project ID:		Lead Worker ☐
Project:		Project Name:		Task ☐
Reason:				Supervisor ☐
Received By:				Hard Lock WO ☐
Inspected By:				

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection
Sub-Division:
Area:
Sub-Area:
Owner:
Location:
Classification:

Maintenance Zone:**Alternate Zone:**

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Locations

<u>Address</u>		<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

5/11/2022


SSO INSPECTION 5-6-2022 0.62 INCHES OF RAIN

12:37 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220509-0002




Work Order Detail Report

5/11/2022

SSO INSPECTION 5-6-2022 0.62 INCHES OF RAIN

12:37 PM

2,224,536.21778722	668,887.44048372
2,226,741.35609348	679,432.95121680
2,226,591.76420106	679,420.92761880
2,227,825.14395215	684,881.15948047



Work Order Detail Report

5/11/2022

SSO INSPECTION 5-6-2022 0.62 INCHES OF RAIN

12:37 PM

Work Order Assets								
Object Type	Description 1		Description 2					
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed	
Sewer Control Valve					FAIRFAX AT NORTH PARK			
SSO 431						26		
Sewer Control Valve					NORTH PARK AND COVENTRY			
SSO 114						16		
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH			
SSO 121						35		
Sewer Structure								
SA16AAWB0						3094		
Sewer Control Valve					FAIRMOUNT AT FAIRFAX			
SSO 112						7		
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
SSO 99						6		
Sewer Control Valve					3012 NORTH WOODLAND			
SSO 432						14		
Sewer Control Valve								
DB-03						55		
Sewer Control Valve								
DB-01						56		
Sewer Control Valve								
DB-02						57		
Sewer Control Valve					FAIRMOUNT AT DARTMOOR			
CH-04						5		
Sewer Control Valve					FAIRMOUNT AT WELLINGTON			
SSO 110						44		
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
SSO 87						33		
Sewer Control Valve					FAIRMOUNT AT MARLBORO			
SSO 116						4		
Sewer Control Valve					FAIRMOUNT AT ARLINGTON			
SSO 111						46		
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)			
SSO 113						37		
Sewer Control Valve					FAIRMOUNT AND COVENTRY			
SSO 124						47		
Sewer Control Valve					SCARBOROUGH AT LAMBERTON			
CH-50						53		
Sewer Control Valve					BRADFORD AND LEE			
SSO 129						11		
Sewer Control Valve					EDDINGTON			
CH-52						2		
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")			
SSO 88						42		
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL			
SSO 122						36		
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")			
SSO 89						34		
Sewer Structure								
SA16ADZB0						1536		
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.			
SSO 91						20		
Sewer Structure								
SA16ADPH0						4446		
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON			
SSO 120						8		
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY			

Work Order Detail Report

5/11/2022

SSO INSPECTION 5-6-2022 0.62 INCHES OF RAIN

12:37 PM

SSO 103	19
Sewer Control Valve SSO 104	3003 EUCLID HEIGHTS BLVD 15
Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior F 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQD0	4987
Sewer Structure SA16AQCC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND ATHERSTONE 54
Sewer Structure SA16APEF0	1809

Work Order Detail Report

5/11/2022


SSO INSPECTION 5-6-2022 0.62 INCHES OF RAIN

12:37 PM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	5/9/2022/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	5/9/2022/	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	5/9/2022/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	5/9/2022/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Not Sound	5/9/2022/	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	5/9/2022/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	5/9/2022/	
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Not Sound	5/9/2022/	
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	5/9/2022/	
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	5/9/2022/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	5/9/2022/	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	5/9/2022/	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	5/9/2022/	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	5/9/2022/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	5/9/2022/	
needs block					
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	5/9/2022/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	5/9/2022/	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	5/9/2022/	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	5/9/2022/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	5/9/2022/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	5/9/2022/	
22	A-9 BRADFORD AT LEE SA16AFL0 (INTERSECTION)	☐	Sound	5/9/2022/	
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	5/9/2022/	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	5/9/2022/	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	5/9/2022/	
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	5/9/2022/	
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	5/9/2022/	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220509-0002



Work Order Detail Report

5/11/2022

SSO INSPECTION 5-6-2022 0.62 INCHES OF RAIN

12:37 PM

28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	5/9/2022/
29	B-42 12537 CEDAR SA16ACZA0	☐	Sound	5/9/2022/
30	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	5/9/2022/
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	5/9/2022/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	5/9/2022/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	5/9/2022/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	5/9/2022/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Not Sound	5/9/2022/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Not Sound	5/9/2022/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Sound	5/9/2022/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Sound	5/9/2022/
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Sound	5/9/2022/
40	C-59 3427 THORNE RD SA16AQD0	☐	Sound	5/9/2022/
41	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	5/9/2022/
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	5/9/2022/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	5/9/2022/
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Not Sound	5/9/2022/
needs block				
45	C-50 3593 FENLEY SA16APEH0	☐	Sound	5/9/2022/

Tasks/Resources

SWCT26 Inspection

Crew:

Status:

*Cal'c UC: \$6.41

*Task Cost: \$288.32

Start Dt: 5/9/2022

Supervisor:

UOM: Each

of Units: 45.00

*Unit Cost: \$0.00

End Dt: 5/9/2022

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
12459 Eathridge, David	Hours	4.00	\$90.56		5/9/2022	5/9/2022
11213 Owens, Will	Hours	4.00	\$90.56		5/9/2022	5/9/2022
29960 Jackson, Jeff	Hours	4.00	\$0.00		5/9/2022	5/9/2022

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	4.00	\$53.60		5/9/2022	5/9/2022
CHFLT55 FORD F250 PICK UP 0	Hours	4.00	\$53.60		5/9/2022	5/9/2022
CHFT-500 FORD F250 PICK UP TRUCK	Each	4.00	\$0.00		5/9/2022	5/9/2022

Task Comment: SSO INSPECTIONS 0.62 INCHES OF RAIN

Work Order Detail Report

5/11/2022

SSO INSPECTION 5-6-2022 0.62 INCHES OF RAIN

12:37 PM

			*Actual	*Estimated	*Difference
Projected Complete:		Lock: ☐	WO Duration	4.98	0.00
Repair Type:			Labor Hours	12.00	0.00
Subcontractor:			Labor Costs	\$181.12	\$0.00
Profit Center:			Material Costs	0.00	0.00
			Fluids Costs	0.00	0.00
Quantity:	0.00	Lock: ☐	Equipment Costs	107.20	0.00
Unit of Measure:	Each		Contractor Costs	0.00	0.00
*Unit Cost:	\$0.00		Misc. Costs	0.00	0.00
WO Hours:	0.00		Total Costs	\$288.32	\$0.00
Use Task Info:			True	True	

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:			
City:		Phone:	Cell #:
State:		Fax #:	
Zip:		E-mail:	
Billing Data			
Contact Name:		*Billing Amount:	Billing Required: ☐
Invoice Number:		Date Bill Sent:	Billing Processed: ☐
Incoming Account #:		Payment Received:	Imported to Financials: ☐
		Payment Method:	

Associated PMs	
<u>PM Code and Description</u>	<u>Closed</u>
SSO-02 SSO INSPECTION	☒

Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	aferrone	5/9/2022	10:09 AM
Supervisor Notification	Email Queued Successfully!	aferrone	5/9/2022	10:09 AM
Status Change	From New Work Order to Complete	aferrone	5/11/2022	12:36 PM

Rate:	Opened At:	Televised: ☐
Recieved By:	Pipe Footage Cleaned :	Power Rooter: ☐
Work From:	Gallons Used:	Jet: ☐
Pipe Size:	WO User 23:	Gap Vac: ☐
Pipe Condition:	WO User 24:	Dye Test: ☐
Could Not Open:	WO User 9:	Gap Root Cut: ☐
Additional Repair:	User 10:	GIS Correction?: ☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: ☐
Test Performed Thru	Appointment Date:	
Dye Test Results:		
WO User 51:	E Mail:	
Measurement:	Measurement Line 2:	
History:		

Work Order Detail Report

5/11/2022

SSO INSPECTION 5-6-2022 0.62 INCHES OF RAIN

12:37 PM


Manhole Basin Repair:	Pipe Size:	
Material Used:	PVC Tees, Angles, Sleeves	
Pipe Repair:	WO User 44:	
Street Repair:	WO User 45:	
Grass Repair:	WO User 46:	
Curb Repair:		
Driveway- Sidewalk Repair:		
Construction Crew:		
WO User 39:		
WO User 40:	OUPS #:	
WO User 41:	WO User 48:	
WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	
WO User 72:	WO User 82:	Televised: ☐
WO User 73:	Quantity:	Paid: ☐
WO User 74:	WO User 84:	WO User 104: ☐
WO User 75:	WO User 85:	WO User 105: ☐
WO User 76:	WO User 86:	WO User 106: ☐
WO User 92 Date:	WO User 97 Date:	
WO User 93 Date:	WO User 98 Date:	
WO User 94 Date:	WO User 99 Date:	
WO User 95 Date:	WO User 100 Date:	
WO User 96 Date:	WO User 101 Date:	
WO User 77:	WO User 87:	WO User 107: ☐
WO User 78:	WO User 88:	WO User 108: ☐
WO User 79:	WO User 89:	WO User 109: ☐
WO User 80:	WO User 90:	WO User 110: ☐
WO User 81:	WO User 91:	WO User 111: ☐
WO Creator: aferrone	WO Creation Date: 5/9/2022	PM Trigger: Rec #: 12722



Daily Precipitation Report

Saturday, May 21, 2022

Accumulation in Inches



Work Order Detail Report

5/25/2022

SSO INSPECTIONS 5-21-2022 1.06" OF RAIN

3:02 PM

WO Number: 220524-0001		Category:	SSOs	
Status: Complete		Problem:	Storm Response	
Status Date: 5/25/2022 3:01 pm		Main Task:	Inspection	
Asset: SSO 431				
Location: FAIRFAX AT NORTH PARK				
Cause: Weather		Assigned By:		
Assigned Crew:		Assigned Date:		
Supervisor:	Jackson, Jeff	Start Date: 5/24/2022	7:59 AM	<u>Override</u>
Lead Worker:	Palmisano, Anthony	End Date: 5/25/2022	2:58 PM	<u>Notifications</u>
Priority:	High			
Account #:				
Proj No - Acct:				
Project:		Project ID:		
Reason:		Project Name:		
Received By:				
Inspected By:				

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection
Sub-Division:
Area:
Sub-Area:
Owner:
Location:
Classification:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Maintenance Zone:**Alternate Zone:**

Work Order Locations

<u>Address</u>	<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>
<u>General Location</u>	
FAIRFAX AT NORTH PARK	
2,220,655.65435414	665,517.24643672
NORTH PARK AND COVENTRY	Doan Brook
2,219,873.16674590	666,048.82312946
FAIRMOUNT SOUTH OF SCARBOROUGH	DOAN BROOK - MAIN BRANCH
2,220,364.86097248	666,446.72325230
FAIRMOUNT AT FAIRFAX	DOAN BROOK - MAIN BRANCH
2,220,920.81917815	666,080.57995571
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	DOAN BROOK - MAIN BRANCH
2,223,053.81655256	664,693.25202172
3012 NORTH WOODLAND	DOAN BROOK - MAIN BRANCH
2,222,845.06631389	664,689.08536339
	Doan Brook
2,226,440.21168265	664,329.55524255
2,226,354.79813956	664,409.89202413
2,226,389.92077273	664,379.07548472
FAIRMOUNT AT DARTMOOR	
2,225,149.97508989	664,453.31024438
FAIRMOUNT AT WELLINGTON	DOAN BROOK - MAIN BRANCH
2,223,969.26550905	664,532.08075613
	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

5/25/2022

SSO INSPECTIONS 5-21-2022 1.06" OF RAIN

3:02 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

5/25/2022

SSO INSPECTIONS 5-21-2022 1.06" OF RAIN

3:02 PM

2,224,536.21778722	668,887.44048372
2,226,741.35609348	679,432.95121680
2,226,591.76420106	679,420.92761880
2,227,825.14395215	684,881.15948047

Work Order Detail Report

5/25/2022

SSO INSPECTIONS 5-21-2022 1.06" OF RAIN

3:02 PM

Work Order Assets							
Object Type	Description 1		Description 2				
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve					FAIRFAX AT NORTH PARK		
SSO 431						26	
Sewer Control Valve					NORTH PARK AND COVENTRY		
SSO 114						16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Control Valve					3012 NORTH WOODLAND		
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO		
SSO 116						4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY		
SSO 124						47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON		
CH-50						53	
Sewer Control Valve					BRADFORD AND LEE		
SSO 129						11	
Sewer Control Valve					EDDINGTON		
CH-52						2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL		
SSO 122						36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		

Work Order Detail Report

5/25/2022

SSO INSPECTIONS 5-21-2022 1.06" OF RAIN

3:02 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

5/25/2022

SSO INSPECTIONS 5-21-2022 1.06" OF RAIN

3:02 PM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Not Sound	5/25/2022/11:54 am	5/25/2022
Reset					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	5/25/2022/11:55 am	5/25/2022
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	5/25/2022/12:00 pm	5/25/2022
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	5/25/2022/12:00 pm	5/25/2022
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Sound	5/25/2022/11:55 am	5/25/2022
Meter in manhole					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	5/25/2022/12:01 pm	5/25/2022
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	5/25/2022/11:58 am	5/25/2022
Meter in manhole					
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	5/25/2022/12:01 pm	5/25/2022
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	5/25/2022/12:01 pm	5/25/2022
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	5/25/2022/12:02 pm	5/25/2022
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	5/25/2022/12:12 pm	5/25/2022
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	5/25/2022/12:12 pm	5/25/2022
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	5/25/2022/12:13 pm	5/25/2022
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	5/25/2022/11:59 am	5/25/2022
Meter in manhole					
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	5/25/2022/12:13 pm	5/25/2022
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	5/25/2022/12:16 pm	5/25/2022
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	5/25/2022/12:14 pm	5/25/2022
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	5/25/2022/12:14 pm	5/25/2022
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	5/25/2022/12:15 pm	5/25/2022
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	5/25/2022/12:15 pm	5/25/2022
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	5/25/2022/12:15 pm	5/25/2022
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Sound	5/25/2022/12:14 pm	5/25/2022
Monitor					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	5/25/2022/ 8:16 am	5/25/2022
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	5/25/2022/ 8:40 am	5/25/2022

Work Order Detail Report

5/25/2022

SSO INSPECTIONS 5-21-2022 1.06" OF RAIN

3:02 PM

25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	5/25/2022/ 8:42 am	5/25/2022
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Not Sound	5/25/2022/ 8:52 am	5/25/2022
Reset					
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Not Sound	5/25/2022/ 8:57 am	5/25/2022
Reset					
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	5/25/2022/ 9:03 am	5/25/2022
29	B-42 12537 CEDAR SA16ACZA0	☐	Sound	5/25/2022/ 9:28 am	5/25/2022
30	B-15 COVENTRY AND CEDAR SA16ADB0	☐	Sound	5/25/2022/12:16 pm	5/25/2022
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	5/25/2022/ 9:38 am	5/25/2022
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	5/25/2022/ 9:45 am	5/25/2022
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	5/25/2022/10:07 am	5/25/2022
Meter in hole					
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	5/24/2022/ 8:13 am	5/24/2022
Meter in manhole					
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Not Sound	5/24/2022/ 9:47 am	5/24/2022
Blocked still overflowing					
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Not Sound	5/24/2022/ 9:35 am	
Reset					
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Sound	5/24/2022/ 9:53 am	5/24/2022
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Not Sound	5/24/2022/10:02 am	5/24/2022
Reset					
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Sound	5/24/2022/10:09 am	5/24/2022
40	C-59 3427 THORNE RD SA16AQD0	☐	Sound	5/24/2022/ 9:12 am	5/24/2022
41	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	5/24/2022/ 9:08 am	5/24/2022
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	5/24/2022/ 8:59 am	5/24/2022
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	5/24/2022/ 8:21 am	
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	5/24/2022/ 8:30 am	
Meter in manhole					
45	C-50 3593 FENLEY SA16APEH0	☐	Sound	5/24/2022/ 8:45 am	5/24/2022

Work Order Detail Report

5/25/2022

SSO INSPECTIONS 5-21-2022 1.06" OF RAIN

3:02 PM

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:	*Cal'c UC: \$12.29	*Task Cost: \$553.12	Start Dt: 5/24/2022		
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 5/25/2022		
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	12.00	\$258.48		5/24/2022	5/25/2022
28056 Palmisano, Anthony	Hours	4.00	\$80.24		5/24/2022	5/25/2022
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	12.00	\$160.80		5/24/2022	5/25/2022
CHFLT55 FORD F250 PICK UP 0	Hours	4.00	\$53.60		5/24/2022	5/25/2022
Task Comment: SSO INSPECTION 1.06" OF RAIN						

Projected Complete:	Lock: ☐	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	14.98	0.00	0.00
Subcontractor:		Labor Costs	\$338.72	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity: 0.00	Lock: ☐	Equipment Costs	214.40	0.00	0.00
Unit of Measure: Each		Contractor Costs	0.00	0.00	0.00
*Unit Cost: \$0.00		Misc. Costs	0.00	0.00	0.00
WO Hours: 0.00		Total Costs	\$553.12	\$0.00	\$0.00
		Use Task Info:	True	True	

Billing	
Billed Party	
Customer ID:	Customer Number:
Customer Name:	Last Name:
Address:	
City:	Phone:
State:	Fax #:
Zip:	E-mail:
	Cell #:
Billing Data	
Contact Name:	*Billing Amount:
Invoice Number:	Date Bill Sent:
Incoming Account #:	Payment Received:
	Payment Method:
	Billing Required: ☐
	Billing Processed: ☐
	Imported to Financials: ☐

Associated PMs	
PM Code and Description	Closed
SSO-02 SSO INSPECTION	☒

Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	5/24/2022	7:23 AM
Supervisor Notification	Email Queued Successfully!	jjackson	5/24/2022	7:23 AM
Status Change	From New Work Order to Complete	aferrone	5/25/2022	3:01 PM

Work Order Detail Report

SSO INSPECTIONS 5-21-2022 1.06" OF RAIN

5/25/2022

3:02 PM

Rate:	Opened At:	Televised:	☐
Recieved By:	Pipe Footage Cleaned :	Power Rooter:	☐
Work From:	Gallons Used:	Jet:	☐
Pipe Size:	WO User 23:	Gap Vac:	☐
Pipe Condition:	WO User 24:	Dye Test:	☐
Could Not Open:	WO User 9:	Gap Root Cut:	☐
Additional Repair:	User 10:	GIS Correction?:	☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	☐
Test Performed Throug	Appointment Date: 5/24/2022 7:30 AM		
Dye Test Results:			
WO User 51:			
Measurement:	E Mail:		
History:	Measurement Line 2:		
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Slec		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:			
WO User 40:	OUPS #:		
WO User 41:	WO User 48:		
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	☐
WO User 73:	Quantity:	Paid:	☐
WO User 74:	WO User 84:	WO User 104:	☐
WO User 75:	WO User 85:	WO User 105:	☐
WO User 76:	WO User 86:	WO User 106:	☐
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	☐
WO User 78:	WO User 88:	WO User 108:	☐
WO User 79:	WO User 89:	WO User 109:	☐
WO User 80:	WO User 90:	WO User 110:	☐
WO User 81:	WO User 91:	WO User 111:	☐
WO Creator: jjackson	WO Creation Date: 5/24/2022	PM Trigger:	Rec #: 12787