

CITY OF
**CLEVELAND
HEIGHTS** 
LAW DEPARTMENT

December 15, 2022

Via E-Mail: vezner.kris@epa.gov and Berger.Jake@epa.gov

Kris P. Vezner, Esq.
Associate Regional Counsel
U.S. Environmental Protection Agency
Region 5 (C-14J)
77 West Jackson Blvd.
Chicago, IL 60604

and

Jake Berger
Physical Scientist
Water Enforcement & Compliance Assurance Branch
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Mail Code ECW-15J
Chicago, IL 60604

Re: November 2022 Overflow Monitoring Reports
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through November 27, 2022, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,




William R. Hanna
Director of Law
Enclosures

cc: Thomas Benson, Esq., EPA Attorney
James Vinch, Esq., EPA Attorney
James Zimny, EPA Engineer
U.S. EPA Region 5 Water Enforcement Branch
Mark Klingenstein, Environmental Engineer
Erm Gomes, Ohio EPA
Allison Cycyk, Ohio EPA
Casey Galligan, Ohio EPA
David Brumbaugh, Ohio EPA
Bill Fischbein, Ohio EPA
Kahlil Seren, Mayor
Collette Clinkscale, Director of Public Works
Steve Barker, Public Relations
Anthony Ferrone, Utilities Commissioner
Kevin Vander Tuig, P.E. (Outside Engineer)
Mathew St. Pierre, (Outside Engineer)
Dan Porter (Outside Engineer)
Cindy Biacofsky (Outside Engineer)
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)



Daily Precipitation Report
Friday, November 11, 2022
Accumulation in inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Friday, November 11, 2022

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	2.32	1.86	1.23	0.61	0.23
Brecksville	1.85	1.51	0.97	0.55	0.22
Brook Park	1.60	1.23	0.94	0.46	0.15
Cleveland Industrial Pkwy	1.40	1.07	0.83	0.40	0.15
Dille Ave PS	n/a	n/a	n/a	n/a	n/a
Division Ave PS	1.46	1.12	0.83	0.39	0.15
Easterly WWTP	1.23	0.88	0.53	0.24	0.09
Independence	2.14	1.74	1.12	0.47	0.20
James Rhodes HS	1.57	1.20	0.90	0.38	0.13
Jennings PS	1.51	1.18	0.84	0.35	0.14
Macedonia	1.45	1.12	0.68	0.39	0.17
Maple Heights	2.37	1.94	1.22	0.69	0.26
Mary Street PS	1.39	1.04	0.71	0.31	0.13
Mayfield Heights	2.24	1.83	1.33	0.60	0.22
Moreland Hills	1.99	1.51	0.99	0.41	0.17
North Olmsted	1.10	0.88	0.62	0.37	0.13
North Royalton	1.52	1.18	0.71	0.32	0.13
Oakwood	1.52	1.16	0.68	0.36	0.16
Olmsted Falls	1.50	1.21	0.98	0.63	0.23
Parma	1.81	1.45	1.12	0.53	0.20
Richfield	1.55	1.24	0.76	0.37	0.15
Shaker Heights	1.97	1.58	0.96	0.41	0.15
South Euclid	1.58	1.19	0.66	0.32	0.15
Southerly WWTC	1.88	1.56	1.08	0.47	0.23
Strongsville C WWTP	1.87	1.53	1.19	0.55	0.18
Strongsville Foltz	1.62	1.34	0.98	0.45	0.17
University Heights	1.99	1.56	0.88	0.45	0.20
Wade Park	1.48	1.08	0.65	0.30	0.09
Westerly WWTP	1.35	1.03	0.79	0.38	0.14
Westlake	0.97	0.52	0.09	0.29	0.04

Work Order Detail Report

11/18/2022

SSO INSPECTION 11-11-2022 1.99 INCHES OF RAIN

10:00 AM

WO Number:	221115-0003	Category:	SSOs			
Status:	Complete	Problem:	Storm Response			
Status Date:	11/18/2022 9:59 am	Main Task:	Inspection			
Asset:	SSO 431					
Location:	FAIRFAX AT NORTH PARK					
Cause:	Weather					
Assigned Crew:						
Supervisor:	Jackson, Jeff	Assigned By:	15854 Ferrone, Anthony			
Lead Worker:	Manco, Angelo	Assigned Date:	11/14/2022			
Priority:	High	Start Date:	11/15/2022 7:30 AM			
Account #:						
Proj No - Acct:						
Project:						
Reason:						
Received By:						
Inspected By:						
Request Comments for Work Order						
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.						

Location

Department:	Sewer Collection
Division:	Sewer
Sub-Division:	
Area:	
Sub-Area:	
Owner:	
Location:	
Classification:	

Maintenance Zone:

Alternate Zone:

Work Order Locations

<u>Address</u>		<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Detail Report

11/18/2022

SSO INSPECTION 11-11-2022 1.99 INCHES OF RAIN

10:00 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)
2,223,111.44143730 664,794.46048072 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO
2,221,638.88762389 665,726.15513962 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON
2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)
2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY
2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON
2,221,598.28993607 666,996.61322863
MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423 665,499.19660404 DOAN BROOK
BRADFORD AND LEE
2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH
EDDINGTON
2,221,299.08384156 674,932.84604380
HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL
2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")
2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD

HAMPSHIRE AT EUCLID HTS. BLVD.
2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON
2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY
2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD
2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd
2,227,113.30810548 671,276.67684697
LEE RD. & SUPERIOR AVE.
2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE
2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND
2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND
2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON
2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD

2225 NOBLE ROAD
2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF
2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE
2,228,126.76638040 684,188.23206055

2,220,777.89623564 666,181.72575080

2,218,501.67473823 671,997.54581206

2,216,759.55453481 670,474.59347738

Work Order Detail Report

11/18/2022

SSO INSPECTION 11-11-2022 1.99 INCHES OF RAIN

10:00 AM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

11/18/2022

SSO INSPECTION 11-11-2022 1.99 INCHES OF RAIN

10:00 AM

Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>	<u>Description 2</u>	<u>Asset ID</u>	<u>Completed</u>
Sewer Control Valve								FAIRFAX AT NORTH PARK		
SSO 431									26	
Sewer Control Valve								NORTH PARK AND COVENTRY		
SSO 114									16	
Sewer Control Valve								FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121									35	
Sewer Structure										
SA16AAWBO									3094	
Sewer Control Valve								FAIRMOUNT AT FAIRFAX		
SSO 112									7	
Sewer Control Valve								FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99									6	
Sewer Control Valve								3012 NORTH WOODLAND		
SSO 432									14	
Sewer Control Valve										
DB-03									55	
Sewer Control Valve										
DB-01									56	
Sewer Control Valve										
DB-02									57	
Sewer Control Valve								FAIRMOUNT AT DARTMOOR		
CH-04									5	
Sewer Control Valve										
SSO 110								FAIRMOUNT AT WELLINGTON		
Sewer Control Valve									44	
SSO 87										
Sewer Control Valve								FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 116									33	
Sewer Control Valve										
SSO 111								FAIRMOUNT AT MARLBORO		
Sewer Control Valve									4	
SSO 113										
Sewer Control Valve								FAIRMOUNT AT ARLINGTON		
SSO 124									46	
Sewer Control Valve										
CH-50								FAIRMOUNT & COVENTRY (SCARBOROUGH)		
Sewer Control Valve									37	
SSO 129										
Sewer Control Valve								FAIRMOUNT AND COVENTRY		
CH-52									47	
Sewer Control Valve										
SSO 88								SCARBOROUGH AT LAMBERTON		
Sewer Control Valve									53	
SSO 122										
Sewer Control Valve								BRADFORD AND LEE		
SSO 89									11	
Sewer Structure										
SA16ADZB0								EDDINGTON		
Sewer Control Valve									2	
SSO 91										
Sewer Structure								HAMPSHIRE LANE AT MAYFIELD (18")		
SA16ADPH0									42	
Sewer Control Valve										
SSO 120								EAST OVERLOOK AT EDGEHILL		
Sewer Control Valve									36	
SSO 128										
Sewer Control Valve								HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89									34	
Sewer Structure										
SA16ADZB0								1536		
Sewer Control Valve										
SSO 91								HAMPSHIRE AT EUCLID HTS. BLVD.		
Sewer Structure									20	
SA16ADPH0										
Sewer Control Valve								4446		
SSO 120										
Sewer Control Valve								CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 128									8	
Sewer Control Valve										
SSO 128								2828 BERKSHIRE, EAST OF COVENTRY		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 221115-0003

Work Order Detail Report

11/18/2022

SSO INSPECTION 11-11-2022 1.99 INCHES OF RAIN

10:00 AM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

11/18/2022

SSO INSPECTION 11-11-2022 1.99 INCHES OF RAIN

10:00 AM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	11/15/2022/	
DE					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	11/15/2022/	
DE					
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	11/15/2022/	
DE					
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	11/15/2022/	
DE					
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	11/15/2022/	
DE					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	11/15/2022/	
DE					
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	11/15/2022/	
DE					
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	11/15/2022/	
DE					
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	11/15/2022/	
DE					
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	11/15/2022/	
DE					
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	11/15/2022/	
DE					
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	11/15/2022/	
DE					
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	11/15/2022/	
DE					
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUPO (INTERSECTION)	<input type="checkbox"/>	Sound	11/15/2022/	
DE					
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	11/15/2022/	
DE					
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	11/15/2022/	
DE					
17	A-35 2393 COVENTRY SA16AAASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	11/15/2022/	
DE					
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Not Sound	11/15/2022/	
DE					

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 221115-0003

Work Order Detail Report

11/18/2022

SSO INSPECTION 11-11-2022 1.99 INCHES OF RAIN

10:00 AM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	11/15/2022/
DE				
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	11/15/2022/
DE				
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	11/15/2022/
DE				
22	A-9 BRADFORD AT LEE SA16AFL0 (INTERSECTION)	<input type="checkbox"/>	Sound	11/15/2022/
DE				
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	11/16/2022/
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	11/15/2022/
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	/
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	11/16/2022/
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO	<input type="checkbox"/>	Sound	11/15/2022/
28	B-46 EDGEHILL AT E OVERLOOK SA16AEFP0	<input type="checkbox"/>	Sound	11/16/2022/
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	11/16/2022/
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	11/16/2022/
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	11/16/2022/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	11/16/2022/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	11/16/2022/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	11/16/2022/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	11/15/2022/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	11/16/2022/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	11/16/2022/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	11/15/2022/
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	11/15/2022/
40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	11/15/2022/
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	11/15/2022/
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	11/15/2022/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	11/15/2022/
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	11/15/2022/
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Not Sound	11/15/2022/

Work Order Detail Report

11/18/2022

SSO INSPECTION 11-11-2022 1.99 INCHES OF RAIN

10:00 AM

Tasks/Resources		Status: SWCT26 Inspection		*Cal'c UC: \$19.35	*Task Cost: \$870.80	Start Dt: 11/15/2022
Crew:	UOM:	Each		# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 11/15/2022
Employee						
Resource	UOM	Units		*Total Cost	Alt Description	Start Dt
12459 Eatridge, David	Hours	8.00		\$207.04		11/15/2022
19356 Manco, Angelo	Hours	8.00		\$217.84		11/15/2022
13859 Moten, Robert	Hours	8.00		\$197.52		11/15/2022
Equipment						
Resource	UOM	Units		*Total Cost	Alt Description	Start Dt
CHFLT50 FORD F250 CREW CAB	Hours	8.00		\$107.20		11/15/2022
5						
CHFLT55 FORD 350 CREW CAB	Hours	8.00		\$141.20		11/15/2022
9						

Task Comment: SSO INSPECTION 11-11-2022

			*Actual	*Estimated	*Difference
Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	7.35	0.00	0.00
Repair Type:		Labor Hours	24.00	0.00	0.00
Subcontractor:		Labor Costs	\$622.40	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity:	0.00	Equipment Costs	248.40	0.00	0.00
Unit of Measure:	Each	Contractor Costs	0.00	0.00	0.00
*Unit Cost:	\$0.00	Misc. Costs	0.00	0.00	0.00
WO Hours:	0.00	Total Costs	\$870.80	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	Billing Required: <input type="checkbox"/>
Invoice Number:		Date Bill Sent:	Billing Processed: <input type="checkbox"/>
Incoming Account #:		Payment Received:	Imported to Financials: <input type="checkbox"/>
		Payment Method:	

Associated PMs		PM Code and Description	Closed
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>

Tracking		Description	By	Date	Time
Item					
Work Order Creation		From Routine Work SSO-02 - SSO INSPECTION	aferrone	11/15/2022	10:50 AM
Supervisor Notification		Email Queued Successfully!	aferrone	11/15/2022	10:50 AM
Leadworker Notification		Email Queued Successfully!	aferrone	11/15/2022	10:50 AM
Status Change		From New Work Order to Closed In Field	amanco	11/16/2022	10:15 AM
Status Change		From Closed In Field to Complete	aferrone	11/18/2022	9:59 AM

Work Order Detail Report

11/18/2022

SSO INSPECTION 11-11-2022 1.99 INCHES OF RAIN


10:00 AM

Rate:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned.	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:	Appointment Date:		
Dye Test Results:			
WO User 51:			
Measurement:	E Mail:		
History:	Measurement Line 2:		
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sleeves		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Repair:			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: aferrone	WO Creation Date: 11/15/2022	PM Trigger:	Rec #: 13228

 **Northeast Ohio
Regional Sewer District**

Daily Precipitation Report
Sunday, November 27, 2022

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Sunday, November 27, 2022

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.47	0.31	0.27	0.19	0.07
Brecksville	0.43	0.32	0.27	0.19	0.08
Brock Park	0.50	0.43	0.36	0.24	0.08
Cleveland Industrial Pkwy	0.55	0.47	0.39	0.26	0.08
Dille Ave PS	0.46	0.40	0.34	0.24	0.08
Division Ave PS	0.50	0.43	0.36	0.26	0.08
Easterly WWTP	0.56	0.48	0.39	0.29	0.09
Independence	0.43	0.30	0.28	0.19	0.08
James Rhodes HS	0.48	0.38	0.33	0.24	0.08
Jennings PS	0.49	0.39	0.34	0.23	0.08
Macedonia	0.44	0.34	0.30	0.18	0.08
Maple Heights	0.38	0.26	0.25	0.17	0.07
Mary Street PS	0.50	0.41	0.36	0.26	0.08
Mayfield Heights	0.53	0.33	0.29	0.19	0.07
Moreland Hills	0.66	0.49	0.43	0.27	0.10
North Olmsted	0.56	0.46	0.38	0.21	0.09
North Royalton	0.38	0.27	0.24	0.18	0.08
Oakwood	0.44	0.36	0.31	0.19	0.07
Olmsted Falls	0.63	0.53	0.45	0.26	0.09
Parma	0.53	0.39	0.34	0.24	0.09
Richfield	0.45	0.37	0.32	0.19	0.08
Shaker Heights	0.43	0.31	0.28	0.20	0.07
South Euclid	0.47	0.36	0.32	0.24	0.08
Southerly WWTC	0.45	0.33	0.29	0.22	0.08
Strongsville C WWTP	0.49	0.39	0.34	0.24	0.08
Strongsville Foltz	0.34	0.34	0.30	0.21	0.07
University Heights	0.46	0.34	0.30	0.23	0.07
Wade Park	0.50	0.43	0.38	0.28	0.09
Westerly WWTP	0.48	0.42	0.34	0.24	0.07
Westlake	0.64	0.52	0.42	0.26	0.09

Work Order Detail Report

12/1/2022

SSO INSPECTION 11-27-2022 0.46 INCHES OF RAIN

10:13 AM

WO Number:	221130-0003	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	12/1/2022 10:12 am	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather		
Assigned Crew:			
Supervisor:	Jackson, Jeff	Assigned By:	
Lead Worker:	Manco, Angelo	Assigned Date:	
Priority:	High	Start Date:	11/30/2022 7:10 AM
Account #:		End Date:	11/30/2022 3:10 PM
Proj No - Acct:		Project ID:	Override
Project:		Project Name:	Notifications
Reason:			Problem <input type="checkbox"/>
Received By:			Overdue <input type="checkbox"/>
Inspected By:			Lead Worker <input type="checkbox"/>
			Task <input type="checkbox"/>
			Supervisor <input type="checkbox"/>
			Hard Lock WO <input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer

Comments for Crew
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
Address	X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339		Doan Brook
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH

Work Order Detail Report

12/1/2022

SSO INSPECTION 11-27-2022 0.46 INCHES OF RAIN

10:13 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

12/1/2022

SSO INSPECTION 11-27-2022 0.46 INCHES OF RAIN

10:13 AM

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

Work Order Detail Report

12/1/2022

SSO INSPECTION 11-27-2022 0.46 INCHES OF RAIN

10:13 AM

Work Order Assets

Object Type	System ID 1	System ID 2	Description 1	Description 2	Asset ID	Completed
			Odometer	Hourmeter	Othermeter	PM Description
Sewer Control Valve						FAIRFAX AT NORTH PARK
SSO 431						26
Sewer Control Valve						NORTH PARK AND COVENTRY
SSO 114						16
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH
SSO 121						35
Sewer Structure						
SA16AAWB0						3094
Sewer Control Valve						FAIRMOUNT AT FAIRFAX
SSO 112						7
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)
SSO 99						6
Sewer Control Valve						3012 NORTH WOODLAND
SSO 432						14
Sewer Control Valve						55
DB-03						
Sewer Control Valve						56
DB-01						
Sewer Control Valve						57
DB-02						
Sewer Control Valve						FAIRMOUNT AT DARTMOOR
CH-04						5
Sewer Control Valve						FAIRMOUNT AT WELLINGTON
SSO 110						44
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)
SSO 87						33
Sewer Control Valve						FAIRMOUNT AT MARLBORO
SSO 116						4
Sewer Control Valve						FAIRMOUNT AT ARLINGTON
SSO 111						46
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)
SSO 113						37
Sewer Control Valve						FAIRMOUNT AND COVENTRY
SSO 124						47
Sewer Control Valve						SCARBOROUGH AT LAMBERTON
CH-50						53
Sewer Control Valve						BRADFORD AND LEE
SSO 129						11
Sewer Control Valve						EDDINGTON
CH-52						2
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")
SSO 88						42
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL
SSO 122						36
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")
SSO 89						34
Sewer Structure						
SA16ADZB0						1536
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.
SSO 91						20
Sewer Structure						
SA16ADPH0						4446
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON
SSO 120						8
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY
SSO 91						

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 221130-0003

Work Order Detail Report

12/1/2022

SSO INSPECTION 11-27-2022 0.46 INCHES OF RAIN

10:13 AM

SSO 103	19
Sewer Control Valve	
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	
CH-30	South Taylor between Antisdale Ave and Superior F 52
Sewer Control Valve	
DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve	
SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve	
SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve	
SSO 95	1685 CUMBERLAND 18
Sewer Control Valve	
SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	
SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve	
SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve	
CH-51	LANGTON AND AHERSTONE 54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

12/1/2022

SSO INSPECTION 11-27-2022 0.46 INCHES OF RAIN

10:13 AM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0 Angelo & David	<input type="checkbox"/>	Sound	11/30/2022/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNBO (IN MEDIAN-CEMENT) Angelo & David	<input type="checkbox"/>	Sound	11/30/2022/	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0 Angelo & David	<input type="checkbox"/>	Sound	11/30/2022/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK) Angelo & David	<input type="checkbox"/>	Sound	11/30/2022/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK) Angelo & David	<input type="checkbox"/>	Sound	11/30/2022/	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN) Angelo & David	<input type="checkbox"/>	Sound	11/30/2022/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD) Angelo & David	<input type="checkbox"/>	Not Sound	11/30/2022/	
8	A-6 FAIRMOUNT AT SHELBYNE ST16BZJK0 (WEST BOUND LANE) Angelo & David	<input type="checkbox"/>	Not Sound	11/30/2022/	
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK) Angelo & David	<input type="checkbox"/>	Sound	11/30/2022/	
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND) Angelo & David	<input type="checkbox"/>	Sound	11/30/2022/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN) Angelo & David	<input type="checkbox"/>	Sound	11/30/2022/	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION) Angelo & David	<input type="checkbox"/>	Sound	11/30/2022/	
13	A-1 3041 FAIRMOUNT SA16AAUTO (TREE LAWN NEAR SIDEWALK) Angelo & David	<input type="checkbox"/>	Sound	11/30/2022/	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION) Angelo & David	<input type="checkbox"/>	Sound	11/30/2022/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION) Angelo & David	<input type="checkbox"/>	Sound	11/30/2022/	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN) Angelo & David	<input type="checkbox"/>	Sound	11/30/2022/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION) Angelo & David	<input type="checkbox"/>	Not Sound	11/30/2022/	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION) Angelo & David	<input type="checkbox"/>	Sound	11/30/2022/	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 221130-0003

Work Order Detail Report

12/1/2022

SSO INSPECTION 11-27-2022 0.46 INCHES OF RAIN

10:13 AM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	11/30/2022/
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	11/30/2022/
Angelo & David				
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	11/30/2022/
Angelo & David				
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	11/30/2022/
Angelo & David	Block missing			
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	11/30/2022/
Will Owens				
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	11/30/2022/
Will Owens				
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	11/30/2022/
Will Owens				
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	11/30/2022/
Will Owens				
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	11/30/2022/
Will Owens				
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	11/30/2022/
Will Owens				
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	11/30/2022/
Will Owens				
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	11/30/2022/
Will Owens				
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	11/30/2022/
Will Owens				
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	11/30/2022/
Will Owens				
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	11/30/2022/
Will Owens				
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	11/30/2022/
David & Angelo.				
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	11/30/2022/
David & Angelo				
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	11/30/2022/
David & Angelo				
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	11/30/2022/
David & Angelo				
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	11/30/2022/
David & Angelo. / metered				
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	11/30/2022/
David & Angelo				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 221130-0003

Work Order Detail Report

12/1/2022

SSO INSPECTION 11-27-2022 0.46 INCHES OF RAIN

10:13 AM

40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	11/30/2022/
David & Angelo				
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	11/30/2022/
David & Angelo				
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	11/30/2022/
David & Angelo				
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	11/30/2022/
David & Angelo				
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Not Sound	11/30/2022/
David & Angelo / Block missing, water flowing				
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	11/30/2022/
David & Angelo				

Tasks/Resources

SWCT26 Inspection

Crew:

Status:

*Cal'c UC: \$19.56

*Task Cost: \$880.32

Start Dt: 11/30/2022

Supervisor:

UOM: Each

of Units: 45.00

*Unit Cost: \$0.00

End Dt: 11/30/2022

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
11213 Owens, Will	Hours	8.00	\$207.04		11/30/2022	11/30/2022
12459 Eathridge, David	Hours	8.00	\$207.04		11/30/2022	11/30/2022
19356 Manco, Angelo	Hours	8.00	\$217.84		11/30/2022	11/30/2022

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB	Hours	8.00	\$107.20		11/30/2022	11/30/2022
5						
CHFLT55 FORD 350 CREW CAB	Hours	8.00	\$141.20		11/30/2022	11/30/2022
9						

Task Comment: SSO INSPECTION 0.46" OF RAIN

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	8.00	0.00	0.00
Subcontractor:		Labor Costs	24.00	0.00	0.00
Profit Center:		Material Costs	\$631.92	\$0.00	\$0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	248.40	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$880.32	\$0.00	\$0.00
		Use Task Info:	True	True	

Work Order Detail Report

12/1/2022

SSO INSPECTION 11-27-2022 0.46 INCHES OF RAIN

10:13 AM

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:	Cell #:	
City:		Fax #:		
State:		E-mail:		
Zip:				
Billing Data		*Billing Amount:		Billing Required: <input type="checkbox"/>
Contact Name:		Date Bill Sent:	Billing Processed: <input type="checkbox"/>	
Invoice Number:		Payment Received:	Imported to Financials: <input type="checkbox"/>	
Incoming Account #:		Payment Method:		
Associated PMs		Closed <input checked="" type="checkbox"/>		
PM Code and Description				
SSO-02 SSO INSPECTION				
Tracking	Description	By	Date	Time
Item				
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	11/30/2022	7:57 AM
Supervisor Notification	Email Queued Successfully!	jjackson	11/30/2022	7:57 AM
Leadworker Notification	Email Queued Successfully!	jjackson	11/30/2022	7:57 AM
Status Change	From New Work Order to Complete	aferrone	12/1/2022	10:12 AM
Rate:	Opened At:		Televised: <input type="checkbox"/>	
Received By:	Pipe Footage Cleaned		Power Rooter: <input type="checkbox"/>	
Work From:	Gallons Used:		Jet: <input type="checkbox"/>	
Pipe Size:	WO User 23:		Gap Vac: <input type="checkbox"/>	
Pipe Condition:	WO User 24:		Dye Test: <input type="checkbox"/>	
Could Not Open:	WO User 9:		Gap Root Cut: <input type="checkbox"/>	
Additional Repair:	User 10:		GIS Correction?: <input type="checkbox"/>	
Dye Test Reason:	Appointment Date DNL		Test Tee Correction: <input type="checkbox"/>	
Test Performed Through:	Appointment Date: 11/30/2022 8:00 AM			
Dye Test Results:				
WO User 51:	E Mail:			
Measurement:	Measurement Line 2:			
History:	Pipe Size:			
Manhole Basin Repair:	PVC Tees, Angles, Slic			
Material Used:	WO User 44:			
Pipe Repair:	WO User 45:			
Street Repair:	WO User 46:			
Grass Repair:	OUPS #:			
Curb Repair:	WO User 48:			
Driveway- Sidewalk Re				
Construction Crew:				
WO User 39:				
WO User 40:				
WO User 41:				

Work Order Detail Report

12/1/2022

SSO INSPECTION 11-27-2022 0.46 INCHES OF RAIN

10:13 AM

WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	
WO User 72:	WO User 82:	Televised: <input type="checkbox"/>
WO User 73:	Quantity:	Paid: <input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104: <input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105: <input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106: <input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:	
WO User 93 Date:	WO User 98 Date:	
WO User 94 Date:	WO User 99 Date:	
WO User 95 Date:	WO User 100 Date:	
WO User 96 Date:	WO User 101 Date:	
WO User 77:	WO User 87:	WO User 107: <input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108: <input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109: <input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110: <input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111: <input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 11/30/2022	PM Trigger: Rec #: 13245