



Law Department

May 15, 2023

Via E-Mail: vezner.kris@epa.gov and Berger.Jake@epa.gov

Kris P. Vezner, Esq.
Associate Regional Counsel
U.S. Environmental Protection Agency
Region 5 (C-14J)
77 West Jackson Blvd.
Chicago, IL 60604

and

Jake Berger
Physical Scientist
Water Enforcement & Compliance Assurance Branch
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Mail Code ECW-15J
Chicago, IL 60604

Re: April 2023 Overflow Monitoring Reports
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through April 30, 2023, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,


A handwritten signature in blue ink that reads "William R. Hanna".
William R. Hanna
Director of Law

Enclosures

cc: Thomas Benson, Esq., EPA Attorney
James Vinch, Esq., EPA Attorney
James Zimny, EPA Engineer
U.S. EPA Region 5 Water Enforcement Branch
Mark Klingenstein, Environmental Engineer
Erm Gomes, Ohio EPA
Allison Cycyk, Ohio EPA
Casey Galligan, Ohio EPA
David Brumbaugh, Ohio EPA
Bill Fischbein, Ohio EPA
Kahlil Seren, Mayor
Collette Clinkscale, Director of Public Works
Steve Barker, Public Relations
Anthony Ferrone, Utilities Commissioner
Kevin Vander Tuig, P.E. (Outside Engineer)
Mathew St. Pierre, (Outside Engineer)
Dan Porter (Outside Engineer)
Cindy Biacofsky (Outside Engineer)
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

Northeast Ohio Regional Sewer District

Daily Precipitation Report
Wednesday, April 5, 2023
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report
Wednesday, April 5, 2023

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.86	0.86	0.77	0.44	0.16
Brecksville	0.68	0.66	0.57	0.43	0.17
Brook Park	0.47	0.45	0.33	0.15	0.09
Cleveland Industrial Pkwy	0.36	0.35	0.24	0.12	0.06
Dille Ave PS	0.35	0.35	0.27	0.14	0.07
Division Ave PS	0.36	0.35	0.22	0.12	0.07
Easterly WWTP	0.35	0.35	0.26	0.15	0.09
Independence	0.90	0.88	0.79	0.50	0.19
James Rhodes HS	0.59	0.58	0.50	0.28	0.24
Jennings PS	0.57	0.56	0.48	0.27	0.22
Macedonia	0.74	0.73	0.63	0.48	0.23
Maple Heights	0.77	0.75	0.68	0.42	0.16
Mary Street PS	0.35	0.34	0.25	0.14	0.06
Mayfield Heights	0.86	0.85	0.78	0.45	0.21
Moreland Hills	0.91	0.89	0.80	0.57	0.22
North Olmsted	0.46	0.45	0.32	0.15	0.10
North Royalton	0.80	0.78	0.67	0.43	0.15
Oakwood	0.73	0.72	0.65	0.55	0.29
Olmsted Falls	0.38	0.36	0.27	0.14	0.07
Parma	0.62	0.60	0.50	0.20	0.14
Richfield	0.73	0.72	0.59	0.38	0.19
Shaker Heights	0.68	0.67	0.58	0.30	0.13
South Euclid	0.42	0.41	0.33	0.19	0.09
Southerly WWTC	0.51	0.51	0.44	0.20	0.13
Strongsville C WWTP	0.70	0.67	0.56	0.26	0.21
Strongsville Foltz	0.67	0.64	0.53	0.22	0.15
University Heights	0.70	0.69	0.60	0.37	0.26
Wade Park	0.35	0.35	0.26	0.16	0.07
Westerly WWTP	0.30	0.29	0.19	0.10	0.06
Westlake	0.53	0.53	0.37	0.16	0.06

Work Order Detail Report

4/10/2023

SSO INSPECTIONS 4-5-2023 0.70 INCHES OF RAIN

9:43 AM

WO Number: 230406-0001	Category:	SSOs
Status: Complete	Problem:	Storm Response
Status Date: 4/10/2023 9:42 am	Main Task:	Inspection

Asset: SSO 431

Location: FAIRFAX AT NORTH PARK

Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	4/5/2023 7:40 AM
Lead Worker:	Manco, Angelo	End Date:	4/5/2023 2:40 PM
Priority:	High	Override Notifications	<input type="checkbox"/> Problem <input type="checkbox"/> Overdue <input type="checkbox"/> Lead Worker <input type="checkbox"/> Task <input type="checkbox"/> Supervisor <input type="checkbox"/> Hard Lock WO
Account #:		Project ID:	
Proj No - Acct:		Project Name:	
Project:			
Reason:			
Received By:			
Inspected By:			

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
Address	X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339		Doan Brook
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230406-0001

Work Order Detail Report

4/10/2023

SSO INSPECTIONS 4-5-2023 0.70 INCHES OF RAIN

9:43 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)
2,223,111.44143730 664,794.46048072 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO
2,221,638.88762389 665,726.15513962 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON
2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)
2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY
2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON
2,221,598.28993607 666,996.61322863
MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423 665,499.19660404 DOAN BROOK
BRADFORD AND LEE
2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH
EDDINGTON
2,221,299.08384156 674,932.84604380
HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL
2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")
2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD

HAMPSHIRE AT EUCLID HTS. BLVD.
2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON
2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY
2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD
2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd
2,227,113.30810548 671,276.67684697
LEE RD. & SUPERIOR AVE.
2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE
2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND
2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND
2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON
2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD

2225 NOBLE ROAD
2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF
2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE
2,228,126.76638040 684,188.23206055

2,220,777.89623564 666,181.72575080

2,218,501.67473823 671,997.54581206

2,216,759.55453481 670,474.59347738

Work Order Detail Report

4/10/2023

SSO INSPECTIONS 4-5-2023 0.70 INCHES OF RAIN

9:43 AM

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

Work Order Detail Report

4/10/2023

SSO INSPECTIONS 4-5-2023 0.70 INCHES OF RAIN

9:43 AM

Work Order Assets

Object Type	System ID 1	System ID 2	Description 1	Odometer	Hourmeter	Othermeter	Description 2	PM Description	Asset ID	Completed
Sewer Control Valve	SSO 431						FAIRFAX AT NORTH PARK		26	
Sewer Control Valve	SSO 114						NORTH PARK AND COVENTRY		16	
Sewer Control Valve	SSO 121						FAIRMOUNT SOUTH OF SCARBOROUGH		35	
Sewer Structure	SA16AAWB0							3094		
Sewer Control Valve	SSO 112						FAIRMOUNT AT FAIRFAX		7	
Sewer Control Valve	SSO 99						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		6	
Sewer Control Valve	SSO 432						3012 NORTH WOODLAND		14	
Sewer Control Valve	DB-03								55	
Sewer Control Valve	DB-01								56	
Sewer Control Valve	DB-02							57		
Sewer Control Valve	CH-04						FAIRMOUNT AT DARTMOOR		5	
Sewer Control Valve	SSO 110						FAIRMOUNT AT WELLINGTON		44	
Sewer Control Valve	SSO 87						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		33	
Sewer Control Valve	SSO 116						FAIRMOUNT AT MARLBORO		4	
Sewer Control Valve	SSO 111						FAIRMOUNT AT ARLINGTON		46	
Sewer Control Valve	SSO 113						FAIRMOUNT & COVENTRY (SCARBOROUGH)		37	
Sewer Control Valve	SSO 124						FAIRMOUNT AND COVENTRY		47	
Sewer Control Valve	CH-50						SCARBOROUGH AT LAMBERTON		53	
Sewer Control Valve	SSO 129						BRADFORD AND LEE		11	
Sewer Control Valve	CH-52						EDDINGTON		2	
Sewer Control Valve	SSO 88						HAMPSHIRE LANE AT MAYFIELD (18")		42	
Sewer Control Valve	SSO 122						EAST OVERLOOK AT EDGEHILL		36	
Sewer Control Valve	SSO 89						HAMPSHIRE LANE AT MAYFIELD (36")		34	
Sewer Structure	SA16ADZB0							1536		
Sewer Control Valve	SSO 91						HAMPSHIRE AT EUCLID HTS. BLVD.		20	
Sewer Structure	SA16ADPH0							4446		
Sewer Control Valve	SSO 120						CEDAR BTW. FAIRMOUNT/DEMINGTON		8	
Sewer Control Valve							2828 BERKSHIRE, EAST OF COVENTRY			

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230406-0001

Work Order Detail Report

4/10/2023

SSO INSPECTIONS 4-5-2023 0.70 INCHES OF RAIN

9:43 AM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	3402
SA16AGMG0	
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	4987
SA16AQD0	
Sewer Structure	3745
SA16AQCO	
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	1809
SA16APEF0	

Work Order Detail Report

4/10/2023

SSO INSPECTIONS 4-5-2023 0.70 INCHES OF RAIN

9:43 AM

Check List					
	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	4/6/2023/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	4/6/2023/	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	4/6/2023/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	4/6/2023/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	4/6/2023/	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	4/6/2023/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	4/6/2023/	
8	A-6 FAIRMOUNT AT SHELBOURNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	4/6/2023/	
9	A-5 FAIRMOUNT AT SHELBOURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	4/6/2023/	
10	A-7 FAIRMOUNT AT SHELBOURNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	4/6/2023/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	4/6/2023/	
Meter					
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/6/2023/	
Meter					
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	4/6/2023/	
Meter					
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	4/6/2023/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/6/2023/	
Meter					
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	4/6/2023/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/6/2023/	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	4/6/2023/	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	4/6/2023/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	4/6/2023/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	4/6/2023/	
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	4/6/2023/	
Meter					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	4/6/2023/	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	4/6/2023/	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230406-0001

Work Order Detail Report

4/10/2023

SSO INSPECTIONS 4-5-2023 0.70 INCHES OF RAIN

9:43 AM

25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	4/6/2023/
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	4/6/2023/
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Not Sound	4/6/2023/
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Not Sound	4/6/2023/
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	4/6/2023/
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	4/6/2023/
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Not Sound	4/6/2023/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	4/6/2023/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	4/6/2023/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	4/6/2023/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	4/6/2023/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Not Sound	4/6/2023/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	4/6/2023/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	4/6/2023/
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	4/6/2023/
40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	4/6/2023/
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	4/6/2023/
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	4/6/2023/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	4/6/2023/
Meter				
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	4/6/2023/
Replaced block				
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	4/6/2023/

Tasks/Resources						
SMCT36 Inspection						
Crew:	Status:		*Cal'c UC: \$22.70	*Task Cost: \$1,021.52	Start Dt:	4/5/2023
Supervisor:	UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:	4/5/2023
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
19356 Manco, Angelo	Hours	8.00	\$217.84		4/5/2023	4/5/2023
11213 Owens, Will	Hours	8.00	\$207.04		4/5/2023	4/5/2023
13859 Moten, Robert	Hours	8.00	\$197.52		4/5/2023	4/5/2023
40404 Don Johnson		8.00	\$150.72		4/5/2023	4/5/2023
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD 350 CAB AND 8 CHASSIS	Hours	8.00	\$141.20		4/5/2023	4/5/2023
CHFLT50 FORD F250 CREW CAB	Hours	8.00	\$107.20		4/5/2023	4/5/2023

5

Task Comment: SSO INSPECTIONS 0.70 INCHES OF RAIN

Work Order Detail Report

4/10/2023

SSO INSPECTIONS 4-5-2023 0.70 INCHES OF RAIN

9:43 AM

			*Actual	*Estimated	*Difference
Projected Complete:		Lock: <input type="checkbox"/>	WO Duration	7.00	0.00
Repair Type:			Labor Hours	32.00	0.00
Subcontractor:			Labor Costs	\$773.12	\$0.00
Profit Center:			Material Costs	0.00	0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Fluids Costs	0.00	0.00
Unit of Measure:	Each		Equipment Costs	248.40	0.00
*Unit Cost:	\$0.00		Contractor Costs	0.00	0.00
WO Hours:	0.00		Misc. Costs	0.00	0.00
			Total Costs	\$1,021.52	\$0.00
			Use Task Info:	True	True

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	
City:		Cell #:	
State:		Fax #:	
Zip:		E-mail:	
Billing Data			
Contact Name:		*Billing Amount:	<input type="checkbox"/>
Invoice Number:		Date Bill Sent:	<input type="checkbox"/>
Incoming Account #:		Payment Received:	<input type="checkbox"/>
		Payment Method:	<input type="checkbox"/>
Imported to Financials:		<input type="checkbox"/>	

Associated PMs		PM Code and Description	Closed
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>

Tracking					
Item	Description	By	Date	Time	
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	4/6/2023	7:25 AM	
Supervisor Notification	Email Queued Successfully!	jjackson	4/6/2023	7:25 AM	
Leadworker Notification	Email Queued Successfully!	jjackson	4/6/2023	7:26 AM	
Status Change	From New Work Order to Closed In Field	amanco	4/7/2023	1:54 PM	
Status Change	From Closed In Field to Complete	aferrone	4/10/2023	9:42 AM	

Rate:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:	Appointment Date: 4/6/2023	8:00 AM	
Dye Test Results:			
WO User 51:	E Mail:		
Measurement:	Measurement Line 2:		
History:			

Work Order Detail Report

4/10/2023

SSO INSPECTIONS 4-5-2023 0.70 INCHES OF RAIN

9:43 AM


Manhole Basin Repair:	Pipe Size:	
Material Used:	PVC Tees, Angles, Slat	
Pipe Repair:	WO User 44:	
Street Repair:	WO User 45:	
Grass Repair:	WO User 46:	
Curb Repair:		
Driveway- Sidewalk Re		
Construction Crew:		
WO User 39:	OUPS #:	
WO User 40:	WO User 48:	
WO User 41:		
WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	
WO User 72:	WO User 82:	Televised: <input type="checkbox"/>
WO User 73:	Quantity:	Paid: <input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104: <input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105: <input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106: <input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:	
WO User 93 Date:	WO User 98 Date:	
WO User 94 Date:	WO User 99 Date:	
WO User 95 Date:	WO User 100 Date:	
WO User 96 Date:	WO User 101 Date:	
WO User 77:	WO User 87:	WO User 107: <input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108: <input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109: <input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110: <input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111: <input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 4/6/2023	PM Trigger: Rec #: 13593

 **Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Sunday, April 16, 2023

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Sunday, April 16, 2023

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.55	0.55	0.53	0.33	0.11	0.06
Brecksville	0.39	0.39	0.39	0.26	0.09	0.04
Brook Park	0.38	0.37	0.37	0.27	0.12	0.06
Cleveland Industrial Pkwy	0.27	0.26	0.26	0.19	0.06	0.03
Dille Ave PS	0.23	0.23	0.23	0.16	0.08	0.03
Division Ave PS	0.30	0.30	0.30	0.20	0.08	0.04
Easterly WWTP	0.44	0.44	0.44	0.31	0.13	0.06
Independence	0.26	0.26	0.26	0.21	0.07	0.04
James Rhodes HS	0.27	0.27	0.27	0.19	0.08	0.04
Jennings PS	0.25	0.25	0.25	0.18	0.09	0.04
Macedonia	0.40	0.40	0.40	0.29	0.13	0.08
Maple Heights	0.52	0.52	0.52	0.29	0.12	0.06
Mary Street PS	0.27	0.27	0.27	0.19	0.10	0.05
Mayfield Heights	0.49	0.49	0.49	0.30	0.11	0.06
Moreland Hills	0.47	0.47	0.46	0.32	0.12	0.06
North Olmsted	0.88	0.88	0.86	0.43	0.26	0.21
North Royalton	0.22	0.22	0.22	0.15	0.07	0.04
Oakwood	0.46	0.46	0.46	0.32	0.15	0.07
Olmsted Falls	n/a	n/a	n/a	n/a	n/a	n/a
Parma	0.26	0.26	0.26	0.20	0.08	0.04
Richfield	0.33	0.33	0.32	0.22	0.08	0.04
Shaker Heights	0.53	0.53	0.53	0.29	0.12	0.09
South Euclid	0.54	0.54	0.53	0.29	0.14	0.07
Southerly WWTC	0.24	0.23	0.23	0.18	0.09	0.04
Strongsville C WWTP	0.37	0.37	0.36	0.28	0.14	0.09
Strongsville Foltz	0.30	0.30	0.30	0.27	0.13	0.06
University Heights	0.56	0.56	0.56	0.29	0.13	0.06
Wade Park	0.38	0.38	0.38	0.30	0.13	0.08
Westerly WWTP	0.20	0.20	0.20	0.13	0.05	0.02
Westlake	0.75	0.75	0.74	0.36	0.23	0.12

Work Order Detail Report

4/20/2023

SSO INSPECTION 4-16-2023 0.56 INCHES OF RAIN

1:58 PM

WO Number:	230420-0001	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	4/20/2023 1:51 pm	Main Task:	Inspection
Asset: SSO 431			
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather	Assigned By:	15854 Ferrone, Anthony
Assigned Crew:		Assigned Date:	4/16/2023
Supervisor:	Jackson, Jeff	Start Date:	4/18/2023 8:00 AM
Lead Worker:	Manco, Angelo	End Date:	4/18/2023
Priority:	High		
Account #:		Project ID:	<input type="checkbox"/> Problem
Proj No - Acct:		Project Name:	<input type="checkbox"/> Overdue
Project:			<input type="checkbox"/> Lead Worker
Reason:			<input type="checkbox"/> Task
Received By:			<input type="checkbox"/> Supervisor
Inspected By:			<input type="checkbox"/> Hard Lock WO

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
Address	X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK	2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY	2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH	2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX	2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND	2,222,845.06631389	664,689.08536339	Doan Brook
	2,226,440.21168265	664,329.55524255	
	2,226,354.79813956	664,409.89202413	
	2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR	2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON	2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

4/20/2023

SSO INSPECTION 4-16-2023 0.56 INCHES OF RAIN

1:58 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

4/20/2023

SSO INSPECTION 4-16-2023 0.56 INCHES OF RAIN

1:58 PM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

4/20/2023

SSO INSPECTION 4-16-2023 0.56 INCHES OF RAIN

1:58 PM

Work Order Assets								
Object Type	System ID 1	System ID 2	Description 1	Hourmeter	Othermeter	PM Description	Asset ID	Completed
			Odometer					
Sewer Control Valve						FAIRFAX AT NORTH PARK		
SSO 431							26	
Sewer Control Valve						NORTH PARK AND COVENTRY		
SSO 114							16	
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121							35	
Sewer Structure								
SA16AAWB0							3094	
Sewer Control Valve						FAIRMOUNT AT FAIRFAX		
SSO 112							7	
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99							6	
Sewer Control Valve						3012 NORTH WOODLAND		
SSO 432							14	
Sewer Control Valve								
DB-03							55	
Sewer Control Valve								
DB-01							56	
Sewer Control Valve								
DB-02							57	
Sewer Control Valve						FAIRMOUNT AT DARTMOOR		
CH-04							5	
Sewer Control Valve						FAIRMOUNT AT WELLINGTON		
SSO 110							44	
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87							33	
Sewer Control Valve						FAIRMOUNT AT MARLBORO		
SSO 116							4	
Sewer Control Valve						FAIRMOUNT AT ARLINGTON		
SSO 111							46	
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113							37	
Sewer Control Valve						FAIRMOUNT AND COVENTRY		
SSO 124							47	
Sewer Control Valve						SCARBOROUGH AT LAMBERTON		
CH-50							53	
Sewer Control Valve						BRADFORD AND LEE		
SSO 129							11	
Sewer Control Valve						EDDINGTON		
CH-52							2	
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88							42	
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL		
SSO 122							36	
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89							34	
Sewer Structure								
SA16ADZB0							1536	
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91							20	
Sewer Structure								
SA16ADPH0							4446	
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120							8	
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230420-0001

Work Order Detail Report

4/20/2023

SSO INSPECTION 4-16-2023 0.56 INCHES OF RAIN

1:58 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEFO	1809

Work Order Detail Report

4/20/2023

SSO INSPECTION 4-16-2023 0.56 INCHES OF RAIN

1:58 PM

Check List					
	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	/	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	/	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	/	
8	A-6 FAIRMOUNT AT SHELBOURNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	/	
9	A-5 FAIRMOUNT AT SHELBOURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	/	
10	A-7 FAIRMOUNT AT SHELBOURNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	/	
METER					
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	/	
METER					
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	/	
METER					
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	/	
METER					
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	/	
METER					
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	/	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	/	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	/	
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Sound	/	
METER					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	/	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	/	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230420-0001

Work Order Detail Report

4/20/2023

SSO INSPECTION 4-16-2023 0.56 INCHES OF RAIN

1:58 PM

METER

25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	/
----	--	--------------------------	-------	---

METER

26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	/
----	-------------------------------	--------------------------	-------	---

METER

27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	/
----	---	--------------------------	-------	---

28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	/
----	--	--------------------------	-------	---

METER

29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	/
----	----------------------------	--------------------------	-------	---

30	B-15 COVENTRY AND CEDAR SA16ADB0	<input type="checkbox"/>	Sound	/
----	-------------------------------------	--------------------------	-------	---

31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	/
----	-------------------------------	--------------------------	-------	---

32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	/
----	--	--------------------------	-------	---

33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	/
----	---------------------------------------	--------------------------	-------	---

34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	/
----	--	--------------------------	-----------	---

35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	/
----	------------------------------------	--------------------------	-------	---

36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	/
----	---	--------------------------	-------	---

37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	/
----	--	--------------------------	-------	---

38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	/
----	---	--------------------------	-------	---

39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	/
----	---------------------------------------	--------------------------	-------	---

40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Not Sound	/
----	-------------------------------	--------------------------	-----------	---

41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	/
----	-------------------------------	--------------------------	-------	---

42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	/
----	------------------------------	--------------------------	-------	---

43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	/
----	---	--------------------------	-------	---

44	C-51 AATHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	/
----	---	--------------------------	-------	---

45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	/
----	----------------------------	--------------------------	-------	---

Work Order Detail Report

4/20/2023

SSO INSPECTION 4-16-2023 0.56 INCHES OF RAIN

1:58 PM

Tasks/Resources		Status: Complete		*Cal'd UC: \$14.96	*Task Cost: \$673.28	Start Dt: 4/18/2023
SWCT26 Inspection		UOM: Each		# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 4/18/2023
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
11213 Owens, Will	Hours	8.00	\$207.04		4/18/2023	4/18/2023
29960 Jackson, Jeff	Hours	4.00	\$0.00		4/18/2023	4/18/2023
19356 Manco, Angelo	Hours	8.00	\$217.84		4/18/2023	4/18/2023
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	8.00	\$107.20		4/18/2023	4/18/2023
CHFT-500 FORD F250 PICK UP TRUCK	Each	4.00	\$0.00		4/18/2023	4/18/2023
CHFLT55 FORD 350 CAB AND 8 CHASSIS	Hours	8.00	\$141.20		4/18/2023	4/18/2023

Task Comment: SSO INSPECTIONS 0.56" OF RAIN

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	0.00	0.00	0.00
Subcontractor:		Labor Costs	\$424.88	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	248.40	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$673.28	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	<input type="checkbox"/>
Invoice Number:		Date Bill Sent:	<input type="checkbox"/>
Incoming Account #:		Payment Received:	<input type="checkbox"/>
		Payment Method:	<input type="checkbox"/>
			Billing Required: <input type="checkbox"/>
			Billing Processed: <input type="checkbox"/>
			Imported to Financials: <input type="checkbox"/>

Associated PMs		PM Code and Description	Closed
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>
Tracking			
Item	Description	By	Date
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	aferrone	4/20/2023
Supervisor Notification	Email Queued Successfully!	aferrone	4/20/2023
Leadworker Notification	Email Queued Successfully!	aferrone	4/20/2023
Status Change	From New Work Order to Complete	aferrone	4/20/2023
			Time 1:40 PM
			4/20/2023
			1:41 PM
			4/20/2023
			1:51 PM

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230420-0001

Work Order Detail Report

4/20/2023


SSO INSPECTION 4-16-2023 0.56 INCHES OF RAIN

1:58 PM

Rate:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:	Appointment Date:		
Dye Test Results:			
WO User 51:			
Measurement:	E Mail:		
History:	Measurement Line 2:		
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sled		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: aferrone	WO Creation Date: 4/20/2023	PM Trigger:	Rec #: 13630

**Northeast Ohio
Regional Sewer District**

**Daily Precipitation Report
Saturday, April 22, 2023**
Accumulation in inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Saturday, April 22, 2023

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.97	0.69	0.49	0.22	0.12
Brecksville	1.02	0.76	0.57	0.28	0.10
Brook Park	0.67	0.51	0.33	0.17	0.06
Cleveland Industrial Pkwy	0.71	0.51	0.33	0.16	0.05
Dille Ave PS	0.79	0.62	0.44	0.20	0.06
Division Ave PS	0.77	0.57	0.37	0.17	0.05
Easterly WWTP	0.90	0.70	0.46	0.23	0.08
Independence	0.89	0.67	0.51	0.25	0.09
James Rhodes HS	0.77	0.59	0.40	0.19	0.06
Jennings PS	0.80	0.63	0.45	0.22	0.08
Macedonia	0.90	0.69	0.54	0.25	0.08
Maple Heights	0.92	0.66	0.49	0.24	0.09
Mary Street PS	0.85	0.65	0.45	0.22	0.07
Mayfield Heights	1.00	0.73	0.51	0.22	0.12
Moreland Hills	1.05	0.73	0.57	0.26	0.12
North Olmsted	0.71	0.49	0.33	0.13	0.09
North Royalton	0.84	0.63	0.46	0.24	0.09
Oakwood	1.02	0.72	0.56	0.26	0.12
Olmsted Falls	0.71	0.50	0.34	0.15	0.06
Parma	0.81	0.61	0.42	0.21	0.07
Richfield	0.95	0.75	0.60	0.28	0.09
Shaker Heights	0.93	0.66	0.46	0.22	0.12
South Euclid	0.96	0.70	0.48	0.22	0.11
Southerly WWTC	0.94	0.70	0.51	0.24	0.09
Strongsville C WWTP	0.77	0.59	0.39	0.21	0.07
Strongsville Foltz	0.68	0.51	0.33	0.17	0.05
University Heights	1.02	0.70	0.48	0.22	0.16
Wade Park	0.90	0.70	0.48	0.23	0.09
Westerly WWTP	0.63	0.49	0.32	0.15	0.05
Westlake	0.72	0.50	0.33	0.13	0.08

Work Order Detail Report

SSO INSPECTION 4-22-2023 1.02 INCHES OF RAIN

4/27/2023

12:18 PM

WO Number: 230426-0001	Category:	SSOs
Status: Complete	Problem:	Storm Response
Status Date: 4/27/2023 12:17 pm	Main Task:	Inspection

Asset: SSO 431	Location: FAIRFAX AT NORTH PARK	Cause: Weather	Assigned By:
Assigned Crew:	Supervisor: Jackson, Jeff	Assigned Date:	Start Date: 4/26/2023 7:15 AM
Lead Worker: Manco, Angelo	Priority: High	End Date: 4/26/2023 3:15 PM	Override Notifications
Account #:	Proj No - Acct:	Project ID:	Problem <input type="checkbox"/>
Project:	Reason:	Project Name:	Overdue <input type="checkbox"/>
Received By:	Inspected By:	Lead Worker <input type="checkbox"/>	Task <input type="checkbox"/>
		Supervisor <input type="checkbox"/>	Supervisor <input type="checkbox"/>
			Hard Lock WO <input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339		Doan Brook
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH

Work Order Detail Report

4/27/2023

SSO INSPECTION 4-22-2023 1.02 INCHES OF RAIN

12:18 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)
2,223,111.44143730 664,794.46048072 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO
2,221,638.88762389 665,726.15513962 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON
2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)
2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY
2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON
2,221,598.28993607 666,996.61322863 MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423 665,499.19660404 DOAN BROOK
BRADFORD AND LEE
2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH
EDDINGTON
2,221,299.08384156 674,932.84604380 HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481 672,922.02624655 EAST OVERLOOK AT EDGEHILL
2,218,479.60588473 671,538.70289771 HAMPSHIRE LANE AT MAYFIELD (36")
2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD

HAMPSHIRE AT EUCLID HTS. BLVD.
2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON
2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY
2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD
2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd
2,227,113.30810548 671,276.67684697 LEE RD. & SUPERIOR AVE.
2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE
2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND
2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND
2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON
2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD

2225 NOBLE ROAD
2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF
2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE
2,228,126.76638040 684,188.23206055

2,220,777.89623564 666,181.72575080

2,218,501.67473823 671,997.54581206

2,216,759.55453481 670,474.59347738

Work Order Detail Report

4/27/2023

SSO INSPECTION 4-22-2023 1.02 INCHES OF RAIN

12:18 PM

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

2,227,825.14395215 684,881.15948047

Work Order Detail Report

SSO INSPECTION 4-22-2023 1.02 INCHES OF RAIN

4/27/2023

12:18 PM

Work Order Assets		Work Order Assets						
Object Type	System ID 1	System ID 2	Description 1		Description 2		Asset ID	Completed
			Odometer	Hourmeter	Othermeter	PM Description		
Sewer Control Valve	SSO 431					FAIRFAX AT NORTH PARK	26	
Sewer Control Valve	SSO 114					NORTH PARK AND COVENTRY	16	
Sewer Control Valve	SSO 121					FAIRMOUNT SOUTH OF SCARBOROUGH	35	
Sewer Structure	SA16AAWB0						3094	
Sewer Control Valve	SSO 112					FAIRMOUNT AT FAIRFAX	7	
Sewer Control Valve	SSO 99					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	6	
Sewer Control Valve	SSO 432					3012 NORTH WOODLAND	14	
Sewer Control Valve	DB-03						55	
Sewer Control Valve	DB-01						56	
Sewer Control Valve	DB-02						57	
Sewer Control Valve	CH-04					FAIRMOUNT AT DARTMOOR	5	
Sewer Control Valve	SSO 110					FAIRMOUNT AT WELLINGTON	44	
Sewer Control Valve	SSO 87					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	33	
Sewer Control Valve	SSO 116					FAIRMOUNT AT MARLBORO	4	
Sewer Control Valve	SSO 111					FAIRMOUNT AT ARLINGTON	46	
Sewer Control Valve	SSO 113					FAIRMOUNT & COVENTRY (SCARBOROUGH)	37	
Sewer Control Valve	SSO 124					FAIRMOUNT AND COVENTRY	47	
Sewer Control Valve	CH-50					SCARBOROUGH AT LAMBERTON	53	
Sewer Control Valve	SSO 129					BRADFORD AND LEE	11	
Sewer Control Valve	CH-52					EDDINGTON	2	
Sewer Control Valve	SSO 88					HAMPSHIRE LANE AT MAYFIELD (18")	42	
Sewer Control Valve	SSO 122					EAST OVERLOOK AT EDGEHILL	36	
Sewer Control Valve	SSO 89					HAMPSHIRE LANE AT MAYFIELD (36")	34	
Sewer Structure	SA16ADZB0						1536	
Sewer Control Valve	SSO 91					HAMPSHIRE AT EUCLID HTS. BLVD.	20	
Sewer Structure	SA16ADPH0						4446	
Sewer Control Valve	SSO 120					CEDAR BTW. FAIRMOUNT/DEMINGTON	8	
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230426-0001

Work Order Detail Report

4/27/2023

SSO INSPECTION 4-22-2023 1.02 INCHES OF RAIN

12:18 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

4/27/2023

SSO INSPECTION 4-22-2023 1.02 INCHES OF RAIN

12:18 PM

Check List					
	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	4/26/2023/	
Reset					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	4/26/2023/	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	4/26/2023/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	4/26/2023/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	4/26/2023/	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	4/26/2023/	
Replaced rope					
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	4/26/2023/	
8	A-6 FAIRMOUNT AT SHELBOURNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	4/26/2023/	
9	A-5 FAIRMOUNT AT SHELBOURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	4/26/2023/	
10	A-7 FAIRMOUNT AT SHELBOURNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	4/26/2023/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	/	
Metered					
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/26/2023/	
Metered					
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	4/26/2023/	
Metered					
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/26/2023/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/26/2023/	
Metered					
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	4/26/2023/	
17	A-35 2393 COVENTRY SA16AAASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/26/2023/	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	4/26/2023/	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	4/26/2023/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	4/26/2023/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	4/26/2023/	
22	A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	<input type="checkbox"/>	Not Sound	4/26/2023/	
Metered					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	4/26/2023/	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 230426-0001

Work Order Detail Report

4/27/2023

SSO INSPECTION 4-22-2023 1.02 INCHES OF RAIN

12:18 PM

24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	4/26/2023/
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16EEA0	<input type="checkbox"/>	Sound	4/26/2023/
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	4/26/2023/
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	4/26/2023/
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	4/26/2023/
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	4/26/2023/
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	4/26/2023/
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Not Sound	4/26/2023/
Reset block				
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	4/26/2023/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	4/26/2023/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	4/26/2023/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	4/26/2023/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	4/26/2023/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Not Sound	4/26/2023/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	4/26/2023/
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	4/26/2023/
40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Sound	4/26/2023/
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	4/26/2023/
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	4/26/2023/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	4/26/2023/
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	4/26/2023/
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	4/26/2023/

Tasks/Resources

SWCT26 Inspection

Crew:

Status:

*Cal'c UC: \$16.97

*Task Cost: \$763.60

Start Dt: 4/26/2023

Supervisor:

UOM: Each

of Units: 45.00

*Unit Cost: \$0.00

End Dt: 4/26/2023

Employee

Resource

UOM

Units

*Total Cost

Alt Description

Start Dt

End Dt

19356 Manco, Angelo

Hours

8.00

\$217.84

4/26/2023

4/26/2023

11213 Owens, Will

Hours

8.00

\$207.04

4/26/2023

4/26/2023

13859 Moten, Robert

Hours

8.00

\$197.52

4/26/2023

4/26/2023

Equipment

Resource

UOM

Units

*Total Cost

Alt Description

Start Dt

End Dt

CHFLT55 FORD 350 CAB AND
8 CHASSIS

Hours

8.00

\$141.20

4/26/2023

4/26/2023

Task Comment: SSO INSPECTIONS 1.02 INCHES OF RAIN

Work Order Detail Report

4/27/2023

SSO INSPECTION 4-22-2023 1.02 INCHES OF RAIN

12:18 PM

			*Actual	*Estimated	*Difference
Projected Complete:		Lock: <input type="checkbox"/>	WO Duration	8.00	0.00
Repair Type:			Labor Hours	24.00	0.00
Subcontractor:			Labor Costs	\$622.40	\$0.00
Profit Center:			Material Costs	0.00	0.00
			Fluids Costs	0.00	0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Equipment Costs	141.20	0.00
Unit of Measure:	Each		Contractor Costs	0.00	0.00
*Unit Cost:	\$0.00		Misc. Costs	0.00	0.00
WO Hours:	0.00		Total Costs	\$763.60	\$0.00
			Use Task Info:	True	True

Billed Party		Billing
Customer ID:	Customer Number:	
Customer Name:	Last Name:	
Address:	Phone:	
City:	Cell #:	
State:	Fax #:	
Zip:	E-mail:	
Billing Data		
Contact Name:	*Billing Amount:	Billing Required: <input type="checkbox"/>
Invoice Number:	Date Bill Sent:	Billing Processed: <input type="checkbox"/>
Incoming Account #:	Payment Received:	Imported to Financials: <input type="checkbox"/>
Payment Method:		

Associated PMs		PM Code and Description	Closed
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>

Tracking			Date	Time
Item	Description	By		
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	4/26/2023	10:45 AM
Supervisor Notification	Email Queued Successfully!	jjackson	4/26/2023	10:45 AM
Leadworker Notification	Email Queued Successfully!	jjackson	4/26/2023	10:45 AM
Status Change	From New Work Order to Closed In Field	amanco	4/26/2023	2:25 PM
Status Change	From Closed In Field to Complete	aferrone	4/27/2023	12:17 PM

Rate:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned:	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction? <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>
Test Performed Through:	Appointment Date: 4/26/2023	8:00 AM
Dye Test Results:		
WO User 51:	E Mail:	
Measurement:	Measurement Line 2:	
History:		

Work Order Detail Report

4/27/2023

SSO INSPECTION 4-22-2023 1.02 INCHES OF RAIN

12:18 PM

Manhole Basin Repair:

Material Used:

Pipe Repair:

Street Repair:

Grass Repair:

Curb Repair:

Driveway- Sidewalk Re

Construction Crew:

WO User 39:

WO User 40:

WO User 41:

WO User 52:

WO User 53:

WO User 54:

WO User 55:

WO User 56:

WO User 57:

WO User 58:

WO User 59:

WO User 60:

WO User 61:

WO User 72:

WO User 73:

WO User 74:

WO User 75:

WO User 76:

WO User 92 Date:

WO User 93 Date:

WO User 94 Date:

WO User 95 Date:

WO User 96 Date:

WO User 77:

WO User 78:

WO User 79:

WO User 80:

WO User 81:

WO Creator: jjackson

Pipe Size:

PVC Tees, Angles, Slic

WO User 44:

WO User 45:

WO User 46:

OUPS #:

WO User 48:

WO User 62:

WO User 63:

WO User 64:

WO User 65:

WO User 66:

WO User 67:

WO User 68:

WO User 69:

WO User 70:

WO User 71:

WO User 82:

Televised:

Quantity:

Paid:

WO User 84:

WO User 104:

WO User 85:

WO User 105:

WO User 86:

WO User 106:

WO User 97 Date:

WO User 98 Date:

WO User 99 Date:

WO User 100 Date:

WO User 101 Date:

WO User 87:

WO User 107:

WO User 88:

WO User 108:

WO User 89:

WO User 109:

WO User 90:

WO User 110:

WO User 91:

WO User 111:

WO Creation Date: 4/26/2023 PM Trigger:

Rec #: 13642