

CITY OF
CLEVELAND
HEIGHTS 
LAW DEPARTMENT

August 14, 2023

Via E-Mail: vezner.kris@epa.gov and Berger.Jake@epa.gov

Kris P. Vezner, Esq.
Associate Regional Counsel
U.S. Environmental Protection Agency
Region 5 (C-14J)
77 West Jackson Blvd.
Chicago, IL 60604

and

Jake Berger
Physical Scientist
Water Enforcement & Compliance Assurance Branch
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Mail Code ECW-15J
Chicago, IL 60604

Re: July 2023 Overflow Monitoring Reports
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through July 31, 2023, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,


William R. Hanna
Director of Law

Enclosures

cc: Thomas Benson, Esq., EPA Attorney
James Vinch, Esq., EPA Attorney
James Zimny, EPA Engineer
U.S. EPA Region 5 Water Enforcement Branch
Mark Klingenstein, Environmental Engineer
Erm Gomes, Ohio EPA
Allison Cycyk, Ohio EPA
Casey Galligan, Ohio EPA
David Brumbaugh, Ohio EPA
Bill Fischbein, Ohio EPA
Kahlil Seren, Mayor
Collette Clinkscale, Director of Public Works
Steve Barker, Public Relations
Anthony Ferrone, Utilities Commissioner
Kevin Vander Tuig, P.E. (Outside Engineer)
Mathew St. Pierre, (Outside Engineer)
Dan Porter (Outside Engineer)
Cindy Biacofsky (Outside Engineer)
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

Work Order Detail Report

7/5/2023

sso overflow inspections 7-2-2023 0.93'

3:28 PM

WO Number:	230705-0001	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	7/5/2023 3:26 pm	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	7/5/2023 8:00 AM
Lead Worker:	Cardarella, Joe	End Date:	7/5/2023 2:30 PM
Priority:	High	Override Notifications	<input type="checkbox"/>
Account #:		Problem	<input type="checkbox"/>
Proj No - Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:
Area:
Sub-Area:
Owner:
Location:
Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
Address	X Coord	Y Coord	General Location
	FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339		Doan Brook
	2,226,440.21168265	664,329.55524255	
	2,226,354.79813956	664,409.89202413	
	2,226,389.92077273	664,379.07548472	
	FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
2,223,111.44143730	664,794.46048072		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO			
2,221,638.88762389	665,726.15513962		DOAN BROOK - MAIN BRANCH

Work Order Detail Report

7/5/2023

3:28 PM

sso overflow inspections 7-2-2023 0.93'

FAIRMOUNT AT ARLINGTON

2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH

FAIRMOUNT & COVENTRY (SCARBOROUGH)

2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH

FAIRMOUNT AND COVENTRY

2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH

SCARBOROUGH AT LAMBERTON

2,221,598.28993607 666,996.61322863

MONMOUTH, EAST OF DARTMOOR

2,225,152.08663423 665,499.19660404 DOAN BROOK

BRADFORD AND LEE

2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH

EDDINGTON

2,221,299.08384156 674,932.84604380

HAMPSHIRE LANE AT MAYFIELD (18")

2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH

EAST OVERLOOK AT EDGEHILL

2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH

HAMPSHIRE LANE AT MAYFIELD (36")

2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH

2600 HAMPSHIRE RD

HAMPSHIRE AT EUCLID HTS. BLVD.

2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH

CEDAR BTW. FAIRMOUNT/DEMINGTON

2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH

2828 BERKSHIRE, EAST OF COVENTRY

2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH

3003 EUCLID HEIGHTS BLVD

2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH

South Taylor between Antisdale Ave and Superior Rd

2,227,113.30810548 671,276.67684697

LEE RD. & SUPERIOR AVE.

2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA

EUCLID HEIGHTS BLVD AND LEE

2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH

EUCLID HEIGHTS BLVD/CUMBERLAND

2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH

1685 CUMBERLAND

2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH

CUMBERLAND/SOMERTON

2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH

2225 NOBLE RD

2225 NOBLE ROAD

2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH

QUILLIAMS, N. OF RANDOLF

2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH

LANGTON AND AATHERSTONE

2,228,126.76638040 684,188.23206055

2,220,777.89623564 666,181.72575080

2,218,501.67473823 671,997.54581206

2,216,759.55453481 670,474.59347738

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

Work Order Detail Report

sso overflow inspections 7-2-2023 0.93'

7/5/2023

3:28 PM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

7/5/2023

sso overflow inspections 7-2-2023 0.93'

3:28 PM

Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Description 2</u>	<u>Asset ID</u>	<u>Completed</u>
			<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>
Sewer Control Valve					FAIRFAX AT NORTH PARK	
SSO 431					26	
Sewer Control Valve					NORTH PARK AND COVENTRY	
SSO 114					16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH	
SSO 121					35	
Sewer Structure					3094	
SA16AAWB0						
Sewer Control Valve					FAIRMOUNT AT FAIRFAX	
SSO 112					7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	
SSO 99					6	
Sewer Control Valve					3012 NORTH WOODLAND	
SSO 432					14	
Sewer Control Valve					55	
DB-03						
Sewer Control Valve					56	
DB-01						
Sewer Control Valve					57	
DB-02						
Sewer Control Valve					FAIRMOUNT AT DARTMOOR	
CH-04					5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON	
SSO 110					44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	
SSO 87					33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO	
SSO 116					4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON	
SSO 111					46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)	
SSO 113					37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY	
SSO 124					47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON	
CH-50					53	
Sewer Control Valve					BRADFORD AND LEE	
SSO 129					11	
Sewer Control Valve					EDDINGTON	
CH-52					2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")	
SSO 88					42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL	
SSO 122					36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")	
SSO 89					34	
Sewer Structure					1536	
SA16ADZB0						
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.	
SSO 91					20	
Sewer Structure					4446	
SA16ADPH0						
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON	
SSO 120					8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY	
SSO 103					19	
Sewer Control Valve					3003 EUCLID HEIGHTS BLVD	
SSO 104					15	

Work Order Detail Report

7/5/2023

sso overflow inspections 7-2-2023 0.93'

3:28 PM

Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior F 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQQD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

Work Order Detail Report

7/5/2023

sso overflow inspections 7-2-2023 0.93'

3:28 PM

Check List					
	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	7/5/2023/ 2:29 pm	7/5/2023
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	7/5/2023/ 2:29 pm	7/5/2023
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	7/5/2023/ 2:29 pm	7/5/2023
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	7/5/2023/ 2:30 pm	7/5/2023
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	7/5/2023/ 2:30 pm	7/5/2023
Reset					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	7/5/2023/ 2:31 pm	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	7/5/2023/ 2:31 pm	7/5/2023
8	A-6 FAIRMOUNT AT SHELBOURNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Not Sound	7/5/2023/ 2:31 pm	7/5/2023
Reset					
9	A-5 FAIRMOUNT AT SHELBOURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	7/5/2023/ 2:32 pm	7/5/2023
10	A-7 FAIRMOUNT AT SHELBOURNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	7/5/2023/ 2:32 pm	7/5/2023
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	7/5/2023/ 2:33 pm	7/5/2023
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/5/2023/ 2:34 pm	7/5/2023
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	7/5/2023/ 2:34 pm	7/5/2023
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/5/2023/ 2:34 pm	7/5/2023
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	7/5/2023/ 2:35 pm	7/5/2023
Reset					
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	7/5/2023/ 2:35 pm	7/5/2023
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	7/5/2023/ 2:35 pm	7/5/2023
Reset					
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Not Sound	7/5/2023/ 2:36 pm	7/5/2023
Reset					
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	7/5/2023/ 2:36 pm	7/5/2023
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	7/5/2023/ 2:37 pm	7/5/2023
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	7/5/2023/ 2:37 pm	7/5/2023
22	A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	<input type="checkbox"/>	Not Sound	7/5/2023/ 2:37 pm	7/5/2023
Reset monitor					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	7/5/2023/ 2:45 pm	7/5/2023
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	7/5/2023/ 2:46 pm	7/5/2023
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEAO	<input type="checkbox"/>	Sound	7/5/2023/ 2:46 pm	7/5/2023

Work Order Detail Report

7/5/2023

3:28 PM

sso overflow inspections 7-2-2023 0.93'

26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	7/5/2023/ 2:46 pm	7/5/2023
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	7/5/2023/ 2:47 pm	7/5/2023
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	7/5/2023/ 2:47 pm	7/5/2023
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	7/5/2023/ 2:47 pm	7/5/2023
30	B-15 COVENTRY AND CEDAR SA16ADB0	<input type="checkbox"/>	Sound	7/5/2023/ 2:48 pm	7/5/2023
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	7/5/2023/ 2:44 pm	7/5/2023
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	7/5/2023/ 2:45 pm	7/5/2023
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	7/5/2023/ 2:45 pm	7/5/2023
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	7/5/2023/ 2:38 pm	7/5/2023
Reset					
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Not Sound	7/5/2023/ 2:38 pm	7/5/2023
Reset					
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Not Sound	7/5/2023/ 2:39 pm	7/5/2023
Reset					
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Not Sound	/ 2:39 pm	7/5/2023
Reset					
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Not Sound	7/5/2023/ 2:39 pm	7/5/2023
Reset					
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	7/5/2023/ 2:40 pm	7/5/2023
40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Not Sound	7/5/2023/ 2:40 pm	7/5/2023
Reset					
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	7/5/2023/ 2:41 pm	7/5/2023
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	7/5/2023/ 2:41 pm	7/5/2023
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Not Sound	7/5/2023/ 2:42 pm	7/5/2023
Reset					
44	C-51 AATHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	7/5/2023/ 2:42 pm	7/5/2023
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	7/5/2023/ 2:42 pm	7/5/2023

Tasks/Resources

SWCT26 Inspection

Crew:	Status:	*Cal'c UC: \$12.04	*Task Cost: \$541.59	Start Dt: 7/5/2023
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 7/5/2023

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
12459 Eathridge, David	Hours	7.00	\$181.16		7/5/2023	7/5/2023
22394 Cardarella, Joe	Hours	7.00	\$172.83		7/5/2023	7/5/2023

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	7.00	\$93.80		7/5/2023	7/5/2023
CHFLT55 FORD F250 PICK UP 0	Hours	7.00	\$93.80		7/5/2023	7/5/2023

Task Comment: sso overflow 7-2-2023 0.93

Work Order Detail Report

7/5/2023

sso overflow inspections 7-2-2023 0.93'

3:28 PM

			*Actual	*Estimated	*Difference
Projected Complete:		Lock: <input type="checkbox"/>	WO Duration	6.50	0.00
Repair Type:			Labor Hours	14.00	0.00
Subcontractor:			Labor Costs	\$353.99	\$0.00
Profit Center:			Material Costs	0.00	0.00
			Fluids Costs	0.00	0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Equipment Costs	187.60	0.00
Unit of Measure:	Each		Contractor Costs	0.00	0.00
*Unit Cost:	\$0.00		Misc. Costs	0.00	0.00
WO Hours:	0.00		Total Costs	\$541.59	\$0.00
			Use Task Info:	True	True

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	
Invoice Number:		Date Bill Sent:	
Incoming Account #:		Payment Received:	
		Payment Method:	
Associated PMs		Imported to Financials: <input type="checkbox"/>	

Tracking	PM Code and Description		Closed
	SSO-02 SSO INSPECTION		<input checked="" type="checkbox"/>
Item	Description	By	
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jackson	7/5/2023
Supervisor Notification	Email Queued Successfully!	jackson	7/5/2023
Status Change	From New Work Order to Complete	jackson	7/5/2023

Rate:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned.	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNU	Test Tee Correction: <input type="checkbox"/>
Test Performed Through:	Appointment Date: 7/5/2023	8:00 AM
Dye Test Results:		
WO User 51:	E Mail:	
Measurement:	Measurement Line 2:	
History:		
Manhole Basin Repair:	Pipe Size:	
Material Used:	PVC Tees, Angles, Slee	
Pipe Repair:	WO User 44:	
Street Repair:	WO User 45:	
Grass Repair:	WO User 46:	
Curb Repair:		
Driveway- Sidewalk Re		
Construction Crew:		
WO User 39:	OUPS #:	
WO User 40:	WO User 48:	
WO User 41:		


Work Order Detail Report

7/5/2023

sso overflow inspections 7-2-2023 0.93'

3:28 PM

WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised: <input type="checkbox"/>	
WO User 73:	Quantity:	Paid: <input type="checkbox"/>	
WO User 74:	WO User 84:	WO User 104: <input type="checkbox"/>	
WO User 75:	WO User 85:	WO User 105: <input type="checkbox"/>	
WO User 76:	WO User 86:	WO User 106: <input type="checkbox"/>	
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107: <input type="checkbox"/>	
WO User 78:	WO User 88:	WO User 108: <input type="checkbox"/>	
WO User 79:	WO User 89:	WO User 109: <input type="checkbox"/>	
WO User 80:	WO User 90:	WO User 110: <input type="checkbox"/>	
WO User 81:	WO User 91:	WO User 111: <input type="checkbox"/>	
WO Creator: jjackson	WO Creation Date: 7/5/2023	PM Trigger:	Rec #: 13838



Work Order Detail Report

7/18/2023

sso overflow inspection 7-15-2023 0.28"

12:58 PM

WO Number:	230710-0003	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	7/18/2023 12:56 pm	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather	Assigned By:	15854 Ferrone, Anthony
Assigned Crew:			
Supervisor:	Jackson, Jeff	Assigned Date:	7/6/2023
Lead Worker:	Manco, Angelo	Start Date:	7/15/2023 7:30 AM
Priority:	High	End Date:	7/15/2023 2:30 PM
Account #:			
Proj No - Acct:			
Project:			
Reason:			
Received By:			
Inspected By:			

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer

Comments for Crew
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations

Address 2

Address	X Coord	Y Coord	General Location	Address 2
FAIRFAX AT NORTH PARK	2,220,655.65435414	665,517.24643672	Doan Brook	
NORTH PARK AND COVENTRY	2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH	2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX	2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND	2,222,845.06631389	664,689.08536339	Doan Brook	
	2,226,440.21168265	664,329.55524255		
	2,226,354.79813956	664,409.89202413		
	2,226,389.92077273	664,379.07548472		
	FAIRMOUNT AT DARTMOOR			
	2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH	
	FAIRMOUNT AT WELLINGTON			
	2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH	
	FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
	2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH	
	FAIRMOUNT AT MARLBORO			
	2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH	

Work Order Detail Report

7/18/2023

sso overflow inspection 7-15-2023 0.28"

12:58 PM

FAIRMOUNT AT ARLINGTON

2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)

2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY

2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON

2,221,598.28993607 666,996.61322863
MONMOUTH, EAST OF DARTMOOR

2,225,152.08663423 665,499.19660404 DOAN BROOK
BRADFORD AND LEE

2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH
EDDINGTON

2,221,299.08384156 674,932.84604380
HAMPSHIRE LANE AT MAYFIELD (18")

2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL

2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")

2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH

2600 HAMPSHIRE RD

HAMPSHIRE AT EUCLID HTS. BLVD.

2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON

2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY

2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD

2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd

2,227,113.30810548 671,276.67684697
LEE RD. & SUPERIOR AVE.

2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE

2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND

2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND

2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON

2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD

2225 NOBLE ROAD

2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF

2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE

2,228,126.76638040 684,188.23206055

2,220,777.89623564 666,181.72575080

2,218,501.67473823 671,997.54581206

2,216,759.55453481 670,474.59347738

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

Work Order Detail Report

7/18/2023

sso overflow inspection 7-15-2023 0.28"

12:58 PM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

7/18/2023

sso overflow inspection 7-15-2023 0.28"

12:58 PM

Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Description 2</u>	<u>PM Description</u>	<u>Asset ID</u>	<u>Completed</u>
Sewer Control Valve				FAIRFAX AT NORTH PARK			
SSO 431						26	
Sewer Control Valve				NORTH PARK AND COVENTRY			
SSO 114						16	
Sewer Control Valve				FAIRMOUNT SOUTH OF SCARBOROUGH			
SSO 121						35	
Sewer Structure						3094	
SA16AAWB0							
Sewer Control Valve				FAIRMOUNT AT FAIRFAX			
SSO 112						7	
Sewer Control Valve				FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
SSO 99						6	
Sewer Control Valve				3012 NORTH WOODLAND			
SSO 432						14	
Sewer Control Valve						55	
DB-03							
Sewer Control Valve						56	
DB-01							
Sewer Control Valve						57	
DB-02							
Sewer Control Valve				FAIRMOUNT AT DARTMOOR			
CH-04						5	
Sewer Control Valve				FAIRMOUNT AT WELLINGTON			
SSO 110						44	
Sewer Control Valve				FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
SSO 87						33	
Sewer Control Valve				FAIRMOUNT AT MARLBORO			
SSO 116						4	
Sewer Control Valve				FAIRMOUNT AT ARLINGTON			
SSO 111						46	
Sewer Control Valve				FAIRMOUNT & COVENTRY (SCARBOROUGH)			
SSO 113						37	
Sewer Control Valve				FAIRMOUNT AND COVENTRY			
SSO 124						47	
Sewer Control Valve				SCARBOROUGH AT LAMBERTON			
CH-50						53	
Sewer Control Valve				BRADFORD AND LEE			
SSO 129						11	
Sewer Control Valve				EDDINGTON			
CH-52						2	
Sewer Control Valve				HAMPSHIRE LANE AT MAYFIELD (18")			
SSO 88						42	
Sewer Control Valve				EAST OVERLOOK AT EDGEHILL			
SSO 122						36	
Sewer Control Valve				HAMPSHIRE LANE AT MAYFIELD (36")			
SSO 89						34	
Sewer Structure						1536	
SA16ADZB0							
Sewer Control Valve				HAMPSHIRE AT EUCLID HTS. BLVD.			
SSO 91						20	
Sewer Structure						4446	
SA16ADPH0							
Sewer Control Valve				CEDAR BTW. FAIRMOUNT/DEMINGTON			
SSO 120						8	
Sewer Control Valve				2828 BERKSHIRE, EAST OF COVENTRY			
SSO 103						19	
Sewer Control Valve				3003 EUCLID HEIGHTS BLVD			
SSO 104						15	

Work Order Detail Report

7/18/2023

sso overflow inspection 7-15-2023 0.28"

12:58 PM

Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior F 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQQD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

Work Order Detail Report

7/18/2023

sso overflow inspection 7-15-2023 0.28"

12:58 PM

Check List					
	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	7/11/2023/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	7/11/2023/	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	7/11/2023/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	7/11/2023/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	7/11/2023/	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	7/11/2023/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	7/11/2023/	
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Not Sound	7/11/2023/	
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	7/11/2023/	
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	7/11/2023/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	7/11/2023/	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	7/11/2023/	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	7/11/2023/	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/11/2023/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	7/11/2023/	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	7/11/2023/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/11/2023/	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Not Sound	7/11/2023/	
needs new block/no block					
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	7/11/2023/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	7/11/2023/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	7/11/2023/	
22	A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	<input type="checkbox"/>	Not Sound	7/11/2023/	
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	7/11/2023/	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Not Sound	7/11/2023/	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEAO	<input type="checkbox"/>	Sound	7/11/2023/	
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	7/11/2023/	
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Not Sound	7/11/2023/	
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPFO	<input type="checkbox"/>	Sound	7/11/2023/	

Work Order Detail Report

7/18/2023

12:58 PM

sso overflow inspection 7-15-2023 0.28"

29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Not Sound	7/11/2023/
30	B-15 COVENTRY AND CEDAR SA16ADBHQ0	<input type="checkbox"/>	Sound	7/11/2023/
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Not Sound	7/11/2023/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	7/11/2023/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Not Sound	7/11/2023/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	7/11/2023/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	7/11/2023/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	7/11/2023/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	7/11/2023/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Not Sound	7/11/2023/
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	7/11/2023/
40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Not Sound	7/11/2023/
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	7/11/2023/
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	7/11/2023/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Not Sound	7/11/2023/
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	7/11/2023/
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	7/11/2023/

Tasks/Resources

SWCT26 Inspection

Crew:	Status:	*Cal'c UC: \$6.98	*Task Cost: \$314.16	Start Dt: 7/15/2023
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 7/15/2023

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
19356 Manco, Angelo	Hours	7.00	\$190.61		7/15/2023	7/15/2023

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD 350 CREW CAB 9	Hours	7.00	\$123.55		7/15/2023	7/15/2023

Task Comment: sso overflow inspection - 7-15-2023 = 0.28'

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	7.00	0.00	0.00
Subcontractor:		Labor Costs	\$190.61	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	123.55	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$314.16	\$0.00	\$0.00
		Use Task Info:	True	True	

Work Order Detail Report

7/18/2023

sso overflow inspection 7-15-2023 0.28"

12:58 PM

Billed Party		Billing	
Customer ID: Customer Name: Address: City: State: Zip:		Customer Number: Last Name: Phone: Fax #: E-mail:	Cell #:
Billing Data		*Billing Amount: Date Bill Sent: Payment Received: Payment Method:	
Contact Name: Invoice Number: Incoming Account #:		Billing Required: <input type="checkbox"/> Billing Processed: <input type="checkbox"/> Imported to Financials: <input type="checkbox"/>	

Associated PMs		PM Code and Description	Closed	
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>	
Tracking	Description	By	Date	Time
Item				
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	aerrone	7/10/2023	9:57 AM
Supervisor Notification	Email Queued Successfully!	aerrone	7/10/2023	9:57 AM
Leadworker Notification	Email Queued Successfully!	aerrone	7/10/2023	9:58 AM
Status Change	From New Work Order to Missing Required Data	aerrone	7/17/2023	4:16 PM
Status Change	From Missing Required Data to Complete	jackson	7/18/2023	12:56 PM

Rate:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned.	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>
Test Performed Through:	Appointment Date:	
Dye Test Results:		
WO User 51:	E Mail:	
Measurement:	Measurement Line 2:	
History:		
Manhole Basin Repair:	Pipe Size:	
Material Used:	PVC Tees, Angles, Sier	
Pipe Repair:	WO User 44:	
Street Repair:	WO User 45:	
Grass Repair:	WO User 46:	
Curb Repair:		
Driveway- Sidewalk Re:		
Construction Crew:		
WO User 39:	OUPS #:	
WO User 40:	WO User 48:	
WO User 41:		

WO User 52:	WO User 62:
WO User 53:	WO User 63:
WO User 54:	WO User 64:
WO User 55:	WO User 65:
WO User 56:	WO User 66:
WO User 57:	WO User 67:
WO User 58:	WO User 68:
WO User 59:	WO User 69:
WO User 60:	WO User 70:
WO User 61:	WO User 71:

Work Order Detail Report

7/18/2023

sso overflow inspection 7-15-2023 0.28"

12:58 PM


WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: aferrone	WO Creation Date: 7/10/2023	PM Trigger:	Rec #: 13849

 **Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Thursday, July 20, 2023

Accumulation in inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Thursday, July 20, 2023

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.83	0.83	0.83	0.76	0.28	0.12
Brecksville	2.30	2.30	2.30	2.16	1.20	0.51
Brook Park	2.49	2.49	2.49	2.44	1.35	0.61
Cleveland Industrial Pkwy	1.91	1.91	1.91	1.91	1.24	0.59
Dille Ave PS	1.46	1.46	1.46	1.41	0.65	0.29
Division Ave PS	1.35	1.35	1.34	1.29	0.56	0.28
Easterly WWTP	0.98	0.98	0.96	0.81	0.28	0.14
Independence	2.21	2.21	2.21	2.11	1.19	0.60
James Rhodes HS	1.75	1.75	1.75	1.75	1.14	0.43
Jennings PS	1.46	1.46	1.46	1.45	0.78	0.29
Macedonia	1.85	1.85	1.84	1.71	0.98	0.54
Maple Heights	1.34	1.34	1.34	1.33	0.62	0.33
Mary Street PS	1.52	1.52	1.52	1.43	0.59	0.27
Mayfield Heights	0.88	0.88	0.76	0.57	0.27	0.11
Moreland Hills	1.04	1.04	1.04	0.95	0.50	0.27
North Olmsted	1.95	1.95	1.95	1.95	1.05	0.42
North Royalton	2.69	2.69	2.69	2.56	1.49	0.59
Oakwood	1.68	1.68	1.67	1.48	0.82	0.49
Olmsted Falls	1.92	1.92	1.92	1.89	1.37	0.59
Parma	1.99	1.99	1.99	1.91	0.84	0.35
Richfield	1.93	1.93	1.89	1.70	1.19	0.47
Shaker Heights	1.14	1.14	1.14	1.09	0.47	0.22
South Euclid	1.12	1.12	0.99	0.79	0.35	0.19
Southerly WWTP	1.31	1.31	1.31	1.31	0.62	0.26
Strongsville C WWTP	2.18	2.18	2.17	2.15	1.51	0.63
Strongsville Foltz	1.38	1.38	1.38	1.26	0.87	0.39
University Heights	1.28	1.28	1.25	1.10	0.58	0.26
Wade Park	1.43	1.43	1.35	1.23	0.59	0.27
Westerly WWTP	0.95	0.95	0.95	0.91	0.42	0.20
Westlake	2.19	2.19	2.18	2.18	1.21	0.66

Work Order Detail Report

7/21/2023

sso overflow inspection 7-21-2023 = 1.28"

3:50 PM

WO Number:	230721-0004	Category:	SSOs
Status:	Closed In Field	Problem:	Storm Response
Status Date:	7/21/2023 3:01 pm	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	7/21/2023 8:00 AM
Lead Worker:	Manco, Angelo	End Date:	7/21/2023 2:30 PM
Priority:	High	Override Notifications	<input type="checkbox"/>
Account #:		Problem	<input type="checkbox"/>
Proj No - Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Locations

Address 2

Address	X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK	2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY	2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH	2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX	2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND	2,222,845.06631389	664,689.08536339	Doan Brook
	2,226,440.21168265	664,329.55524255	
	2,226,354.79813956	664,409.89202413	
	2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR	2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON	2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO	2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

7/21/2023

sso overflow inspection 7-21-2023 = 1.28"

3:50 PM

FAIRMOUNT AT ARLINGTON
2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)
2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY
2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON
2,221,598.28993607 666,996.61322863
MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423 665,499.19660404 DOAN BROOK
BRADFORD AND LEE
2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH
EDDINGTON
2,221,299.08384156 674,932.84604380
HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL
2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")
2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD

HAMPSHIRE AT EUCLID HTS. BLVD.
2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON
2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY
2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD
2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd
2,227,113.30810548 671,276.67684697
LEE RD. & SUPERIOR AVE.
2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE
2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND
2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND
2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON
2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD

2225 NOBLE ROAD
2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF
2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE
2,228,126.76638040 684,188.23206055

2,220,777.89623564 666,181.72575080

2,218,501.67473823 671,997.54581206

2,216,759.55453481 670,474.59347738

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

Work Order Detail Report

7/21/2023

sso overflow inspection 7-21-2023 = 1.28"

3:50 PM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

7/21/2023

sso overflow inspection 7-21-2023 = 1.28"

3:50 PM

Work Order Assets

Object Type	System ID 1	System ID 2	Description 1			PM Description	Asset ID	Completed
			Odometer	Hourmeter	Othermeter			
Sewer Control Valve	SSO 431					FAIRFAX AT NORTH PARK		
Sewer Control Valve	SSO 114					NORTH PARK AND COVENTRY	26	
Sewer Control Valve	SSO 121					FAIRMOUNT SOUTH OF SCARBOROUGH	16	
Sewer Structure	SA16AAWB0						35	
Sewer Control Valve	SSO 112					FAIRMOUNT AT FAIRFAX	3094	
Sewer Control Valve	SSO 99						7	
Sewer Control Valve	SSO 432					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	6	
Sewer Control Valve	DB-03						3012 NORTH WOODLAND	14
Sewer Control Valve	DB-01						55	
Sewer Control Valve	DB-02						56	
Sewer Control Valve	CH-04					FAIRMOUNT AT DARTMOOR	57	
Sewer Control Valve	SSO 110						4	
Sewer Control Valve	SSO 87					FAIRMOUNT AT WELLINGTON	44	
Sewer Control Valve	SSO 116					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	33	
Sewer Control Valve	SSO 111					FAIRMOUNT AT MARLBORO	46	
Sewer Control Valve	SSO 113					FAIRMOUNT AT ARLINGTON	47	
Sewer Control Valve	SSO 124					FAIRMOUNT & COVENTRY (SCARBOROUGH)	53	
Sewer Control Valve	CH-50					SCARBOROUGH AT LAMBERTON	37	
Sewer Control Valve	SSO 129					BRADFORD AND LEE	2	
Sewer Control Valve	CH-52					EDDINGTON	42	
Sewer Control Valve	SSO 88					HAMPSHIRE LANE AT MAYFIELD (18")	36	
Sewer Control Valve	SSO 122					EAST OVERLOOK AT EDGEHILL	34	
Sewer Control Valve	SSO 89					HAMPSHIRE LANE AT MAYFIELD (36")	11	
Sewer Structure	SA16ADZB0					FAIRMOUNT AND COVENTRY	1536	
Sewer Control Valve	SSO 91					SCARBOROUGH AT LAMBERTON	20	
Sewer Structure	SA16ADPH0					BRADFORD AND LEE	4446	
Sewer Control Valve	SSO 120					EDDINGTON	8	
Sewer Control Valve	SSO 103					HAMPSHIRE AT EUCLID HTS. BLVD.	42	
Sewer Control Valve	SSO 104					EAST OVERLOOK AT EDGEHILL	36	
						HAMPSHIRE LANE AT MAYFIELD (18")	34	
						EAST OVERLOOK AT EDGEHILL	11	
						HAMPSHIRE LANE AT MAYFIELD (36")	2	
						FAIRMOUNT AND COVENTRY	42	
						SCARBOROUGH AT LAMBERTON	34	
						BRADFORD AND LEE	1536	
						EDDINGTON	20	
						HAMPSHIRE AT EUCLID HTS. BLVD.	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (18")	36	
						EAST OVERLOOK AT EDGEHILL	34	
						HAMPSHIRE LANE AT MAYFIELD (36")	11	
						FAIRMOUNT AND COVENTRY	2	
						SCARBOROUGH AT LAMBERTON	42	
						BRADFORD AND LEE	34	
						EDDINGTON	1536	
						HAMPSHIRE AT EUCLID HTS. BLVD.	20	
						EAST OVERLOOK AT EDGEHILL	4446	
						HAMPSHIRE LANE AT MAYFIELD (18")	8	
						EAST OVERLOOK AT EDGEHILL	36	
						HAMPSHIRE LANE AT MAYFIELD (36")	34	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2	
						BRADFORD AND LEE	42	
						EDDINGTON	34	
						HAMPSHIRE AT EUCLID HTS. BLVD.	1536	
						EAST OVERLOOK AT EDGEHILL	20	
						HAMPSHIRE LANE AT MAYFIELD (18")	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (36")	36	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2	
						BRADFORD AND LEE	42	
						EDDINGTON	34	
						HAMPSHIRE AT EUCLID HTS. BLVD.	1536	
						EAST OVERLOOK AT EDGEHILL	20	
						HAMPSHIRE LANE AT MAYFIELD (18")	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (36")	36	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2	
						BRADFORD AND LEE	42	
						EDDINGTON	34	
						HAMPSHIRE AT EUCLID HTS. BLVD.	1536	
						EAST OVERLOOK AT EDGEHILL	20	
						HAMPSHIRE LANE AT MAYFIELD (18")	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (36")	36	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2	
						BRADFORD AND LEE	42	
						EDDINGTON	34	
						HAMPSHIRE AT EUCLID HTS. BLVD.	1536	
						EAST OVERLOOK AT EDGEHILL	20	
						HAMPSHIRE LANE AT MAYFIELD (18")	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (36")	36	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2	
						BRADFORD AND LEE	42	
						EDDINGTON	34	
						HAMPSHIRE AT EUCLID HTS. BLVD.	1536	
						EAST OVERLOOK AT EDGEHILL	20	
						HAMPSHIRE LANE AT MAYFIELD (18")	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (36")	36	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2	
						BRADFORD AND LEE	42	
						EDDINGTON	34	
						HAMPSHIRE AT EUCLID HTS. BLVD.	1536	
						EAST OVERLOOK AT EDGEHILL	20	
						HAMPSHIRE LANE AT MAYFIELD (18")	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (36")	36	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2	
						BRADFORD AND LEE	42	
						EDDINGTON	34	
						HAMPSHIRE AT EUCLID HTS. BLVD.	1536	
						EAST OVERLOOK AT EDGEHILL	20	
						HAMPSHIRE LANE AT MAYFIELD (18")	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (36")	36	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2	
						BRADFORD AND LEE	42	
						EDDINGTON	34	
						HAMPSHIRE AT EUCLID HTS. BLVD.	1536	
						EAST OVERLOOK AT EDGEHILL	20	
						HAMPSHIRE LANE AT MAYFIELD (18")	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (36")	36	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2	
						BRADFORD AND LEE	42	
						EDDINGTON	34	
						HAMPSHIRE AT EUCLID HTS. BLVD.	1536	
						EAST OVERLOOK AT EDGEHILL	20	
						HAMPSHIRE LANE AT MAYFIELD (18")	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (36")	36	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2	
						BRADFORD AND LEE	42	
						EDDINGTON	34	
						HAMPSHIRE AT EUCLID HTS. BLVD.	1536	
						EAST OVERLOOK AT EDGEHILL	20	
						HAMPSHIRE LANE AT MAYFIELD (18")	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (36")	36	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2	
						BRADFORD AND LEE	42	
						EDDINGTON	34	
						HAMPSHIRE AT EUCLID HTS. BLVD.	1536	
						EAST OVERLOOK AT EDGEHILL	20	
						HAMPSHIRE LANE AT MAYFIELD (18")	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (36")	36	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2	
						BRADFORD AND LEE	42	
						EDDINGTON	34	
						HAMPSHIRE AT EUCLID HTS. BLVD.	1536	
						EAST OVERLOOK AT EDGEHILL	20	
						HAMPSHIRE LANE AT MAYFIELD (18")	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (36")	36	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2	
						BRADFORD AND LEE	42	
						EDDINGTON	34	
						HAMPSHIRE AT EUCLID HTS. BLVD.	1536	
						EAST OVERLOOK AT EDGEHILL	20	
						HAMPSHIRE LANE AT MAYFIELD (18")	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (36")	36	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2	
						BRADFORD AND LEE	42	
						EDDINGTON	34	
						HAMPSHIRE AT EUCLID HTS. BLVD.	1536	
						EAST OVERLOOK AT EDGEHILL	20	
						HAMPSHIRE LANE AT MAYFIELD (18")	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (36")	36	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2	
						BRADFORD AND LEE	42	
						EDDINGTON	34	
						HAMPSHIRE AT EUCLID HTS. BLVD.	1536	
						EAST OVERLOOK AT EDGEHILL	20	
						HAMPSHIRE LANE AT MAYFIELD (18")	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (36")	36	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2	
						BRADFORD AND LEE	42	
						EDDINGTON	34	
						HAMPSHIRE AT EUCLID HTS. BLVD.	1536	
						EAST OVERLOOK AT EDGEHILL	20	
						HAMPSHIRE LANE AT MAYFIELD (18")	4446	
						EAST OVERLOOK AT EDGEHILL	8	
						HAMPSHIRE LANE AT MAYFIELD (36")	36	
						FAIRMOUNT AND COVENTRY	11	
						SCARBOROUGH AT LAMBERTON	2</	

Work Order Detail Report

7/21/2023

sso overflow inspection 7-21-2023 = 1.28"

3:50 PM

Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior F 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQQD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND ATERSTONE 54
Sewer Structure SA16APEF0	1809

Work Order Detail Report

7/21/2023

sso overflow inspection 7-21-2023 = 1.28"

3:50 PM

Check List					
	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	7/21/2023/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Not Sound	7/21/2023/	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	7/21/2023/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	7/21/2023/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	7/21/2023/	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	7/21/2023/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Not Sound	7/21/2023/	
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	7/21/2023/	
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	7/21/2023/	
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Not Sound	7/21/2023/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	7/21/2023/	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/21/2023/	
13	A-1 3041 FAIRMOUNT SA16AAUTO (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Not Sound	7/21/2023/	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/21/2023/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/21/2023/	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	7/21/2023/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/21/2023/	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>		7/21/2023/	
No block					
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	7/21/2023/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	7/21/2023/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	7/21/2023/	
22	A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	<input type="checkbox"/>	Not Sound	7/21/2023/	
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	7/21/2023/	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	7/21/2023/	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	7/21/2023/	
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Not Sound	7/21/2023/	
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO	<input type="checkbox"/>	Sound	7/21/2023/	
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Not Sound	7/21/2023/	

Work Order Detail Report

7/21/2023

3:50 PM

sso overflow inspection 7-21-2023 = 1.28"

29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Not Sound	7/21/2023/
30	B-15 COVENTRY AND CEDAR SA16ADBHO	<input type="checkbox"/>	Sound	7/21/2023/
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	7/21/2023/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	7/21/2023/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	7/21/2023/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	7/21/2023/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Not Sound	7/21/2023/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Not Sound	7/21/2023/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Not Sound	7/21/2023/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Not Sound	7/21/2023/
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	7/21/2023/
40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Sound	7/21/2023/
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	7/21/2023/
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	7/21/2023/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Not Sound	7/21/2023/
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	7/21/2023/
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	7/21/2023/

Tasks/Resources

SWCT26 Inspection

Crew:	Status:	*Cal'c UC: \$5.93	*Task Cost: \$266.63	Start Dt: 7/21/2023
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 7/21/2023

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	7.00	\$172.83		7/21/2023	7/21/2023

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	7.00	\$93.80		7/21/2023	7/21/2023

Task Comment: sso overflow inspection 7-20-2023 = 1.28"

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	6.50	0.00	0.00
Subcontractor:		Labor Costs	7.00	0.00	0.00
Profit Center:		Material Costs	\$172.83	\$0.00	\$0.00
Quantity: 0.00	Lock: <input type="checkbox"/>	Fluids Costs	0.00	0.00	0.00
Unit of Measure: Each		Equipment Costs	93.80	0.00	0.00
*Unit Cost: \$0.00		Contractor Costs	0.00	0.00	0.00
WO Hours: 0.00		Misc. Costs	0.00	0.00	0.00
		Total Costs	\$266.63	\$0.00	\$0.00
		Use Task Info:	True	True	

Work Order Detail Report

7/21/2023

sso overflow inspection 7-21-2023 = 1.28"

3:50 PM

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	
Invoice Number:		Date Bill Sent:	
Incoming Account #:		Payment Received:	
		Payment Method:	
		Billing Required:	<input type="checkbox"/>
		Billing Processed:	<input type="checkbox"/>
		Imported to Financials:	<input type="checkbox"/>

Associated PMs		PM Code and Description	Closed	
Tracking	Item	Description	Date	Time
	Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	7/21/2023 12:07 PM
	Supervisor Notification	Email Queued Successfully!	jjackson	7/21/2023 12:07 PM
	Leadworker Notification	Email Queued Successfully!	jjackson	7/21/2023 12:08 PM
	Status Change	From New Work Order to Closed In Field	amanco	7/21/2023 3:01 PM

Rate:	Opened At:	Televised:	<input type="checkbox"/>
Recieved By:	Pipe Footage Cleaned	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	<input type="checkbox"/>
Test Performed Throuç	Appointment Date: 7/21/2023 8:00 AM		
Dye Test Results:			
WO User 51:	E Mail:		
Measurement:	Measurement Line 2:		
History:			
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sles		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		

Work Order Detail Report

7/21/2023

sso overflow inspection 7-21-2023 = 1.28"

3:50 PM


WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 7/21/2023	PM Trigger:	Rec #: 13895


**Northwest Ohio
Regional Sewer District**

Daily Precipitation Report

Sunday, July 23, 2023

Accumulation in inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Sunday, July 23, 2023

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	1.33	1.33	1.26	1.07	0.89	0.47
Brecksville	0.19	0.19	0.15	0.14	0.13	0.06
Brook Park	0.15	0.15	0.14	0.10	0.08	0.05
Cleveland Industrial Pkwy	0.17	0.17	0.17	0.10	0.09	0.08
Dille Ave PS	0.52	0.50	0.31	0.29	0.28	0.13
Division Ave PS	0.77	0.77	0.77	0.72	0.64	0.35
Easterly WWTP	0.46	0.38	0.28	0.19	0.16	0.12
Independence	0.09	0.09	0.08	0.06	0.04	0.03
James Rhodes HS	0.67	0.67	0.65	0.62	0.58	0.32
Jennings PS	0.84	0.84	0.83	0.79	0.74	0.45
Macedonia	0.09	0.09	0.09	0.08	0.07	0.04
Maple Heights	0.23	0.23	0.21	0.18	0.12	0.05
Mary Street PS	0.57	0.56	0.36	0.35	0.29	0.14
Mayfield Heights	0.50	0.50	0.49	0.45	0.35	0.24
Moreland Hills	0.13	0.13	0.13	0.13	0.08	0.06
North Olmsted	0.10	0.10	0.10	0.09	0.05	0.03
North Royalton	0.24	0.24	0.23	0.20	0.17	0.07
Oakwood	0.30	0.30	0.30	0.29	0.26	0.19
Olmsted Falls	0.16	0.16	0.15	0.14	0.07	0.05
Parma	0.54	0.54	0.52	0.47	0.41	0.22
Richfield	0.05	0.05	0.04	0.03	0.03	0.01
Shaker Heights	0.57	0.57	0.51	0.34	0.34	0.15
South Euclid	0.67	0.67	0.64	0.41	0.32	0.23
Southerly WWTC	0.16	0.16	0.16	0.13	0.13	0.10
Strongsville C WWTP	0.62	0.62	0.58	0.53	0.49	0.21
Strongsville Foltz	0.58	0.58	0.54	0.53	0.49	0.25
University Heights	0.70	0.70	0.67	0.55	0.51	0.29
Wade Park	0.39	0.36	0.29	0.22	0.21	0.14
Westerly WWTP	0.52	0.52	0.52	0.49	0.44	0.32
Westlake	0.08	0.08	0.08	0.07	0.04	0.02

Work Order Detail Report

7/25/2023

3:23 PM

sso overflow inspections 7-23-2023 0.70

WO Number: 230725-0001	Category:	SSOs
Status: Closed In Field	Problem:	Storm Response
Status Date: 7/25/2023 3:08 pm	Main Task:	Inspection

Asset: SSO 431

Location: FAIRFAX AT NORTH PARK

Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	7/25/2023 7:30 AM
Lead Worker:	Manco, Angelo	End Date:	7/25/2023 2:00 PM
Priority:	High	Override Notifications	<input type="checkbox"/>
Account #:		Problem	<input type="checkbox"/>
Proj No - Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations

Address 2

Address	X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK	2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY	2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH	2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX	2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND	2,222,845.06631389	664,689.08536339	Doan Brook
	2,226,440.21168265	664,329.55524255	
	2,226,354.79813956	664,409.89202413	
	2,226,389.92077273	664,379.07548472	
	2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
	2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH
	2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
	2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Detail Report

7/25/2023

3:23 PM

sso overflow inspections 7-23-2023 0.70

FAIRMOUNT AT ARLINGTON
2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)
2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY
2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON
2,221,598.28993607 666,996.61322863
MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423 665,499.19660404 DOAN BROOK
BRADFORD AND LEE
2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH
EDDINGTON
2,221,299.08384156 674,932.84604380
HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL
2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")
2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD
HAMPSHIRE AT EUCLID HTS. BLVD.
2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON
2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY
2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD
2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd
2,227,113.30810548 671,276.67684697
LEE RD. & SUPERIOR AVE.
2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE
2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND
2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND
2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON
2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD
2225 NOBLE ROAD
2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF
2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE
2,228,126.76638040 684,188.23206055
2,220,777.89623564 666,181.72575080
2,218,501.67473823 671,997.54581206
2,216,759.55453481 670,474.59347738
2,224,536.21778722 668,887.44048372
2,226,741.35609348 679,432.95121680
2,226,591.76420106 679,420.92761880

Work Order Detail Report

7/25/2023

sso overflow inspections 7-23-2023 0.70

3:23 PM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

7/25/2023

3:23 PM

sso overflow inspections 7-23-2023 0.70

Work Order Assets

Object Type	System ID 1	System ID 2	Description 1			PM Description	Asset ID	Completed
			Odometer	Hourmeter	Othermeter			
Sewer Control Valve	SSO 431					FAIRFAX AT NORTH PARK	26	
Sewer Control Valve	SSO 114					NORTH PARK AND COVENTRY	16	
Sewer Control Valve	SSO 121					FAIRMOUNT SOUTH OF SCARBOROUGH	35	
Sewer Structure	SA16AAWB0						3094	
Sewer Control Valve	SSO 112					FAIRMOUNT AT FAIRFAX	7	
Sewer Control Valve	SSO 99					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	6	
Sewer Control Valve	SSO 432					3012 NORTH WOODLAND	14	
Sewer Control Valve	DB-03						55	
Sewer Control Valve	DB-01						56	
Sewer Control Valve	DB-02						57	
Sewer Control Valve	CH-04					FAIRMOUNT AT DARTMOOR	5	
Sewer Control Valve	SSO 110					FAIRMOUNT AT WELLINGTON	44	
Sewer Control Valve	SSO 87					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	33	
Sewer Control Valve	SSO 116					FAIRMOUNT AT MARLBORO	4	
Sewer Control Valve	SSO 111					FAIRMOUNT AT ARLINGTON	46	
Sewer Control Valve	SSO 113					FAIRMOUNT & COVENTRY (SCARBOROUGH)	37	
Sewer Control Valve	SSO 124					FAIRMOUNT AND COVENTRY	47	
Sewer Control Valve	CH-50					SCARBOROUGH AT LAMBERTON	53	
Sewer Control Valve	SSO 129					BRADFORD AND LEE	11	
Sewer Control Valve	CH-52					EDDINGTON	2	
Sewer Control Valve	SSO 88					HAMPSHIRE LANE AT MAYFIELD (18")	42	
Sewer Control Valve	SSO 122					EAST OVERLOOK AT EDGEHILL	36	
Sewer Control Valve	SSO 89					HAMPSHIRE LANE AT MAYFIELD (36")	34	
Sewer Structure	SA16ADZB0						1536	
Sewer Control Valve	SSO 91					HAMPSHIRE AT EUCLID HTS. BLVD.	20	
Sewer Structure	SA16ADPH0						4446	
Sewer Control Valve	SSO 120					CEDAR BTW. FAIRMOUNT/DEMINGTON	8	
Sewer Control Valve	SSO 103					2828 BERKSHIRE, EAST OF COVENTRY	19	
Sewer Control Valve	SSO 104					3003 EUCLID HEIGHTS BLVD	15	

Work Order Detail Report

7/25/2023

3:23 PM

sso overflow inspections 7-23-2023 0.70

Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior R 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQQD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

Work Order Detail Report

7/25/2023

3:23 PM

sso overflow inspections 7-23-2023 0.70

<u>Check List</u>	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	7/25/2023/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	7/25/2023/	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	7/25/2023/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Not Sound	7/25/2023/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	7/25/2023/	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	7/25/2023/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	7/25/2023/	
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Not Sound	7/25/2023/	
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	7/25/2023/	
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	7/25/2023/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	7/25/2023/	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/25/2023/	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	7/25/2023/	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/25/2023/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/25/2023/	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	7/25/2023/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/25/2023/	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>		/	
<u>Missing block / replaced</u>					
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Not Sound	7/25/2023/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	7/25/2023/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	/	
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/25/2023/	
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	7/25/2023/	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	7/25/2023/	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	7/25/2023/	
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	7/25/2023/	
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	7/25/2023/	
28	B-46 EDGEHILL AT E OVERLOOK SA16AEFP0	<input type="checkbox"/>	Not Sound	7/25/2023/	

Work Order Detail Report

7/25/2023

3:23 PM

sso overflow inspections 7-23-2023 0.70

29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	7/25/2023/
30	B-15 COVENTRY AND CEDAR SA16ADB0	<input type="checkbox"/>	Sound	7/25/2023/
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	7/25/2023/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	7/25/2023/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	7/25/2023/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	7/25/2023/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	7/25/2023/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Not Sound	7/25/2023/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	7/25/2023/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	7/25/2023/
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	7/25/2023/
40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Sound	7/25/2023/
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	7/25/2023/
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	7/25/2023/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	7/25/2023/
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	7/25/2023/
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	7/25/2023/

Tasks/Resources

SWCT26 Inspection

Crew: **Status:** *Cal'd UC: \$6.98 *Task Cost: \$314.16 **Start Dt:** 7/25/2023
Supervisor: **UOM:** Each # of Units: 45.00 *Unit Cost: \$0.00 **End Dt:** 7/25/2023

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
19356 Manco, Angelo	Hours	7.00	\$190.61		7/25/2023	7/25/2023

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD 350 CREW CAB 9	Hours	7.00	\$123.55		7/25/2023	7/25/2023

Task Comment: sso overflow inspections 7-23-2023 0.70"

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	6.50	0.00	0.00
Subcontractor:		Labor Costs	7.00	0.00	0.00
Profit Center:		Material Costs	\$190.61	\$0.00	\$0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	0.00	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$314.16	\$0.00	\$0.00
		Use Task Info:	True	True	

Work Order Detail Report

7/25/2023

3:23 PM

sso overflow inspections 7-23-2023 0.70

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	Cell #:
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data		Billing Required: <input type="checkbox"/>	
Contact Name:		*Billing Amount:	
Invoice Number:		Date Bill Sent:	
Incoming Account #:		Payment Received:	
		Payment Method:	
Associated PMs		Closed <input checked="" type="checkbox"/>	
Tracking	PM Code and Description		
	SSO-02 SSO INSPECTION		
Item	Description	By	Date
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	7/25/2023
Supervisor Notification	Email Queued Successfully!	jjackson	7/25/2023
Leadworker Notification	Email Queued Successfully!	jjackson	7/25/2023
Status Change	From New Work Order to Closed In Field	amanco	7/25/2023
Rate:	Opened At:	Televised: <input type="checkbox"/>	
Received By:	Pipe Footage Cleaned.	Power Rooter: <input type="checkbox"/>	
Work From:	Gallons Used:	Jet: <input type="checkbox"/>	
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>	
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>	
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>	
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>	
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>	
Test Performed Through:	Appointment Date: 7/25/2023	8:00 AM	
Dye Test Results:	E Mail:		
WO User 51:	Measurement Line 2:		
Measurement:	Pipe Size:		
History:	PVC Tees, Angles, Sles		
Manhole Basin Repair:	WO User 44:		
Material Used:	WO User 45:		
Pipe Repair:	WO User 46:		
Street Repair:	OUPS #:		
Grass Repair:	WO User 48:		
Curb Repair:	WO User 62:		
Driveway- Sidewalk Re	WO User 63:		
Construction Crew:	WO User 64:		
WO User 39:	WO User 65:		
WO User 40:	WO User 66:		
WO User 41:	WO User 67:		
WO User 52:	WO User 68:		
WO User 53:	WO User 69:		
WO User 54:	WO User 70:		
WO User 55:	WO User 71:		
WO User 56:			
WO User 57:			
WO User 58:			
WO User 59:			
WO User 60:			
WO User 61:			

Work Order Detail Report

7/25/2023

3:23 PM

sso overflow inspections 7-23-2023 0.70

WO User 72:

WO User 82:

Televised:

WO User 73:

Quantity:

Paid:

WO User 74:

WO User 84:

WO User 104:

WO User 75:

WO User 85:

WO User 105:

WO User 76:

WO User 86:

WO User 106:

WO User 92 Date:

WO User 97 Date:

WO User 93 Date:

WO User 98 Date:

WO User 94 Date:

WO User 99 Date:

WO User 95 Date:

WO User 100 Date:

WO User 96 Date:

WO User 101 Date:

WO User 77:

WO User 87:

WO User 107:

WO User 78:

WO User 88:

WO User 108:

WO User 79:

WO User 89:

WO User 109:

WO User 80:

WO User 90:

WO User 110:

WO User 81:

WO User 91:

WO User 111:

WO Creator: jjackson

WO Creation Date: 7/25/2023

PM Trigger:


Rec #: 13899

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Thursday, July 27, 2023

Accumulation in inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report
 Thursday, July 27, 2023

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	1.08	1.08	0.99	0.94	0.48	0.21
Brecksville	0.42	0.42	0.40	0.30	0.16	0.11
Brook Park	0.45	0.45	0.45	0.44	0.27	0.13
Cleveland Industrial Pkwy	0.54	0.54	0.47	0.46	0.32	0.17
Dille Ave PS	0.70	0.70	0.68	0.66	0.36	0.23
Division Ave PS	0.49	0.49	0.48	0.46	0.34	0.23
Easterly WWTP	0.49	0.49	0.47	0.44	0.31	0.15
Independence	0.65	0.65	0.65	0.63	0.26	0.16
James Rhodes HS	0.76	0.76	0.70	0.68	0.37	0.24
Jennings PS	0.75	0.74	0.70	0.69	0.36	0.22
Macedonia	0.76	0.76	0.75	0.68	0.31	0.20
Maple Heights	1.05	1.05	0.99	0.96	0.49	0.21
Mary Street PS	0.63	0.62	0.61	0.59	0.37	0.22
Mayfield Heights	1.19	1.19	1.10	1.00	0.49	0.21
Moreland Hills	1.15	1.15	0.92	0.76	0.38	0.18
North Olmsted	0.38	0.38	0.36	0.35	0.25	0.16
North Royalton	0.20	0.20	0.19	0.16	0.10	0.05
Oakwood	0.49	0.49	0.48	0.39	0.17	0.09
Olmsted Falls	0.37	0.37	0.37	0.36	0.31	0.18
Parma	0.65	0.65	0.65	0.63	0.31	0.20
Richfield	0.52	0.52	0.52	0.44	0.17	0.09
Shaker Heights	0.96	0.96	0.87	0.85	0.45	0.23
South Euclid	0.85	0.85	0.81	0.79	0.45	0.24
Southwesterly WWTC	0.82	0.82	0.77	0.75	0.40	0.25
Strongsville C WWTP	0.50	0.50	0.50	0.49	0.20	0.19
Strongsville Foltz	0.32	0.32	0.32	0.30	0.17	0.10
University Heights	1.23	1.23	1.21	1.17	0.63	0.28
Wade Park	0.63	0.63	0.61	0.60	0.31	0.15
Westerly WWTP	0.43	0.43	0.42	0.40	0.29	0.18
Westlake	0.56	0.56	0.56	0.56	0.44	0.25

Work Order Detail Report

7/28/2023

sso overflow inspection 7-28-2023 1.23"

2:05 PM

WO Number:	230728-0004	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	7/28/2023 2:04 pm	Main Task:	Inspection

Asset: SSO 431

Location: FAIRFAX AT NORTH PARK

Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	7/28/2023 7:30 AM <input checked="" type="checkbox"/> Override
Lead Worker:	Eathridge, David	End Date:	7/28/2023 2:00 PM <input checked="" type="checkbox"/> Notifications
Priority:	High	Project ID:	<input type="checkbox"/> Problem <input type="checkbox"/> Overdue
Account #:		Project Name:	<input type="checkbox"/> Lead Worker <input type="checkbox"/> Task
Proj No - Acct:			<input type="checkbox"/> Supervisor <input type="checkbox"/> Hard Lock WO
Project:			
Reason:			
Received By:			
Inspected By:			

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Locations

<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>	<u>Address 2</u>
FAIRFAX AT NORTH PARK	2,220,655.65435414	665,517.24643672	Doan Brook	
NORTH PARK AND COVENTRY	2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH	2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX	2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND	2,222,845.06631389	664,689.08536339	Doan Brook	
	2,226,440.21168265	664,329.55524255		
	2,226,354.79813956	664,409.89202413		
	2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR	2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON	2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT MARLBORO	2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH	

Work Order Detail Report

7/28/2023

sso overflow inspection 7-28-2023 1.23"

2:05 PM

FAIRMOUNT AT ARLINGTON
2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)
2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY
2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON
2,221,598.28993607 666,996.61322863
MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423 665,499.19660404 DOAN BROOK
BRADFORD AND LEE
2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH
EDDINGTON
2,221,299.08384156 674,932.84604380
HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL
2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")
2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD

HAMPSHIRE AT EUCLID HTS. BLVD.
2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON
2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY
2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD
2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd
2,227,113.30810548 671,276.67684697
LEE RD. & SUPERIOR AVE.
2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE
2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND
2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND
2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON
2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD

2225 NOBLE ROAD
2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF
2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE
2,228,126.76638040 684,188.23206055

2,220,777.89623564 666,181.72575080

2,218,501.67473823 671,997.54581206

2,216,759.55453481 670,474.59347738

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

Work Order Detail Report

sso overflow inspection 7-28-2023 1.23"

7/28/2023

2:05 PM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

7/28/2023

sso overflow inspection 7-28-2023 1.23"

2:05 PM

Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>			<u>Description 2</u>	<u>Asset ID</u>	<u>Completed</u>
			<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>		
Sewer Control Valve						FAIRFAX AT NORTH PARK		
SSO 431							26	
Sewer Control Valve						NORTH PARK AND COVENTRY		
SSO 114							16	
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121							35	
Sewer Structure								3094
SA16AAWB0								
Sewer Control Valve						FAIRMOUNT AT FAIRFAX		
SSO 112							7	
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99							6	
Sewer Control Valve						3012 NORTH WOODLAND		
SSO 432							14	
Sewer Control Valve								55
DB-03								
Sewer Control Valve								56
DB-01								
Sewer Control Valve								57
DB-02								
Sewer Control Valve						FAIRMOUNT AT DARTMOOR		
CH-04							5	
Sewer Control Valve						FAIRMOUNT AT WELLINGTON		
SSO 110							44	
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87							33	
Sewer Control Valve						FAIRMOUNT AT MARLBORO		
SSO 116							4	
Sewer Control Valve						FAIRMOUNT AT ARLINGTON		
SSO 111							46	
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113							37	
Sewer Control Valve						FAIRMOUNT AND COVENTRY		
SSO 124							47	
Sewer Control Valve						SCARBOROUGH AT LAMBERTON		
CH-50							53	
Sewer Control Valve						BRADFORD AND LEE		
SSO 129							11	
Sewer Control Valve						EDDINGTON		
CH-52							2	
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88							42	
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL		
SSO 122							36	
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89							34	
Sewer Structure								1536
SA16ADZB0								
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91							20	
Sewer Structure								4446
SA16ADPH0								
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120							8	
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103							19	
Sewer Control Valve						3003 EUCLID HEIGHTS BLVD		
SSO 104							15	

Work Order Detail Report

7/28/2023

sso overflow inspection 7-28-2023 1.23"

2:05 PM

Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior F 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQQD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

Work Order Detail Report

7/28/2023

sso overflow inspection 7-28-2023 1.23"

2:05 PM

Check List

<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1 A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	7/28/2023/ 8:05 am	
2 A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Not Sound	7/28/2023/ 8:08 am	
3 A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	7/28/2023/ 8:11 am	
4 A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	7/28/2023/	
5 A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	7/28/2023/ 8:20 am	
6 A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	7/28/2023/ 8:25 am	
7 A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	7/28/2023/	
8 A-6 FAIRMOUNT AT SHELBOURNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Not Sound	7/28/2023/	
9 A-5 FAIRMOUNT AT SHELBOURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	7/28/2023/	
10 A-7 FAIRMOUNT AT SHELBOURNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	7/28/2023/	
11 A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	7/28/2023/	
12 A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/28/2023/	
13 A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	7/28/2023/	
14 A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/28/2023/	
15 A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/28/2023/	
16 A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	7/28/2023/	
17 A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	7/28/2023/	
18 A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Not Sound	7/28/2023/	
19 A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	7/28/2023/	
20 A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	7/28/2023/	
21 A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	7/28/2023/	
22 A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	<input type="checkbox"/>	Sound	7/28/2023/	
23 B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	7/28/2023/	
24 B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	7/28/2023/	
25 B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	7/28/2023/	
26 B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Not Sound	7/28/2023/	
27 HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	7/28/2023/	
28 B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Not Sound	7/28/2023/	
29 B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	7/28/2023/	

Work Order Detail Report

7/28/2023

sso overflow inspection 7-28-2023 1.23"

2:05 PM

30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	7/28/2023/
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	7/28/2023/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	7/28/2023/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	7/28/2023/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	7/28/2023/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	7/28/2023/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Not Sound	7/28/2023/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	7/28/2023/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	7/28/2023/
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	7/28/2023/
40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	7/28/2023/
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	7/28/2023/
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	7/28/2023/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Not Sound	7/28/2023/
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	7/28/2023/
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	7/28/2023/

Tasks/Resources

SMCT36 Inspection

Crew:	Status:	*Cal'c UC: \$12.18	*Task Cost: \$547.92	Start Dt: 7/28/2023
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 7/28/2023

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
12459 Eathridge, David	Hours	6.00	\$155.28		7/28/2023	7/28/2023
13859 Moten, Robert	Hours	6.00	\$148.14		7/28/2023	7/28/2023
28056 Palmisano, Anthony	Hours	6.00	\$138.60		7/28/2023	7/28/2023

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD 350 CREW CAB 9	Hours	6.00	\$105.90		7/28/2023	7/28/2023

Task Comment: sso inspections 7-27-2023 1.23"

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	18.00	0.00	0.00
Subcontractor:		Labor Costs	\$442.02	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	105.90	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$547.92	\$0.00	\$0.00
		Use Task Info:	True	True	

Work Order Detail Report

7/28/2023

sso overflow inspection 7-28-2023 1.23"

2:05 PM

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	<input type="checkbox"/>
Invoice Number:		Date Bill Sent:	<input type="checkbox"/>
Incoming Account #:		Payment Received:	<input type="checkbox"/>
		Payment Method:	<input type="checkbox"/>
Billing Required: <input type="checkbox"/>			
Billing Processed: <input type="checkbox"/>			
Imported to Financials: <input type="checkbox"/>			

Associated PMs		PM Code and Description	Closed
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>
Tracking	Description	By	Date
Item			Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	7/28/2023 1:20 PM
Supervisor Notification	Email Queued Successfully!	jjackson	7/28/2023 1:20 PM
Status Change	From New Work Order to Closed In Field	jjackson	7/28/2023 1:50 PM
Status Change	From Closed In Field to Complete	jjackson	7/28/2023 2:04 PM

Rate:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned.	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNU	Test Tee Correction: <input type="checkbox"/>
Test Performed Through:	Appointment Date: 7/28/2023 7:30 AM	
Dye Test Results:		
WO User 51:	E Mail:	
Measurement:	Measurement Line 2:	
History:		
Manhole Basin Repair:	Pipe Size:	
Material Used:	PVC Tees, Angles, Sles	
Pipe Repair:	WO User 44:	
Street Repair:	WO User 45:	
Grass Repair:	WO User 46:	
Curb Repair:		
Driveway- Sidewalk Re		
Construction Crew:		
WO User 39:	OUPS #:	
WO User 40:	WO User 48:	
WO User 41:		
WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	

Work Order Detail Report

7/28/2023

sso overflow inspection 7-28-2023 1.23"

2:05 PM

WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 7/28/2023	PM Trigger:	Rec #: 13912