

CITY OF
CLEVELAND
HEIGHTS
LAW DEPARTMENT

November 13, 2023

Via E-Mail: vezner.kris@epa.gov and Berger.Jake@epa.gov

Kris P. Vezner, Esq.
Associate Regional Counsel
U.S. Environmental Protection Agency
Region 5 (C-14J)
77 West Jackson Blvd.
Chicago, IL 60604

and

Jake Berger
Physical Scientist
Water Enforcement & Compliance Assurance Branch
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Mail Code ECW-15J
Chicago, IL 60604


Re: October 2023 Overflow Monitoring Reports
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through October 31, 2023, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,




William R. Hanna
Director of Law

Enclosures

Overflow Monitoring Update
November 13, 2023

cc: Thomas Benson, Esq., EPA Attorney
James Vinch, Esq., EPA Attorney
James Zimny, EPA Engineer
U.S. EPA Region 5 Water Enforcement Branch
Mark Klingenstein, Environmental Engineer
Erm Gomes, Ohio EPA
Allison Cycyk, Ohio EPA
Casey Galligan, Ohio EPA
David Brumbaugh, Ohio EPA
Bill Fischbein, Ohio EPA
Kahlil Seren, Mayor
Collette Clinkscale, Director of Public Works
Steve Barker, Public Relations
Anthony Ferrone, Utilities Commissioner
Kevin Vander Tuig, P.E. (Outside Engineer)
Mathew St. Pierre, (Outside Engineer)
Dan Porter (Outside Engineer)
Cindy Biacofsky (Outside Engineer)
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

Daily Precipitation Report
Thursday, October 5, 2023
Accumulation in Inches



Northeast Ohio Regional Sewer District **Daily Precipitation Report** Thursday, October 5, 2023

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.31	0.31	0.29	0.21	0.09	0.05
Brecksville	0.57	0.57	0.54	0.43	0.20	0.11
Brook Park	0.69	0.69	0.62	0.47	0.22	0.10
Cleveland Industrial Pkwy	0.74	0.74	0.67	0.52	0.27	0.13
Dille Ave PS	0.50	0.50	0.47	0.36	0.18	0.11
Division Ave PS	0.53	0.53	0.49	0.34	0.18	0.10
Easterly WWTP	0.49	0.49	0.44	0.31	0.12	0.05
Independence	0.55	0.55	0.50	0.38	0.27	0.16
James Rhodes HS	0.50	0.50	0.46	0.33	0.14	0.07
Jennings PS	0.58	0.58	0.54	0.42	0.22	0.14
Macedonia	0.29	0.29	0.27	0.25	0.10	0.04
Maple Heights	0.45	0.45	0.42	0.32	0.15	0.09
Mary Street PS	0.50	0.50	0.47	0.34	0.17	0.10
Mayfield Heights	0.27	0.27	0.25	0.17	0.07	0.04
Moreland Hills	0.31	0.31	0.30	0.29	0.14	0.06
North Olmsted	0.58	0.58	0.50	0.35	0.17	0.09
North Royalton	0.58	0.58	0.53	0.42	0.29	0.15
Oakwood	0.30	0.30	0.28	0.26	0.11	0.05
Olmsted Falls	0.61	0.61	0.55	0.41	0.18	0.07
Parma	0.44	0.44	0.41	0.29	0.13	0.07
Richfield	0.53	0.53	0.51	0.45	0.23	0.16
Shaker Heights	0.50	0.50	0.47	0.37	0.22	0.16
South Euclid	0.47	0.47	0.45	0.32	0.20	0.15
Southerly WWTC	0.46	0.46	0.43	0.31	0.17	0.07
Strongsville C WWTP	0.70	0.70	0.65	0.50	0.24	0.11
Strongsville Foltz	0.61	0.61	0.57	0.44	0.21	0.09
University Heights	0.53	0.53	0.50	0.38	0.24	0.16
Wade Park	0.48	0.48	0.45	0.33	0.13	0.06
Westerly WWTP	0.53	0.53	0.49	0.35	0.18	0.08
Westlake	0.69	0.68	0.62	0.46	0.29	0.11

Work Order Detail Report

10/13/2023

SSO INSPECTIONS 10-5-2023 0.53 INCHES OF RAIN

11:29 AM

WO Number: 231009-0005	Category: SSOs
Status: Complete	Problem: Storm Response
Status Date: 10/13/2023 11:28 am	Main Task: Inspection
Asset: SSO 431	
Location: FAIRFAX AT NORTH PARK	
Cause: Weather	Assigned By:
Assigned Crew:	Assigned Date:
Supervisor: Jackson, Jeff	Start Date: 10/9/2023 7:26 AM Override
Lead Worker: Manco, Angelo	End Date: 10/9/2023 2:26 PM Notifications
Priority: High	Problem ☐
Account #:	Overdue ☐
Proj No - Acct:	Lead Worker ☐
Project:	Task ☐
Reason:	Supervisor ☐
Received By:	Hard Lock WO ☐
Inspected By:	

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer
Sub-Division:
Area:
Sub-Area:
Owner:
Location:
Classification:
Maintenance Zone:

Alternate Zone:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Locations

<u>Address</u>	<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>
<u>General Location</u>	
FAIRFAX AT NORTH PARK	
2,220,655.65435414	665,517.24643672
NORTH PARK AND COVENTRY	Doan Brook
2,219,873.16674590	666,048.82312946
FAIRMOUNT SOUTH OF SCARBOROUGH	DOAN BROOK - MAIN BRANCH
2,220,364.86097248	666,446.72325230
FAIRMOUNT AT FAIRFAX	DOAN BROOK - MAIN BRANCH
2,220,920.81917815	666,080.57995571
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	DOAN BROOK - MAIN BRANCH
2,223,053.81655256	664,693.25202172
3012 NORTH WOODLAND	DOAN BROOK - MAIN BRANCH
2,222,845.06631389	664,689.08536339
	Doan Brook
2,226,440.21168265	664,329.55524255
2,226,354.79813956	664,409.89202413
2,226,389.92077273	664,379.07548472
FAIRMOUNT AT DARTMOOR	
2,225,149.97508989	664,453.31024438
FAIRMOUNT AT WELLINGTON	DOAN BROOK - MAIN BRANCH
2,223,969.26550905	664,532.08075613
	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

10/13/2023

SSO INSPECTIONS 10-5-2023 0.53 INCHES OF RAIN

11:29 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

10/13/2023

SSO INSPECTIONS 10-5-2023 0.53 INCHES OF RAIN

11:29 AM

2,224,536.21778722	668,887.44048372
2,226,741.35609348	679,432.95121680
2,226,591.76420106	679,420.92761880
2,227,825.14395215	684,881.15948047

Work Order Detail Report

10/13/2023

SSO INSPECTIONS 10-5-2023 0.53 INCHES OF RAIN

11:29 AM

Work Order Assets

Object Type	Description 1		Description 2				
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve					FAIRFAX AT NORTH PARK		
SSO 431						26	
Sewer Control Valve					NORTH PARK AND COVENTRY		
SSO 114						16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Control Valve					3012 NORTH WOODLAND		
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO		
SSO 116						4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY		
SSO 124						47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON		
CH-50						53	
Sewer Control Valve					BRADFORD AND LEE		
SSO 129						11	
Sewer Control Valve					EDDINGTON		
CH-52						2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL		
SSO 122						36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		

Work Order Detail Report

10/13/2023

SSO INSPECTIONS 10-5-2023 0.53 INCHES OF RAIN

11:29 AM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

10/13/2023

SSO INSPECTIONS 10-5-2023 0.53 INCHES OF RAIN

11:29 AM

Check List				
	Item	Completed	Condition	Completion Date/Time
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Not Sound	10/9/2023/
Reset block				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	10/9/2023/
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	10/9/2023/
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	10/9/2023/
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Sound	10/9/2023/
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	10/9/2023/
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	10/9/2023/
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Not Sound	10/9/2023/
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	10/9/2023/
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	10/9/2023/
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	10/9/2023/
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	10/9/2023/
13	A-1 3041 FAIRMOUNT SA16AAUTO (TREE LAWN NEAR SIDEWALK)	☐	Sound	10/9/2023/
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	10/9/2023/
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	10/9/2023/
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	10/9/2023/
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	10/9/2023/
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	10/9/2023/
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	10/9/2023/
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	10/9/2023/
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	10/9/2023/
22	A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	☐	Not Sound	10/9/2023/
Reset block				
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	10/9/2023/
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	10/9/2023/
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	10/9/2023/
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	10/9/2023/

Work Order Detail Report

10/13/2023

SSO INSPECTIONS 10-5-2023 0.53 INCHES OF RAIN

11:29 AM

27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	10/9/2023/
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Not Sound	10/9/2023/
Reset block				
29	B-42 12537 CEDAR SA16ACZA0	☐		10/9/2023/
Not on list				
30	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	10/9/2023/
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	10/9/2023/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	10/9/2023/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	10/9/2023/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐		10/9/2023/
Not on list				
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐		10/9/2023/
Not on list				
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐		10/9/2023/
Not on list				
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐		10/9/2023/
Not on list				
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Sound	10/9/2023/
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Sound	10/9/2023/
40	C-59 3427 THORNE RD SA16AQD0	☐	Sound	10/9/2023/
41	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	10/9/2023/
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	10/9/2023/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	10/9/2023/
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Not Sound	10/9/2023/
Reset block				
45	C-50 3593 FENLEY SA16APEH0	☐	Sound	10/9/2023/

Tasks/Resources

SMCT36 Inspection

Crew:

Status:

*Cal'c UC: \$17.47

*Task Cost: \$663.76

Start Dt: 10/9/2023

Supervisor:

UOM: Each

of Units: 38.00

*Unit Cost: \$0.00

End Dt: 10/9/2023

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
19356 Manco, Angelo	Hours	8.00	\$217.84		10/9/2023	10/9/2023
22394 Cardarella, Joe	Hours	8.00	\$197.52		10/9/2023	10/9/2023

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	8.00	\$107.20		10/9/2023	10/9/2023
CHFLT55 FORD 350 CREW CAB 9	Hours	8.00	\$141.20		10/9/2023	10/9/2023

Task Comment: SSO INSPECTIONS 10-9-2023 0.53 INCHES OF RAIN

Work Order Detail Report

10/13/2023

SSO INSPECTIONS 10-5-2023 0.53 INCHES OF RAIN

11:29 AM

			<u>*Actual</u>	<u>*Estimated</u>	<u>*Difference</u>
Projected Complete:		Lock: ☐	WO Duration	7.00	0.00
Repair Type:			Labor Hours	16.00	0.00
Subcontractor:			Labor Costs	\$415.36	\$0.00
Profit Center:			Material Costs	0.00	0.00
			Fluids Costs	0.00	0.00
Quantity:	0.00	Lock: ☐	Equipment Costs	248.40	0.00
Unit of Measure:	Each		Contractor Costs	0.00	0.00
*Unit Cost:	\$0.00		Misc. Costs	0.00	0.00
WO Hours:	0.00		Total Costs	\$663.76	\$0.00
			Use Task Info:	True	True

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	Cell #:
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	Billing Required: ☐
Invoice Number:		Date Bill Sent:	Billing Processed: ☐
Incoming Account #:		Payment Received:	Imported to Financials: ☐
		Payment Method:	

Associated PMs		
PM Code and Description		Closed
SSO-02 SSO INSPECTION		☒

Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	aferrone	10/9/2023	12:09 PM
Supervisor Notification	Email Queued Successfully!	aferrone	10/9/2023	12:09 PM
Leadworker Notification	Email Queued Successfully!	aferrone	10/9/2023	12:09 PM
Status Change	From New Work Order to Closed In Field	amanco	10/9/2023	3:09 PM
Status Change	From Closed In Field to Complete	aferrone	10/13/2023	11:28 AM

Rate:	Opened At:	Televised: ☐
Recieved By:	Pipe Footage Cleaned	Power Rooter: ☐
Work From:	Gallons Used:	Jet: ☐
Pipe Size:	WO User 23:	Gap Vac: ☐
Pipe Condition:	WO User 24:	Dye Test: ☐
Could Not Open:	WO User 9:	Gap Root Cut: ☐
Additional Repair:	User 10:	GIS Correction?: ☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: ☐
Test Performed Throug	Appointment Date:	
Dye Test Results:		
WO User 51:		
Measurement:	E Mail:	
History:	Measurement Line 2:	

Work Order Detail Report

10/13/2023

SSO INSPECTIONS 10-5-2023 0.53 INCHES OF RAIN

11:29 AM


Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Slec		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:			
WO User 40:	OUPS #:		
WO User 41:	WO User 48:		
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	☐
WO User 73:	Quantity:	Paid:	☐
WO User 74:	WO User 84:	WO User 104:	☐
WO User 75:	WO User 85:	WO User 105:	☐
WO User 76:	WO User 86:	WO User 106:	☐
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	☐
WO User 78:	WO User 88:	WO User 108:	☐
WO User 79:	WO User 89:	WO User 109:	☐
WO User 80:	WO User 90:	WO User 110:	☐
WO User 81:	WO User 91:	WO User 111:	☐
WO Creator: aferrone	WO Creation Date: 10/9/2023	PM Trigger:	Rec #: 15106

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Sunday, October 15, 2023

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Sunday, October 15, 2023

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.38	0.31	0.23	0.11	0.04	0.02
Brecksville	0.45	0.36	0.29	0.15	0.05	0.03
Brook Park	0.49	0.44	0.30	0.14	0.05	0.03
Cleveland Industrial Pkwy	0.31	0.30	0.21	0.09	0.05	0.04
Dille Ave PS	0.14	0.11	0.09	0.05	0.02	0.02
Division Ave PS	0.14	0.11	0.07	0.05	0.03	0.03
Easterly WWTP	0.12	0.07	0.06	0.06	0.06	0.04
Independence	0.36	0.30	0.22	0.10	0.06	0.03
James Rhodes HS	0.30	0.29	0.23	0.12	0.06	0.05
Jennings PS	0.29	0.25	0.19	0.12	0.06	0.06
Macedonia	0.31	0.19	0.13	0.07	0.05	0.02
Maple Heights	0.42	0.30	0.22	0.13	0.05	0.03
Mary Street PS	0.17	0.13	0.10	0.04	0.02	0.02
Mayfield Heights	0.30	0.30	0.22	0.11	0.05	0.03
Moreland Hills	0.50	0.35	0.19	0.09	0.08	0.06
North Olmsted	0.39	0.36	0.25	0.13	0.05	0.03
North Royalton	0.38	0.37	0.26	0.10	0.04	0.02
Oakwood	0.39	0.24	0.17	0.09	0.06	0.04
Olmsted Falls	0.42	0.40	0.27	0.14	0.07	0.04
Parma	0.36	0.35	0.25	0.10	0.04	0.03
Richfield	0.35	0.22	0.14	0.09	0.04	0.04
Shaker Heights	0.45	0.29	0.24	0.13	0.07	0.04
South Euclid	0.19	0.17	0.15	0.10	0.06	0.03
Southerly WWTC	0.23	0.21	0.15	0.07	0.03	0.02
Strongsville C WWTP	0.63	0.48	0.33	0.17	0.06	0.04
Strongsville Foltz	0.34	0.26	0.18	0.07	0.04	0.02
University Heights	0.34	0.27	0.24	0.15	0.08	0.05
Wade Park	0.12	0.08	0.07	0.04	0.03	0.03
Westerly WWTP	0.07	0.05	0.03	0.03	0.02	0.02
Westlake	0.24	0.22	0.16	0.08	0.03	0.02

WO Number: 231017-0001		Category:	SSOs	
Status:	Complete	Problem:	Storm Response	
Status Date:	10/17/2023 3:15 pm	Main Task:	Inspection	
Asset: SSO 431				
Location: FAIRFAX AT NORTH PARK				
Cause:	Weather		Assigned By:	
Assigned Crew:			Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	10/17/2023 8:00 AM	<u>Override</u>
Lead Worker:	Manco, Angelo	End Date:	10/17/2023 2:30 PM	<u>Notifications</u>
Priority:	High			
Account #:			Problem ☐	
Proj No - Acct:			Overdue ☐	
Project:			Lead Worker ☐	
Reason:			Task ☐	
Received By:			Supervisor ☐	
Inspected By:			Hard Lock WO ☐	
Project ID:				
Project Name:				

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location		Comments for Crew Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.
Department:	Sewer Collection	
Division:	Sewer	
Sub-Division:		
Area:		
Sub-Area:		
Owner:		
Location:		
Classification:		
Maintenance Zone:	Alternate Zone:	

Work Order Locations			Address 2
Address			
X Coord	Y Coord	General Location	
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672	Doan Brook	
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339	Doan Brook	
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT MARLBORO			
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH	

Work Order Detail Report

10/17/2023

iso inspections 10-15-2023 0.34'

3:17 PM

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564 666,181.72575080		
2,218,501.67473823 671,997.54581206		
2,216,759.55453481 670,474.59347738		
2,224,536.21778722 668,887.44048372		
2,226,741.35609348 679,432.95121680		
2,226,591.76420106 679,420.92761880		

Work Order Detail Report

10/17/2023

also inspections 10-15-2023 0.34'

3:17 PM

2,227,825.14395215	684,881.15948047
--------------------	------------------

Work Order Detail Report

10/17/2023

iso inspections 10-15-2023 0.34'

3:17 PM

Work Order Assets

Object Type		Description 1			Description 2		
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve					FAIRFAX AT NORTH PARK		
SSO 431						26	
Sewer Control Valve					NORTH PARK AND COVENTRY		
SSO 114						16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Control Valve					3012 NORTH WOODLAND		
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO		
SSO 116						4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY		
SSO 124						47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON		
CH-50						53	
Sewer Control Valve					BRADFORD AND LEE		
SSO 129						11	
Sewer Control Valve					EDDINGTON		
CH-52						2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL		
SSO 122						36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103						19	
Sewer Control Valve					3003 EUCLID HEIGHTS BLVD		
SSO 104						15	

Work Order Detail Report

10/17/2023

so inspections 10-15-2023 0.34'

3:17 PM

Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

10/17/2023

iso inspections 10-15-2023 0.34'

3:17 PM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	10/17/2023/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	10/17/2023/	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	10/17/2023/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	10/17/2023/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Not Sound	10/17/2023/	
Construction in area					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	10/17/2023/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	10/17/2023/	
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	10/17/2023/	
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	10/17/2023/	
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Not Sound	10/17/2023/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	10/17/2023/	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	10/17/2023/	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	10/17/2023/	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	10/17/2023/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	10/17/2023/	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	10/17/2023/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	10/17/2023/	
Manhole cover needs painted for SSO					
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	10/17/2023/	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	10/17/2023/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	10/17/2023/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	10/17/2023/	
22	A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	☐	Not Sound	10/17/2023/	
Metered manhole					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	10/17/2023/	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	10/17/2023/	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Not Sound	10/17/2023/	
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	10/17/2023/	
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	10/17/2023/	

Work Order Detail Report

10/17/2023

sso inspections 10-15-2023 0.34'

3:17 PM

28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	10/17/2023/
29	B-42 12537 CEDAR SA16ACZA0	☐	Not Sound	10/17/2023/
30	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	10/17/2023/
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	10/17/2023/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	10/17/2023/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	10/17/2023/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐		10/17/2023/
Block missing				
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐		10/17/2023/
No Block / new construction				
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐		10/17/2023/
New construction / no block				
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Not Sound	10/17/2023/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Sound	10/17/2023/
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Sound	10/17/2023/
40	C-59 3427 THORNE RD SA16AQQD0	☐	Sound	10/17/2023/
41	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	10/17/2023/
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	10/17/2023/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	10/17/2023/
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	10/17/2023/
45	C-50 3593 FENLEY SA16APEH0	☐	Sound	10/17/2023/

Tasks/Resources

SWCT26 Inspection

Crew:	Status:	*Cal'c UC: \$12.09	*Task Cost: \$544.25	Start Dt: 10/17/2023
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 10/17/2023

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
19356 Manco, Angelo	Hours	5.00	\$136.15		10/17/2023	10/17/2023
11213 Owens, Will	Hours	5.00	\$129.40		10/17/2023	10/17/2023
13859 Moten, Robert	Hours	5.00	\$123.45		10/17/2023	10/17/2023

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD 350 CREW CAB 9	Hours	5.00	\$88.25		10/17/2023	10/17/2023
CHFLT50 FORD F250 CREW CAB 5	Hours	5.00	\$67.00		10/17/2023	10/17/2023

Task Comment: sso overflow inspection 10-15-2023 0.34'

Work Order Detail Report

10/17/2023

so inspections 10-15-2023 0.34'

3:17 PM

			<u>*Actual</u>	<u>*Estimated</u>	<u>*Difference</u>
Projected Complete:	Lock: ☐	WO Duration	6.50	0.00	0.00
Repair Type:		Labor Hours	15.00	0.00	0.00
Subcontractor:		Labor Costs	\$389.00	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity: 0.00	Lock: ☐	Equipment Costs	155.25	0.00	0.00
Unit of Measure: Each		Contractor Costs	0.00	0.00	0.00
Unit Cost: \$0.00		Misc. Costs	0.00	0.00	0.00
WO Hours: 0.00		Total Costs	\$544.25	\$0.00	\$0.00
		Use Task Info:	True	True	

Billing		
Billed Party		
Customer ID:	Customer Number:	
Customer Name:	Last Name:	
Address:		
City:	Phone: Cell #:	
State:	Fax #:	
Zip:	E-mail:	
Billing Data		
Contact Name:	*Billing Amount:	Billing Required: ☐
Invoice Number:	Date Bill Sent:	Billing Processed: ☐
Incoming Account #:	Payment Received:	Imported to Financials: ☐
	Payment Method:	

Associated PMs

PM Code and Description	Closed
SSO-02 SSO INSPECTION	☒

Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	10/17/2023	7:45 AM
Supervisor Notification	Email Queued Successfully!	jjackson	10/17/2023	7:45 AM
Leadworker Notification	Email Queued Successfully!	jjackson	10/17/2023	7:46 AM
Status Change	From New Work Order to Closed In Field	amanco	10/17/2023	2:26 PM
Status Change	From Closed In Field to Complete	jjackson	10/17/2023	3:15 PM

Rate:	Opened At:	Televised: ☐
Received By:	Pipe Footage Cleaned:	Power Rooter: ☐
Work From:	Gallons Used:	Jet: ☐
Pipe Size:	WO User 23:	Gap Vac: ☐
Pipe Condition:	WO User 24:	Dye Test: ☐
Could Not Open:	WO User 9:	Gap Root Cut: ☐
Additional Repair:	User 10:	GIS Correction?: ☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: ☐
Test Performed Throug	Appointment Date: 10/17/2023 8:00 AM	
Dye Test Results:		
WO User 51:		
Measurement:	E Mail:	
History:	Measurement Line 2:	
Manhole Basin Repair:	Pipe Size:	
Material Used:	PVC Tees, Angles, Slee	
Pipe Repair:	WO User 44:	
Street Repair:	WO User 45:	
Grass Repair:	WO User 46:	
Curb Repair:		
Driveway- Sidewalk Re		
Construction Crew:		
WO User 39:		
WO User 40:	OUPS #:	
WO User 41:	WO User 48:	

Work Order Detail Report

10/17/2023

so inspections 10-15-2023 0.34'

3:17 PM


NO User 52:	WO User 62:		
NO User 53:	WO User 63:		
NO User 54:	WO User 64:		
NO User 55:	WO User 65:		
NO User 56:	WO User 66:		
NO User 57:	WO User 67:		
NO User 58:	WO User 68:		
NO User 59:	WO User 69:		
NO User 60:	WO User 70:		
NO User 61:	WO User 71:		
NO User 72:	WO User 82:	Televised:	☐
NO User 73:	Quantity:	Paid:	☐
NO User 74:	WO User 84:	WO User 104:	☐
NO User 75:	WO User 85:	WO User 105:	☐
NO User 76:	WO User 86:	WO User 106:	☐
NO User 92 Date:	WO User 97 Date:		
NO User 93 Date:	WO User 98 Date:		
NO User 94 Date:	WO User 99 Date:		
NO User 95 Date:	WO User 100 Date:		
NO User 96 Date:	WO User 101 Date:		
NO User 77:	WO User 87:	WO User 107:	☐
NO User 78:	WO User 88:	WO User 108:	☐
NO User 79:	WO User 89:	WO User 109:	☐
NO User 80:	WO User 90:	WO User 110:	☐
NO User 81:	WO User 91:	WO User 111:	☐
NO Creator: jjackson	WO Creation Date: 10/17/2023	PM Trigger:	Rec #: 15125

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Thursday, October 19, 2023

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Thursday, October 19, 2023

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.54	0.54	0.46	0.36	0.15	0.08
Brecksville	0.62	0.62	0.53	0.27	0.20	0.12
Brook Park	0.35	0.35	0.21	0.13	0.06	0.03
Cleveland Industrial Pkwy	0.37	0.37	0.24	0.15	0.06	0.04
Dille Ave PS	0.29	0.29	0.18	0.12	0.05	0.03
Division Ave PS	0.38	0.38	0.25	0.14	0.06	0.03
Easterly WWTP	0.26	0.26	0.17	0.10	0.04	0.02
Independence	0.60	0.60	0.50	0.47	0.22	0.10
James Rhodes HS	0.36	0.36	0.22	0.14	0.05	0.03
Jennings PS	0.34	0.34	0.21	0.14	0.05	0.03
Macedonia	0.25	0.25	0.20	0.12	0.06	0.05
Maple Heights	0.49	0.49	0.42	0.39	0.19	0.10
Mary Street PS	0.33	0.33	0.21	0.12	0.05	0.03
Mayfield Heights	0.50	0.49	0.40	0.30	0.13	0.07
Moreland Hills	0.34	0.34	0.28	0.15	0.08	0.05
North Olmsted	0.24	0.24	0.18	0.11	0.05	0.03
North Royalton	0.68	0.68	0.58	0.55	0.25	0.13
Oakwood	0.31	0.31	0.26	0.14	0.06	0.04
Olmsted Falls	0.28	0.28	0.17	0.12	0.04	0.02
Parma	0.57	0.57	0.43	0.36	0.16	0.07
Richfield	0.34	0.34	0.26	0.17	0.11	0.09
Shaker Heights	0.61	0.61	0.53	0.42	0.20	0.10
South Euclid	0.47	0.47	0.34	0.27	0.10	0.06
Southerly WWTC	0.62	0.62	0.52	0.46	0.21	0.10
Strongsville C WWTP	0.54	0.54	0.37	0.25	0.12	0.06
Strongsville Foltz	0.59	0.59	0.44	0.30	0.15	0.07
University Heights	0.76	0.76	0.65	0.55	0.20	0.09
Wade Park	0.29	0.29	0.19	0.12	0.06	0.04
Westerly WWTP	0.29	0.29	0.19	0.13	0.06	0.04
Westlake	0.17	0.17	0.14	0.09	0.04	0.02

WO Number: 231023-0001	Category: SSOs
Status: New Work Order	Problem: Storm Response
Status Date: 10/23/2023 7:53 am	Main Task: Inspection
Asset: SSO 431	
Location: FAIRFAX AT NORTH PARK	
Cause: Weather	Assigned By:
Assigned Crew:	Assigned Date:
Supervisor: Jackson, Jeff	Start Date: 10/20/2023 8:00 AM
Lead Worker: Cardarella, Joe	End Date: 10/20/2023 1:00 PM
Priority: High	Override
Account #:	Notifications
Proj No - Acct:	Problem ☐
Project:	Overdue ☐
Reason:	Lead Worker ☐
Received By:	Task ☐
Inspected By:	Supervisor ☐
	Hard Lock WO ☐
	Project ID:
	Project Name:

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location	
Department: Sewer Collection	Comments for Crew Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.
Division: Sewer	
Sub-Division:	
Area:	
Sub-Area:	
Owner:	
Location:	
Classification:	
Maintenance Zone:	Alternate Zone:

Work Order Locations			Address 2
Address			
X Coord	Y Coord	General Location	
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672	Doan Brook	
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339	Doan Brook	
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT MARLBORO			
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH	

Work Order Detail Report

10/24/2023

so overflow inspections 10-19-2023 0.76'

12:02 PM

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

10/24/2023

also overflow inspections 10-19-2023 0.76'

12:02 PM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

10/24/2023

so overflow inspections 10-19-2023 0.76'

12:02 PM

Work Order Assets

<u>Object Type</u>	<u>Description 1</u>			<u>Description 2</u>		<u>Asset ID</u>	<u>Completed</u>
	<u>System ID 1</u>	<u>System ID 2</u>	<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>	
Sewer Control Valve						FAIRFAX AT NORTH PARK	
SSO 431						26	
Sewer Control Valve						NORTH PARK AND COVENTRY	
SSO 114						16	
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH	
SSO 121						35	
Sewer Structure						3094	
SA16AAWB0							
Sewer Control Valve						FAIRMOUNT AT FAIRFAX	
SSO 112						7	
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	
SSO 99						6	
Sewer Control Valve						3012 NORTH WOODLAND	
SSO 432						14	
Sewer Control Valve						55	
DB-03							
Sewer Control Valve						56	
DB-01							
Sewer Control Valve						57	
DB-02							
Sewer Control Valve						FAIRMOUNT AT DARTMOOR	
CH-04						5	
Sewer Control Valve						FAIRMOUNT AT WELLINGTON	
SSO 110						44	
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	
SSO 87						33	
Sewer Control Valve						FAIRMOUNT AT MARLBORO	
SSO 116						4	
Sewer Control Valve						FAIRMOUNT AT ARLINGTON	
SSO 111						46	
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)	
SSO 113						37	
Sewer Control Valve						FAIRMOUNT AND COVENTRY	
SSO 124						47	
Sewer Control Valve						SCARBOROUGH AT LAMBERTON	
CH-50						53	
Sewer Control Valve						BRADFORD AND LEE	
SSO 129						11	
Sewer Control Valve						EDDINGTON	
CH-52						2	
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")	
SSO 88						42	
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL	
SSO 122						36	
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")	
SSO 89						34	
Sewer Structure						1536	
SA16ADZB0							
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.	
SSO 91						20	
Sewer Structure						4446	
SA16ADPH0							
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON	
SSO 120						8	
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY	
SSO 103						19	
Sewer Control Valve						3003 EUCLID HEIGHTS BLVD	
SSO 104						15	

Work Order Detail Report

10/24/2023

so overflow inspections 10-19-2023 0.76'

12:02 PM

Sewer Structure	3402
SA16AGMG0	
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

10/24/2023

iso overflow inspections 10-19-2023 0.76'

12:02 PM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Not Sound	10/23/2023/10:22 am	10/23/2023
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	10/23/2023/10:25 pm	10/23/2023
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	10/23/2023/10:01 am	10/23/2023
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	10/23/2023/10:06 am	10/23/2023
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Not Sound	10/23/2023/10:14 am	10/23/2023
Reset					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	10/23/2023/10:33 am	10/23/2023
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	10/23/2023/ 9:25 am	10/23/2023
8	A-6 FAIRMOUNT AT SHELburne ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	10/23/2023/ 8:56 am	10/23/2023
9	A-5 FAIRMOUNT AT SHELburne SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	10/23/2023/ 8:52 am	10/23/2023
10	A-7 FAIRMOUNT AT SHELburne SA16AAVH0 (EAST BOUND)	☐	Sound	10/23/2023/ 8:45 am	10/23/2023
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	10/23/2023/ 8:40 am	10/23/2023
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	10/23/2023/ 9:20 am	10/23/2023
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	10/23/2023/10:38 am	10/23/2023
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	10/23/2023/ 9:35 am	10/23/2023
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	10/23/2023/ 9:40 am	10/23/2023
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	10/23/2023/ 9:45 am	10/23/2023
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	10/23/2023/ 9:50 am	10/23/2023
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	10/23/2023/ 9:56 am	10/23/2023
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	10/23/2023/ 9:12 am	10/23/2023
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	10/23/2023/ 8:25 am	10/23/2023
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	10/23/2023/ 8:30 am	10/23/2023
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Not Sound	10/23/2023/ 8:20 am	10/23/2023
Reset					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Not Sound	10/23/2023/ 3:12 pm	10/23/2023
Reset					
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	10/23/2023/ 3:14 pm	10/23/2023
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	10/23/2023/ 3:14 pm	10/23/2023
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	10/23/2023/ 3:14 pm	10/23/2023
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	10/23/2023/ 3:14 pm	10/23/2023

Work Order Detail Report

10/24/2023

iso overflow inspections 10-19-2023 0.76'

12:02 PM

28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	10/23/2023/ 3:15 pm	10/23/2023
29	B-42 12537 CEDAR SA16ACZA0	☐	Sound	10/23/2023/ 3:15 pm	10/23/2023
30	B-15 COVENTRY AND CEDAR SA16ADBHO	☐	Sound	10/23/2023/ 3:15 pm	10/23/2023
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	10/23/2023/ 3:13 pm	10/23/2023
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Not Sound	10/23/2023/ 3:13 pm	10/23/2023
Reset					
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	/ 3:13 pm	10/23/2023
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Not Sound	10/23/2023/ 3:06 pm	10/23/2023
Wood block needs repair					
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Not Sound	10/23/2023/ 3:06 pm	10/23/2023
Needs to be restrung					
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Sound	10/23/2023/ 3:07 pm	10/23/2023
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Not Sound	10/23/2023/ 3:07 pm	10/23/2023
Reset					
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Not Sound	10/23/2023/ 3:09 pm	10/23/2023
Construction					
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Not Sound	10/23/2023/ 3:09 pm	10/23/2023
Reset					
40	C-59 3427 THORNE RD SA16AQQD0	☐	Sound	10/23/2023/ 3:10 pm	10/23/2023
41	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	10/23/2023/ 3:10 pm	10/23/2023
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	10/23/2023/ 3:10 pm	10/23/2023
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Not Sound	10/23/2023/ 3:11 pm	10/23/2023
Reset					
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	10/23/2023/ 3:11 pm	10/23/2023
45	C-50 3593 FENLEY SA16APEH0	☐	Sound	10/23/2023/ 3:11 pm	10/23/2023

Tasks/Resources						
SMCT36 Inspection						
Crew:		Status:	*Cal'c UC: \$8.60	*Task Cost: \$386.85	Start Dt: 10/20/2023	
Supervisor:		UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 10/20/2023	
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	5.00	\$123.45		10/20/2023	10/20/2023
40151 Mc Coy, Sam	Hours	5.00	\$129.40		10/20/2023	10/20/2023
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	5.00	\$67.00		10/20/2023	10/20/2023
CHFLT55 FORD F250 PICK UP 0	Hours	5.00	\$67.00		10/20/2023	10/20/2023
Task Comment: sso overflow inspections 10-19-2023 0.76'						

Work Order Detail Report

10/24/2023

iso overflow inspections 10-19-2023 0.76'

12:02 PM

			<u>*Actual</u>	<u>*Estimated</u>	<u>*Difference</u>
Projected Complete:	Lock: ☐	WO Duration	5.00	0.00	0.00
Repair Type:		Labor Hours	10.00	0.00	0.00
Subcontractor:		Labor Costs	\$252.85	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity: 0.00	Lock: ☐	Equipment Costs	134.00	0.00	0.00
Unit of Measure: Each		Contractor Costs	0.00	0.00	0.00
Unit Cost: \$0.00		Misc. Costs	0.00	0.00	0.00
WO Hours: 0.00		Total Costs	\$386.85	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	Cell #:
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	Billing Required: ☐
Invoice Number:		Date Bill Sent:	Billing Processed: ☐
Incoming Account #:		Payment Received:	Imported to Financials: ☐
		Payment Method:	

Associated PMs	
PM Code and Description	Closed
SSO-02 SSO INSPECTION	☒

Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO	jjackson	10/23/2023	7:53 AM
Supervisor Notification	INSPECTION Email Queued Successfully!	jjackson	10/23/2023	7:53 AM

Rate:	Opened At:	Televised: ☐
Received By:	Pipe Footage Cleaned:	Power Rooter: ☐
Work From:	Gallons Used:	Jet: ☐
Pipe Size:	WO User 23:	Gap Vac: ☐
Pipe Condition:	WO User 24:	Dye Test: ☐
Could Not Open:	WO User 9:	Gap Root Cut: ☐
Additional Repair:	User 10:	GIS Correction?: ☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: ☐
Test Performed Throug	Appointment Date: 10/23/2023 8:00 AM	
Dye Test Results:		
WO User 51:	E Mail:	
Measurement:	Measurement Line 2:	
History:	Pipe Size:	
Manhole Basin Repair:	PVC Tees, Angles, Sler	
Material Used:	WO User 44:	
Pipe Repair:	WO User 45:	
Street Repair:	WO User 46:	
Grass Repair:		
Curb Repair:		
Driveway- Sidewalk Re		
Construction Crew:		
WO User 39:		
WO User 40:	OUPS #:	
WO User 41:	WO User 48:	

Work Order Detail Report

10/24/2023

also overflow inspections 10-19-2023 0.76'

12:02 PM

NO User 52:	WO User 62:		
NO User 53:	WO User 63:		
NO User 54:	WO User 64:		
NO User 55:	WO User 65:		
NO User 56:	WO User 66:		
NO User 57:	WO User 67:		
NO User 58:	WO User 68:		
NO User 59:	WO User 69:		
NO User 60:	WO User 70:		
NO User 61:	WO User 71:		
NO User 72:	WO User 82:	Televised:	☐
NO User 73:	Quantity:	Paid:	☐
NO User 74:	WO User 84:	WO User 104:	☐
NO User 75:	WO User 85:	WO User 105:	☐
NO User 76:	WO User 86:	WO User 106:	☐
NO User 92 Date:	WO User 97 Date:		
NO User 93 Date:	WO User 98 Date:		
NO User 94 Date:	WO User 99 Date:		
NO User 95 Date:	WO User 100 Date:		
NO User 96 Date:	WO User 101 Date:		
NO User 77:	WO User 87:	WO User 107:	☐
NO User 78:	WO User 88:	WO User 108:	☐
NO User 79:	WO User 89:	WO User 109:	☐
NO User 80:	WO User 90:	WO User 110:	☐
NO User 81:	WO User 91:	WO User 111:	☐
NO Creator: jjackson	WO Creation Date: 10/23/2023	PM Trigger:	Rec #: 15137

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Monday, October 30, 2023

Accumulation in Inches

L a k e E r i e

L a k e
C o u n t y

Easterly
WWTP 0.31

South
Euclid 0.46

Mayfield
Heights 0.49

Westerly
WWTP 0.31

Wade
Park 0.47

University
Heights 0.53

Division PS 0.38

Dille PS 0.39

Beachwood 0.53

Mary
Street PS 0.47

Shaker
Heights 0.52

Moreland
Hills 0.46

Jennings PS 0.48

Cleveland
Industrial Pkwy 0.49

James
Rhodes HS 0.50

Southerly
WWTC 0.51

Maple
Heights 0.53

North
Olmsted 0.42

Brook Park 0.40

Parma 0.44

Independence 0.46

Oakwood 0.45

Olmsted
Falls 0.35

Strongsville
"C" WWTP 0.38

L o r a i n
C o u n t y

C u y a h o g a
C o u n t y

Strongsville

North
Royalton 0.33

Brecksville 0.38

Macedonia 0.45

Foltz 0.29

M e d i n a C o u n t y

Richfield 0.24

S u m m i t
C o u n t y

Northeast Ohio Regional Sewer District

Daily Precipitation Report

Monday, October 30, 2023

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.53	0.27	0.19	0.12	0.06
Brecksville	0.38	0.25	0.16	0.12	0.05
Brook Park	0.40	0.27	0.18	0.10	0.04
Cleveland Industrial Pkwy	0.49	0.31	0.22	0.12	0.05
Dille Ave PS	0.39	0.27	0.19	0.10	0.05
Division Ave PS	0.38	0.28	0.21	0.12	0.05
Easterly WWTP	0.31	0.24	0.19	0.12	0.05
Independence	0.46	0.28	0.16	0.10	0.05
James Rhodes HS	0.50	0.29	0.19	0.11	0.05
Jennings PS	0.48	0.30	0.20	0.11	0.05
Macedonia	0.45	0.21	0.18	0.12	0.06
Maple Heights	0.53	0.26	0.18	0.11	0.05
Mary Street PS	0.47	0.29	0.21	0.11	0.05
Mayfield Heights	0.49	0.29	0.20	0.13	0.06
Moreland Hills	0.46	0.23	0.16	0.11	0.05
North Olmsted	0.42	0.30	0.22	0.13	0.06
North Royalton	0.33	0.25	0.15	0.10	0.05
Oakwood	0.45	0.21	0.17	0.12	0.06
Olmsted Falls	0.35	0.27	0.20	0.12	0.05
Parma	0.44	0.30	0.19	0.11	0.05
Richfield	0.24	0.21	0.16	0.11	0.04
Shaker Heights	0.52	0.30	0.18	0.12	0.05
South Euclid	0.46	0.31	0.19	0.10	0.05
Southerly WWTC	0.51	0.30	0.18	0.11	0.05
Strongsville C WWTP	0.38	0.28	0.18	0.10	0.04
Strongsville Foltz	0.29	0.23	0.16	0.10	0.04
University Heights	0.53	0.32	0.18	0.11	0.06
Wade Park	0.47	0.35	0.23	0.12	0.06
Westerly WWTP	0.31	0.28	0.21	0.12	0.05
Westlake	0.39	0.30	0.22	0.13	0.05

Work Order Detail Report

11/2/2023

so overflow inspections 10-30-2023 0.53

3:02 PM

WO Number: 231101-0002		Category: SSOs
Status: Complete	Problem: Storm Response	
Status Date: 11/2/2023 3:00 pm	Main Task: Inspection	
Asset: SSO 431		
Location: FAIRFAX AT NORTH PARK		
Cause: Weather	Assigned By:	
Assigned Crew:	Assigned Date:	
Supervisor: Jackson, Jeff	Start Date: 11/1/2023 8:00 AM	<u>Override</u>
Lead Worker: Eathridge, David	End Date: 11/1/2023 2:30 PM	<u>Notifications</u>
Priority: High		Problem ☐
Account #:		Overdue ☐
Proj No - Acct:	Project ID:	Lead Worker ☐
Project:	Project Name:	Task ☐
Reason:		Supervisor ☐
Received By:		Hard Lock WO ☐
Inspected By:		

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location		Comments for Crew
Department: Sewer Collection		Inspect all (45) SSO's when rainfall is one quarter (1/4")
Division: Sewer		inch or higher.
Sub-Division:		
Area:		
Sub-Area:		
Owner:		
Location:		
Classification:		
Maintenance Zone:	Alternate Zone:	

Work Order Locations

<u>Address</u>		<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265		664,329.55524255
2,226,354.79813956		664,409.89202413
2,226,389.92077273		664,379.07548472
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

11/2/2023

so overflow inspections 10-30-2023 0.53

3:02 PM

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

11/2/2023

so overflow inspections 10-30-2023 0.53

3:02 PM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

11/2/2023

so overflow inspections 10-30-2023 0.53

3:02 PM

Work Order Assets

Object Type		Description 1			Description 2		
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve					FAIRFAX AT NORTH PARK		
SSO 431						26	
Sewer Control Valve					NORTH PARK AND COVENTRY		
SSO 114						16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Control Valve					3012 NORTH WOODLAND		
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO		
SSO 116						4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY		
SSO 124						47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON		
CH-50						53	
Sewer Control Valve					BRADFORD AND LEE		
SSO 129						11	
Sewer Control Valve					EDDINGTON		
CH-52						2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL		
SSO 122						36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103						19	
Sewer Control Valve					3003 EUCLID HEIGHTS BLVD		
SSO 104						15	

Work Order Detail Report

11/2/2023

so overflow inspections 10-30-2023 0.53

3:02 PM

Sewer Structure	3402
SA16AGMG0	
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

11/2/2023

also overflow inspections 10-30-2023 0.53

3:02 PM

Check List

	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	11/1/2023/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Not Sound	11/1/2023/	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	11/1/2023/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	11/1/2023/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Sound	11/1/2023/	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	11/1/2023/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	11/1/2023/	
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Not Sound	11/1/2023/	
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	11/1/2023/	
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	11/1/2023/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	11/1/2023/	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	11/1/2023/	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Not Sound	11/1/2023/	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	11/1/2023/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	11/1/2023/	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	11/1/2023/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	11/1/2023/	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	11/1/2023/	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	11/1/2023/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	11/1/2023/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	11/1/2023/	
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Sound	11/1/2023/	
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	11/1/2023/	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	11/1/2023/	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	11/1/2023/	
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	11/1/2023/	
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	11/1/2023/	
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	11/1/2023/	
29	B-42 12537 CEDAR SA16ACZA0	☐	Sound	11/1/2023/	

Work Order Detail Report

11/2/2023

sso overflow inspections 10-30-2023 0.53

3:02 PM

30	B-15 COVENTRY AND CEDAR SA16ADB0	☐	Sound	11/1/2023/
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	11/1/2023/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	11/1/2023/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	11/1/2023/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	11/1/2023/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Sound	11/1/2023/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Sound	11/1/2023/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Sound	11/1/2023/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Sound	11/1/2023/
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Sound	11/1/2023/
40	C-59 3427 THORNE RD SA16AQQD0	☐	Sound	11/1/2023/
41	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	11/1/2023/
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	11/1/2023/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	11/1/2023/
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	11/1/2023/
45	C-50 3593 FENLEY SA16APEH0	☐	Sound	11/1/2023/

Tasks/Resources

SMCT36 Inspection

Crew:

Status:

*Cal'c UC: \$5.54

*Task Cost: \$249.52

Start Dt: 11/1/2023

Supervisor:

UOM: Each

of Units: 45.00

*Unit Cost: \$0.00

End Dt: 11/1/2023

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
12459 Eathridge, David	Hours	4.00	\$103.52		11/1/2023	11/1/2023
28056 Palmisano, Anthony	Hours	4.00	\$92.40		11/1/2023	11/1/2023

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT93 FORD F250 4 X 4 PICK UP	Hours	4.00	\$53.60		11/1/2023	11/1/2023

1

Task Comment: sso overflow inspection 10-30-2023 0.53

Projected Complete:

Lock: ☐

Repair Type:

Subcontractor:

Profit Center:

Quantity: 0.00

Lock: ☐

Unit of Measure: Each

Unit Cost: \$0.00

NO Hours: 0.00

	*Actual	*Estimated	*Difference
WO Duration	6.50	0.00	0.00
Labor Hours	8.00	0.00	0.00
Labor Costs	\$195.92	\$0.00	\$0.00
Material Costs	0.00	0.00	0.00
Fluids Costs	0.00	0.00	0.00
Equipment Costs	53.60	0.00	0.00
Contractor Costs	0.00	0.00	0.00
Misc. Costs	0.00	0.00	0.00
Total Costs	\$249.52	\$0.00	\$0.00
Use Task Info:	True	True	

Work Order Detail Report

11/2/2023

SSO overflow inspections 10-30-2023 0.53

3:02 PM

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:			
City:		Phone:	Cell #:
State:		Fax #:	
Zip:		E-mail:	

Billing Data		
Contact Name:	*Billing Amount:	Billing Required: ☐
Invoice Number:	Date Bill Sent:	Billing Processed: ☐
Incoming Account #:	Payment Received:	Imported to Financials: ☐
	Payment Method:	

Associated PMs

PM Code and Description	Closed
SSO-02 SSO INSPECTION	☒

Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	11/1/2023	12:09 PM
Supervisor Notification	Email Queued Successfully!	jjackson	11/1/2023	12:09 PM
Status Change	From New Work Order to Complete	jjackson	11/2/2023	3:00 PM

Rate:	Opened At:	Televised: ☐
Received By:	Pipe Footage Cleaned:	Power Rooter: ☐
Work From:	Gallons Used:	Jet: ☐
Pipe Size:	WO User 23:	Gap Vac: ☐
Pipe Condition:	WO User 24:	Dye Test: ☐
Could Not Open:	WO User 9:	Gap Root Cut: ☐
Additional Repair:	User 10:	GIS Correction?: ☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: ☐
Test Performed Through:	Appointment Date: 11/1/2023 8:00 AM	

NO User 51:	
Measurement:	E Mail:
History:	Measurement Line 2:
Manhole Basin Repair:	Pipe Size:
Material Used:	PVC Tees, Angles, Sleeves
Pipe Repair:	WO User 44:
Street Repair:	WO User 45:
Grass Repair:	WO User 46:
Curb Repair:	
Driveway - Sidewalk Repair:	
Construction Crew:	
NO User 39:	
NO User 40:	OUPS #:
NO User 41:	WO User 48:
NO User 52:	WO User 62:
NO User 53:	WO User 63:
NO User 54:	WO User 64:
NO User 55:	WO User 65:
NO User 56:	WO User 66:
NO User 57:	WO User 67:
NO User 58:	WO User 68:
NO User 59:	WO User 69:
NO User 60:	WO User 70:
NO User 61:	WO User 71:

Work Order Detail Report

11/2/2023

ssso overflow inspections 10-30-2023 0.53

3:02 PM

NO User 72:	WO User 82:	Televised:	☐
NO User 73:	Quantity:	Paid:	☐
NO User 74:	WO User 84:	WO User 104:	☐
NO User 75:	WO User 85:	WO User 105:	☐
NO User 76:	WO User 86:	WO User 106:	☐
NO User 92 Date:	WO User 97 Date:		
NO User 93 Date:	WO User 98 Date:		
NO User 94 Date:	WO User 99 Date:		
NO User 95 Date:	WO User 100 Date:		
NO User 96 Date:	WO User 101 Date:		
NO User 77:	WO User 87:	WO User 107:	☐
NO User 78:	WO User 88:	WO User 108:	☐
NO User 79:	WO User 89:	WO User 109:	☐
NO User 80:	WO User 90:	WO User 110:	☐
NO User 81:	WO User 91:	WO User 111:	☐
NO Creator: jjackson	WO Creation Date: 11/1/2023	PM Trigger:	Rec #: 15163