

CITY OF
CLEVELAND
HEIGHTS
LAW DEPARTMENT

December 11, 2023

Via E-Mail: vezner.kris@epa.gov and Berger.Jake@epa.gov

Kris P. Vezner, Esq.
Associate Regional Counsel
U.S. Environmental Protection Agency
Region 5 (C-14J)
77 West Jackson Blvd.
Chicago, IL 60604

and

Jake Berger
Physical Scientist
Water Enforcement & Compliance Assurance Branch
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Mail Code ECW-15J
Chicago, IL 60604


Re: November 2023 Overflow Monitoring Reports
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through November 30, 2023, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,




William R. Hanna
Director of Law

cc: Thomas Benson, Esq., EPA Attorney
James Vinch, Esq., EPA Attorney
James Zimny, EPA Engineer
U.S. EPA Region 5 Water Enforcement Branch
Mark Klingenstein, Environmental Engineer
Erm Gomes, Ohio EPA
Allison Cycyk, Ohio EPA
Casey Galligan, Ohio EPA
David Brumbaugh, Ohio EPA
Bill Fischbein, Ohio EPA
Kahlil Seren, Mayor
Collette Clinkscale, Director of Public Works
Steve Barker, Public Relations
Anthony Ferrone, Utilities Commissioner
Kevin Vander Tuig, P.E. (Outside Engineer)
Mathew St. Pierre, (Outside Engineer)
Dan Porter (Outside Engineer)
Cindy Biacofsky (Outside Engineer)
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report
Friday, November 17, 2023
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report Friday, November 17, 2023

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.82	0.68	0.42	0.18	0.08	0.04
Brecksville	0.97	0.77	0.56	0.28	0.11	0.06
Brook Park	0.73	0.60	0.35	0.20	0.09	0.05
Cleveland Industrial Pkwy	0.66	0.51	0.33	0.18	0.07	0.03
Dille Ave PS	0.62	0.47	0.29	0.15	0.06	0.04
Division Ave PS	0.69	0.51	0.31	0.15	0.07	0.03
Easterly WWTP	0.81	0.65	0.36	0.16	0.10	0.07
Independence	0.84	0.67	0.45	0.19	0.07	0.04
James Rhodes HS	0.59	0.47	0.31	0.17	0.06	0.03
Jennings PS	0.60	0.47	0.31	0.17	0.07	0.03
Macedonia	0.88	0.70	0.52	0.26	0.08	0.05
Maple Heights	0.72	0.62	0.42	0.17	0.08	0.03
Mary Street PS	0.67	0.52	0.31	0.16	0.07	0.05
Mayfield Heights	0.77	0.65	0.42	0.20	0.08	0.03
Moreland Hills	0.95	0.83	0.50	0.21	0.09	0.04
North Olmsted	0.70	0.56	0.34	0.19	0.08	0.03
North Royalton	0.87	0.71	0.46	0.21	0.07	0.04
Oakwood	0.89	0.72	0.48	0.24	0.08	0.04
Olmsted Falls	0.79	0.62	0.34	0.20	0.10	0.05
Parma	0.82	0.65	0.43	0.19	0.09	0.04
Richfield	0.82	0.70	0.53	0.29	0.10	0.04
Shaker Heights	0.72	0.56	0.35	0.16	0.07	0.04
South Euclid	0.78	0.63	0.39	0.18	0.07	0.05
Southerly WWTC	0.52	0.44	0.29	0.14	0.07	0.03
Strongsville C WWTP	0.87	0.69	0.45	0.21	0.08	0.04
Strongsville Foltz	0.94	0.75	0.49	0.22	0.08	0.04
University Heights	0.70	0.59	0.36	0.16	0.08	0.04
Wade Park	0.69	0.54	0.36	0.16	0.08	0.04
Westerly WWTP	0.66	0.47	0.28	0.14	0.06	0.03
Westlake	0.74	0.54	0.34	0.16	0.07	0.03

WO Number: 231121-0001

Category: SSOs

Status: Complete

Problem: Storm Response

Status Date: 11/21/2023 3:38 pm

Main Task: Inspection

Asset: SSO 431

Assigned By:

Location: FAIRFAX AT NORTH PARK

Assigned Date:

Cause: Weather

Start Date: 11/21/2023 8:00 AM

Override

Assigned Crew:

End Date: 11/21/2023 2:30 PM

Notifications

Supervisor: Jackson, Jeff

Project ID:

Problem ☐

Lead Worker: Manco, Angelo

Project Name:

Overdue ☐

Priority: High

Lead Worker ☐

Account #:

Task ☐

Proj No - Acct:

Supervisor ☐

Project:

Hard Lock WO ☐

Reason:

Received By:

Inspected By:

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Locations			Address 2
Address			
X Coord	Y Coord	General Location	
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672	Doan Brook	
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339	Doan Brook	
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT MARLBORO			
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH	

Work Order Detail Report

11/21/2023

so overflow inspections 11-17-2023 0.70

3:39 PM

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

11/21/2023

so overflow inspections 11-17-2023 0.70

3:39 PM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

11/21/2023

ssso overflow inspections 11-17-2023 0.70

3:39 PM

Work Order Assets							
Object Type		Description 1			Description 2		Completed
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	
Sewer Control Valve					FAIRFAX AT NORTH PARK		
SSO 431						26	
Sewer Control Valve					NORTH PARK AND COVENTRY		
SSO 114						16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Control Valve					3012 NORTH WOODLAND		
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO		
SSO 116						4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY		
SSO 124						47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON		
CH-50						53	
Sewer Control Valve					BRADFORD AND LEE		
SSO 129						11	
Sewer Control Valve					EDDINGTON		
CH-52						2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL		
SSO 122						36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103						19	
Sewer Control Valve					3003 EUCLID HEIGHTS BLVD		
SSO 104						15	

Work Order Detail Report

11/21/2023

so overflow inspections 11-17-2023 0.70

3:39 PM

Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

11/21/2023

so overflow inspections 11-17-2023 0.70

3:39 PM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	11/21/2023/ 9:13 am	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT) Block missing (rope still on ledge)	☐	Sound	11/21/2023/ 9:20 am	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0 Buried under pile of leaves	☐	Sound	11/21/2023/ 9:29 am	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	11/21/2023/ 9:33 am	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Sound	11/21/2023/ 9:38 am	
Controlled					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	11/21/2023/ 9:47 am	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	11/21/2023/ 9:48 am	
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	11/21/2023/ 9:58 am	
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	11/21/2023/ 9:59 am	
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	11/21/2023/10:00 am	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	11/21/2023/10:03 am	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	11/21/2023/10:07 am	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	11/21/2023/10:10 am	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	11/21/2023/10:12 am	
Controlled					
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	11/21/2023/10:14 am	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	11/21/2023/10:17 am	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	11/21/2023/ 9:08 am	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	11/21/2023/10:22 am	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	11/21/2023/10:25 am	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	11/21/2023/10:29 am	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	11/21/2023/10:33 am	
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Sound	11/21/2023/10:41 am	
Metered					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Not Sound	/ 8:15 am	11/21/2023
No block					
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	11/21/2023/ 8:20 am	11/21/2023
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	11/21/2023/ 8:25 am	

Work Order Detail Report

11/21/2023

sso overflow inspections 11-17-2023 0.70

3:39 PM

26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	11/21/2023/ 8:25 am	11/21/2023
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	11/21/2023/ 8:30 am	11/21/2023
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	11/21/2023/ 8:36 am	11/21/2023
29	B-42 12537 CEDAR SA16ACZA0	☐		/	
Not on SSO paper					
30	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	11/21/2023/ 9:05 am	11/21/2023
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	11/21/2023/ 9:15 am	11/21/2023
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	11/21/2023/ 9:32 am	11/21/2023
Not on sso list					
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	11/21/2023/ 9:32 am	11/21/2023
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐		/	
Not on sso List					
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐		/	
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐		/	
Not on sso list					
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐		/	
Not on sso list					
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Sound	11/21/2023/12:15 am	11/21/2023
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Sound	11/21/2023/12:20 pm	11/21/2023
40	C-59 3427 THORNE RD SA16AQD0	☐	Sound	11/21/2023/12:35 pm	11/21/2023
41	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	11/21/2023/12:37 pm	11/21/2023
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	11/21/2023/12:50 pm	11/21/2023
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	11/21/2023/ 1:10 pm	11/21/2023
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	11/21/2023/ 1:20 pm	11/21/2023
45	C-50 3593 FENLEY SA16APEH0	☐	Not Sound	11/21/2023/ 1:27 pm	11/21/2023
Unable to set block because of the flow of the water					

Tasks/Resources

SMCT36 Inspection

Crew:		Status:	*Cal'c UC: \$9.67		*Task Cost: \$435.12		Start Dt: 11/21/2023	
Supervisor:		UOM: Each	# of Units: 45.00		*Unit Cost: \$0.00		End Dt: 11/21/2023	
Employee								
Resource		UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt	
19356 Manco, Angelo		Hours	4.00	\$111.08		11/21/2023	11/21/2023	
12459 Eathridge, David		Hours	4.00	\$105.60		11/21/2023	11/21/2023	
28056 Palmisano, Anthony		Hours	4.00	\$94.24		11/21/2023	11/21/2023	
Equipment								
Resource		UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt	
CHFLT55 FORD 350 CREW CAB 9		Hours	4.00	\$70.60		11/21/2023	11/21/2023	
CHFLT93 FORD F250 4 X 4 PICK UP 1		Hours	4.00	\$53.60		11/21/2023	11/21/2023	
Task Comment: sso overflow inspection 11-17-2023 0.70'								

Work Order Detail Report

11/21/2023

SSO overflow inspections 11-17-2023 0.70

3:39 PM

			<u>*Actual</u>	<u>*Estimated</u>	<u>*Difference</u>
Projected Complete:	Lock: ☐	WO Duration	6.50	0.00	0.00
Repair Type:		Labor Hours	12.00	0.00	0.00
Subcontractor:		Labor Costs	\$310.92	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity:	0.00	Equipment Costs	124.20	0.00	0.00
Unit of Measure:	Each	Contractor Costs	0.00	0.00	0.00
Unit Cost:	\$0.00	Misc. Costs	0.00	0.00	0.00
WO Hours:	0.00	Total Costs	\$435.12	\$0.00	\$0.00
Use Task Info:			True	True	

Billing		
Billed Party		
Customer ID:	Customer Number:	
Customer Name:	Last Name:	
Address:		
City:	Phone:	Cell #:
State:	Fax #:	
Zip:	E-mail:	
Billing Data		
Contact Name:	*Billing Amount:	Billing Required: ☐
Invoice Number:	Date Bill Sent:	Billing Processed: ☐
Incoming Account #:	Payment Received:	Imported to Financials: ☐
	Payment Method:	

Associated PMs	PM Code and Description	Closed
	SSO-02 SSO INSPECTION	☒

Tracking	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	11/21/2023	7:15 AM
Supervisor Notification	Email Queued Successfully!	jjackson	11/21/2023	7:15 AM
Leadworker Notification	Email Queued Successfully!	jjackson	11/21/2023	7:15 AM
Status Change	From New Work Order to Closed In Field	deathridge	11/21/2023	2:27 PM
Status Change	From Closed In Field to Complete	jjackson	11/21/2023	3:38 PM

Rate:	Opened At:	Televised: ☐
Received By:	Pipe Footage Cleaned:	Power Rooter: ☐
Work From:	Gallons Used:	Jet: ☐
Pipe Size:	WO User 23:	Gap Vac: ☐
Pipe Condition:	WO User 24:	Dye Test: ☐
Could Not Open:	WO User 9:	Gap Root Cut: ☐
Additional Repair:	User 10:	GIS Correction?: ☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: ☐
Test Performed Thru:	Appointment Date: 11/22/2023 8:00 AM	
Dye Test Results:		
WO User 51:		
Measurement:	E Mail:	
History:	Measurement Line 2:	
Manhole Basin Repair:	Pipe Size:	
Material Used:	PVC Tees, Angles, Sleeves	
Pipe Repair:	WO User 44:	
Street Repair:	WO User 45:	
Grass Repair:	WO User 46:	
Curb Repair:		
Driveway- Sidewalk Repair:		
Construction Crew:		
WO User 39:		
WO User 40:	OUPS #:	
WO User 41:	WO User 48:	

Work Order Detail Report

11/21/2023

ssso overflow inspections 11-17-2023 0.70

3:39 PM

NO User 52:	WO User 62:	
NO User 53:	WO User 63:	
NO User 54:	WO User 64:	
NO User 55:	WO User 65:	
NO User 56:	WO User 66:	
NO User 57:	WO User 67:	
NO User 58:	WO User 68:	
NO User 59:	WO User 69:	
NO User 60:	WO User 70:	
NO User 61:	WO User 71:	
NO User 72:	WO User 82:	Televised: ☐
NO User 73:	Quantity:	Paid: ☐
NO User 74:	WO User 84:	WO User 104: ☐
NO User 75:	WO User 85:	WO User 105: ☐
NO User 76:	WO User 86:	WO User 106: ☐
NO User 92 Date:	WO User 97 Date:	
NO User 93 Date:	WO User 98 Date:	
NO User 94 Date:	WO User 99 Date:	
NO User 95 Date:	WO User 100 Date:	
NO User 96 Date:	WO User 101 Date:	
NO User 77:	WO User 87:	WO User 107: ☐
NO User 78:	WO User 88:	WO User 108: ☐
NO User 79:	WO User 89:	WO User 109: ☐
NO User 80:	WO User 90:	WO User 110: ☐
NO User 81:	WO User 91:	WO User 111: ☐
NO Creator: jjackson	WO Creation Date: 11/21/2023	PM Trigger: Rec #: 15215

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Sunday, November 26, 2023

Accumulation in Inches

Lake
County

Lake Erie

Easterly
WWTP

Mayfield
Heights

0.39

South
Euclid

0.42

Wade
Park

0.34

Westerly
WWTP

0.27

Division PS

0.30

Dille PS

0.27

Mary
Street PS

0.31

Shaker
Heights

0.30

Beachwood

0.33

Moreland
Hills

0.34

James
Rhodes HS

0.32

Cleveland
Industrial Pkwy

0.31

Jennings PS

0.35

Southerly
WWTC

0.32

Maple
Heights

0.28

Westlake

0.27

North
Olmsted

0.28

Olmsted
Falls

0.29

Brook Park

0.33

Parma

0.34

Independence

0.35

Oakwood

0.28

Strongsville
"C" WWTP

0.33

Cuyahoga
County

Lorain
County

Strongsville
Foltz

0.19

North
Royalton

0.28

Brecksville

0.35

Macedonia

0.28

Summit
County

Richfield

0.28

Medina County

Northeast Ohio Regional Sewer District

Daily Precipitation Report

Sunday, November 26, 2023

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.33	0.30	0.20	0.09	0.04	0.02
Brecksville	0.35	0.28	0.22	0.09	0.04	0.02
Brook Park	0.33	0.30	0.18	0.09	0.03	0.02
Cleveland Industrial Pkwy	0.31	0.28	0.18	0.08	0.03	0.01
Dille Ave PS	0.27	0.25	0.15	0.07	0.03	0.01
Division Ave PS	0.30	0.28	0.19	0.10	0.04	0.02
Easterly WWTP	0.39	0.36	0.23	0.12	0.04	0.02
Independence	0.35	0.31	0.23	0.10	0.03	0.02
James Rhodes HS	0.32	0.29	0.18	0.09	0.03	0.02
Jennings PS	0.35	0.32	0.20	0.09	0.03	0.02
Macedonia	0.28	0.23	0.17	0.07	0.02	0.01
Maple Heights	0.28	0.26	0.18	0.08	0.03	0.02
Mary Street PS	0.31	0.28	0.17	0.08	0.03	0.01
Mayfield Heights	0.39	0.32	0.22	0.10	0.04	0.02
Moreland Hills	0.34	0.27	0.16	0.08	0.03	0.02
North Olmsted	0.28	0.25	0.16	0.08	0.03	0.01
North Royalton	0.28	0.24	0.18	0.08	0.03	0.01
Oakwood	0.28	0.23	0.18	0.08	0.03	0.01
Olmsted Falls	0.29	0.27	0.15	0.08	0.03	0.02
Parma	0.34	0.31	0.21	0.09	0.04	0.02
Richfield	0.28	0.23	0.19	0.08	0.03	0.01
Shaker Heights	0.30	0.27	0.18	0.08	0.03	0.02
South Euclid	0.42	0.36	0.22	0.11	0.04	0.02
Southerly WWTC	0.32	0.28	0.19	0.08	0.03	0.01
Strongsville C WWTP	0.33	0.28	0.17	0.08	0.04	0.02
Strongsville Foltz	0.19	0.17	0.11	0.05	0.02	0.01
University Heights	0.36	0.31	0.20	0.09	0.04	0.02
Wade Park	0.34	0.32	0.21	0.10	0.03	0.02
Westerly WWTP	0.27	0.27	0.19	0.10	0.03	0.02
Westlake	0.27	0.26	0.16	0.08	0.03	0.02

Work Order Detail Report

so overflow inspections 11-26-2023 0.36'

11/30/2023 3:17 PM

WO Number: 231129-0001

Category: SSOs
Problem: Storm Response
Main Task: Inspection
Status Date: 11/29/2023 3:53 pm
Asset: SSO 431

Location: FAIRFAX AT NORTH PARK

Assigned Crew: Weather

Supervisor: Jackson, Jeff
Lead Worker: Manco, Angelo

Priority: High

Account #: 1

Proj No - Acct: 1

Project: 1

Reason: 1

Received By: 1

Inspected By: 1

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location: Sewer Collection
Department: Sewer

Sub-Division: 1

Area: 1

Sub-Area: 1

Owner: 1

Location: 1

Classification: 1

Maintenance Zone: 1

Work Order Locations

Address X Coord Y Coord General Location Address 2

FAIRFAX AT NORTH PARK 665,517,24643672 Doan Brook

NORTH PARK AND COVENTRY

2,219,873,16674590 DOAN BROOK - MAIN BRANCH

FAIRMOUNT SOUTH OF SCARBOROUGH

2,220,364,86097248 DOAN BROOK - MAIN BRANCH

FAIRMOUNT AT FAIRFAX

2,220,920,81917815 DOAN BROOK - MAIN BRANCH

FAIRMOUNT AT NORTH WOODLAND (S. SIDE)

2,223,053,81655256 DOAN BROOK - MAIN BRANCH

3012 NORTH WOODLAND

2,222,845,06631389 Doan Brook

2,226,440,21168265

2,226,354,79813956

2,226,389,92077273

FAIRMOUNT AT DARTMOOR

2,225,149,97508989 DOAN BROOK - MAIN BRANCH

FAIRMOUNT AT WELLINGTON

2,223,969,26550905 DOAN BROOK - MAIN BRANCH

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)

2,223,111,44143730 DOAN BROOK - MAIN BRANCH

FAIRMOUNT AT MARLBORO

2,221,638,88762389 DOAN BROOK - MAIN BRANCH

A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 231129-0001

Work Order Detail Report

so overflow inspections 11-26-2023 0.36'

11/30/2023 3:17 PM

FAIRMOUNT AT ARLINGTON	2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)	2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY	2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON	2,221,598.2893607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR	2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE	2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON	2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")	2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL	2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")	2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD			
HAMPSHIRE AT EUCLID HTS. BLVD.	2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON	2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY	2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD	2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd			
LEE RD. & SUPERIOR AVE.	2,227,113.30810548	671,276.67684697	
2,224,449.07983814	672,366.92072946		HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE	2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND	2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND	2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON	2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD			
2225 NOBLE ROAD	2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF	2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE	2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080		
2,218,501.67473823	671,997.54581206		
2,216,759.55453481	670,474.59347738		
2,224,536.21778722	668,887.44048372		
2,226,741.35609348	679,432.95121680		
2,226,591.76420106	679,420.92761880		

Work Order Detail Report

so overflow inspections 11-26-2023 0.36'

3:17 PM

11/30/2023

2,227,825.14395215 684,881.15948047

Work Order Detail Report

so overflow inspections 11-26-2023 0.36'

11/30/2023 3:17 PM

Work Order Assets

Object Type	System ID 1	System ID 2	Description 1	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Description 2	Completed
Sewer Structure	SA16AWB0							3094	FAIRMOUNT AT FAIRFAX	
Sewer Control Valve	SSO 112							7	FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	
Sewer Control Valve	SSO 99							6	3012 NORTH WOODLAND	
Sewer Control Valve	SSO 432							14		
Sewer Control Valve	DB-03							55		
Sewer Control Valve	DB-01							56		
Sewer Control Valve	DB-02							57	FAIRMOUNT AT DARTMOOR	
Sewer Control Valve	CH-04							5	FAIRMOUNT AT WELLINGTON	
Sewer Control Valve	SSO 110							44	FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	
Sewer Control Valve	SSO 87							33	FAIRMOUNT AT MARLBORO	
Sewer Control Valve	SSO 116							4	FAIRMOUNT AT ARLINGTON	
Sewer Control Valve	SSO 111							46	FAIRMOUNT & COVENTRY (SCARBOROUGH)	
Sewer Control Valve	SSO 113							37	FAIRMOUNT AND COVENTRY	
Sewer Control Valve	SSO 124							47	SCARBOROUGH AT LAMBERTON	
Sewer Control Valve	CH-50							53	BRADFORD AND LEE	
Sewer Control Valve	SSO 129							11	EDDINGTON	
Sewer Control Valve	CH-52							2	HAMPSHIRE LANE AT MAYFIELD (18")	
Sewer Control Valve	SSO 88							42	EAST OVERLOOK AT EDGEHILL	
Sewer Control Valve	SSO 122							36	HAMPSHIRE LANE AT MAYFIELD (36")	
Sewer Control Valve	SSO 89							34		
Sewer Structure	SA16ADZB0							1536	HAMPSHIRE AT EUCLID HTS. BLVD.	
Sewer Control Valve	SSO 91							20		
Sewer Structure	SA16ADPH0							4446	CEDAR BTW. FAIRMOUNT/DEMINGTON	
Sewer Control Valve	SSO 120							8		
Sewer Control Valve	SSO 103							19	2828 BERKSHIRE, EAST OF COVENTRY	
Sewer Control Valve	SSO 104							15	3003 EUCLID HEIGHTS BLVD	

'Hidden' field indicates permission to view the secured field is turned off.

WO#: 231129-0001

Sewer Structure		SA16AGMG0
Sewer Control Valve		CH-30
Sewer Control Valve		DV-11
Sewer Control Valve		SSO 108
Sewer Control Valve		SSO 106
Sewer Control Valve		SSO 95
Sewer Control Valve		SSO 105
Sewer Structure		SA16AQD0
Sewer Structure		SA16AQCC0
Sewer Control Valve		SSO 102
Sewer Control Valve		SSO 107
Sewer Control Valve		CH-51
Sewer Structure		SA16APEF0
South Taylor between Antisdale Ave and Superior F		3402
LEE RD. & SUPERIOR AVE.		52
EUCUID HEIGHTS BLVD AND LEE		22
EUCUID HEIGHTS BLVD/CUMBERLAND		43
1685 CUMBERLAND		18
CUMBERLAND/SOMERTON		30
4987		
3745		
2225 NOBLE ROAD		3
QUILLIAMS, N. OF RANDOLF		38
LANGTON AND ATHERSTONE		54
1809		

Work Order Detail Report

so overflow inspections 11-26-2023 0.36'

11/30/2023
3:17 PM

Check List

Item	Completed	Condition	Completion Date/Time	Est Completion Date
1 A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	11/29/2023/	
2 A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	11/29/2023/	
3 A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	/	
4 A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	11/29/2023/	
5 A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐		11/29/2023/	
Controlled				
3 A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	11/29/2023/	
7 A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	11/29/2023/	
3 A-6 FAIRMOUNT AT SHELburne ST16ZBK0 (WEST BOUND LANE)	☐	Sound	11/29/2023/	
9 A-5 FAIRMOUNT AT SHELburne SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	11/29/2023/	
10 A-7 FAIRMOUNT AT SHELburne SA16AAVH0 (EAST BOUND)	☐	Sound	11/29/2023/	
11 A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	/	
12 A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	11/29/2023/	
13 A-1 3041 FAIRMOUNT SA16AAU10 (TREE LAWN NEAR SIDEWALK)	☐	Sound	11/29/2023/	
14 A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐		11/29/2023/	
Controlled				
15 A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	11/29/2023/	
16 A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	11/29/2023/	
17 A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Not Sound	11/29/2023/	
No block				
18 A-50 SCARBOROUGH AND LAMBERTON SA16AANES	☐	Sound	11/29/2023/	
19 A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	11/29/2023/	
20 A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	11/29/2023/	
21 A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	11/29/2023/	
22 A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Not Sound	11/29/2023/	
23 B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Not Sound	11/29/2023/ 8:37 am	
24 B-10 HAMPshire LANE AT MAYFIELD SA16BACB0	☐	Sound	11/29/2023/ 8:44 am	
25 B-11 HAMPshire LANE AT MAYFIELD SA16AEAA0	☐	Sound	11/29/2023/ 9:44 am	
26 B-61 2600 HAMPshire SA16ADZB0	☐	Sound	11/29/2023/ 8:47 am	
27 HAMPshire AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	/ 8:50 am	

A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 231129-0001

11/30/2023
3:17 PM

Work Order Detail Report

so overflow inspections 11-26-2023 0.36'

28	B-46 EDGEHILL AT E OVERLOOK	SA16AEPF0	SA16ACZAO	11/29/2023/ 8:53 am	Sound	☐	
29	B-42 12537 CEDAR SA16ACZAO			/		☐	
Not on list							
30	B-15 COVENTRY AND CEDAR	SA16ADBHO		11/29/2023/ 9:01 am	Sound	☐	
31	B-23 2828 BERKSHIRE SA16AETA0			11/29/2023/ 9:16 am	Sound	☐	
32	B-24 3003 EUCLID HTS. BLVD.	ST16AALB0		/		☐	
Man hole sso# not on list							
33	B-56 LEE AND MEADOWBROOK	SA16AGMG0		11/29/2023/ 9:30 am	Sound	☐	
34	C-30 S TAYLOR NORTH OF	SUPERIOR SA16AIVF0		11/29/2023/ 9:45 am	Not Sound	☐	
Sso# 56 on list , no block (set new block)							
35	C-12 LEE AND SUPERIOR	SA16AGTJ0		/		☐	
Not on list							
36	C-28 EUCLID HTS. BLVD AND LEE RD	SA16AGTE0		/		☐	
37	C-26 EUCLID HTS BLVD AND	CUMBERLAND SA16AIRL0		/		☐	
Not on list							
38	C-25 CUMBERLAND AND SOMERTON	SA16AISAO		11/29/2023/ 9:53 am	Sound	☐	
39	C-17 1685 CUMBERLAND RD	SA16AQICB0		11/29/2023/ 9:56 am	Sound	☐	
40	C-59 3427 THORNE RD SA16AQAQD0			11/29/2023/10:02 am	Sound	☐	
41	C-60 3415 THORNE RD SA16AQAQC0			11/29/2023/10:15 am	Sound	☐	
42	C-22 2225 NOBLE RD ST16ZLHB0			11/29/2023/10:13 am	Sound	☐	
43	C-27 QUILIAMS NORTH OF	RANDOLPH SA16AOUQ0		11/29/2023/10:19 am	Sound	☐	
44	C-51 ATHERSTONE AND LANGTON	SA16AOKAO		11/29/2023/10:19 am	Sound	☐	
45	C-50 3593 FENLEY SA16APEH0			11/29/2023/10:37 am	Sound	☐	

Tasks/Resources

Crew:	Status:	*Calc UC: \$6.20	*Task Cost: \$279.00	Start Dt: 11/29/2023
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 11/29/2023
Employee				
Resource	UOM	Units	*Total Cost	Alt Description
28056 Palmisano, Anthony	Hours	5.00	\$117.80	11/29/2023 11/29/2023
40404 Don Johnson		5.00	\$94.20	11/29/2023 11/29/2023
Equipment				
Resource	UOM	Units	*Total Cost	Alt Description
CHFLT55 FORD F250 PICK UP	Hours	5.00	\$67.00	11/29/2023 11/29/2023
0				
Task Comment: sso overflow inspection 11-26-2023 0.36'				

Work Order Detail Report

so overflow inspections 11-26-2023 0.36

11/30/2023 3:17 PM

Projected Complete:	WO Duration	Labor Hours	Labor Costs	Material Costs	Fluids Costs	Equipment Costs	Contractor Costs	Misc. Costs	Total Costs	Use Task Info:	Actual	Estimated	Difference
☐ Lock:	6.00	10.00	\$212.00	0.00	0.00	67.00	0.00	0.00	\$279.00	True	0.00	\$0.00	\$0.00
Repair Type:													
Subcontractor:													
Profit Center:													
Quantity:													
Unit of Measure:													
Unit Cost:													
VO Hours:													

Billed Party Customer ID: Customer Name: Address: City: State: Zip:		Billing Data Contact Name: Invoice Number: Incoming Account #: *Billing Amount: Date Bill Sent: Payment Received: Payment Method:	
Customer Number: Last Name: Phone: Fax #: E-mail:		Billing Required: Billing Processed: Imported to Financials:	

Associated PMS PM Code and Description SSO-02 SSO INSPECTION Closed

Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jackson	11/29/2023	11:14 AM
Supervisor Notification	Email Queued Successfully!	jackson	11/29/2023	11:14 AM
Leadworker Notification	Email Queued Successfully!	jackson	11/29/2023	11:14 AM
Status Change	From New Work Order to Closed in Field	deathridge	11/29/2023	3:53 PM

Date: Received By: Work From: Pipe Size: Pipe Condition: Could Not Open: Additional Repair: Dye Test Reason: Test Performed Thru: Dye Test Results: Measurement: History:	Opened At: Pipe Footage Cleaned: Gallons Used: WO User 23: WO User 24: WO User 9: User 10: Appointment Date DNL Appointment Date: 11/29/2023 8:00 AM	Televised: Power Rooted: Jet: Gap Vac: Dye Test: Gap Root Cut: GIS Correction?: Test Tee Correction:
--	--	---

Manhole Basin Repair: Material Used: Pipe Repair: Street Repair: Grass Repair: Curb Repair: Driveway-Sidewalk Re: Construction Crew: VO User 39: VO User 40: VO User 41:	Pipe Size: PVC Tees, Angles, Slee: WO User 44: WO User 45: WO User 46: OUPS #: WO User 48:
--	--

WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:		
WO User 73:	Quantity:		
WO User 74:	WO User 84:		
WO User 75:	WO User 85:		
WO User 76:	WO User 86:		
VO User 92 Date:	WO User 97 Date:		
VO User 93 Date:	WO User 98 Date:		
VO User 94 Date:	WO User 99 Date:		
VO User 95 Date:	WO User 100 Date:		
VO User 96 Date:	WO User 101 Date:		
NO User 77:	WO User 87:		
NO User 78:	WO User 88:		
NO User 79:	WO User 89:		
NO User 80:	WO User 90:		
NO User 81:	WO User 91:		
NO Creator:			
jackson			
WO Creation Date: 11/29/2023 PM Trigger:			
Rec #: 15227			
	WO User 107:	☐	
	WO User 108:	☐	
	WO User 109:	☐	
	WO User 110:	☐	
	WO User 111:	☐	
	Televised:	☐	
	Paid:	☐	
	WO User 104:	☐	
	WO User 105:	☐	
	WO User 106:	☐	