

CITY OF
CLEVELAND
HEIGHTS
LAW DEPARTMENT

January 16, 2024

Via E-Mail: vezner.kris@epa.gov and Berger.Jake@epa.gov

Kris P. Vezner, Esq.
Associate Regional Counsel
U.S. Environmental Protection Agency
Region 5 (C-14J)
77 West Jackson Blvd.
Chicago, IL 60604

and

Jake Berger
Physical Scientist
Water Enforcement & Compliance Assurance Branch
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Mail Code ECW-15J
Chicago, IL 60604


Re: December 2023 Overflow Monitoring Reports
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through December, 2023, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,


William R. Hanna
Director of Law

Enclosures

Page Two
January 16, 2024


cc: Thomas Benson, Esq., EPA Attorney
James Vinch, Esq., EPA Attorney
James Zimny, EPA Engineer
U.S. EPA Region 5 Water Enforcement Branch
Mark Klingenstein, Environmental Engineer
Erm Gomes, Ohio EPA
Allison Cycyk, Ohio EPA
Casey Galligan, Ohio EPA
David Brumbaugh, Ohio EPA
Bill Fischbein, Ohio EPA
Kahlil Seren, Mayor
Collette Clinkscale, Director of Public Works
Steve Barker, Public Relations
Anthony Ferrone, Utilities Commissioner
Kevin Vander Tuig, P.E. (Outside Engineer)
Mathew St. Pierre, (Outside Engineer)
Dan Porter (Outside Engineer)
Cindy Biacofsky (Outside Engineer)
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Sunday, December 3, 2023

Accumulation in inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Sunday, December 3, 2023

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.30	0.25	0.19	0.13	0.06	0.03
Brecksville	0.06	0.05	0.04	0.02	0.02	0.01
Brook Park	0.31	0.30	0.21	0.13	0.13	0.12
Cleveland Industrial Pkwy	0.24	0.23	0.19	0.18	0.07	0.03
Dille Ave PS	0.32	0.29	0.25	0.14	0.12	0.12
Division Ave PS	0.22	0.20	0.18	0.17	0.10	0.06
Easterly WWTP	0.16	0.15	0.13	0.11	0.09	0.07
Independence	0.13	0.11	0.08	0.05	0.03	0.02
James Rhodes HS	0.30	0.29	0.20	0.17	0.08	0.08
Jennings PS	0.31	0.30	0.24	0.17	0.10	0.09
Macedonia	0.16	0.14	0.13	0.09	0.07	0.04
Maple Heights	0.21	0.17	0.12	0.08	0.04	0.03
Mary Street PS	0.26	0.22	0.19	0.14	0.09	0.05
Mayfield Heights	0.25	0.21	0.17	0.15	0.07	0.03
Moreland Hills	0.37	0.35	0.22	0.14	0.10	0.08
North Olmsted	0.21	0.19	0.18	0.17	0.07	0.03
North Royalton	0.04	0.03	0.02	0.01	0.01	0.01
Oakwood	0.07	0.06	0.04	0.02	0.02	0.01
Olmsted Falls	0.09	0.09	0.09	0.07	0.03	0.02
Parma	0.21	0.19	0.16	0.14	0.08	0.04
Richfield	0.27	0.27	0.26	0.16	0.12	0.09
Shaker Heights	0.25	0.23	0.21	0.17	0.08	0.04
South Euclid	0.33	0.29	0.22	0.18	0.10	0.07
Southerly WWTC	0.24	0.23	0.19	0.16	0.06	0.03
Strongsville C WWTP	0.20	0.19	0.15	0.13	0.10	0.06
Strongsville Foltz	0.07	0.05	0.04	0.02	0.02	0.02
University Heights	0.26	0.23	0.17	0.14	0.06	0.04
Wade Park	0.25	0.22	0.20	0.17	0.11	0.07
Westerly WWTP	0.14	0.12	0.11	0.10	0.06	0.03
Westlake	0.21	0.21	0.19	0.19	0.12	0.07

Work Order Detail Report

12/8/2023

ssso overflow inspections 12-3-2023 0.26'

9:25 AM

WO Number: 231207-0002	Category: SSOs
Status: Complete	Problem: Storm Response
Status Date: 12/8/2023 9:24 am	Main Task: Inspection
Asset: SSO 431	
Location: FAIRFAX AT NORTH PARK	
Cause: Weather	Assigned By:
Assigned Crew:	Assigned Date:
Supervisor: Jackson, Jeff	Start Date: 12/6/2023 8:00 AM
Lead Worker: Hooten, Daniel	End Date: 12/6/2023 2:00 PM
Priority: High	Override
Account #:	Notifications
Proj No - Acct:	Problem ☐
Project:	Overdue ☐
Reason:	Lead Worker ☐
Received By:	Task ☐
Inspected By:	Supervisor ☐
	Hard Lock WO ☐

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location	
Department: Sewer Collection	Comments for Crew
Division: Sewer	
Sub-Division:	
Area:	
Sub-Area:	
Owner:	
Location:	
Classification:	
Maintenance Zone:	Alternate Zone:

Work Order Locations			Address 2
Address			
X Coord	Y Coord	General Location	
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672	Doan Brook	
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339	Doan Brook	
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT MARLBORO			
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH	

Work Order Detail Report

12/8/2023

so overflow inspections 12-3-2023 0.26'

9:25 AM

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

12/8/2023

iso overflow inspections 12-3-2023 0.26'

9:25 AM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

12/8/2023

so overflow inspections 12-3-2023 0.26'

9:25 AM

Work Order Assets

Object Type		Description 1			Description 2	Asset ID	Completed
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve					FAIRFAX AT NORTH PARK		
SSO 431						26	
Sewer Control Valve					NORTH PARK AND COVENTRY		
SSO 114						16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35	
Sewer Structure						3094	
SA16AAWB0							
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Control Valve					3012 NORTH WOODLAND		
SSO 432						14	
Sewer Control Valve						55	
DB-03							
Sewer Control Valve						56	
DB-01							
Sewer Control Valve						57	
DB-02					FAIRMOUNT AT DARTMOOR		
Sewer Control Valve						5	
CH-04					FAIRMOUNT AT WELLINGTON		
Sewer Control Valve						44	
SSO 110					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
Sewer Control Valve						33	
SSO 87					FAIRMOUNT AT MARLBORO		
Sewer Control Valve						4	
SSO 116					FAIRMOUNT AT ARLINGTON		
Sewer Control Valve						46	
SSO 111					FAIRMOUNT & COVENTRY (SCARBOROUGH)		
Sewer Control Valve						37	
SSO 113					FAIRMOUNT AND COVENTRY		
Sewer Control Valve						47	
SSO 124					SCARBOROUGH AT LAMBERTON		
Sewer Control Valve						53	
CH-50					BRADFORD AND LEE		
Sewer Control Valve						11	
SSO 129					EDDINGTON		
Sewer Control Valve						2	
CH-52					HAMPSHIRE LANE AT MAYFIELD (18")		
Sewer Control Valve						42	
SSO 88					EAST OVERLOOK AT EDGEHILL		
Sewer Control Valve						36	
SSO 122					HAMPSHIRE LANE AT MAYFIELD (36")		
Sewer Control Valve						34	
SSO 89							
Sewer Structure						1536	
SA16ADZB0					HAMPSHIRE AT EUCLID HTS. BLVD.		
Sewer Control Valve						20	
SSO 91							
Sewer Structure						4446	
SA16ADPH0					CEDAR BTW. FAIRMOUNT/DEMINGTON		
Sewer Control Valve						8	
SSO 120					2828 BERKSHIRE, EAST OF COVENTRY		
Sewer Control Valve						19	
SSO 103					3003 EUCLID HEIGHTS BLVD		
Sewer Control Valve						15	
SSO 104							

Work Order Detail Report

12/8/2023

so overflow inspections 12-3-2023 0.26'

9:25 AM

Sewer Structure		
SA16AGMG0		3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F	
CH-30		52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.	
DV-11		9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE	
SSO 108		22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND	
SSO 106		43
Sewer Control Valve	1685 CUMBERLAND	
SSO 95		18
Sewer Control Valve	CUMBERLAND/SOMERTON	
SSO 105		30
Sewer Structure		
SA16AQD0		4987
Sewer Structure		
SA16AQQC0		3745
Sewer Control Valve	2225 NOBLE ROAD	
SSO 102		3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF	
SSO 107		38
Sewer Control Valve	LANGTON AND ATHERSTONE	
CH-51		54
Sewer Structure		
SA16APEF0		1809

Work Order Detail Report

12/8/2023

iso overflow inspections 12-3-2023 0.26'

9:25 AM

Check List				
	Item	Completed	Condition	Completion Date/Time
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	12/6/2023/ 8:08 am
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	12/6/2023/ 8:30 am
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	12/6/2023/
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	12/6/2023/
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Sound	12/7/2023/
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	12/6/2023/
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	12/6/2023/
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	12/6/2023/
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	12/6/2023/
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐		/
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	12/6/2023/
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	12/6/2023/
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	12/6/2023/
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	12/6/2023/
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	12/6/2023/
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	12/6/2023/
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	12/6/2023/
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	12/6/2023/
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	12/6/2023/
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	12/6/2023/
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	12/6/2023/
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Sound	12/6/2023/
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Not Sound	12/6/2023/
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	12/6/2023/
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	12/6/2023/
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	12/6/2023/
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	12/6/2023/
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	12/6/2023/
29	B-42 12537 CEDAR SA16ACZA0	☐	Sound	12/6/2023/

Work Order Detail Report

12/8/2023

9:25 AM

sso overflow inspections 12-3-2023 0.26'

30	B-15 COVENTRY AND CEDAR SA16ADB0	☐	Sound	12/6/2023/
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	12/6/2023/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	12/6/2023/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	12/6/2023/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	12/6/2023/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Sound	12/6/2023/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Sound	12/6/2023/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Sound	12/6/2023/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Sound	12/6/2023/
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Sound	12/6/2023/
40	C-59 3427 THORNE RD SA16AQD0	☐	Sound	12/6/2023/
41	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	12/6/2023/
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	12/6/2023/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	12/6/2023/
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	12/6/2023/
45	C-50 3593 FENLEY SA16APEH0	☐	Sound	12/6/2023/

Tasks/Resources

SMCT36 Inspection

Crew:

Status:

*Cal'c UC: \$3.66

*Task Cost: \$164.68

Start Dt: 12/6/2023

Supervisor:

UOM: Each

of Units: 45.00

*Unit Cost: \$0.00

End Dt: 12/6/2023

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
19356 Manco, Angelo	Hours	4.00	\$111.08		12/6/2023	12/6/2023

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT93 FORD F250 4 X 4 PICK UP	Hours	4.00	\$53.60		12/6/2023	12/6/2023

Task Comment: sso overflow inspections 12-3-2023 0.26'

Projected Complete:

Lock: ☐

Repair Type:

Subcontractor:

Profit Center:

Quantity: 0.00

Lock: ☐

Unit of Measure: Each

Unit Cost: \$0.00

NO Hours: 0.00

	*Actual	*Estimated	*Difference
WO Duration	6.00	0.00	0.00
Labor Hours	4.00	0.00	0.00
Labor Costs	\$111.08	\$0.00	\$0.00
Material Costs	0.00	0.00	0.00
Fluids Costs	0.00	0.00	0.00
Equipment Costs	53.60	0.00	0.00
Contractor Costs	0.00	0.00	0.00
Misc. Costs	0.00	0.00	0.00
Total Costs	\$164.68	\$0.00	\$0.00
Use Task Info:	True	True	

Work Order Detail Report

12/8/2023

ssso overflow inspections 12-3-2023 0.26'

9:25 AM

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:			
City:		Phone:	Cell #:
State:		Fax #:	
Zip:		E-mail:	

Billing Data		
Contact Name:	*Billing Amount:	Billing Required: ☐
Invoice Number:	Date Bill Sent:	Billing Processed: ☐
Incoming Account #:	Payment Received:	Imported to Financials: ☐
	Payment Method:	

Associated PMs		Closed
<u>PM Code and Description</u>		☒
SSO-02 SSO INSPECTION		

Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	12/7/2023	2:33 PM
Supervisor Notification	Email Queued Successfully!	jjackson	12/7/2023	2:33 PM
Status Change	From New Work Order to Complete	jjackson	12/8/2023	9:24 AM

Rate:	Opened At:	Televised:	☐
Received By:	Pipe Footage Cleaned:	Power Rooter:	☐
Work From:	Gallons Used:	Jet:	☐
Pipe Size:	WO User 23:	Gap Vac:	☐
Pipe Condition:	WO User 24:	Dye Test:	☐
Could Not Open:	WO User 9:	Gap Root Cut:	☐
Additional Repair:	User 10:	GIS Correction?:	☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	☐
Test Performed Through:	Appointment Date: 12/6/2023 8:00 AM		

Dye Test Results:	
NO User 51:	
Measurement:	E Mail:
History:	Measurement Line 2:
Manhole Basin Repair:	Pipe Size:
Material Used:	PVC Tees, Angles, Sleeves
Pipe Repair:	WO User 44:
Street Repair:	WO User 45:
Grass Repair:	WO User 46:
Curb Repair:	
Driveway- Sidewalk Repair:	
Construction Crew:	
NO User 39:	
NO User 40:	OUPS #:
NO User 41:	WO User 48:

NO User 52:	WO User 62:
NO User 53:	WO User 63:
NO User 54:	WO User 64:
NO User 55:	WO User 65:
NO User 56:	WO User 66:
NO User 57:	WO User 67:
NO User 58:	WO User 68:
NO User 59:	WO User 69:
NO User 60:	WO User 70:
NO User 61:	WO User 71:

Work Order Detail Report

12/8/2023


iso overflow inspections 12-3-2023 0.26'

9:25 AM

NO User 72:	WO User 82:	Televised:	☐
NO User 73:	Quantity:	Paid:	☐
NO User 74:	WO User 84:	WO User 104:	☐
NO User 75:	WO User 85:	WO User 105:	☐
NO User 76:	WO User 86:	WO User 106:	☐
NO User 92 Date:	WO User 97 Date:		
NO User 93 Date:	WO User 98 Date:		
NO User 94 Date:	WO User 99 Date:		
NO User 95 Date:	WO User 100 Date:		
NO User 96 Date:	WO User 101 Date:		
NO User 77:	WO User 87:	WO User 107:	☐
NO User 78:	WO User 88:	WO User 108:	☐
NO User 79:	WO User 89:	WO User 109:	☐
NO User 80:	WO User 90:	WO User 110:	☐
NO User 81:	WO User 91:	WO User 111:	☐
NO Creator: jjackson	WO Creation Date: 12/7/2023	PM Trigger:	Rec #: 15248

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report
Saturday, December 9, 2023
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report Saturday, December 9, 2023

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.51	0.46	0.43	0.35	0.19	0.10
Brecksville	0.37	0.35	0.34	0.28	0.10	0.06
Brook Park	0.49	0.46	0.43	0.32	0.12	0.07
Cleveland Industrial Pkwy	0.47	0.44	0.42	0.31	0.13	0.08
Dille Ave PS	0.45	0.42	0.41	0.30	0.12	0.07
Division Ave PS	0.47	0.45	0.42	0.31	0.11	0.06
Easterly WWTP	0.50	0.48	0.45	0.34	0.13	0.08
Independence	0.52	0.46	0.45	0.39	0.19	0.08
James Rhodes HS	0.44	0.41	0.40	0.30	0.10	0.05
Jennings PS	0.48	0.44	0.42	0.30	0.09	0.04
Macedonia	0.30	0.28	0.27	0.18	0.08	0.06
Maple Heights	0.45	0.39	0.37	0.32	0.18	0.08
Mary Street PS	0.43	0.40	0.38	0.28	0.10	0.05
Mayfield Heights	0.51	0.44	0.42	0.34	0.19	0.09
Moreland Hills	0.39	0.37	0.35	0.27	0.14	0.09
North Olmsted	n/a	n/a	n/a	n/a	n/a	n/a
North Royalton	0.63	0.54	0.52	0.46	0.16	0.13
Oakwood	0.38	0.36	0.35	0.25	0.12	0.08
Olmsted Falls	0.66	0.64	0.59	0.44	0.24	0.15
Parma	0.58	0.55	0.53	0.38	0.13	0.06
Richfield	0.43	0.39	0.38	0.28	0.16	0.12
Shaker Heights	0.53	0.51	0.50	0.41	0.17	0.10
South Euclid	0.53	0.50	0.48	0.31	0.14	0.06
Southerly WWTC	0.53	0.51	0.49	0.37	0.14	0.07
Strongsville C WWTP	0.56	0.51	0.50	0.37	0.12	0.07
Strongsville Foltz	0.68	0.61	0.59	0.47	0.20	0.08
University Heights	0.58	0.56	0.54	0.42	0.21	0.12
Wade Park	0.48	0.45	0.43	0.30	0.11	0.07
Westerly WWTP	0.48	0.45	0.42	0.31	0.12	0.08
Westlake	0.84	0.83	0.73	0.45	0.17	0.14

Work Order Detail Report

12/13/2023

iso inspections 12-09-2023 0.58'

1:56 PM

WO Number: 231212-0001	Category: SSOs
Status: New Work Order	Problem: Storm Response
Status Date: 12/12/2023 11:56 am	Main Task: Inspection
Asset: SSO 431	
Location: FAIRFAX AT NORTH PARK	
Cause: Weather	Assigned By:
Assigned Crew:	Assigned Date:
Supervisor: Jackson, Jeff	Start Date: 12/12/2023 8:00 AM
Lead Worker: Palmisano, Anthony	End Date: 2:00 PM
Priority: High	Override
Account #:	Notifications
Proj No - Acct:	Problem ☐
Project:	Overdue ☐
Reason:	Lead Worker ☐
Received By:	Task ☐
Inspected By:	Supervisor ☐
	Hard Lock WO ☐

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location	
Department: Sewer Collection	Comments for Crew
Division: Sewer	Inspect all (45) SSO's when rainfall is one quarter (1/4")
Sub-Division:	inch or higher.
Area:	
Sub-Area:	
Owner:	
Location:	
Classification:	
Maintenance Zone:	Alternate Zone:

Work Order Locations		
Address	Address 2	
X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

12/13/2023

iso inspections 12-09-2023 0.58'

1:56 PM

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

12/13/2023

iso inspections 12-09-2023 0.58'

1:56 PM

2,227,825.14395215	684,881.15948047
--------------------	------------------

Work Order Detail Report

12/13/2023

iso inspections 12-09-2023 0.58'

1:56 PM

Work Order Assets

Object Type	Description 1			Description 2		Asset ID	Completed
	System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	
Sewer Control Valve						FAIRFAX AT NORTH PARK	
SSO 431						26	
Sewer Control Valve						NORTH PARK AND COVENTRY	
SSO 114						16	
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH	
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve						FAIRMOUNT AT FAIRFAX	
SSO 112						7	
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	
SSO 99						6	
Sewer Control Valve						3012 NORTH WOODLAND	
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve						FAIRMOUNT AT DARTMOOR	
CH-04						5	
Sewer Control Valve						FAIRMOUNT AT WELLINGTON	
SSO 110						44	
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	
SSO 87						33	
Sewer Control Valve						FAIRMOUNT AT MARLBORO	
SSO 116						4	
Sewer Control Valve						FAIRMOUNT AT ARLINGTON	
SSO 111						46	
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)	
SSO 113						37	
Sewer Control Valve						FAIRMOUNT AND COVENTRY	
SSO 124						47	
Sewer Control Valve						SCARBOROUGH AT LAMBERTON	
CH-50						53	
Sewer Control Valve						BRADFORD AND LEE	
SSO 129						11	
Sewer Control Valve						EDDINGTON	
CH-52						2	
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")	
SSO 88						42	
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL	
SSO 122						36	
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")	
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.	
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON	
SSO 120						8	
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY	
SSO 103						19	
Sewer Control Valve						3003 EUCLID HEIGHTS BLVD	
SSO 104						15	

Sewer Structure	3402
SA16AGMG0	
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	4987
SA16AQD0	
Sewer Structure	3745
SA16AQQC0	
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	1809
SA16APEF0	

Work Order Detail Report

12/13/2023

iso inspections 12-09-2023 0.58'

1:56 PM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	12/12/2023/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	12/12/2023/	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	12/12/2023/	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	12/12/2023/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Sound	12/12/2023/	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	12/12/2023/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	12/12/2023/	
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	12/12/2023/	
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	12/12/2023/	
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	12/12/2023/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	12/12/2023/	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	12/12/2023/	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	12/12/2023/	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	12/12/2023/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	12/12/2023/	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	12/12/2023/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	12/12/2023/	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	12/12/2023/	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	12/13/2023/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	12/12/2023/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	12/12/2023/	
22	A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	☐	Not Sound	12/12/2023/	
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	12/12/2023/	
no block					
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	12/12/2023/	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	12/12/2023/	
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	12/12/2023/	
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	12/12/2023/	
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	12/12/2023/	

Work Order Detail Report

12/13/2023

sso inspections 12-09-2023 0.58'

1:56 PM

29	B-42 12537 CEDAR SA16ACZA0	☐	Sound	12/12/2023/
30	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	12/12/2023/
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	12/12/2023/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	12/12/2023/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Not Sound	12/12/2023/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	12/12/2023/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Sound	12/12/2023/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Sound	12/12/2023/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Sound	12/12/2023/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Sound	12/12/2023/
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Sound	12/12/2023/
40	C-59 3427 THORNE RD SA16AQQD0	☐	Sound	12/12/2023/
41	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	12/12/2023/
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	12/12/2023/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	12/12/2023/
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	12/12/2023/
45	C-50 3593 FENLEY SA16APEH0	☐	Not Sound	12/12/2023/

Tasks/Resources						
SMCT36 Inspection						
Crew:		Status:	*Cal'c UC: \$6.59		*Task Cost: \$296.60	Start Dt: 12/12/2023
Supervisor:		UOM: Each	# of Units: 45.00		*Unit Cost: \$0.00	End Dt:
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
28056 Palmisano, Anthony	Hours	4.00	\$94.24		12/12/2023	
40404 Don Johnson		4.00	\$75.36		12/12/2023	
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 GMC SAVANA SEWER 7 VAN	Hours	4.00	\$73.40		12/12/2023	
CHFLT55 FORD F250 PICK UP 0	Hours	4.00	\$53.60		12/12/2023	
Task Comment: sso overflow inspections 0.58' 12-9-2023						

		*Actual	*Estimated	*Difference
Projected Complete:	Lock: ☐	WO Duration	0.00	0.00
Repair Type:		Labor Hours	8.00	0.00
Subcontractor:		Labor Costs	\$169.60	\$0.00
Profit Center:		Material Costs	0.00	0.00
		Fluids Costs	0.00	0.00
Quantity: 0.00	Lock: ☐	Equipment Costs	127.00	0.00
Unit of Measure: Each		Contractor Costs	0.00	0.00
Unit Cost: \$0.00		Misc. Costs	0.00	0.00
WO Hours: 0.00		Total Costs	\$296.60	\$0.00
		Use Task Info:	True	True

Work Order Detail Report

12/13/2023

so inspections 12-09-2023 0.58'

1:56 PM

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:			
City:		Phone:	Cell #:
State:		Fax #:	
Zip:		E-mail:	

Billing Data		
Contact Name:	*Billing Amount:	Billing Required: ☐
Invoice Number:	Date Bill Sent:	Billing Processed: ☐
Incoming Account #:	Payment Received:	Imported to Financials: ☐
	Payment Method:	

Associated PMs		
PM Code	Description	Closed
SSO-02	SSO INSPECTION	☒

Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	12/12/2023	11:56 AM
Supervisor Notification	Email Queued Successfully!	jjackson	12/12/2023	11:56 AM

Rate:	Opened At:	Televised: ☐
Recieved By:	Pipe Footage Cleaned .	Power Rooter: ☐
Work From:	Gallons Used:	Jet: ☐
Pipe Size:	WO User 23:	Gap Vac: ☐
Pipe Condition:	WO User 24:	Dye Test: ☐
Could Not Open:	WO User 9:	Gap Root Cut: ☐
Additional Repair:	User 10:	GIS Correction?: ☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: ☐
Test Performed Throug	Appointment Date: 12/12/2023 12:00 PM	
Dye Test Results:		
NO User 51:		
Measurement:	E Mail:	
History:	Measurement Line 2:	
Manhole Basin Repair:	Pipe Size:	
Material Used:	PVC Tees, Angles, Sler	
Pipe Repair:	WO User 44:	
Street Repair:	WO User 45:	
Grass Repair:	WO User 46:	
Curb Repair:		
Driveway- Sidewalk Re		
Construction Crew:		
NO User 39:	OUPS #:	
NO User 40:	WO User 48:	
NO User 41:		
NO User 52:	WO User 62:	
NO User 53:	WO User 63:	
NO User 54:	WO User 64:	
NO User 55:	WO User 65:	
NO User 56:	WO User 66:	
NO User 57:	WO User 67:	
NO User 58:	WO User 68:	
NO User 59:	WO User 69:	
NO User 60:	WO User 70:	
NO User 61:	WO User 71:	

Work Order Detail Report

12/13/2023

iso inspections 12-09-2023 0.58'

1:56 PM


NO User 72:	WO User 82:	Televised:	☐
NO User 73:	Quantity:	Paid:	☐
NO User 74:	WO User 84:	WO User 104:	☐
NO User 75:	WO User 85:	WO User 105:	☐
NO User 76:	WO User 86:	WO User 106:	☐
NO User 92 Date:	WO User 97 Date:		
NO User 93 Date:	WO User 98 Date:		
NO User 94 Date:	WO User 99 Date:		
NO User 95 Date:	WO User 100 Date:		
NO User 96 Date:	WO User 101 Date:		
NO User 77:	WO User 87:	WO User 107:	☐
NO User 78:	WO User 88:	WO User 108:	☐
NO User 79:	WO User 89:	WO User 109:	☐
NO User 80:	WO User 90:	WO User 110:	☐
NO User 81:	WO User 91:	WO User 111:	☐
NO Creator: jjackson	WO Creation Date: 12/12/2023	PM Trigger:	Rec #: 15252

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Monday, December 18, 2023

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Monday, December 18, 2023

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.34	0.21	0.17	0.08	0.03	0.01
Brecksville	0.47	0.30	0.22	0.10	0.03	0.02
Brook Park	0.33	0.14	0.11	0.05	0.04	0.02
Cleveland Industrial Pkwy	0.33	0.15	0.13	0.06	0.03	0.02
Dille Ave PS	0.22	0.12	0.08	0.05	0.02	0.01
Division Ave PS	0.23	0.12	0.07	0.04	0.02	0.01
Easterly WWTP	0.12	0.11	0.07	0.04	0.02	0.01
Independence	0.36	0.14	0.10	0.06	0.03	0.02
James Rhodes HS	0.38	0.17	0.14	0.08	0.03	0.01
Jennings PS	0.35	0.17	0.13	0.07	0.03	0.03
Macedonia	0.32	0.18	0.14	0.06	0.03	0.01
Maple Heights	0.42	0.21	0.15	0.07	0.04	0.02
Mary Street PS	0.35	0.17	0.12	0.07	0.03	0.01
Mayfield Heights	0.60	0.29	0.23	0.10	0.04	0.02
Moreland Hills	0.85	0.53	0.38	0.16	0.05	0.02
North Olmsted	n/a	n/a	n/a	n/a	n/a	n/a
North Royalton	0.37	0.22	0.16	0.07	0.02	0.02
Oakwood	0.63	0.38	0.26	0.11	0.05	0.02
Olmsted Falls	0.31	0.20	0.16	0.06	0.03	0.01
Parma	0.40	0.21	0.15	0.07	0.03	0.02
Richfield	0.26	0.17	0.12	0.05	0.03	0.01
Shaker Heights	0.36	0.20	0.15	0.08	0.03	0.01
South Euclid	0.22	0.12	0.08	0.05	0.03	0.01
Southerly WWTC	0.49	0.27	0.21	0.09	0.03	0.03
Strongsville C WWTP	0.49	0.30	0.24	0.11	0.04	0.02
Strongsville Foltz	0.35	0.22	0.17	0.07	0.02	0.02
University Heights	0.38	0.18	0.15	0.08	0.03	0.01
Wade Park	0.21	0.12	0.08	0.04	0.02	0.01
Westerly WWTP	n/a	n/a	n/a	n/a	n/a	n/a
Westlake	0.26	0.12	0.11	0.06	0.02	0.01

Work Order Detail Report

12/20/2023

SSO overflow inspections 12-18-2023 0.38'

2:15 PM

WO Number: 231219-0001		Category: SSOs
Status: New Work Order		Problem: Storm Response
Status Date: 12/19/2023 8:17 am		Main Task: Inspection
Asset: SSO 431		
Location: FAIRFAX AT NORTH PARK		
Cause: Weather		Assigned By:
Assigned Crew:		Assigned Date:
Supervisor: Jackson, Jeff		Start Date: 12/19/2023 8:00 AM
Lead Worker: Eathridge, David		End Date: 12/19/2023 2:15 PM
Priority: High		Override
Account #:		Notifications
Proj No - Acct:		Problem ☐
Project:		Overdue ☐
Reason:		Lead Worker ☐
Received By:		Task ☐
Inspected By:		Supervisor ☐
		Hard Lock WO ☐

Request Comments for Work Order
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location		Comments for Crew
Department: Sewer Collection		Inspect all (45) SSO's when rainfall is one quarter (1/4")
Division: Sewer		inch or higher.
Sub-Division:		
Area:		
Sub-Area:		
Owner:		
Location:		
Classification:		
Maintenance Zone:	Alternate Zone:	

Work Order Locations		
Address	Address 2	
X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

12/20/2023

so overflow inspections 12-18-2023 0.38'

2:15 PM

NO User 72:	WO User 82:	Televised:	☐
NO User 73:	Quantity:	Paid:	☐
NO User 74:	WO User 84:	WO User 104:	☐
NO User 75:	WO User 85:	WO User 105:	☐
NO User 76:	WO User 86:	WO User 106:	☐

NO User 92 Date:	WO User 97 Date:
NO User 93 Date:	WO User 98 Date:
NO User 94 Date:	WO User 99 Date:
NO User 95 Date:	WO User 100 Date:
NO User 96 Date:	WO User 101 Date:

NO User 77:	WO User 87:	WO User 107:	☐
NO User 78:	WO User 88:	WO User 108:	☐
NO User 79:	WO User 89:	WO User 109:	☐
NO User 80:	WO User 90:	WO User 110:	☐
NO User 81:	WO User 91:	WO User 111:	☐

NO Creator:	jjackson	WO Creation Date:	12/19/2023	PM Trigger:		Rec #:	15256
-------------	----------	-------------------	------------	-------------	--	--------	-------

Work Order Detail Report

12/20/2023

so overflow inspections 12-18-2023 0.38'

2:15 PM

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:			
City:		Phone:	Cell #:
State:		Fax #:	
Zip:		E-mail:	

Billing Data		
Contact Name:	*Billing Amount:	Billing Required: ☐
Invoice Number:	Date Bill Sent:	Billing Processed: ☐
Incoming Account #:	Payment Received:	Imported to Financials: ☐
	Payment Method:	

Associated PMs							
<table border="1"> <thead> <tr> <th>PM Code</th> <th>Description</th> <th>Closed</th> </tr> </thead> <tbody> <tr> <td>SSO-02</td> <td>SSO INSPECTION</td> <td>☒</td> </tr> </tbody> </table>	PM Code	Description	Closed	SSO-02	SSO INSPECTION	☒	
PM Code	Description	Closed					
SSO-02	SSO INSPECTION	☒					

Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	12/19/2023	8:17 AM
Supervisor Notification	Email Queued Successfully!	jjackson	12/19/2023	8:17 AM

Rate:	Opened At:	Televised: ☐
Recieved By:	Pipe Footage Cleaned:	Power Rooter: ☐
Work From:	Gallons Used:	Jet: ☐
Pipe Size:	WO User 23:	Gap Vac: ☐
Pipe Condition:	WO User 24:	Dye Test: ☐
Could Not Open:	WO User 9:	Gap Root Cut: ☐
Additional Repair:	User 10:	GIS Correction?: ☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: ☐
Test Performed Throug	Appointment Date: 12/19/2023 8:00 AM	
Dye Test Results:		
NO User 51:		
Measurement:	E Mail:	
History:	Measurement Line 2:	
Manhole Basin Repair:	Pipe Size:	
Material Used:	PVC Tees, Angles, Slec	
Pipe Repair:	WO User 44:	
Street Repair:	WO User 45:	
Grass Repair:	WO User 46:	
Curb Repair:		
Driveway- Sidewalk Re		
Construction Crew:		
NO User 39:		
NO User 40:	OUPS #:	
NO User 41:	WO User 48:	
NO User 52:	WO User 62:	
NO User 53:	WO User 63:	
NO User 54:	WO User 64:	
NO User 55:	WO User 65:	
NO User 56:	WO User 66:	
NO User 57:	WO User 67:	
NO User 58:	WO User 68:	
NO User 59:	WO User 69:	
NO User 60:	WO User 70:	
NO User 61:	WO User 71:	

Work Order Detail Report

12/20/2023

SSO overflow inspections 12-18-2023 0.38'

2:15 PM

29	B-42 12537 CEDAR SA16ACZA0	☐	Sound	12/19/2023/
30	B-15 COVENTRY AND CEDAR SA16ADBHO	☐	Sound	/
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	12/19/2023/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	12/19/2023/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	12/19/2023/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	12/19/2023/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Sound	12/19/2023/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Sound	12/19/2023/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Sound	12/19/2023/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Sound	12/19/2023/
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Sound	12/19/2023/
40	C-59 3427 THORNE RD SA16AQQD0	☐	Sound	12/19/2023/
41	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	12/19/2023/
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	12/19/2023/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	12/19/2023/
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	12/19/2023/
45	C-50 3593 FENLEY SA16APEH0	☐	Sound	12/19/2023/

Tasks/Resources						
SMCT36 Inspection						
Crew:		Status:	*Cal'c UC: \$7.36	*Task Cost: \$331.00	Start Dt: 12/19/2023	
Supervisor:		UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 12/19/2023	
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
12459 Eathridge, David	Hours	5.00	\$132.00		12/19/2023	12/19/2023
40151 Mc Coy, Sam	Hours	5.00	\$132.00		12/19/2023	12/19/2023
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT93 FORD F250 4 X 4 PICK UP	Hours	5.00	\$67.00		12/19/2023	12/19/2023
1						
Task Comment: SSO OVERFLOW INSEPCION 12-18-2023 0.38'						

Projected Complete:	Lock: ☐	WO Duration	*Actual 6.25	*Estimated 0.00	*Difference 0.00
Repair Type:		Labor Hours	10.00	0.00	0.00
Subcontractor:		Labor Costs	\$264.00	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity: 0.00	Lock: ☐	Equipment Costs	67.00	0.00	0.00
Unit of Measure: Each		Contractor Costs	0.00	0.00	0.00
Unit Cost: \$0.00		Misc. Costs	0.00	0.00	0.00
NO Hours: 0.00		Total Costs	\$331.00	\$0.00	\$0.00
		Use Task Info:	True	True	

Work Order Detail Report

12/20/2023

iso overflow inspections 12-18-2023 0.38'

2:15 PM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	12/19/2023/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	12/19/2023/	
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	12/19/2023/	
Construction Zone could not open manhole					
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	12/19/2023/	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐		12/19/2023/	
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	12/19/2023/	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	12/19/2023/	
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	12/19/2023/	
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	12/19/2023/	
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	12/19/2023/	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Not Sound	12/19/2023/	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	12/19/2023/	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	12/19/2023/	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	12/19/2023/	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	12/19/2023/	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	12/19/2023/	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	12/19/2023/	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	12/19/2023/	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	12/19/2023/	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	12/19/2023/	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	12/19/2023/	
22	A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	☐	Sound	12/19/2023/	
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	12/19/2023/	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	12/19/2023/	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	12/19/2023/	
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	12/19/2023/	
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	12/19/2023/	
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	12/19/2023/	

Work Order Detail Report

12/20/2023

so overflow inspections 12-18-2023 0.38'

2:15 PM

Work Order Assets

Object Type		Description 1			Description 2		
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve					FAIRFAX AT NORTH PARK		
SSO 431						26	
Sewer Control Valve					NORTH PARK AND COVENTRY		
SSO 114						16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Control Valve					3012 NORTH WOODLAND		
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO		
SSO 116						4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY		
SSO 124						47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON		
CH-50						53	
Sewer Control Valve					BRADFORD AND LEE		
SSO 129						11	
Sewer Control Valve					EDDINGTON		
CH-52						2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL		
SSO 122						36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103						19	
Sewer Control Valve					3003 EUCLID HEIGHTS BLVD		
SSO 104						15	

Work Order Detail Report

12/20/2023

so overflow inspections 12-18-2023 0.38'

2:15 PM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

12/20/2023


iso overflow inspections 12-18-2023 0.38'

2:15 PM

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report
Wednesday, December 27, 2023
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Wednesday, December 27, 2023

<u>Site Location</u>	Peak Accumulation (inches)					
	<u>24-Hour</u>	<u>6-Hour</u>	<u>3-Hour</u>	<u>1-Hour</u>	<u>15-Minute</u>	<u>5-Minute</u>
Beachwood	0.48	0.35	0.31	0.16	0.06	0.03
Brecksville	0.57	0.40	0.33	0.17	0.06	0.03
Brook Park	0.75	0.62	0.48	0.28	0.11	0.05
Cleveland Industrial Pkwy	0.80	0.65	0.48	0.28	0.11	0.05
Dille Ave PS	0.55	0.45	0.30	0.16	0.09	0.04
Division Ave PS	0.57	0.46	0.30	0.16	0.06	0.03
Easterly WWTP	0.47	0.41	0.24	0.13	0.05	0.03
Independence	0.53	0.42	0.31	0.15	0.05	0.02
James Rhodes HS	0.51	0.37	0.26	0.12	0.05	0.02
Jennings PS	0.65	0.49	0.35	0.17	0.08	0.04
Macedonia	0.67	0.38	0.34	0.22	0.07	0.03
Maple Heights	0.44	0.30	0.26	0.14	0.05	0.02
Mary Street PS	0.63	0.51	0.37	0.20	0.11	0.05
Mayfield Heights	0.53	0.30	0.28	0.17	0.05	0.03
Moreland Hills	0.68	0.36	0.32	0.22	0.07	0.03
North Olmsted	0.83	0.74	0.53	0.27	0.10	0.05
North Royalton	0.58	0.42	0.32	0.16	0.06	0.03
Oakwood	0.68	0.37	0.33	0.21	0.06	0.03
Olmsted Falls	0.82	0.71	0.52	0.27	0.09	0.05
Parma	0.60	0.42	0.29	0.13	0.05	0.03
Richfield	0.60	0.44	0.34	0.16	0.07	0.03
Shaker Heights	0.54	0.40	0.32	0.17	0.06	0.04
South Euclid	0.58	0.41	0.30	0.18	0.07	0.03
Southerly WWTC	0.50	0.37	0.30	0.17	0.07	0.03
Strongsville C WWTP	0.72	0.58	0.43	0.24	0.12	0.05
Strongsville Foltz	0.66	0.53	0.40	0.19	0.08	0.04
University Heights	0.57	0.38	0.30	0.17	0.06	0.02
Wade Park	0.52	0.45	0.27	0.13	0.06	0.03
Westerly WWTP	0.66	0.52	0.37	0.22	0.10	0.04
Westlake	0.79	0.71	0.54	0.24	0.11	0.04

Work Order Detail Report

1/3/2024

12:16 PM

so overflow inspections 01-01-2024 0.18'

WO Number: 240102-0001

Category:

SSOs

Status: New Work Order

Problem:

Storm Response

Status Date: 1/2/2024 8:50 am

Main Task:

Inspection

Asset: SSO 431

Location: FAIRFAX AT NORTH PARK

Cause: Weather

Assigned By:

Assigned Crew:

Assigned Date:

Supervisor: Jackson, Jeff

Start Date: 1/1/2024 8:00 AM

Lead Worker: Mc Coy, Sam

End Date: 1/1/2024 12:05 PM

Priority: High

Override

Account #:

Notifications

Proj No - Acct:

Project ID:

Problem ☐

Project:

Project Name:

Overdue ☐

Reason:

Lead Worker ☐

Received By:

Task ☐

Inspected By:

Supervisor ☐

Hard Lock WO ☐

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Locations

Address		Address 2
X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265 664,329.55524255		
2,226,354.79813956 664,409.89202413		
2,226,389.92077273 664,379.07548472		
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

so overflow inspections 01-01-2024 0.18'

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

1/3/2024

12:16 PM

so overflow inspections 01-01-2024 0.18'

2,227,825.14395215 684,881.15948047

Work Order Detail Report

so overflow inspections 01-01-2024 0.18'

Work Order Assets						
<u>Object Type</u>		<u>Description 1</u>			<u>Description 2</u>	
<u>System ID 1</u>	<u>System ID 2</u>	<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>	<u>Asset ID</u> <u>Completed</u>
Sewer Control Valve					FAIRFAX AT NORTH PARK	26
SSO 431						
Sewer Control Valve					NORTH PARK AND COVENTRY	16
SSO 114						
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH	35
SSO 121						
Sewer Structure						3094
SA16AAWB0					FAIRMOUNT AT FAIRFAX	7
Sewer Control Valve						
SSO 112					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	6
Sewer Control Valve						
SSO 99					3012 NORTH WOODLAND	14
Sewer Control Valve						
SSO 432						55
Sewer Control Valve						
DB-03						56
Sewer Control Valve						
DB-01						57
Sewer Control Valve					FAIRMOUNT AT DARTMOOR	5
DB-02						
Sewer Control Valve					FAIRMOUNT AT WELLINGTON	44
CH-04						
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	33
SSO 110						
Sewer Control Valve					FAIRMOUNT AT MARLBORO	4
SSO 87						
Sewer Control Valve					FAIRMOUNT AT ARLINGTON	46
SSO 116						
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)	37
SSO 111						
Sewer Control Valve					FAIRMOUNT AND COVENTRY	47
SSO 113						
Sewer Control Valve					SCARBOROUGH AT LAMBERTON	53
SSO 124						
Sewer Control Valve					BRADFORD AND LEE	11
CH-50						
Sewer Control Valve					EDDINGTON	2
SSO 129						
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")	42
CH-52						
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL	36
SSO 88						
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")	34
SSO 122						
Sewer Control Valve						
SSO 89						1536
Sewer Structure					HAMPSHIRE AT EUCLID HTS. BLVD.	20
SA16ADZB0						
Sewer Control Valve						4446
SSO 91					CEDAR BTW. FAIRMOUNT/DEMINGTON	8
Sewer Structure						
SA16ADPH0					2828 BERKSHIRE, EAST OF COVENTRY	19
Sewer Control Valve						
SSO 120					3003 EUCLID HEIGHTS BLVD	15
Sewer Control Valve						
SSO 103						
Sewer Control Valve						
SSO 104						

Work Order Detail Report

so overflow inspections 01-01-2024 0.18'

Sewer Structure	3402
SA16AGMG0	South Taylor between Antisdale Ave and Superior F
Sewer Control Valve	52
CH-30	LEE RD. & SUPERIOR AVE.
Sewer Control Valve	9
DV-11	EUCLID HEIGHTS BLVD AND LEE
Sewer Control Valve	22
SSO 108	EUCLID HEIGHTS BLVD/CUMBERLAND
Sewer Control Valve	43
SSO 106	1685 CUMBERLAND
Sewer Control Valve	18
SSO 95	CUMBERLAND/SOMERTON
Sewer Control Valve	30
SSO 105	
Sewer Structure	4987
SA16AQD0	
Sewer Structure	3745
SA16AQQC0	2225 NOBLE ROAD
Sewer Control Valve	3
SSO 102	QUILLIAMS, N. OF RANDOLF
Sewer Control Valve	38
SSO 107	LANGTON AND ATHERSTONE
Sewer Control Valve	54
CH-51	
Sewer Structure	1809
SA16APEF0	

Work Order Detail Report

1/3/2024

12:16 PM

so overflow inspections 01-01-2024 0.18'

Check List				
	Item	Completed	Condition	Completion Date/Time
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	1/2/2024/
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	1/2/2024/
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	1/2/2024/
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	1/2/2024/
Sewer main appears blocked				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐		1/3/2024/
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	1/2/2024/
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	1/2/2024/
8	A-6 FAIRMOUNT AT SHELburne ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	1/2/2024/
Water Main Break at 3 locations on Shelburne possibly				
9	A-5 FAIRMOUNT AT SHELburne SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	1/2/2024/
Water main Break possibly				
10	A-7 FAIRMOUNT AT SHELburne SA16AAVH0 (EAST BOUND)	☐	Sound	1/2/2024/
Water Main Break possibly				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	1/2/2024/
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	1/2/2024/
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐		/
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐		/
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	1/2/2024/
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	1/2/2024/
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	1/2/2024/
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Not Sound	1/2/2024/
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	1/2/2024/
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	1/2/2024/
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	1/2/2024/
22	A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	☐	Not Sound	1/2/2024/
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	1/3/2024/
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	1/2/2024/
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	1/2/2024/
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	1/2/2024/

Work Order Detail Report

1/3/2024

12:16 PM

sso overflow inspections 01-01-2024 0.18'

27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	1/2/2024/
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	1/2/2024/
29	B-42 12537 CEDAR SA16ACZA0	☐	Sound	1/3/2024/
30	B-15 COVENTRY AND CEDAR SA16ADBHO	☐	Sound	1/2/2024/
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	1/2/2024/
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	1/3/2024/
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	1/2/2024/
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	1/2/2024/
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Sound	1/3/2024/
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Sound	1/3/2024/
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRLO	☐	Sound	1/3/2024/
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Sound	1/2/2024/
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Sound	1/2/2024/
40	C-59 3427 THORNE RD SA16AQD0	☐	Sound	1/2/2024/
Need replaced				
41	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	1/2/2024/
Needs replaced				
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	1/2/2024/
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	1/2/2024/
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	1/2/2024/
45	C-50 3593 FENLEY SA16APEH0	☐	Sound	1/2/2024/

Tasks/Resources

SMCT36 Inspection

Crew: Status: *Cal'c UC: \$7.45 *Task Cost: \$335.40 Start Dt: 1/1/2024
Supervisor: UOM: Each # of Units: 45.00 *Unit Cost: \$0.00 End Dt: 1/1/2024

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
40151 Mc Coy, Sam	Hours	4.00	\$105.60		1/1/2024	1/1/2024
12459 Eathridge, David	Hours	4.00	\$105.60		1/1/2024	1/1/2024

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD 350 CREW CAB 9	Hours	4.00	\$70.60		1/1/2024	1/1/2024
CHFLT55 FORD F250 PICK UP 0	Hours	4.00	\$53.60		1/1/2024	1/1/2024

Task Comment: sso overflow inspections

Projected Complete:		Lock: ☐	WO Duration	*Actual4.08	*Estimated0.00	*Difference0.00
Repair Type:			Labor Hours	8.00	0.00	0.00
Subcontractor:			Labor Costs	\$211.20	\$0.00	\$0.00
Profit Center:			Material Costs	0.00	0.00	0.00
			Fluids Costs	0.00	0.00	0.00
Quantity: 0.00		Lock: ☐	Equipment Costs	124.20	0.00	0.00
Unit of Measure: Each			Contractor Costs	0.00	0.00	0.00
Unit Cost: \$0.00			Misc. Costs	0.00	0.00	0.00
WO Hours: 0.00			Total Costs	\$335.40	\$0.00	\$0.00
			Use Task Info:	True	True	

Billing

Billed Party

Customer ID:

Customer Name:

Address:

City:

State:

Zip:

Customer Number:

Last Name:

Phone:

Fax #:

E-mail:

Cell #:

Billing Data

Contact Name:

Invoice Number:

Incoming Account #:

*Billing Amount:

Date Bill Sent:

Payment Received:

Payment Method:

Billing Required: ☐

Billing Processed: ☐

Imported to Financials: ☐

Associated PMs	
PM Code and Description	Closed
SSO-02 SSO INSPECTION	☒

Tracking	
Item	Description
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION
Supervisor Notification	Email Queued Successfully!

Rate:

Received By:

Work From:

Pipe Size:

Pipe Condition:

Could Not Open:

Additional Repair:

Dye Test Reason:

Test Performed Throug

Dye Test Results:

WO User 51:

Measurement:

History:

Manhole Basin Repair:

Material Used:

Pipe Repair:

Street Repair:

Grass Repair:

Curb Repair:

Driveway- Sidewalk Re

Construction Crew:

WO User 39:

WO User 40:

WO User 41:

Opened At:

Pipe Footage Cleaned

Gallons Used:

WO User 23:

WO User 24:

WO User 9:

User 10:

Appointment Date DNL

Appointment Date:

E Mail:

Measurement Line 2:

Pipe Size:

PVC Tees, Angles, Slee

WO User 44:

WO User 45:

WO User 46:

OUPS #:

WO User 48:

Televised: ☐

Power Rooter: ☐

Jet: ☐

Gap Vac: ☐

Dye Test: ☐

Gap Root Cut: ☐

GIS Correction?: ☐

Test Tee Correction: ☐

1/2/2024 8:00 AM

Work Order Detail Report

1/3/2024

iso overflow inspections 01-01-2024 0.18'

12:16 PM

NO User 52:	WO User 62:	
NO User 53:	WO User 63:	
NO User 54:	WO User 64:	
NO User 55:	WO User 65:	
NO User 56:	WO User 66:	
NO User 57:	WO User 67:	
NO User 58:	WO User 68:	
NO User 59:	WO User 69:	
NO User 60:	WO User 70:	
NO User 61:	WO User 71:	
NO User 72:	WO User 82:	Televised: ☐
NO User 73:	Quantity:	Paid: ☐
NO User 74:	WO User 84:	WO User 104: ☐
NO User 75:	WO User 85:	WO User 105: ☐
NO User 76:	WO User 86:	WO User 106: ☐
NO User 92 Date:	WO User 97 Date:	
NO User 93 Date:	WO User 98 Date:	
NO User 94 Date:	WO User 99 Date:	
NO User 95 Date:	WO User 100 Date:	
NO User 96 Date:	WO User 101 Date:	
NO User 77:	WO User 87:	WO User 107: ☐
NO User 78:	WO User 88:	WO User 108: ☐
NO User 79:	WO User 89:	WO User 109: ☐
NO User 80:	WO User 90:	WO User 110: ☐
NO User 81:	WO User 91:	WO User 111: ☐
NO Creator: jjackson	WO Creation Date: 1/2/2024	PM Trigger: Rec #: 15271