

CITY OF
CLEVELAND
HEIGHTS
LAW DEPARTMENT

February 13, 2024

Via E-Mail: vezner.kris@epa.gov and Berger.Jake@epa.gov

Kris P. Vezner, Esq.
Associate Regional Counsel
U.S. Environmental Protection Agency
Region 5 (C-14J)
77 West Jackson Blvd.
Chicago, IL 60604

and

Jake Berger
Physical Scientist
Water Enforcement & Compliance Assurance Branch
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Mail Code ECW-15J
Chicago, IL 60604


Re: January 2024 Overflow Monitoring Reports
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through January 31, 2024, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,



William R. Hanna
Director of Law

Enclosures

Overflow Monitoring Update
February 13, 2024


cc: Thomas Benson, Esq., EPA Attorney
James Vinch, Esq., EPA Attorney
James Zimny, EPA Engineer
U.S. EPA Region 5 Water Enforcement Branch
Mark Klingenstein, Environmental Engineer
Erm Gomes, Ohio EPA
Allison Cycyk, Ohio EPA
Casey Galligan, Ohio EPA
David Brumbaugh, Ohio EPA
Bill Fischbein, Ohio EPA
Kahlil Seren, Mayor
Collette Clinkscale, Director of Public Works
Steve Barker, Public Relations
Anthony Ferrone, Utilities Commissioner
Kevin Vander Tuig, P.E. (Outside Engineer)
Mathew St. Pierre, (Outside Engineer)
Dan Porter (Outside Engineer)
Cindy Biacofsky (Outside Engineer)
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Tuesday, January 9, 2024

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Tuesday, January 9, 2024

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.56	0.29	0.18	0.10	0.06	0.04
Brecksville	0.79	0.41	0.25	0.12	0.04	0.02
Brook Park	0.58	0.38	0.27	0.16	0.05	0.02
Cleveland Industrial Pkwy	0.55	0.37	0.25	0.14	0.06	0.03
Dille Ave PS	0.40	0.27	0.17	0.10	0.04	0.02
Division Ave PS	0.48	0.32	0.20	0.11	0.04	0.02
Easterly WWTP	0.36	0.24	0.14	0.09	0.03	0.02
Independence	0.65	0.35	0.21	0.12	0.05	0.03
James Rhodes HS	0.44	0.30	0.22	0.14	0.05	0.02
Jennings PS	0.60	0.39	0.26	0.15	0.04	0.02
Macedonia	0.80	0.44	0.27	0.12	0.05	0.02
Maple Heights	0.58	0.30	0.18	0.09	0.05	0.02
Mary Street PS	0.48	0.32	0.21	0.12	0.05	0.04
Mayfield Heights	0.62	0.31	0.18	0.11	0.07	0.04
Moreland Hills	0.73	0.37	0.22	0.10	0.06	0.05
North Olmsted	0.64	0.39	0.23	0.12	0.04	0.02
North Royalton	0.79	0.43	0.28	0.16	0.09	0.07
Oakwood	0.74	0.41	0.25	0.12	0.04	0.02
Olmsted Falls	0.55	0.32	0.20	0.10	0.04	0.02
Parma	0.70	0.44	0.27	0.17	0.06	0.03
Richfield	0.81	0.44	0.26	0.12	0.04	0.02
Shaker Heights	0.54	0.31	0.18	0.09	0.03	0.02
South Euclid	0.51	0.32	0.20	0.10	0.03	0.02
Southerly WWTC	0.41	0.28	0.21	0.13	0.05	0.03
Strongsville C WWTP	0.69	0.42	0.28	0.16	0.06	0.03
Strongsville Foltz	0.65	0.38	0.25	0.14	0.05	0.03
University Heights	0.53	0.31	0.18	0.10	0.03	0.02
Wade Park	0.49	0.34	0.20	0.11	0.03	0.02
Westerly WWTP	0.41	0.26	0.16	0.08	0.03	0.02
Westlake	0.70	0.43	0.25	0.13	0.05	0.02

so overflow inspection 01-09-2024 0.53'

WO Number: 240111-0003

Status: Closed In Field

Status Date: 1/11/2024 3:47 pm

Asset: SSO 431

Location: FAIRFAX AT NORTH PARK

Cause: Weather

Assigned Crew:

Supervisor: Jackson, Jeff

Lead Worker: Manco, Angelo

Priority: High

Account #:

Proj No - Acct:

Project:

Reason:

Received By:

Inspected By:

Category: SSOs

Problem: Storm Response

Main Task: Inspection

Assigned By:

Assigned Date:

Start Date: 1/11/2024 8:00 AM

End Date: 1/11/2024 1:15 PM

Project ID:

Project Name:

Override

Notifications

Problem ☐

Overdue ☐

Lead Worker ☐

Task ☐

Supervisor ☐

Hard Lock WO ☐

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Locations			Address 2
Address		General Location	
X Coord	Y Coord		
FAIRFAX AT NORTH PARK		Doan Brook	
2,220,655.65435414	665,517.24643672		
NORTH PARK AND COVENTRY		DOAN BROOK - MAIN BRANCH	
2,219,873.16674590	666,048.82312946		
FAIRMOUNT SOUTH OF SCARBOROUGH		DOAN BROOK - MAIN BRANCH	
2,220,364.86097248	666,446.72325230		
FAIRMOUNT AT FAIRFAX		DOAN BROOK - MAIN BRANCH	
2,220,920.81917815	666,080.57995571		
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		DOAN BROOK - MAIN BRANCH	
2,223,053.81655256	664,693.25202172		
3012 NORTH WOODLAND		Doan Brook	
2,222,845.06631389	664,689.08536339		
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR		DOAN BROOK - MAIN BRANCH	
2,225,149.97508989	664,453.31024438		
FAIRMOUNT AT WELLINGTON		DOAN BROOK - MAIN BRANCH	
2,223,969.26550905	664,532.08075613		
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		DOAN BROOK - MAIN BRANCH	
2,223,111.44143730	664,794.46048072		
FAIRMOUNT AT MARLBORO		DOAN BROOK - MAIN BRANCH	
2,221,638.88762389	665,726.15513962		

Work Order Detail Report

overflow inspection 01-09-2024 0.53'

FAIRMOUNT AT ARLINGTON		
222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
228,126.76638040	684,188.23206055	
220,777.89623564	666,181.72575080	
218,501.67473823	671,997.54581206	
216,759.55453481	670,474.59347738	
224,536.21778722	668,887.44048372	
226,741.35609348	679,432.95121680	
226,591.76420106	679,420.92761880	

Work Order Detail Report

1/12/2024

iso overflow inspection 01-09-2024 0.53'

11:30 AM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

1/12/2024

so overflow inspection 01-09-2024 0.53'

11:30 AM

Work Order Assets

Object Type		Description 1			Description 2		Completed
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	
Sewer Control Valve					FAIRFAX AT NORTH PARK		
SSO 431						26	
Sewer Control Valve					NORTH PARK AND COVENTRY		
SSO 114						16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Control Valve					3012 NORTH WOODLAND		
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO		
SSO 116						4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY		
SSO 124						47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON		
CH-50						53	
Sewer Control Valve					BRADFORD AND LEE		
SSO 129						11	
Sewer Control Valve					EDDINGTON		
CH-52						2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL		
SSO 122						36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103						19	
Sewer Control Valve					3003 EUCLID HEIGHTS BLVD		
SSO 104						15	

Work Order Detail Report

1/12/2024

so overflow inspection 01-09-2024 0.53'

11:30 AM

Check List				
	Item	Completed	Condition	Completion Date/Time
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	1/11/2024/
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	1/11/2024/
3	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	1/11/2024/
4	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	1/11/2024/
5	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	1/11/2024/
6	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	1/11/2024/
7	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	1/11/2024/
8	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	1/11/2024/
9	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	1/11/2024/
10	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	1/11/2024/
11	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	1/11/2024/
12	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	/
13	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	1/11/2024/
14	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	1/11/2024/
15	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	1/11/2024/
16	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	1/11/2024/
17	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Not Sound	1/11/2024/
18	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Not Sound	1/11/2024/
No block				
19	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	1/11/2024/
20	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	1/11/2024/
21	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	1/11/2024/
22	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	1/11/2024/
23	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	1/11/2024/
24	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	1/11/2024/
25	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	1/11/2024/
26	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	1/11/2024/
27	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	1/11/2024/
28	C-59 3427 THORNE RD SA16AQQD0	☐	Sound	1/11/2024/
29	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	1/11/2024/
30	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	1/11/2024/

1/11/2024

sso overflow inspection 01-09-2024 0.53'

31	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	1/11/2024/
32	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Not Sound	1/11/2024/
33	C-50 3593 FENLEY SA16APEH0	☐	Sound	1/11/2024/

Tasks/Resources

SMCT36 Inspection

Crew: Supervisor:

Status: UOM: Each

*Cal'c UC: \$9.33
of Units: 45.00

*Task Cost: \$420.00
*Unit Cost: \$0.00

Start Dt: 1/11/2024
End Dt: 1/11/2024

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
19356 Manco, Angelo	Hours	5.00	\$138.85		1/11/2024	1/11/2024
13859 Moten, Robert	Hours	5.00	\$125.90		1/11/2024	1/11/2024

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD F250 PICK UP 0	Hours	5.00	\$67.00		1/11/2024	1/11/2024
CHFLT55 FORD 350 CREW CAB 9	Hours	5.00	\$88.25		1/11/2024	1/11/2024

Task Comment: sso overflow inspection 01-09-2024 0.53'

Projected Complete: Lock: ☐

Repair Type:

Subcontractor:

Profit Center:

Quantity:	0.00	Lock:	☐	WO Duration	*Actual	*Estimated	*Difference
Unit of Measure:	Each			Labor Hours	5.25	0.00	0.00
Unit Cost:	\$0.00			Labor Costs	10.00	0.00	0.00
WO Hours:	0.00			Labor Costs	\$264.75	\$0.00	\$0.00
				Material Costs	0.00	0.00	0.00
				Fluids Costs	0.00	0.00	0.00
				Equipment Costs	155.25	0.00	0.00
				Contractor Costs	0.00	0.00	0.00
				Misc. Costs	0.00	0.00	0.00
				Total Costs	\$420.00	\$0.00	\$0.00
				Use Task Info:	True	True	

Billing

Billed Party

Customer ID: Customer Name: Address: City: State: Zip:

Customer Number: Last Name: Phone: Cell #: Fax #: E-mail:

Billing Data

Contact Name: Invoice Number: Incoming Account #:

*Billing Amount: Date Bill Sent: Payment Received: Payment Method:

Billing Required: ☐
Billing Processed: ☐
Imported to Financials: ☐

Associated PMs


PM Code and Description	Closed
SSO-02 SSO INSPECTION	☒

Tracking

Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	1/11/2024	10:35 AM
Supervisor Notification	Email Queued Successfully!	jjackson	1/11/2024	10:35 AM
Leadworker Notification	Email Queued Successfully!	jjackson	1/11/2024	10:35 AM
Status Change	From New Work Order to Closed In Field	amanco	1/11/2024	3:47 PM

Rate:	Opened At:	Televised:	☐
Recieved By:	Pipe Footage Cleaned:	Power Rooter:	☐
Work From:	Gallons Used:	Jet:	☐
Pipe Size:	WO User 23:	Gap Vac:	☐
Pipe Condition:	WO User 24:	Dye Test:	☐
Could Not Open:	WO User 9:	Gap Root Cut:	☐
Additional Repair:	User 10:	GIS Correction?:	☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	☐
Test Performed Throug	Appointment Date:	1/11/2024	8:00 AM
Dye Test Results:			
WO User 51:			
Measurement:	E Mail:		
History:	Measurement Line 2:		
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Slee		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:			
WO User 40:	OUPS #:		
WO User 41:	WO User 48:		
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	☐
WO User 73:	Quantity:	Paid:	☐
WO User 74:	WO User 84:	WO User 104:	☐
WO User 75:	WO User 85:	WO User 105:	☐
WO User 76:	WO User 86:	WO User 106:	☐
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	☐
WO User 78:	WO User 88:	WO User 108:	☐
WO User 79:	WO User 89:	WO User 109:	☐
WO User 80:	WO User 90:	WO User 110:	☐
WO User 81:	WO User 91:	WO User 111:	☐
WO Creator: jjackson	WO Creation Date: 1/11/2024	PM Trigger:	Rec #: 15291

Daily Precipitation Report
Friday, January 12, 2024
Accumulation in Inches



Northeast Ohio Regional Sewer District **Daily Precipitation Report** Friday, January 12, 2024

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.28	0.26	0.25	0.18	0.06	0.03
Brecksville	0.33	0.30	0.26	0.19	0.06	0.03
Brook Park	0.40	0.37	0.32	0.24	0.10	0.04
Cleveland Industrial Pkwy	0.35	0.32	0.28	0.20	0.07	0.03
Dille Ave PS	0.28	0.26	0.25	0.17	0.07	0.03
Division Ave PS	0.41	0.38	0.36	0.27	0.11	0.05
Easterly WWTP	0.34	0.33	0.31	0.23	0.10	0.05
Independence	0.35	0.33	0.30	0.15	0.05	0.02
James Rhodes HS	0.29	0.27	0.26	0.19	0.06	0.03
Jennings PS	0.40	0.37	0.35	0.25	0.10	0.05
Macedonia	0.33	0.29	0.25	0.18	0.07	0.03
Maple Heights	0.30	0.28	0.25	0.17	0.06	0.02
Mary Street PS	0.36	0.33	0.31	0.22	0.08	0.03
Mayfield Heights	0.30	0.27	0.23	0.17	0.06	0.02
Moreland Hills	0.32	0.28	0.25	0.17	0.05	0.02
North Olmsted	0.32	0.28	0.25	0.14	0.05	0.02
North Royalton	0.33	0.30	0.25	0.15	0.05	0.03
Oakwood	0.35	0.31	0.25	0.17	0.05	0.02
Olmsted Falls	0.35	0.32	0.27	0.20	0.08	0.03
Parma	0.51	0.48	0.46	0.27	0.09	0.04
Richfield	0.31	0.26	0.22	0.14	0.04	0.02
Shaker Heights	0.34	0.32	0.29	0.18	0.06	0.03
South Euclid	0.33	0.32	0.29	0.20	0.07	0.03
Southerly WWTC	0.27	0.26	0.25	0.19	0.08	0.03
Strongsville C WWTP	0.41	0.37	0.33	0.24	0.09	0.04
Strongsville Foltz	0.41	0.37	0.34	0.25	0.10	0.05
University Heights	0.34	0.32	0.30	0.20	0.07	0.03
Wade Park	0.37	0.36	0.34	0.24	0.09	0.04
Westerly WWTP	0.33	0.31	0.28	0.21	0.08	0.03
Westlake	0.31	0.26	0.24	0.17	0.06	0.03

so overflow inspections 01-13-2024 0.22'

WO Number: 240117-0001

Category: SSOs

Status: New Work Order

Problem: Storm Response

Status Date: 1/17/2024 7:23 am

Main Task: Inspection

Asset: SSO 431

Assigned By:

Location: FAIRFAX AT NORTH PARK

Assigned Date:

Cause: Weather

Start Date: 1/18/2024 8:00 AM

Assigned Crew:

End Date: 1/18/2024 1:35 PM

Supervisor: Jackson, Jeff

Override

Lead Worker: Cardarella, Joe

Notifications

Priority: High

Problem ☐

Account #:

Overdue ☐

Proj No - Acct:

Lead Worker ☐

Project:

Task ☐

Reason:

Supervisor ☐

Received By:

Hard Lock WO ☐

Inspected By:

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Comments for Crew

Sub-Division:

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
Address			
X Coord	Y Coord	General Location	
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672	Doan Brook	
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339	Doan Brook	
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT MARLBORO			
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH	

Work Order Detail Report

so overflow inspections 01-13-2024 0.22'

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

1/18/2024

10:41 AM

iso overflow inspections 01-13-2024 0.22'

2,227,825.14395215 684,881.15948047

Work Order Detail Report

1/18/2024

10:41 AM

so overflow inspections 01-13-2024 0.22'

Work Order Assets						
Object Type	Description 1			Description 2		
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID
Sewer Control Valve					FAIRFAX AT NORTH PARK	26
SSO 431						
Sewer Control Valve					NORTH PARK AND COVENTRY	16
SSO 114						
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH	35
SSO 121						
Sewer Structure						3094
SA16AAWB0					FAIRMOUNT AT FAIRFAX	7
Sewer Control Valve						
SSO 112					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	6
Sewer Control Valve						
SSO 99					3012 NORTH WOODLAND	14
Sewer Control Valve						
SSO 432						55
Sewer Control Valve						
DB-03						56
Sewer Control Valve						
DB-01						57
Sewer Control Valve						
DB-02					FAIRMOUNT AT DARTMOOR	5
Sewer Control Valve						
CH-04					FAIRMOUNT AT WELLINGTON	44
Sewer Control Valve						
SSO 110					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	33
Sewer Control Valve						
SSO 87					FAIRMOUNT AT MARLBORO	4
Sewer Control Valve						
SSO 116					FAIRMOUNT AT ARLINGTON	46
Sewer Control Valve						
SSO 111					FAIRMOUNT & COVENTRY (SCARBOROUGH)	37
Sewer Control Valve						
SSO 113					FAIRMOUNT AND COVENTRY	47
Sewer Control Valve						
SSO 124					SCARBOROUGH AT LAMBERTON	53
Sewer Control Valve						
CH-50					BRADFORD AND LEE	11
Sewer Control Valve						
SSO 129					EDDINGTON	2
Sewer Control Valve						
CH-52					HAMPSHIRE LANE AT MAYFIELD (18")	42
Sewer Control Valve						
SSO 88					EAST OVERLOOK AT EDGEHILL	36
Sewer Control Valve						
SSO 122					HAMPSHIRE LANE AT MAYFIELD (36")	34
Sewer Control Valve						
SSO 89						1536
Sewer Structure						
SA16ADZB0					HAMPSHIRE AT EUCLID HTS. BLVD.	20
Sewer Control Valve						
SSO 91						4446
Sewer Structure						
SA16ADPH0					CEDAR BTW. FAIRMOUNT/DEMINGTON	8
Sewer Control Valve						
SSO 120					2828 BERKSHIRE, EAST OF COVENTRY	19
Sewer Control Valve						
SSO 103					3003 EUCLID HEIGHTS BLVD	15
Sewer Control Valve						
SSO 104						

Work Order Detail Report

1/18/2024

so overflow inspections 01-13-2024 0.22'

10:41 AM

Sewer Structure	3402
SA16AGMG0	
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

1/18/2024

iso overflow inspections 01-13-2024 0.22'

10:41 AM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	1/17/2024/ 2:37 pm	1/17/2024
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	1/17/2024/ 2:38 pm	1/17/2024
3	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	1/17/2024/ 2:38 pm	1/17/2024
4	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	1/17/2024/ 2:38 pm	1/17/2024
5	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	1/17/2024/ 2:38 pm	1/17/2024
6	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	1/17/2024/ 2:39 pm	1/17/2024
7	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	1/17/2024/ 2:39 pm	1/17/2024
8	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	1/17/2024/ 2:39 pm	1/17/2024
9	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	1/17/2024/ 2:40 pm	1/17/2024
10	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	1/17/2024/ 2:40 pm	1/17/2024
11	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	1/17/2024/ 2:40 pm	1/17/2024
12	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	1/17/2024/ 2:40 pm	1/17/2024
13	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	1/17/2024/	1/17/2024
14	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	1/17/2024/ 2:41 pm	1/17/2024
15	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	1/17/2024/ 2:41 pm	1/17/2024
16	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	1/17/2024/ 2:32 pm	1/17/2024
17	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	1/17/2024/ 2:33 pm	1/17/2024
18	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Sound	1/17/2024/ 2:34 pm	1/17/2024
19	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	1/17/2024/ 2:34 pm	1/17/2024
20	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	1/17/2024/ 2:34 pm	1/17/2024
21	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	1/17/2024/ 2:35 pm	1/17/2024
22	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	1/17/2024/ 2:33 pm	1/17/2024
23	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	1/17/2024/ 2:35 pm	1/17/2024
24	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	1/17/2024/ 2:33 pm	1/17/2024
25	B-42 12537 CEDAR SA16ACZA0	☐	Sound	1/17/2024/ 2:35 pm	1/17/2024
26	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	1/17/2024/ 2:36 pm	1/17/2024
27	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	1/17/2024/ 2:36 pm	1/17/2024
28	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	1/17/2024/ 2:36 pm	1/17/2024
29	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	1/17/2024/ 2:36 pm	1/17/2024
30	C-59 3427 THORNE RD SA16AQQD0	☐	Sound	1/17/2024/ 2:37 pm	1/17/2024

Work Order Detail Report

1/18/2024

10:41 AM

ssso overflow inspections 01-13-2024 0.22'

31	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	1/17/2024/ 2:32 pm	1/17/2024
32	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	1/17/2024/ 2:32 pm	1/17/2024
33	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	1/17/2024/ 2:31 pm	1/17/2024
34	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Not Sound	1/17/2024/ 2:31 pm	1/17/2024
35	C-50 3593 FENLEY SA16APEH0	☐	Not Sound	1/17/2024/ 2:30 pm	1/17/2024

Reset

Tasks/Resources

SMCT36 Inspection

Crew: Status: *Cal'c UC: \$7.56 *Task Cost: \$340.05 Start Dt: 1/18/2024
Supervisor: UOM: Each # of Units: 45.00 *Unit Cost: \$0.00 End Dt: 1/18/2024

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	5.00	\$125.90		1/18/2024	1/18/2024
13859 Moten, Robert	Hours	5.00	\$125.90		1/18/2024	1/18/2024

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD 350 CREW CAB 9	Hours	5.00	\$88.25		1/18/2024	1/18/2024

Task Comment: ssso overflow inspections 01-13-2024 0.22'

			*Actual	*Estimated	*Difference
Projected Complete:	Lock: ☐	WO Duration	5.58	0.00	0.00
Repair Type:		Labor Hours	10.00	0.00	0.00
Subcontractor:		Labor Costs	\$251.80	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity: 0.00	Lock: ☐	Equipment Costs	88.25	0.00	0.00
Unit of Measure: Each		Contractor Costs	0.00	0.00	0.00
Unit Cost: \$0.00		Misc. Costs	0.00	0.00	0.00
WO Hours: 0.00		Total Costs	\$340.05	\$0.00	\$0.00
		Use Task Info:	True	True	

Billing

Billed Party

Customer ID: Customer Number:
Customer Name: Last Name:
Address: Phone: Cell #:
City: Fax #:
State: E-mail:
Zip:

Billing Data

Contact Name: *Billing Amount: Billing Required: ☐
Invoice Number: Date Bill Sent: Billing Processed: ☐
Incoming Account #: Payment Received: Imported to Financials: ☐
Payment Method:

Associated PMs

PM Code and Description
SSO-02 SSO INSPECTION

Closed
☒

Tracking

Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	1/17/2024	7:23 AM
Supervisor Notification	Email Queued Successfully!	jjackson	1/17/2024	7:23 AM

Work Order Detail Report

1/18/2024

so overflow inspections 01-13-2024 0.22'

10:41 AM


Rate:	Opened At:	Televised:	☐
Received By:	Pipe Footage Cleaned:	Power Rooter:	☐
Work From:	Gallons Used:	Jet:	☐
Pipe Size:	WO User 23:	Gap Vac:	☐
Pipe Condition:	WO User 24:	Dye Test:	☐
Could Not Open:	WO User 9:	Gap Root Cut:	☐
Additional Repair:	User 10:	GIS Correction?:	☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	☐
Test Performed Through	Appointment Date: 1/17/2024 8:00 AM		
Dye Test Results:			
NO User 51:			
Measurement:	E Mail:		
History:	Measurement Line 2:		
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sleeves		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Repair:			
Construction Crew:			
NO User 39:			
NO User 40:	OUPS #:		
NO User 41:	WO User 48:		
NO User 52:	WO User 62:		
NO User 53:	WO User 63:		
NO User 54:	WO User 64:		
NO User 55:	WO User 65:		
NO User 56:	WO User 66:		
NO User 57:	WO User 67:		
NO User 58:	WO User 68:		
NO User 59:	WO User 69:		
NO User 60:	WO User 70:		
NO User 61:	WO User 71:		
NO User 72:	WO User 82:	Televised:	☐
NO User 73:	Quantity:	Paid:	☐
NO User 74:	WO User 84:	WO User 104:	☐
NO User 75:	WO User 85:	WO User 105:	☐
NO User 76:	WO User 86:	WO User 106:	☐
NO User 92 Date:	WO User 97 Date:		
NO User 93 Date:	WO User 98 Date:		
NO User 94 Date:	WO User 99 Date:		
NO User 95 Date:	WO User 100 Date:		
NO User 96 Date:	WO User 101 Date:		
NO User 77:	WO User 87:	WO User 107:	☐
NO User 78:	WO User 88:	WO User 108:	☐
NO User 79:	WO User 89:	WO User 109:	☐
NO User 80:	WO User 90:	WO User 110:	☐
NO User 81:	WO User 91:	WO User 111:	☐
NO Creator: jjackson	WO Creation Date: 1/17/2024	PM Trigger:	Rec #: 15299

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Friday, January 26, 2024

Accumulation in Inches



WO Number:	240125-0018	Category:	SSOs		
Status:	Closed In Field	Problem:	Storm Response		
Status Date:	1/26/2024 2:53 pm	Main Task:	Inspection		
Asset:	SSO 431				
Location:	FAIRFAX AT NORTH PARK				
Cause:	Weather		Assigned By:		
Assigned Crew:			Assigned Date:		
Supervisor:	Jackson, Jeff	Start Date:	1/26/2024 8:00 AM	Override	
Lead Worker:	Manco, Angelo	End Date:	1/26/2024 12:15 PM	Notifications	
Priority:	High				Problem ☐
Account #:				Overdue	☐
Proj No - Acct:				Lead Worker	☐
Project:				Task	☐
Reason:				Supervisor	☐
Received By:				Hard Lock WO	☐
Inspected By:					

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location:		Comments for Crew Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.
Department:	Sewer Collection	
Division:	Sewer	
Sub-Division:		
Area:		
Sub-Area:		
Owner:		
Location:		
Classification:		
Maintenance Zone:		Alternate Zone:

Work Order Locations			Address 2
Address			
X Coord	Y Coord	General Location	
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672	Doan Brook	
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339	Doan Brook	
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT MARLBORO			
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH	

Work Order Detail Report

1/29/2024

also overflow inspections 01-26-2024 0.26'

1:17 PM

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

1/29/2024

so overflow inspections 01-26-2024 0.26'

1:17 PM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

1/29/2024

so overflow inspections 01-26-2024 0.26'

1:17 PM

Work Order Assets						
Object Type		Description 1			Description 2	
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID
Sewer Control Valve					FAIRFAX AT NORTH PARK	
SSO 431						26
Sewer Control Valve					NORTH PARK AND COVENTRY	
SSO 114						16
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH	
SSO 121						35
Sewer Structure						3094
SA16AAWB0					FAIRMOUNT AT FAIRFAX	
Sewer Control Valve						7
SSO 112					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	
Sewer Control Valve						6
SSO 99					3012 NORTH WOODLAND	
Sewer Control Valve						14
SSO 432						
Sewer Control Valve						55
DB-03						
Sewer Control Valve						56
DB-01						
Sewer Control Valve						57
DB-02					FAIRMOUNT AT DARTMOOR	
Sewer Control Valve						5
CH-04					FAIRMOUNT AT WELLINGTON	
Sewer Control Valve						44
SSO 110					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	
Sewer Control Valve						33
SSO 87					FAIRMOUNT AT MARLBORO	
Sewer Control Valve						4
SSO 116					FAIRMOUNT AT ARLINGTON	
Sewer Control Valve						46
SSO 111					FAIRMOUNT & COVENTRY (SCARBOROUGH)	
Sewer Control Valve						37
SSO 113					FAIRMOUNT AND COVENTRY	
Sewer Control Valve						47
SSO 124					SCARBOROUGH AT LAMBERTON	
Sewer Control Valve						53
CH-50					BRADFORD AND LEE	
Sewer Control Valve						11
SSO 129					EDDINGTON	
Sewer Control Valve						2
CH-52					HAMPSHIRE LANE AT MAYFIELD (18")	
Sewer Control Valve						42
SSO 88					EAST OVERLOOK AT EDGEHILL	
Sewer Control Valve						36
SSO 122					HAMPSHIRE LANE AT MAYFIELD (36")	
Sewer Control Valve						34
SSO 89						
Sewer Structure						1536
SA16ADZB0					HAMPSHIRE AT EUCLID HTS. BLVD.	
Sewer Control Valve						20
SSO 91						
Sewer Structure						4446
SA16ADPH0					CEDAR BTW. FAIRMOUNT/DEMINGTON	
Sewer Control Valve						8
SSO 120					2828 BERKSHIRE, EAST OF COVENTRY	
Sewer Control Valve						19
SSO 103					3003 EUCLID HEIGHTS BLVD	
Sewer Control Valve						15
SSO 104						

Work Order Detail Report

1/29/2024

so overflow inspections 01-26-2024 0.26'

1:17 PM

Sewer Structure	3402
SA16AGMG0	
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

1/29/2024

iso overflow inspections 01-26-2024 0.26'

1:17 PM

Check List				
	Item	Completed	Condition	Completion Date/Time
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	1/26/2024/
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	1/26/2024/
3	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	1/26/2024/
4	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	1/26/2024/
5	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	1/26/2024/
6	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	1/26/2024/
7	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	1/26/2024/
8	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	1/26/2024/
9	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	1/26/2024/
10	A-1 3041 FAIRMOUNT SA16AAUTO (TREE LAWN NEAR SIDEWALK)	☐	Sound	1/26/2024/
11	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	1/26/2024/
12	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	1/26/2024/
13	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	1/26/2024/
14	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	1/26/2024/
15	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	1/26/2024/
16	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	1/26/2024/
17	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	1/26/2024/
18	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Sound	1/26/2024/
19	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	1/26/2024/
20	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	1/26/2024/
21	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	1/26/2024/
22	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	1/26/2024/
23	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	1/26/2024/
24	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	1/26/2024/
25	B-42 12537 CEDAR SA16ACZA0	☐	Sound	1/26/2024/12:16 pm
26	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	1/26/2024/
27	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	1/26/2024/
28	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	1/26/2024/
29	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	1/26/2024/
30	C-59 3427 THORNE RD SA16AQQD0	☐	Sound	1/26/2024/

Work Order Detail Report

sso overflow inspections 01-26-2024 0.26'

1/29/2024

1:17 PM

31	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	/
32	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	1/26/2024/
33	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	1/26/2024/
34	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	1/26/2024/
35	C-50 3593 FENLEY SA16APEH0	☐	Sound	1/26/2024/

Tasks/Resources

SMCT36 Inspection

Crew:

Status:

*Cal'c UC: \$5.59

*Task Cost: \$251.56

Start Dt: 1/26/2024

Supervisor:

UOM: Each

of Units: 45.00

*Unit Cost: \$0.00

End Dt: 1/26/2024

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
12459 Eathridge, David	Hours	4.00	\$105.60		1/26/2024	1/26/2024
40404 Don Johnson		4.00	\$75.36		1/26/2024	1/26/2024

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD 350 CREW CAB 9	Hours	4.00	\$70.60		1/26/2024	1/26/2024

Task Comment: sso overflow inspections 01-26-2024 0.26'

Projected Complete:

Lock: ☐

Repair Type:

Subcontractor:

Profit Center:

Quantity: 0.00

Unit of Measure: Each

Unit Cost: \$0.00

WO Hours: 0.00

	*Actual	*Estimated	*Difference
WO Duration	4.25	0.00	0.00
Labor Hours	8.00	0.00	0.00
Labor Costs	\$180.96	\$0.00	\$0.00
Material Costs	0.00	0.00	0.00
Fluids Costs	0.00	0.00	0.00
Equipment Costs	70.60	0.00	0.00
Contractor Costs	0.00	0.00	0.00
Misc. Costs	0.00	0.00	0.00
Total Costs	\$251.56	\$0.00	\$0.00
Use Task Info:	True	True	

Billed Party

Billing

Customer ID:

Customer Name:

Address:

City:

State:

Zip:

Customer Number:

Last Name:

Phone:

Cell #:

Fax #:

E-mail:

Billing Data

Contact Name:

Invoice Number:

Incoming Account #:

*Billing Amount:

Date Bill Sent:

Payment Received:

Payment Method:

Billing Required: ☐

Billing Processed: ☐

Imported to Financials: ☐

Associated PMs

PM Code and Description

SSO-02 SSO INSPECTION

Closed

☒

Tracking

Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	1/25/2024	3:39 PM
Supervisor Notification	Email Queued Successfully!	jjackson	1/25/2024	3:39 PM
Leadworker Notification	Email Queued Successfully!	jjackson	1/25/2024	3:39 PM
Status Change	From New Work Order to Closed In Field	deathridge	1/26/2024	2:53 PM

Work Order Detail Report

1/29/2024

so overflow inspections 01-26-2024 0.26'

1:17 PM

Rate:

Recieved By:

Work From:

Pipe Size:

Pipe Condition:

Could Not Open:

Additional Repair:

Dye Test Reason:

Test Performed Throug

Dye Test Results:

NO User 51:

Measurement:

History:

Manhole Basin Repair:

Material Used:

Pipe Repair:

Street Repair:

Grass Repair:

Curb Repair:

Driveway- Sidewalk Re

Construction Crew:

NO User 39:

NO User 40:

NO User 41:

NO User 52:

NO User 53:

NO User 54:

NO User 55:

NO User 56:

NO User 57:

NO User 58:

NO User 59:

NO User 60:

NO User 61:

NO User 72:

NO User 73:

NO User 74:

NO User 75:

NO User 76:

NO User 92 Date:

NO User 93 Date:

NO User 94 Date:

NO User 95 Date:

NO User 96 Date:

NO User 77:

NO User 78:

NO User 79:

NO User 80:

NO User 81:

NO Creator:jjackson

Opened At:

Pipe Footage Cleaned:

Gallons Used:

WO User 23:

WO User 24:

WO User 9:

User 10:

Appointment Date DNL

Appointment Date:1/26/20248:00 AM

E Mail:

Measurement Line 2:

Pipe Size:

PVC Tees, Angles, Slec

WO User 44:

WO User 45:

WO User 46:

OUPS #:

WO User 48:

WO User 62:

WO User 63:

WO User 64:

WO User 65:

WO User 66:

WO User 67:

WO User 68:

WO User 69:

WO User 70:

WO User 71:

WO User 82:

Quantity:

WO User 84:

WO User 85:

WO User 86:

WO User 97 Date:

WO User 98 Date:

WO User 99 Date:

WO User 100 Date:

WO User 101 Date:

WO User 87:

WO User 88:

WO User 89:

WO User 90:

WO User 91:

WO Creation Date:1/25/2024

PM Trigger:

Televised:☐

Power Rooter:☐

Jet:☐

Gap Vac:☐

Dye Test:☐

Gap Root Cut:☐

GIS Correction?:☐

Test Tee Correction:☐

Televised:☐

Paid:☐

WO User 104:☐

WO User 105:☐

WO User 106:☐

WO User 107:☐

WO User 108:☐

WO User 109:☐


WO User 110:☐

WO User 111:☐

Rec #:15322

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report
Sunday, January 28, 2024
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Sunday, January 28, 2024

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.69	0.37	0.24	0.12	0.05
Brecksville	0.81	0.42	0.26	0.13	0.06
Brook Park	0.54	0.28	0.19	0.12	0.04
Cleveland Industrial Pkwy	0.77	0.34	0.24	0.13	0.04
Dille Ave PS	0.75	0.39	0.23	0.11	0.04
Division Ave PS	0.73	0.35	0.22	0.11	0.04
Easterly WWTP	0.65	0.39	0.24	0.11	0.04
Independence	0.58	0.36	0.24	0.13	0.06
James Rhodes HS	0.65	0.32	0.22	0.14	0.05
Jennings PS	n/a	n/a	n/a	n/a	n/a
Macedonia	0.71	0.37	0.23	0.11	0.05
Maple Heights	0.73	0.40	0.28	0.15	0.07
Mary Street PS	0.73	0.37	0.24	0.12	0.04
Mayfield Heights	0.78	0.35	0.22	0.11	0.04
Moreland Hills	0.82	0.41	0.26	0.13	0.05
North Olmsted	0.79	0.41	0.24	0.14	0.06
North Royalton	0.64	0.32	0.23	0.13	0.06
Oakwood	0.66	0.36	0.23	0.11	0.06
Olmsted Falls	0.58	0.28	0.19	0.13	0.06
Parma	0.71	0.33	0.23	0.15	0.05
Richfield	0.63	0.30	0.24	0.14	0.04
Shaker Heights	0.76	0.37	0.22	0.11	0.05
South Euclid	0.73	0.33	0.21	0.11	0.04
Southerly WWTC	0.65	0.35	0.23	0.13	0.05
Strongsville C WWTP	0.65	0.30	0.21	0.13	0.05
Strongsville Foltz	0.49	0.25	0.20	0.14	0.06
University Heights	0.82	0.37	0.23	0.13	0.05
Wade Park	0.70	0.35	0.19	0.11	0.04
Westerly WWTP	0.78	0.41	0.26	0.12	0.04
Westlake	0.72	0.37	0.23	0.13	0.06

WO Number: 240202-0005		Category:	SSOs	
Status:	Closed In Field	Problem:	Storm Response	
Status Date:	2/2/2024 3:46 pm	Main Task:	Inspection	
Asset: SSO 431				
Location: FAIRFAX AT NORTH PARK				
Cause:	Weather		Assigned By:	
Assigned Crew:			Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	2/28/2024 8:05 AM	Override
Lead Worker:	Manco, Angelo	End Date:	2/28/2024 1:08 PM	Notifications
Priority:	High			
Account #:		Problem ☐		
Proj No - Acct:		Overdue ☐		
Project:		Lead Worker ☐		
Reason:		Task ☐		
Received By:		Supervisor ☐		
Inspected By:		Hard Lock WO ☐		
Project ID:				
Project Name:				

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location		Comments for Crew Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.
Department:	Sewer Collection	
Division:	Sewer	
Sub-Division:		
Area:		
Sub-Area:		
Owner:		
Location:		
Classification:		
Maintenance Zone:	Alternate Zone:	

Work Order Locations			Address 2
Address			
X Coord	Y Coord	General Location	
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672	Doan Brook	
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339	Doan Brook	
2,226,440.21168265 664,329.55524255			
2,226,354.79813956 664,409.89202413			
2,226,389.92077273 664,379.07548472			
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT MARLBORO			
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH	

Work Order Detail Report

2/5/2024

iso overflow inspections 02-5-2024 0.82'

9:10 AM

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

2/5/2024

also overflow inspections 02-5-2024 0.82'

9:10 AM

2,227,825.14395215 684,881.15948047

Work Order Assets							
Object Type	Description 1			Description 2			
	System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID
Sewer Control Valve						FAIRFAX AT NORTH PARK	
SSO 431							26
Sewer Control Valve						NORTH PARK AND COVENTRY	
SSO 114							16
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH	
SSO 121							35
Sewer Structure							
SA16AAWB0							3094
Sewer Control Valve						FAIRMOUNT AT FAIRFAX	
SSO 112							7
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	
SSO 99							6
Sewer Control Valve						3012 NORTH WOODLAND	
SSO 432							14
Sewer Control Valve							
DB-03							55
Sewer Control Valve							
DB-01							56
Sewer Control Valve							
DB-02							57
Sewer Control Valve						FAIRMOUNT AT DARTMOOR	
CH-04							5
Sewer Control Valve						FAIRMOUNT AT WELLINGTON	
SSO 110							44
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	
SSO 87							33
Sewer Control Valve						FAIRMOUNT AT MARLBORO	
SSO 116							4
Sewer Control Valve						FAIRMOUNT AT ARLINGTON	
SSO 111							46
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)	
SSO 113							37
Sewer Control Valve						FAIRMOUNT AND COVENTRY	
SSO 124							47
Sewer Control Valve						SCARBOROUGH AT LAMBERTON	
CH-50							53
Sewer Control Valve						BRADFORD AND LEE	
SSO 129							11
Sewer Control Valve						EDDINGTON	
CH-52							2
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")	
SSO 88							42
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL	
SSO 122							36
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")	
SSO 89							34
Sewer Structure							
SA16ADZB0							1536
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.	
SSO 91							20
Sewer Structure							
SA16ADPH0							4446
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON	
SSO 120							8
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY	
SSO 103							19
Sewer Control Valve						3003 EUCLID HEIGHTS BLVD	
SSO 104							15

Work Order Detail Report

2/5/2024

so overflow inspections 02-5-2024 0.82'

9:10 AM

Sewer Structure		
SA16AGMG0		3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F	
CH-30		52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.	
DV-11		9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE	
SSO 108		22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND	
SSO 106		43
Sewer Control Valve	1685 CUMBERLAND	
SSO 95		18
Sewer Control Valve	CUMBERLAND/SOMERTON	
SSO 105		30
Sewer Structure		
SA16AQD0		4987
Sewer Structure		
SA16AQQC0		3745
Sewer Control Valve	2225 NOBLE ROAD	
SSO 102		3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF	
SSO 107		38
Sewer Control Valve	LANGTON AND ATHERSTONE	
CH-51		54
Sewer Structure		
SA16APEF0		1809

Work Order Detail Report

2/5/2024

iso overflow inspections 02-5-2024 0.82'

9:10 AM

Check List

	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	2/2/2024/ 8:22 am	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	2/2/2024/ 8:27 am	
3	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	2/2/2024/ 8:31 am	
4	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	/ 8:36 am	
5	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	2/2/2024/ 8:39 am	
6	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	2/2/2024/ 8:46 am	
7	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	2/2/2024/ 8:51 am	
8	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	2/2/2024/ 9:32 am	
9	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	2/2/2024/ 9:39 am	
10	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐		2/2/2024/ 9:44 am	
Couldn't open manhole cover					
11	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	2/2/2024/ 9:50 am	
12	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	2/2/2024/ 9:55 am	
13	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	2/2/2024/10:02 am	
Debris in manhole					
14	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐		2/2/2024/10:09 am	
No block					
15	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	2/2/2024/10:19 am	
16	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	2/2/2024/10:23 am	
17	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	2/2/2024/10:27 am	
18	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Sound	2/2/2024/10:35 am	
19	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	2/2/2024/12:16 pm	
20	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	2/2/2024/12:25 pm	
21	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	2/2/2024/12:25 pm	
22	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	2/2/2024/12:30 pm	
23	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Sound	2/2/2024/12:34 pm	
24	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	2/2/2024/12:37 pm	
25	B-42 12537 CEDAR SA16ACZA0	☐		/	
26	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	2/2/2024/12:42 pm	
27	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	2/2/2024/12:48 pm	
28	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐		/	

sso overflow inspections 02-5-2024 0.82'

29	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐		/
30	C-59 3427 THORNE RD SA16AQD0	☐	Sound	2/2/2024/ 1:12 pm
31	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	2/2/2024/ 1:12 pm
32	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	2/2/2024/ 1:22 pm
33	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	2/2/2024/ 1:29 am
34	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	2/2/2024/ 1:33 pm
35	C-50 3593 FENLEY SA16APEH0	☐	Sound	2/2/2024/ 1:39 pm

Tasks/Resources

SMCT36 Inspection

Crew:

Supervisor:

Employee

Status:

UOM: Each

*Cal'c UC: \$4.29

*Task Cost: \$192.90

Start Dt: 2/28/2024

of Units: 45.00

*Unit Cost: \$0.00

End Dt: 2/28/2024

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
13859 Moten, Robert	Hours	5.00	\$125.90		2/28/2024	2/28/2024

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	5.00	\$67.00		2/28/2024	2/28/2024

Task Comment: sso overflow inspections 1-28-2024 0.82'

Projected Complete:

Repair Type:

Subcontractor:

Profit Center:

Lock: ☐

WO Duration

Labor Hours

Labor Costs

Material Costs

Fluids Costs

Equipment Costs

Contractor Costs

Misc. Costs

Total Costs

Use Task Info:

Quantity: 0.00

Unit of Measure: Each

Unit Cost: \$0.00

WO Hours: 0.00

Lock: ☐

Actual

Estimated

Difference

5.05

0.00

0.00

\$125.90

0.00

0.00

67.00

0.00

0.00

\$192.90

True

0.00

0.00

0.00

\$0.00

True

Billing

Billed Party

Customer ID:

Customer Name:

Address:

City:

State:

Zip:

Customer Number:

Last Name:

Phone:

Fax #:

E-mail:

Cell #:

Billing Data

Contact Name:

Invoice Number:

Incoming Account #:

*Billing Amount:

Date Bill Sent:

Payment Received:

Payment Method:

Billing Required: ☐

Billing Processed: ☐

Imported to Financials: ☐

Associated PMs	
PM Code and Description	Closed
SSO-02 SSO INSPECTION	☒

Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	2/2/2024	1:56 PM
Supervisor Notification	Email Queued Successfully!	jjackson	2/2/2024	1:56 PM
Leadworker Notification	Email Queued Successfully!	jjackson	2/2/2024	1:56 PM
Status Change	From New Work Order to Closed In Field	amanco	2/2/2024	3:46 PM

Work Order Detail Report

2/5/2024

iso overflow inspections 02-5-2024 0.82'

9:10 AM

Rate:	Opened At:	Televised:	☐
Recieved By:	Pipe Footage Cleaned :	Power Rooter:	☐
Work From:	Gallons Used:	Jet:	☐
Pipe Size:	WO User 23:	Gap Vac:	☐
Pipe Condition:	WO User 24:	Dye Test:	☐
Could Not Open:	WO User 9:	Gap Root Cut:	☐
Additional Repair:	User 10:	GIS Correction?:	☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	☐
Test Performed Throug	Appointment Date: 2/2/2024	8:00 AM	
Dye Test Results:			
NO User 51:			
Measurement:	E Mail:		
History:	Measurement Line 2:		
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Slee		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
NO User 39:			
NO User 40:	OUPS #:		
NO User 41:	WO User 48:		
NO User 52:	WO User 62:		
NO User 53:	WO User 63:		
NO User 54:	WO User 64:		
NO User 55:	WO User 65:		
NO User 56:	WO User 66:		
NO User 57:	WO User 67:		
NO User 58:	WO User 68:		
NO User 59:	WO User 69:		
NO User 60:	WO User 70:		
NO User 61:	WO User 71:		
NO User 72:	WO User 82:	Televised:	☐
NO User 73:	Quantity:	Paid:	☐
NO User 74:	WO User 84:	WO User 104:	☐
NO User 75:	WO User 85:	WO User 105:	☐
NO User 76:	WO User 86:	WO User 106:	☐
NO User 92 Date:	WO User 97 Date:		
NO User 93 Date:	WO User 98 Date:		
NO User 94 Date:	WO User 99 Date:		
NO User 95 Date:	WO User 100 Date:		
NO User 96 Date:	WO User 101 Date:		
NO User 77:	WO User 87:	WO User 107:	☐
NO User 78:	WO User 88:	WO User 108:	☐
NO User 79:	WO User 89:	WO User 109:	☐
NO User 80:	WO User 90:	WO User 110:	☐
NO User 81:	WO User 91:	WO User 111:	☐
NO Creator: jjackson	WO Creation Date: 2/2/2024	PM Trigger:	Rec #: 15349