

CITY OF
**CLEVELAND
HEIGHTS** 
LAW DEPARTMENT

May 15, 2024

Via E-Mail: vezner.kris@epa.gov and Berger.Jake@epa.gov

Kris P. Vezner, Esq.
Associate Regional Counsel
U.S. Environmental Protection Agency
Region 5 (C-14J)
77 West Jackson Blvd.
Chicago, IL 60604

and

Jake Berger
Physical Scientist
Water Enforcement & Compliance Assurance Branch
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Mail Code ECW-15J
Chicago, IL 60604


Re: April 2024 Overflow Monitoring Reports
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through April 30, 2024, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.


Very truly yours,



William R. Hanna
Director of Law

Enclosures


cc: Thomas Benson, Esq., EPA Attorney
James Vinch, Esq., EPA Attorney
James Zimny, EPA Engineer
U.S. EPA Region 5 Water Enforcement Branch
Mark Klingenstein, Environmental Engineer
Erm Gomes, Ohio EPA
Allison Cycyk, Ohio EPA
Casey Galligan, Ohio EPA
David Brumbaugh, Ohio EPA
Bill Fischbein, Ohio EPA
Kahlil Seren, Mayor
Collette Clinkscale, Director of Public Works
Steve Barker, Public Relations
Anthony Ferrone, Utilities Commissioner
Kevin Vander Tuig, P.E. (Outside Engineer)
Sarah Fuller (Outside Engineer)
Dan Porter (Outside Engineer)
Cindy Biacofsky (Outside Engineer)
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Monday, April 1, 2024

Accumulation in Inches



Summit County

Northeast Ohio Regional Sewer District

Daily Precipitation Report

Monday, April 1, 2024

<u>Site Location</u>	<u>Peak Accumulation (inches)</u>					
	<u>24-Hour</u>	<u>6-Hour</u>	<u>3-Hour</u>	<u>1-Hour</u>	<u>15-Minute</u>	
					<u>5-Minute</u>	
Beachwood	1.10	0.65	0.44	0.26	0.11	0.05
Brecksville	0.96	0.68	0.40	0.18	0.08	0.04
Brook Park	1.03	0.65	0.36	0.20	0.17	0.12
Cleveland Industrial Pkwy	1.11	0.71	0.40	0.20	0.11	0.05
Dille Ave PS	1.11	0.67	0.42	0.25	0.11	0.05
Division Ave PS	1.18	0.71	0.45	0.31	0.13	0.07
Easterly WWTP	0.99	0.57	0.40	0.28	0.08	0.04
Independence	1.03	0.66	0.39	0.17	0.13	0.06
James Rhodes HS	1.09	0.73	0.40	0.21	0.11	0.05
Jennings PS	n/a	n/a	n/a	n/a	n/a	n/a
Macedonia	0.86	0.59	0.37	0.17	0.07	0.04
Maple Heights	1.08	0.65	0.41	0.22	0.11	0.06
Mary Street PS	1.15	0.71	0.43	0.26	0.11	0.05
Mayfield Heights	1.04	0.55	0.49	0.29	0.11	0.05
Moreland Hills	1.20	0.72	0.46	0.25	0.13	0.06
North Olmsted	0.99	0.66	0.36	0.17	0.10	0.05
North Royalton	0.92	0.61	0.37	0.17	0.09	0.04
Oakwood	1.03	0.70	0.40	0.18	0.09	0.05
Olmsted Falls	0.93	0.64	0.37	0.16	0.10	0.05
Parma	1.04	0.68	0.41	0.17	0.14	0.06
Richfield	0.94	0.58	0.34	0.21	0.12	0.06
Shaker Heights	1.13	0.69	0.42	0.23	0.12	0.07
South Euclid	1.04	0.57	0.47	0.30	0.12	0.06
Southerly WWTC	1.07	0.73	0.40	0.20	0.09	0.04
Strongsville C WWTP	0.94	0.63	0.38	0.16	0.10	0.05
Strongsville Foltz	0.93	0.57	0.35	0.22	0.13	0.06
University Heights	1.21	0.69	0.50	0.31	0.13	0.07
Wade Park	1.20	0.65	0.54	0.36	0.15	0.09
Westerly WWTP	1.20	0.72	0.47	0.32	0.13	0.09
Westlake	1.08	0.69	0.40	0.19	0.10	0.04

Work Order Detail Report

4/9/2024

so overflow inspections 4-1-2024 1,21'

8:12 AM

WO Number:	240405-0001	Category:	SSOs
Status:	New Work Order	Problem:	Storm Response
Status Date:	4/5/2024 10:04 am	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	4/5/2024 8:00 AM
Lead Worker:	Mc Coy, Sam	End Date:	4/5/2024 1:00 PM
Priority:	High	Override Notifications	<input type="checkbox"/>
Account #:		Problem	<input type="checkbox"/>
Proj No - Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer

Comments for Crew
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations

Address 2

Address	X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339		Doan Brook
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
2,223,111.44143730	664,794.46048072		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO			
2,221,638.88762389	665,726.15513962		DOAN BROOK - MAIN BRANCH

Work Order Detail Report

4/9/2024

iso overflow inspections 4-1-2024 1,21'

8:12 AM

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

4/9/2024

sso overflow inspections 4-1-2024 1,21'

8:12 AM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

4/9/2024

so overflow inspections 4-1-2024 1,21'

8:12 AM

Work Order Assets

Object Type	System ID 1	System ID 2	Description 1	Description 2	PM Description	Asset ID	Completed
Sewer Control Valve	SSO 431			FAIRFAX AT NORTH PARK			
Sewer Control Valve	SSO 114			26			
Sewer Control Valve	SSO 121			NORTH PARK AND COVENTRY			
Sewer Structure	SA16AAWB0			16			
Sewer Control Valve	SSO 112			FAIRMOUNT SOUTH OF SCARBOROUGH			
Sewer Control Valve	SSO 99			35			
Sewer Control Valve	SSO 432				3094		
Sewer Control Valve	DB-03			FAIRMOUNT AT FAIRFAX			
Sewer Control Valve	DB-01			7			
Sewer Control Valve	DB-02			FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
Sewer Control Valve	CH-04			6			
Sewer Control Valve	SSO 110			3012 NORTH WOODLAND			
Sewer Control Valve	SSO 87			14			
Sewer Control Valve	SSO 116				55		
Sewer Control Valve	SSO 111						
Sewer Control Valve	SSO 113			56			
Sewer Control Valve	SSO 124				57		
Sewer Control Valve	CH-50			FAIRMOUNT AT DARTMOOR			
Sewer Control Valve	SSO 129			5			
Sewer Control Valve	CH-52			FAIRMOUNT AT WELLINGTON			
Sewer Control Valve	SSO 88			44			
Sewer Control Valve	SSO 122			FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
Sewer Control Valve	SSO 89			33			
Sewer Structure	SA16ADZB0			FAIRMOUNT AT MARLBORO			
Sewer Control Valve	SSO 91			4			
Sewer Structure	SA16ADPH0			FAIRMOUNT AT ARLINGTON			
Sewer Control Valve	SSO 120			46			
Sewer Control Valve	SSO 103			FAIRMOUNT & COVENTRY (SCARBOROUGH)			
Sewer Control Valve	SSO 104			37			
				FAIRMOUNT AND COVENTRY			
				47			
				SCARBOROUGH AT LAMBERTON			
				53			
				BRADFORD AND LEE			
				11			
				EDDINGTON			
				2			
				HAMPSHIRE LANE AT MAYFIELD (18")			
				42			
				EAST OVERLOOK AT EDGEHILL			
				36			
				HAMPSHIRE LANE AT MAYFIELD (36")			
				34			
					1536		
					HAMPSHIRE AT EUCLID HTS. BLVD.		
					20		
						4446	
						CEDAR BTW. FAIRMOUNT/DEMINGTON	
						8	
						2828 BERKSHIRE, EAST OF COVENTRY	
						19	
						3003 EUCLID HEIGHTS BLVD	
						15	

Work Order Detail Report

4/9/2024

8:12 AM

so overflow inspections 4-1-2024 1,21'

Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior F 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQQD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

Work Order Detail Report

4/9/2024

so overflow inspections 4-1-2024 1,21'

8:12 AM

Check List		<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
	<u>Item</u>				
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	4/5/2024/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	4/5/2024/	
3	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	4/5/2024/	
4	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	4/5/2024/	
5	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Not Sound	4/5/2024/	
6	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	4/5/2024/	
7	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	4/5/2024/	
8	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Not Sound	4/5/2024/	
9	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/5/2024/	
10	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	4/5/2024/	
11	A-32 FAIRMOUNT AT ARLINGTON SA16AAUPO (INTERSECTION)	<input type="checkbox"/>	Sound	4/5/2024/	
12	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/5/2024/	
13	A-35 2393 COVENTRY SA16AAASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	4/5/2024/	
Needs to be replaced					
14	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	4/5/2024/	
15	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	4/5/2024/	
16	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	4/5/2024/	
17	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	4/5/2024/	
18	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	4/5/2024/	
19	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	4/5/2024/	
20	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	4/5/2024/	
21	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEAO	<input type="checkbox"/>	Sound	4/5/2024/	
22	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	4/5/2024/	
23	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO	<input type="checkbox"/>	Sound	4/5/2024/	
24	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	4/5/2024/	
25	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	4/5/2024/	
26	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	4/5/2024/	
27	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	4/5/2024/	
28	B-56 LEE AND MEADOWBROOK SA16AGMGO	<input type="checkbox"/>	Sound	4/5/2024/	
29	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	4/5/2024/	

Work Order Detail Report

4/9/2024

8:12 AM

sso overflow inspections 4-1-2024 1,21'

30	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	4/5/2024/
Entire Manhole needs to be replaced including block/string			
31	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	4/5/2024/
Entire manhole needs to be replaced including block/string			
32	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	4/5/2024/
33	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	4/5/2024/
34	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	4/5/2024/
Manhole under construction not able to open			
35	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	4/5/2024/

Tasks/Resources

SMCT36 Inspection

Crew:	Status:	*Cal'c UC: \$5.69	*Task Cost: \$199.00	Start Dt: 4/5/2024
Supervisor:	UOM: Each	# of Units: 35.00	*Unit Cost: \$0.00	End Dt: 4/5/2024

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
40151 Mc Coy, Sam	Hours	5.00	\$132.00		4/5/2024	4/5/2024

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT93 FORD F250 4 X 4 PICK UP	Hours	5.00	\$67.00		4/5/2024	4/5/2024

Task Comment: sso overflow inspection 4-1-2024 1.21'

			*Actual	*Estimated	*Difference
*Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	5.00	0.00	0.00
Repair Type:		Labor Hours	5.00	0.00	0.00
Subcontractor:		Labor Costs	\$132.00	\$0.00	\$0.00
*Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity:	0.00	Equipment Costs	67.00	0.00	0.00
Jnt of Measure:	Each	Contractor Costs	0.00	0.00	0.00
Unit Cost:	\$0.00	Misc. Costs	0.00	0.00	0.00
NO Hours:	0.00	Total Costs	\$199.00	\$0.00	\$0.00
		Use Task Info:	True	True	

Billing

Billed Party

Customer ID:	Customer Number:
Customer Name:	Last Name:
Address:	
City:	Phone:
State:	Cell #:
Zip:	Fax #:
	E-mail:

Billing Data

Contact Name:	*Billing Amount:	Billing Required: <input type="checkbox"/>
Invoice Number:	Date Bill Sent:	Billing Processed: <input type="checkbox"/>
Incoming Account #:	Payment Received:	Imported to Financials: <input type="checkbox"/>
	Payment Method:	

Associated PMs

PM Code and Description

SSO-02 SSO INSPECTION

Closed

Tracking

Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jackson	4/5/2024	10:04 AM
Supervisor Notification	Email Queued Successfully!	jackson	4/5/2024	10:04 AM

Work Order Detail Report

4/9/2024

8:12 AM

SSO overflow inspections 4-1-2024 1,21'


Rate:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned.	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:	Appointment Date: 4/5/2024	8:00 AM	
Dye Test Results:	E Mail:		
WO User 51:	Measurement Line 2:		
Measurement:	Pipe Size:		
History:	PVC Tees, Angles, Sier		
Manhole Basin Repair:	WO User 44:		
Material Used:	WO User 45:		
Pipe Repair:	WO User 46:		
Street Repair:			
Grass Repair:			
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:	Televised:	<input type="checkbox"/>
WO User 59:	WO User 69:	Paid:	<input type="checkbox"/>
WO User 60:	WO User 70:	WO User 104:	<input type="checkbox"/>
WO User 61:	WO User 71:	WO User 105:	<input type="checkbox"/>
WO User 72:	WO User 82:	WO User 106:	<input type="checkbox"/>
WO User 73:	Quantity:		
WO User 74:	WO User 84:		
WO User 75:	WO User 85:		
WO User 76:	WO User 86:		
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 4/5/2024	PM Trigger:	Rec #: 15491

Northwest Ohio Regional Sewer District

Daily Precipitation Report

Friday, April 12, 2024

Accumulation in Inches



Work Order Detail Report

4/15/2024

SSO overflow inspections 4-12-2024 0.77'

11:34 AM

WO Number:	240412-0003	Category:	SSOs
Status:	New Work Order	Problem:	Storm Response
Status Date:	4/12/2024 7:32 am	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	4/12/2024 8:00 AM
Lead Worker:	Cardarella, Joe	End Date:	4/12/2024 1:30 PM
Priority:	High	Override Notifications	<input type="checkbox"/>
Account #:		Problem	<input type="checkbox"/>
Proj No - Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer

Comments for Crew
Inspect all (45) SSO's when rainfall is one quarter (1/4")
inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations

<u>Address</u>		<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

4/15/2024

ISO overflow inspections 4-12-2024 0.77'

11:34 AM

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	LEE RD. & SUPERIOR AVE.
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

4/15/2024

:so overflow inspections 4-12-2024 0.77'

11:34 AM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

4/15/2024

SSO overflow inspections 4-12-2024 0.77'

11:34 AM

Work Order Assets

Object Type	System ID 1	System ID 2	Description 1			Description 2		Completed
			Odometer	Hourmeter	Othermeter	PM Description	Asset ID	
Sewer Control Valve						FAIRFAX AT NORTH PARK		
SSO 431						26		
Sewer Control Valve						NORTH PARK AND COVENTRY		
SSO 114						16		
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35		
Sewer Structure							3094	
SA16AAWB0								
Sewer Control Valve						FAIRMOUNT AT FAIRFAX		
SSO 112						7		
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6		
Sewer Control Valve						3012 NORTH WOODLAND		
SSO 432						14		
Sewer Control Valve							55	
DB-03								
Sewer Control Valve							56	
DB-01								
Sewer Control Valve							57	
DB-02								
Sewer Control Valve						FAIRMOUNT AT DARTMOOR		
CH-04						5		
Sewer Control Valve						FAIRMOUNT AT WELLINGTON		
SSO 110						44		
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33		
Sewer Control Valve						FAIRMOUNT AT MARLBORO		
SSO 116						4		
Sewer Control Valve						FAIRMOUNT AT ARLINGTON		
SSO 111						46		
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37		
Sewer Control Valve						FAIRMOUNT AND COVENTRY		
SSO 124						47		
Sewer Control Valve						SCARBOROUGH AT LAMBERTON		
CH-50						53		
Sewer Control Valve						BRADFORD AND LEE		
SSO 129						11		
Sewer Control Valve						EDDINGTON		
CH-52						2		
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42		
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL		
SSO 122						36		
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34		
Sewer Structure							1536	
SA16ADZB0								
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20		
Sewer Structure							4446	
SA16ADPH0								
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8		
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103						19		
Sewer Control Valve						3003 EUCLID HEIGHTS BLVD		
SSO 104						15		

Work Order Detail Report

4/15/2024

ISO overflow inspections 4-12-2024 0.77'

11:34 AM

Check List

	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	4/12/2024/ 1:12 pm	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	4/12/2024/ 1:25 pm	
3	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	4/12/2024/12:51 pm	
4	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	4/12/2024/12:48 pm	
5	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	4/12/2024/12:28 pm	
6	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	4/12/2024/10:25 am	
7	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Not Sound	4/12/2024/10:23 am	
Still surcharging					
8	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	4/12/2024/10:18 am	
9	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/12/2024/12:33 pm	
10	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	4/12/2024/	
11	A-32 FAIRMOUNT AT ARLINGTON SA16AAUPO (INTERSECTION)	<input type="checkbox"/>	Not Sound	4/12/2024/ 1:02 pm	
12	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/12/2024/ 1:07 pm	
13	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/12/2024/ 1:31 pm	
14	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	4/12/2024/12:41 pm	
15	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	4/12/2024/12:43 pm	
16	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	4/12/2024/10:09 am	
17	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	4/12/2024/10:04 am	
18	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	4/12/2024/10:12 am	
19	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	4/12/2024/ 9:12 am	
20	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	4/12/2024/ 9:19 am	
21	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEAO	<input type="checkbox"/>	Sound	4/12/2024/ 9:19 am	
22	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	4/12/2024/ 9:22 am	
23	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO	<input type="checkbox"/>	Sound	4/12/2024/ 9:27 am	
24	B-46 EDGEHILL AT E OVERLOOK SA16AEPFO	<input type="checkbox"/>	Sound	4/12/2024/ 9:29 am	
25	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>		/	
26	B-15 COVENTRY AND CEDAR SA16ADBHO	<input type="checkbox"/>	Sound	4/12/2024/ 9:41 am	
27	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Not Sound	4/12/2024/ 9:35 am	
Do not see block meter in manhole					
28	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Not Sound	4/12/2024/ 9:55 am	
Still surcharging					

Work Order Detail Report

4/15/2024

sso overflow inspections 4-12-2024 0.77'

11:34 AM

29	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	4/12/2024/ 9:56 am	
30	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	4/12/2024/ 8:46 am	
31	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	4/12/2024/ 8:42 am	
32	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Not Sound	4/12/2024/ 8:32 am	
	Reset				
33	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	4/12/2024/ 8:07 am	
34	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Not Sound	4/12/2024/ 8:17 am	
	Still surcharging				
35	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	4/12/2024/ 8:23 am	

Tasks/Resources					
SMCT36 Inspection					
Crew:		Status:		*Cal'd UC: \$5.51	*Task Cost: \$192.90
Supervisor:		UOM:	Each	# of Units: 35.00	Start Dt: 4/12/2024 End Dt: 4/12/2024
Employee					
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt
22394 Cardarella, Joe	Hours	5.00	\$125.90		4/12/2024 4/12/2024
Equipment					
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt
CHFLT50 FORD F250 CREW CAB	Hours	5.00	\$67.00		4/12/2024 4/12/2024
5					
Task Comment: sso overflow inspections 4-12-2024 0.77'					

Projected Complete:		Lock: <input type="checkbox"/>	*Actual	*Estimated	*Difference
Repair Type:			WO Duration	5.50	0.00
Subcontractor:			Labor Hours	5.00	0.00
Profit Center:			Labor Costs	\$125.90	\$0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Material Costs	0.00	0.00
Unit of Measure:	Each		Fluids Costs	0.00	0.00
Unit Cost:	\$0.00		Equipment Costs	67.00	0.00
VO Hours:	0.00		Contractor Costs	0.00	0.00
			Misc. Costs	0.00	0.00
			Total Costs	\$192.90	\$0.00
			Use Task Info:	True	True

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:		Cell #:
City:		Fax #:		
State:		E-mail:		
Zip:				

Billing Data		*Billing Amount:	Billing Required: <input type="checkbox"/>
Contact Name:		Date Bill Sent:	Billing Processed: <input type="checkbox"/>
Invoice Number:		Payment Received:	Imported to Financials: <input type="checkbox"/>
Incoming Account #:		Payment Method:	

Associated PMs		PM Code and Description	Closed
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>

Tracking		Description	By	Date	Time
Item					
Work Order Creation		From Routine Work SSO-02 - SSO INSPECTION	jackson	4/12/2024	7:32 AM
Supervisor Notification		Email Queued Successfully!	jackson	4/12/2024	7:32 AM

Work Order Detail Report

4/15/2024

ISO overflow inspections 4-12-2024 0.77'

11:34 AM


Rate:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned.	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:	Appointment Date: 4/12/2024 8:30 AM		
Dye Test Results:			
WO User 51:	E Mail:		
Measurement:	Measurement Line 2:		
History:	Pipe Size:		
Manhole Basin Repair:	PVC Tees, Angles, Sockets:		
Material Used:	WO User 44:		
Pipe Repair:	WO User 45:		
Street Repair:	WO User 46:		
Grass Repair:			
Curb Repair:			
Driveway- Sidewalk Repair:			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 4/12/2024	PM Trigger:	Rec #: 15509

 **Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Wednesday, April 17, 2024

Accumulation in inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Wednesday, April 17, 2024

<u>Site Location</u>	<u>Peak Accumulation (inches)</u>				
	<u>24-Hour</u>	<u>6-Hour</u>	<u>3-Hour</u>	<u>1-Hour</u>	<u>15-Minute</u>
Beachwood	0.51	0.50	0.50	0.46	0.28
Brecksville	0.82	0.82	0.82	0.76	0.47
Brook Park	0.37	0.37	0.37	0.33	0.20
Cleveland Industrial Pkwy	0.28	0.28	0.28	0.25	0.16
Dille Ave PS	0.27	0.27	0.27	0.23	0.14
Division Ave PS	0.41	0.41	0.41	0.37	0.26
Easterly WWTP	0.60	0.60	0.60	0.56	0.43
Independence	0.62	0.62	0.62	0.58	0.43
James Rhodes HS	0.21	0.21	0.21	0.18	0.08
Jennings PS	n/a	n/a	n/a	n/a	n/a
Macedonia	0.54	0.53	0.53	0.49	0.38
Maple Heights	0.64	0.63	0.63	0.59	0.43
Mary Street PS	0.29	0.29	0.29	0.25	0.16
Mayfield Heights	0.44	0.41	0.41	0.37	0.16
Moreland Hills	1.08	1.06	1.06	1.01	0.77
North Olmsted	0.61	0.61	0.61	0.56	0.46
North Royalton	0.52	0.52	0.52	0.48	0.34
Oakwood	0.50	0.49	0.49	0.46	0.29
Olmsted Falls	0.36	0.36	0.36	0.32	0.23
Parma	0.45	0.45	0.45	0.41	0.28
Richfield	0.37	0.35	0.35	0.33	0.22
Shaker Heights	0.29	0.29	0.29	0.25	0.10
South Euclid	0.29	0.29	0.29	0.24	0.10
Southerly WWTC	0.31	0.31	0.31	0.28	0.14
Strongsville C WWTP	0.24	0.24	0.24	0.21	0.09
Strongsville Foltz	0.74	0.74	0.74	0.72	0.59
University Heights	0.22	0.22	0.22	0.20	0.07
Wade Park	0.28	0.28	0.28	0.24	0.11
Westerly WWTP	0.33	0.33	0.33	0.30	0.19
Westlake	0.44	0.43	0.43	0.37	0.15

Work Order Detail Report

4/22/2024

7:38 AM

iso overflow inspections 4-17-2024 0.22'

WO Number:	240419-0002	Category:	SSOs
Status:	New Work Order	Problem:	Storm Response
Status Date:	4/19/2024 7:39 am	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	4/19/2024 8:00 AM
Lead Worker:	Mc Coy, Sam	End Date:	4/19/2024 1:35 PM
Priority:	High	Override Notifications	<input type="checkbox"/>
Account #:		Problem	<input type="checkbox"/>
Proj No - Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer

Comments for Crew
Inspect all (45) SSO's when rainfall is one quarter (1/4")
inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations

Address	Address 2	
X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

4/22/2024

7:38 AM

so overflow inspections 4-17-2024 0.22'

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

4/22/2024

sso overflow inspections 4-17-2024 0.22'

7:38 AM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

4/22/2024

iso overflow inspections 4-17-2024 0.22'

7:38 AM

Work Order Assets

Object Type	System ID 1	System ID 2	Description 1			PM Description	Asset ID	Completed
			Odometer	Hourmeter	Othermeter			
Sewer Control Valve						FAIRFAX AT NORTH PARK		
SSO 431						26		
Sewer Control Valve						NORTH PARK AND COVENTRY		
SSO 114						16		
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35		
Sewer Structure							3094	
SA16AAWB0								
Sewer Control Valve						FAIRMOUNT AT FAIRFAX		
SSO 112						7		
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6		
Sewer Control Valve						3012 NORTH WOODLAND		
SSO 432						14		
Sewer Control Valve							55	
DB-03								
Sewer Control Valve						56		
DB-01								
Sewer Control Valve						57		
DB-02								
Sewer Control Valve						FAIRMOUNT AT DARTMOOR		
CH-04						5		
Sewer Control Valve						FAIRMOUNT AT WELLINGTON		
SSO 110						44		
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33		
Sewer Control Valve						FAIRMOUNT AT MARLBORO		
SSO 116						4		
Sewer Control Valve						FAIRMOUNT AT ARLINGTON		
SSO 111						46		
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37		
Sewer Control Valve						FAIRMOUNT AND COVENTRY		
SSO 124						47		
Sewer Control Valve						SCARBOROUGH AT LAMBERTON		
CH-50						53		
Sewer Control Valve						BRADFORD AND LEE		
SSO 129						11		
Sewer Control Valve						EDDINGTON		
CH-52						2		
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42		
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL		
SSO 122						36		
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34		
Sewer Structure							1536	
SA16ADZB0								
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20		
Sewer Structure							4446	
SA16ADPH0								
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8		
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103						19		
Sewer Control Valve						3003 EUCLID HEIGHTS BLVD		
SSO 104						15		

Work Order Detail Report

4/22/2024

7:38 AM

so overflow inspections 4-17-2024 0.22'

Sewer Structure		
SA16AGMG0	3402	
Sewer Control Valve		
CH-30	52	South Taylor between Antisdale Ave and Superior F
Sewer Control Valve		
DV-11	9	LEE RD. & SUPERIOR AVE.
Sewer Control Valve		
SSO 108	22	EUCLID HEIGHTS BLVD AND LEE
Sewer Control Valve		
SSO 106	43	EUCLID HEIGHTS BLVD/CUMBERLAND
Sewer Control Valve		
SSO 95	18	1685 CUMBERLAND
Sewer Control Valve		
SSO 105	30	CUMBERLAND/SOMERTON
Sewer Structure		
SA16AQQD0	4987	
Sewer Structure		
SA16AQQC0	3745	
Sewer Control Valve		
SSO 102	3	2225 NOBLE ROAD
Sewer Control Valve		
SSO 107	38	QUILLIAMS, N. OF RANDOLF
Sewer Control Valve		
CH-51	54	LANGTON AND AHERSTONE
Sewer Structure		
SA16APEF0	1809	

Work Order Detail Report

4/22/2024

iso overflow inspections 4-17-2024 0.22'

7:38 AM

Check List					
	<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	4/19/2024/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	4/19/2024/	
3	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	4/19/2024/	
4	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	4/19/2024/	
5	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Not Sound	4/19/2024/	
6	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	4/19/2024/	
7	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	4/19/2024/	
8	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	4/19/2024/	
9	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/19/2024/	
10	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	4/19/2024/	
11	A-32 FAIRMOUNT AT ARLINGTON SA16AAUPO (INTERSECTION)	<input type="checkbox"/>	Sound	4/19/2024/	
12	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/19/2024/	
13	A-35 2393 COVENTRY SA16AAASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/19/2024/	
14	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	4/19/2024/	
15	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	4/19/2024/	
16	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	4/19/2024/	
17	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	4/19/2024/	
18	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Sound	4/19/2024/	
19	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	4/19/2024/	
20	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	4/19/2024/	
21	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	4/19/2024/	
22	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	4/19/2024/	
23	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO0	<input type="checkbox"/>	Sound	4/19/2024/	
24	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	4/19/2024/	
25	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	4/19/2024/	
26	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	4/19/2024/	
27	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	4/19/2024/	
28	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	4/19/2024/	
29	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	4/19/2024/	
30	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	4/19/2024/	

Work Order Detail Report

4/22/2024

7:38 AM

sso overflow inspections 4-17-2024 0.22'

31	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	4/19/2024/
32	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	4/19/2024/
33	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOQU0	<input type="checkbox"/>	Not Sound	4/19/2024/
Partially block sewer main				
34	C-51 ATHERSTONE AND LANGTON SA16AOKAO	<input type="checkbox"/>	Sound	4/19/2024/
35	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	4/19/2024/

Tasks/Resources						
SMCT36 Inspection						
Crew:		Status:		*Cal'c UC: \$5.69	*Task Cost: \$199.00	Start Dt: 4/19/2024
Supervisor:		UOM:	Each	# of Units: 35.00	*Unit Cost: \$0.00	End Dt: 4/19/2024
Employee						
Resource	UOM	Units		*Total Cost	Alt Description	Start Dt
40151 Mc Coy, Sam	Hours	5.00		\$132.00		4/19/2024
Equipment						
Resource	UOM	Units		*Total Cost	Alt Description	Start Dt
CHFLT93 FORD F250 4 X 4 PICK UP	Hours	5.00		\$67.00		4/19/2024
1						
Task Comment: sso overflow inspections 4-17-2024 0.22'						

			*Actual	*Estimated	*Difference
Projected Complete:		Lock: <input type="checkbox"/>	WO Duration	5.58	0.00
Repair Type:			Labor Hours	5.00	0.00
Subcontractor:			Labor Costs	\$132.00	\$0.00
Profit Center:			Material Costs	0.00	0.00
			Fluids Costs	0.00	0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Equipment Costs	67.00	0.00
Unit of Measure:	Each		Contractor Costs	0.00	0.00
Unit Cost:	\$0.00		Misc. Costs	0.00	0.00
NO Hours:	0.00		Total Costs	\$199.00	\$0.00
			Use Task Info:	True	True

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:		Cell #:
City:		Fax #:		
State:		E-mail:		
Zip:				
Billing Data				
Contact Name:		*Billing Amount:		Billing Required: <input type="checkbox"/>
Invoice Number:		Date Bill Sent:		Billing Processed: <input type="checkbox"/>
Incoming Account #:		Payment Received:		Imported to Financials: <input type="checkbox"/>
		Payment Method:		

Associated PMs		PM Code and Description	Closed
SSO-02 SSO INSPECTION			<input checked="" type="checkbox"/>

Tracking		Description	By	Date	Time
Item					
Work Order Creation		From Routine Work SSO-02 - SSO INSPECTION	jackson	4/19/2024	7:39 AM
Supervisor Notification		Email Queued Successfully!	jackson	4/19/2024	7:39 AM

Work Order Detail Report

4/22/2024

ISO overflow inspections 4-17-2024 0.22'

7:38 AM

Rate:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned.	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:	Appointment Date: 4/19/2024 8:00 AM		
Dye Test Results:			
WO User 51:	E Mail:		
Measurement:	Measurement Line 2:		
History:	Pipe Size:		
Manhole Basin Repair:	PVC Tees, Angles, Sockets:		
Material Used:	WO User 44:		
Pipe Repair:	WO User 45:		
Street Repair:	WO User 46:		
Grass Repair:			
Curb Repair:			
Driveway- Sidewalk Repair:			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	Quantity:	Paid:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 4/19/2024	PM Trigger:	Rec #: 15524