

CITY OF
**CLEVELAND
HEIGHTS** 
LAW DEPARTMENT

September 12, 2024

Via E-Mail: vezner.kris@epa.gov and Berger.Jake@epa.gov

Kris P. Vezner, Esq.
Associate Regional Counsel
U.S. Environmental Protection Agency
Region 5 (C-14J)
77 West Jackson Blvd.
Chicago, IL 60604

and

Jake Berger
Physical Scientist
Water Enforcement & Compliance Assurance Branch
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Mail Code ECW-15J
Chicago, IL 60604

Re: August 2024 Overflow Monitoring Reports
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through August 31, 2024, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,


William R. Hanna
Director of Law

Enclosures


cc: Thomas Benson, Esq., EPA Attorney
James Vinch, Esq., EPA Attorney
James Zimny, EPA Engineer
U.S. EPA Region 5 Water Enforcement Branch
Mark Klingenstein, Environmental Engineer
Erm Gomes, Ohio EPA
Allison Cycyk, Ohio EPA
Casey Galligan, Ohio EPA
David Brumbaugh, Ohio EPA
Bill Fischbein, Ohio EPA
Kahlil Seren, Mayor
Collette Clinkscale, Director of Public Works
Steve Barker, Public Relations
Anthony Ferrone, Utilities Commissioner
Kevin Vander Tuig, P.E. (Outside Engineer)
Mathew St. Pierre, (Outside Engineer)
Dan Porter (Outside Engineer)
Cindy Biacofsky (Outside Engineer)
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Tuesday, August 6, 2024

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report
Tuesday, August 6, 2024

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
					5-Minute
Beachwood	0.82	0.82	0.78	0.77	0.68
Brecksville	0.70	0.63	0.62	0.56	0.49
Brook Park	0.34	0.34	0.29	0.18	0.09
Cleveland Industrial Pkwy	0.28	0.28	0.24	0.17	0.11
Dille Ave PS	0.60	0.60	0.58	0.57	0.53
Division Ave PS	0.67	0.67	0.63	0.63	0.60
Easterly WWTP	0.87	0.87	0.81	0.81	0.60
Independence	0.61	0.61	0.49	0.42	0.35
James Rhodes HS	0.39	0.39	0.28	0.24	0.22
Jennings PS	n/a	n/a	n/a	n/a	n/a
Macedonia	0.66	0.57	0.46	0.43	0.37
Maple Heights	0.38	0.38	0.29	0.26	0.24
Mary Street PS	0.50	0.50	0.47	0.47	0.42
Mayfield Heights	1.13	1.12	1.08	1.08	0.80
Moreland Hills	0.53	0.53	0.52	0.51	0.47
North Olmsted	0.41	0.41	0.41	0.31	0.15
North Royalton	0.57	0.57	0.56	0.47	0.34
Oakwood	0.54	0.49	0.44	0.43	0.40
Olmsted Falls	0.27	0.26	0.25	0.13	0.08
Parma	0.47	0.47	0.31	0.20	0.14
Richfield	0.58	0.38	0.33	0.32	0.23
Shaker Heights	0.96	0.96	0.94	0.93	0.86
South Euclid	1.01	1.01	0.97	0.97	0.64
Southerly WWTC	0.33	0.31	0.21	0.18	0.17
Strongsville C WWTP	0.31	0.30	0.26	0.16	0.13
Strongsville Foltz	0.74	0.65	0.59	0.48	0.29
University Heights	0.97	0.97	0.91	0.90	0.76
Wade Park	0.74	0.74	0.68	0.67	0.52
Westerly WWTP	0.22	0.22	0.18	0.18	0.14
Westlake	0.60	0.55	0.49	0.43	0.31

Work Order Detail Report

8/12/2024

sso overflow inspections 8-6-2024 0.97'

3:17 PM

WO Number:	240809-0002	Category:	SSOs
Status:	New Work Order	Problem:	Storm Response
Status Date:	8/9/2024 7:41 am	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	8/8/2024 8:00 AM
Lead Worker:	Cardarella, Joe	End Date:	8/8/2024 2:30 PM
Priority:	High	Project ID:	<input type="checkbox"/> Problem
Account #:		Project Name:	<input type="checkbox"/> Overdue
Proj No - Acct:			<input type="checkbox"/> Lead Worker
Project:			<input type="checkbox"/> Task
Reason:			<input type="checkbox"/> Supervisor
Received By:			<input type="checkbox"/> Hard Lock WO
Inspected By:			

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations

Address 2

<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>	<u>Address 2</u>
FAIRFAX AT NORTH PARK				
2,220,655.65435414	665,517.24643672		Doan Brook	
NORTH PARK AND COVENTRY				
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH				
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX				
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)				
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND				
2,222,845.06631389	664,689.08536339		Doan Brook	
2,226,440.21168265	664,329.55524255			
2,226,354.79813956	664,409.89202413			
2,226,389.92077273	664,379.07548472			
FAIRMOUNT AT DARTMOOR				
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON				
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)				
2,223,111.44143730	664,794.46048072		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT MARLBORO				
2,221,638.88762389	665,726.15513962		DOAN BROOK - MAIN BRANCH	

Work Order Detail Report

8/12/2024

sso overflow inspections 8-6-2024 0.97'

3:17 PM

Rate:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>
Test Performed Through:	Appointment Date: 8/9/2024	8:00 AM
Dye Test Results:		
WO User 51:		
Measurement:	E Mail:	
History:	Measurement Line 2:	
Manhole Basin Repair:	Pipe Size:	
Material Used:	PVC Tees, Angles, Sleeves	
Pipe Repair:	WO User 44:	
Street Repair:	WO User 45:	
Grass Repair:	WO User 46:	
Curb Repair:		
Driveway- Sidewalk Repair:		
Construction Crew:		
WO User 39:	OUPS #:	
WO User 40:	WO User 48:	
WO User 41:		
WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	
WO User 72:	WO User 82:	Televised: <input type="checkbox"/>
WO User 73:	Quantity:	Paid: <input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104: <input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105: <input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106: <input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:	
WO User 93 Date:	WO User 98 Date:	
WO User 94 Date:	WO User 99 Date:	
WO User 95 Date:	WO User 100 Date:	
WO User 96 Date:	WO User 101 Date:	
WO User 77:	WO User 87:	WO User 107: <input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108: <input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109: <input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110: <input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111: <input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 8/9/2024	PM Trigger: Rec #: 15759

Work Order Detail Report

8/12/2024

3:17 PM

sso overflow inspections 8-6-2024 0.97'

31	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	/
32	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	/
33	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	/
34	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Not Sound	/
35	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Not Sound	/

Tasks/Resources						
SMCT36 Inspection						
Crew:		Status:		*Cal'c UC: \$6.61	*Task Cost: \$231.48	Start Dt: 8/8/2024
Supervisor:		UOM:	Each	# of Units: 35.00	*Unit Cost: \$0.00	End Dt: 8/8/2024
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	6.00	\$151.08		8/8/2024	8/8/2024
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	6.00	\$80.40		8/8/2024	8/8/2024

Task Comment: sso overflow inspections 8-6-2024 0.97'

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	6.50	0.00	0.00
Subcontractor:		Labor Costs	6.00	0.00	0.00
Profit Center:		Material Costs	\$151.08	\$0.00	\$0.00
		Fluids Costs	0.00	0.00	0.00
Quantity:	0.00	Equipment Costs	80.40	0.00	0.00
Unit of Measure:	Each	Contractor Costs	0.00	0.00	0.00
*Unit Cost:	\$0.00	Misc. Costs	0.00	0.00	0.00
WO Hours:	0.00	Total Costs	\$231.48	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	Cell #:
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	Billing Required: <input type="checkbox"/>
Invoice Number:		Date Bill Sent:	Billing Processed: <input type="checkbox"/>
Incoming Account #:		Payment Received:	Imported to Financials: <input type="checkbox"/>
		Payment Method:	

Associated PMs		PM Code and Description	Closed
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>

Tracking	Description	By	Date	Time
Item				
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jackson	8/9/2024	7:41 AM
Supervisor Notification	Email Queued Successfully!	jackson	8/9/2024	7:41 AM

Work Order Detail Report

8/12/2024

sso overflow inspections 8-6-2024 0.97'

3:17 PM

Check List

<u>Item</u>	<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1 A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	/	
2 A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	/	
3 A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	/	
4 A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	/	
5 A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Not Sound	/	
6 A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	/	
7 A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	/	
8 A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	/	
9 A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	/	
10 A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	/	
11 A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	/	
12 A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	/	
13 A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	/	
14 A-50 SCARBOROUGH AND LAMBERTON SA16AAANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	/	
15 A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Not Sound	/	
16 A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	/	
17 A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	/	
18 A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	<input type="checkbox"/>	Not Sound	/	
19 B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Not Sound	/	
20 B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	/	
21 B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	/	
22 B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Not Sound	/	
23 HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO	<input type="checkbox"/>	Not Sound	/	
24 B-46 EDGEHILL AT E OVERLOOK SA16AEPFO	<input type="checkbox"/>	Not Sound	/	
25 B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>		/	
26 B-15 COVENTRY AND CEDAR SA16ADBHQ	<input type="checkbox"/>	Sound	/	
27 B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	/	
28 B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	/	
29 C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVFO	<input type="checkbox"/>	Sound	/	
30 C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	/	

Work Order Detail Report

8/12/2024

sso overflow inspections 8-6-2024 0.97'

3:17 PM

Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior F 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQQD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

Work Order Detail Report

8/12/2024

3:17 PM

Work Order Assets

Object Type	System ID 1	System ID 2	Description 1			Description 2		Asset ID	Completed
			Odometer	Hourmeter	Othermeter	PM Description			
Sewer Control Valve						FAIRFAX AT NORTH PARK			
SSO 431							26		
Sewer Control Valve						NORTH PARK AND COVENTRY			
SSO 114							16		
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH			
SSO 121							35		
Sewer Structure									
SA16AAWB0							3094		
Sewer Control Valve						FAIRMOUNT AT FAIRFAX			
SSO 112							7		
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
SSO 99							6		
Sewer Control Valve						3012 NORTH WOODLAND			
SSO 432							14		
Sewer Control Valve									
DB-03							55		
Sewer Control Valve									
DB-01							56		
Sewer Control Valve									
DB-02							57		
Sewer Control Valve						FAIRMOUNT AT DARTMOOR			
CH-04							5		
Sewer Control Valve						FAIRMOUNT AT WELLINGTON			
SSO 110							44		
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
SSO 87							33		
Sewer Control Valve						FAIRMOUNT AT MARLBORO			
SSO 116							4		
Sewer Control Valve						FAIRMOUNT AT ARLINGTON			
SSO 111							46		
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)			
SSO 113							37		
Sewer Control Valve						FAIRMOUNT AND COVENTRY			
SSO 124							47		
Sewer Control Valve						SCARBOROUGH AT LAMBERTON			
CH-50							53		
Sewer Control Valve						BRADFORD AND LEE			
SSO 129							11		
Sewer Control Valve						EDDINGTON			
CH-52							2		
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")			
SSO 88							42		
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL			
SSO 122							36		
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")			
SSO 89							34		
Sewer Structure									
SA16ADZB0							1536		
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.			
SSO 91							20		
Sewer Structure									
SA16ADPH0									
Sewer Control Valve						4446			
SSO 120						CEDAR BTW. FAIRMOUNT/DEMINGTON			
Sewer Control Valve							8		
SSO 103						2828 BERKSHIRE, EAST OF COVENTRY			
Sewer Control Valve							19		
SSO 104						3003 EUCLID HEIGHTS BLVD			
Sewer Control Valve							15		

Work Order Detail Report

sso overflow inspections 8-6-2024 0.97'

8/12/2024

3:17 PM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

8/12/2024

sso overflow inspections 8-6-2024 0.97'

3:17 PM

FAIRMOUNT AT ARLINGTON
2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)
2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY
2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON
2,221,598.28993607 666,996.61322863
MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423 665,499.19660404 DOAN BROOK
BRADFORD AND LEE
2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH
EDDINGTON
2,221,299.08384156 674,932.84604380
HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL
2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")
2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD

HAMPSHIRE AT EUCLID HTS. BLVD.
2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON
2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY
2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD
2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd
2,227,113.30810548 671,276.67684697
LEE RD. & SUPERIOR AVE.
2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE
2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND
2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND
2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON
2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD

2225 NOBLE ROAD
2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF
2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE
2,228,126.76638040 684,188.23206055

2,220,777.89623564 666,181.72575080


2,218,501.67473823 671,997.54581206

2,216,759.55453481 670,474.59347738

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Sunday, August 18, 2024

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.63	0.57	0.56	0.49	0.29	0.13
Brecksville	0.93	0.68	0.57	0.46	0.21	0.11
Brook Park	0.57	0.54	0.53	0.43	0.20	0.11
Cleveland Industrial Pkwy	0.84	0.79	0.79	0.58	0.27	0.25
Dille Ave PS	0.48	0.48	0.47	0.43	0.26	0.11
Division Ave PS	0.66	0.64	0.63	0.57	0.34	0.14
Easterly WWTP	0.74	0.71	0.71	0.59	0.33	0.18
Independence	0.35	0.26	0.26	0.14	0.08	0.06
James Rhodes HS	0.67	0.51	0.51	0.30	0.18	0.14
Jennings PS	n/a	n/a	n/a	n/a	n/a	n/a
Macedonia	0.21	0.17	0.17	0.12	0.08	0.04
Maple Heights	0.45	0.45	0.44	0.24	0.12	0.07
Mary Street PS	0.55	0.53	0.52	0.49	0.25	0.10
Mayfield Heights	0.50	0.29	0.27	0.19	0.18	0.14
Moreland Hills	0.58	0.35	0.34	0.23	0.23	0.20
North Olmsted	0.24	0.21	0.21	0.11	0.09	0.05
North Royalton	0.48	0.40	0.39	0.33	0.21	0.13
Oakwood	0.27	0.25	0.25	0.19	0.09	0.06
Olmsted Falls	0.47	0.25	0.23	0.20	0.20	0.20
Parma	0.71	0.60	0.60	0.40	0.18	0.10
Richfield	0.32	0.24	0.24	0.23	0.09	0.04
Shaker Heights	0.23	0.23	0.23	0.18	0.11	0.05
South Euclid	0.73	0.59	0.56	0.47	0.28	0.13
Southerly WWTC	0.45	0.38	0.38	0.30	0.18	0.11
Strongsville C WWTP	0.29	0.26	0.26	0.19	0.10	0.08
Strongsville Foltz	0.15	0.09	0.08	0.06	0.06	0.04
University Heights	0.70	0.59	0.58	0.46	0.26	0.14
Wade Park	0.50	0.49	0.48	0.34	0.29	0.16
Westerly WWTP	0.61	0.58	0.57	0.50	0.30	0.14
Westlake	0.65	0.63	0.63	0.48	0.21	0.11

Work Order Detail Report

8/23/2024

SSO INSPECTION 8/18/2024 0.70 INCHES OF RAIN

8:19 AM

WO Number:	240820-0001	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	8/23/2024 8:18 am	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather		
Assigned Crew:			
Supervisor:	Jackson, Jeff	Assigned By:	
Lead Worker:	Cardarella, Joe	Assigned Date:	8/18/2024
Priority:	High	Start Date:	8/20/2024 7:16 AM
Account #:		End Date:	8/20/2024 3:16 PM
Proj No - Acct:		Project ID:	
Project:		Project Name:	
Reason:			
Received By:			Lead Worker <input type="checkbox"/>
Inspected By:			Task <input type="checkbox"/>
			Supervisor <input type="checkbox"/>
			Hard Lock WO <input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Locations

<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>	<u>Address 2</u>
FAIRFAX AT NORTH PARK				
2,220,655.65435414	665,517.24643672		Doan Brook	
NORTH PARK AND COVENTRY				
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH				
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX				
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)				
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND				
2,222,845.06631389	664,689.08536339		Doan Brook	
2,226,440.21168265	664,329.55524255			
2,226,354.79813956	664,409.89202413			
2,226,389.92077273	664,379.07548472			
FAIRMOUNT AT DARTMOOR				
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON				
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH	

Work Order Detail Report

8/23/2024

SSO INSPECTION 8/18/2024 0.70 INCHES OF RAIN

8:19 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 240820-0001

Work Order Detail Report

8/23/2024

SSO INSPECTION 8/18/2024 0.70 INCHES OF RAIN

8:19 AM

Work Order Assets							
<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>	<u>Description 2</u>
			<u>Odometer</u>			<u>Asset ID</u>	<u>Completed</u>
Sewer Control Valve						FAIRFAX AT NORTH PARK	
SSO 431						26	
Sewer Control Valve						NORTH PARK AND COVENTRY	
SSO 114						16	
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH	
SSO 121						35	
Sewer Structure							3094
SA16AAWB0						FAIRMOUNT AT FAIRFAX	
Sewer Control Valve						7	
SSO 112						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	
Sewer Control Valve						6	
SSO 99						3012 NORTH WOODLAND	
Sewer Control Valve						14	
SSO 432							
Sewer Control Valve						55	
DB-03							
Sewer Control Valve						56	
DB-01							
Sewer Control Valve						57	
DB-02						FAIRMOUNT AT DARTMOOR	
Sewer Control Valve						5	
CH-04						FAIRMOUNT AT WELLINGTON	
Sewer Control Valve						44	
SSO 110						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	
Sewer Control Valve						33	
SSO 87						FAIRMOUNT AT MARLBORO	
Sewer Control Valve						4	
SSO 116						FAIRMOUNT AT ARLINGTON	
Sewer Control Valve						46	
SSO 111						FAIRMOUNT & COVENTRY (SCARBOROUGH)	
Sewer Control Valve						37	
SSO 113						FAIRMOUNT AND COVENTRY	
Sewer Control Valve						47	
SSO 124						SCARBOROUGH AT LAMBERTON	
Sewer Control Valve						53	
CH-50						BRADFORD AND LEE	
Sewer Control Valve						11	
SSO 129						EDDINGTON	
Sewer Control Valve						2	
CH-52						HAMPSHIRE LANE AT MAYFIELD (18")	
Sewer Control Valve						42	
SSO 88						EAST OVERLOOK AT EDGEHILL	
Sewer Control Valve						36	
SSO 122						HAMPSHIRE LANE AT MAYFIELD (36")	
Sewer Control Valve						34	
SSO 89							
Sewer Structure						1536	
SA16ADZB0							
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.	
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON	
SSO 120						8	
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY	

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 240820-0001

Work Order Detail Report

8/23/2024

SSO INSPECTION 8/18/2024 0.70 INCHES OF RAIN

8:19 AM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior F
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTON
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

8/23/2024

SSO INSPECTION 8/18/2024 0.70 INCHES OF RAIN

8:19 AM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	8/20/2024/ 1:56 pm	8/20/2024
Reset					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Not Sound	8/20/2024/ 1:57 pm	8/20/2024
3	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	8/20/2024/ 1:58 pm	8/20/2024
4	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	8/20/2024/ 1:58 pm	8/20/2024
5	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Not Sound	8/20/2024/ 1:59 pm	8/20/2024
Reset					
6	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	8/20/2024/ 1:59 pm	8/20/2024
7	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	8/20/2024/ 1:59 pm	8/20/2024
8	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	8/20/2024/ 2:00 pm	8/20/2024
9	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/20/2024/ 2:00 pm	8/20/2024
10	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	8/20/2024/ 2:00 pm	8/20/2024
11	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/20/2024/ 2:01 pm	8/20/2024
12	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	8/20/2024/ 2:01 pm	8/20/2024
13	A-35 2393 COVENTRY SA16AAASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	8/20/2024/ 2:02 pm	8/20/2024
Reset					
14	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Not Sound	8/20/2024/ 2:02 pm	8/20/2024
Reset					
15	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Not Sound	8/20/2024/ 2:03 pm	8/20/2024
Reset					
16	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	8/20/2024/ 2:03 pm	8/20/2024
17	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	8/20/2024/ 2:04 pm	8/20/2024
18	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	8/20/2024/ 2:04 pm	8/20/2024
Reset					
19	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Not Sound	8/20/2024/ 2:05 pm	8/20/2024
NR					
20	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	8/20/2024/ 2:05 pm	8/20/2024
21	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	8/20/2024/ 2:06 pm	8/20/2024
22	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Not Sound	8/20/2024/ 2:06 pm	8/20/2024
Reset					
23	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Not Sound	8/20/2024/ 2:07 pm	8/20/2024
Reset					

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 240820-0001

Work Order Detail Report

8/23/2024

SSO INSPECTION 8/18/2024 0.70 INCHES OF RAIN

8:19 AM

24	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Not Sound	8/20/2024/ 2:06 pm	8/20/2024
Reset					
25	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	/	
26	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	8/20/2024/ 2:11 pm	8/20/2024
27	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	8/20/2024/ 2:12 pm	8/20/2024
28	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	8/20/2024/ 2:12 pm	8/20/2024
29	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	8/20/2024/ 2:13 pm	8/20/2024
30	C-59 3427 THORNE RD SA16AQD0	<input type="checkbox"/>	Sound	8/20/2024/ 2:13 pm	8/20/2024
31	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	8/20/2024/ 2:13 pm	8/20/2024
32	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	8/20/2024/ 2:14 pm	8/20/2024
33	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	8/20/2024/ 2:15 pm	8/20/2024
34	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Not Sound	8/20/2024/ 2:14 pm	8/20/2024
NR					
35	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Not Sound	8/20/2024/ 2:14 pm	8/20/2024
Reset					

Tasks/Resources						
SMCT36 Inspection						
Crew:	Status:		*Cal'c UC: \$8.57	*Task Cost: \$308.64	Start Dt: 8/20/2024	
Supervisor:	UOM:	Each	# of Units: 36.00	*Unit Cost: \$0.00	End Dt: 8/20/2024	
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	8.00	\$201.44		8/20/2024	8/20/2024
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	8.00	\$107.20		8/20/2024	8/20/2024
Task Comment: SSO INSPECTION 8/18/2024 0.70"						

Projected Complete:	Lock: <input type="checkbox"/>	*Actual	*Estimated	*Difference
Repair Type:		WO Duration	8.00	0.00
Subcontractor:		Labor Hours	8.00	0.00
Profit Center:		Labor Costs	\$201.44	\$0.00
Quantity:	0.00	Material Costs	0.00	0.00
Unit of Measure:	Each	Fluids Costs	0.00	0.00
*Unit Cost:	\$0.00	Equipment Costs	107.20	0.00
WO Hours:	0.00	Contractor Costs	0.00	0.00
		Misc. Costs	0.00	0.00
		Total Costs	\$308.64	\$0.00
		Use Task Info:	True	

Work Order Detail Report

8/23/2024

SSO INSPECTION 8/18/2024 0.70 INCHES OF RAIN

8:19 AM

Billing					
Billed Party					
Customer ID:		Customer Number:			
Customer Name:		Last Name:			
Address:			Phone:	Cell #:	
City:			Fax #:		
State:			E-mail:		
Zip:					
Billing Data					
Contact Name:		*Billing Amount:	Billing Required: <input type="checkbox"/>		
Invoice Number:		Date Bill Sent:	Billing Processed: <input type="checkbox"/>		
Incoming Account #:		Payment Received:	Imported to Financials: <input type="checkbox"/>		
		Payment Method:			
Associated PMs					
PM Code and Description				Closed <input checked="" type="checkbox"/>	
SSO-02 SSO INSPECTION					
Tracking					
Item	Description	By	Date	Time	
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	aferrone	8/20/2024	12:34 PM	
Supervisor Notification	Email Queued Successfully!	aferrone	8/20/2024	12:34 PM	
Status Change	From New Work Order to Closed In Field	amanco	8/20/2024	3:00 PM	
Status Change	From Closed In Field to Complete	aferrone	8/23/2024	8:18 AM	
Rate:	Opened At:			Televised: <input type="checkbox"/>	
Received By:	Pipe Footage Cleaned			Power Rooter: <input type="checkbox"/>	
Work From:	Gallons Used:			Jet: <input type="checkbox"/>	
Pipe Size:	WO User 23:			Gap Vac: <input type="checkbox"/>	
Pipe Condition:	WO User 24:			Dye Test: <input type="checkbox"/>	
Could Not Open:	WO User 9:			Gap Root Cut: <input type="checkbox"/>	
Additional Repair:	User 10:			GIS Correction?: <input type="checkbox"/>	
Dye Test Reason:	Appointment Date DNL			Test Tee Correction: <input type="checkbox"/>	
Test Performed Through:	Appointment Date:				
Dye Test Results:					
WO User 51:	E Mail:				
Measurement:	Measurement Line 2:				
History:	Pipe Size:				
Manhole Basin Repair:	PVC Tees, Angles, Sier				
Material Used:	WO User 44:				
Pipe Repair:	WO User 45:				
Street Repair:	WO User 46:				
Grass Repair:					
Curb Repair:					
Driveway- Sidewalk Re					
Construction Crew:	OUPS #:				
WO User 39:	WO User 48:				
WO User 40:					
WO User 41:					

Work Order Detail Report

8/23/2024

SSO INSPECTION 8/18/2024 0.70 INCHES OF RAIN

8:19 AM

WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	
WO User 72:	WO User 82:	Televised: <input type="checkbox"/>
WO User 73:	Quantity:	Paid: <input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104: <input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105: <input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106: <input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:	
WO User 93 Date:	WO User 98 Date:	
WO User 94 Date:	WO User 99 Date:	
WO User 95 Date:	WO User 100 Date:	
WO User 96 Date:	WO User 101 Date:	
WO User 77:	WO User 87:	WO User 107: <input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108: <input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109: <input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110: <input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111: <input type="checkbox"/>
WO Creator: aferrone	WO Creation Date: 8/20/2024	PM Trigger: Rec #: 15775