



Law Department

March 20, 2025

Via E-Mail: vezner.kris@epa.gov and Berger.Jake@epa.gov

Kris P. Vezner, Esq.
Associate Regional Counsel
U.S. Environmental Protection Agency
Region 5 (C-14J)
77 West Jackson Blvd.
Chicago, IL 60604

and

Jake Berger
Physical Scientist
Water Enforcement & Compliance Assurance Branch
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Mail Code ECW-15J
Chicago, IL 60604

Re: February 2025 Overflow Monitoring Reports
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through February 28, 2025, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,

A handwritten signature in blue ink that reads "William R. Hanna".
William R. Hanna
Director of Law

Enclosures


cc: Thomas Benson, Esq., EPA Attorney
James Vinch, Esq., EPA Attorney
James Zimny, EPA Engineer
U.S. EPA Region 5 Water Enforcement Branch
Mark Klingenstein, Environmental Engineer
Erm Gomes, Ohio EPA
Allison Cycyk, Ohio EPA
Casey Galligan, Ohio EPA
David Brumbaugh, Ohio EPA
Bill Fischbein, Ohio EPA
Kahlil Seren, Mayor
Dan Horrigan, City Administrator
Collette Clinkscale, Director of Public Works
Steve Barker, Public Relations
Anthony Ferrone, Utilities Commissioner
Kevin Vander Tuig, P.E. (Outside Engineer)
Sarah Fuller, (Outside Engineer)
Dan Porter (Outside Engineer)
Cindy Biacofsky (Outside Engineer)
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

 **Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Thursday, February 13, 2025

Accumulation in inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report
 Thursday, February 13, 2025

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.35	0.35	0.34	0.25	0.09	0.04
Brecksville	0.26	0.24	0.24	0.16	0.06	0.03
Brook Park	0.33	0.32	0.30	0.18	0.06	0.02
Cleveland Industrial Pkwy	0.34	0.34	0.32	0.18	0.05	0.02
Dille Ave PS	0.33	0.33	0.31	0.22	0.07	0.03
Division Ave PS	0.36	0.36	0.33	0.20	0.06	0.03
Easterly WWTP	0.30	0.30	0.28	0.17	0.06	0.03
Independence	0.26	0.25	0.25	0.18	0.05	0.03
James Rhodes HS	0.32	0.32	0.30	0.19	0.06	0.03
Jennings PS	n/a	n/a	n/a	n/a	n/a	n/a
Macedonia	0.23	0.22	0.20	0.14	0.05	0.02
Maple Heights	0.26	0.26	0.25	0.19	0.06	0.03
Mary Street PS	0.33	0.33	0.31	0.21	0.07	0.03
Mayfield Heights	0.34	0.34	0.33	0.24	0.08	0.04
Moreland Hills	0.32	0.31	0.29	0.20	0.08	0.04
North Olmsted	0.28	0.28	0.27	0.15	0.05	0.02
North Royalton	0.25	0.24	0.23	0.16	0.05	0.03
Oakwood	0.25	0.25	0.23	0.16	0.05	0.03
Olmsted Falls	0.30	0.30	0.28	0.16	0.05	0.02
Parma	0.27	0.27	0.26	0.17	0.06	0.03
Richfield	0.22	0.21	0.21	0.14	0.05	0.02
Shaker Heights	0.36	0.35	0.32	0.23	0.09	0.04
South Euclid	0.38	0.38	0.35	0.24	0.09	0.04
Southerly WWTC	0.29	0.28	0.28	0.20	0.08	0.03
Strongsville C WWTP	0.29	0.28	0.27	0.18	0.06	0.03
Strongsville Foltz	0.28	0.28	0.26	0.17	0.05	0.02
University Heights	0.39	0.39	0.36	0.26	0.11	0.05
Wade Park	0.39	0.39	0.37	0.25	0.08	0.04
Westerly WWTP	0.34	0.34	0.33	0.20	0.06	0.03
Westlake	0.29	0.29	0.28	0.14	0.05	0.02

Work Order Detail Report

2/21/2025

SSO overflow inspections 2-13-2025 0.39'

9:56 AM

WO Number:	250218-0001	Category:	SSOs	
Status:	Closed In Field	Problem:	Storm Response	
Status Date:	2/19/2025 1:48 pm	Main Task:	Inspection	
Asset:	SSO 431			
Location:	FAIRFAX AT NORTH PARK			
Cause:	Weather	Assigned By:		
Assigned Crew:		Assigned Date:		
Supervisor:	Jackson, Jeff	Start Date:	2/18/2025 7:00 AM	Override
Lead Worker:	Manco, Angelo	End Date:	2/19/2025 2:30 PM	Notifications
Priority:	High			Problem <input type="checkbox"/>
Account #:				Overdue <input type="checkbox"/>
Proj No - Acct:		Project ID:		Lead Worker <input type="checkbox"/>
Project:		Project Name:		Task <input type="checkbox"/>
Reason:				Supervisor <input type="checkbox"/>
Received By:				Hard Lock WO <input type="checkbox"/>
Inspected By:				

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Locations

<u>Address</u>	<u>Address 2</u>	
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

2/21/2025

ISO overflow inspections 2-13-2025 0.39'

9:56 AM

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	LEE RD. & SUPERIOR AVE.
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

2/21/2025

iso overflow inspections 2-13-2025 0.39'

9:56 AM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

2/21/2025

so overflow inspections 2-13-2025 0.39'

9:56 AM

Work Order Assets

Object Type	System ID 1	System ID 2	Description 1			PM Description	Asset ID	Completed
			Odometer	Hourmeter	Othermeter			
Sewer Control Valve						FAIRFAX AT NORTH PARK		
SSO 431						26		
Sewer Control Valve						NORTH PARK AND COVENTRY		
SSO 114						16		
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35		
Sewer Structure								
SA16AAWB0						3094		
Sewer Control Valve						FAIRMOUNT AT FAIRFAX		
SSO 112						7		
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6		
Sewer Control Valve						3012 NORTH WOODLAND		
SSO 432						14		
Sewer Control Valve								
DB-03						55		
Sewer Control Valve								
DB-01						56		
Sewer Control Valve								
DB-02						57		
Sewer Control Valve						FAIRMOUNT AT DARTMOOR		
CH-04						5		
Sewer Control Valve						FAIRMOUNT AT WELLINGTON		
SSO 110						44		
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33		
Sewer Control Valve						FAIRMOUNT AT MARLBORO		
SSO 116						4		
Sewer Control Valve						FAIRMOUNT AT ARLINGTON		
SSO 111						46		
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37		
Sewer Control Valve						FAIRMOUNT AND COVENTRY		
SSO 124						47		
Sewer Control Valve						SCARBOROUGH AT LAMBERTON		
CH-50						53		
Sewer Control Valve						BRADFORD AND LEE		
SSO 129						11		
Sewer Control Valve						EDDINGTON		
CH-52						2		
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42		
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL		
SSO 122						36		
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34		
Sewer Structure								
SA16ADZB0						1536		
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20		
Sewer Structure								
SA16ADPH0						4446		
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8		
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103						19		
Sewer Control Valve						3003 EUCLID HEIGHTS BLVD		
SSO 104						15		

Work Order Detail Report

2/21/2025

iso overflow inspections 2-13-2025 0.39'

9:56 AM

Sewer Structure	3402
SA16AGMG0	
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	4987
SA16AQD0	
Sewer Structure	3745
SA16AQQC0	
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	1809
SA16APEF0	

Work Order Detail Report

2/21/2025

ISO overflow inspections 2-13-2025 0.39'

9:56 AM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	2/18/2025/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	2/18/2025/	
3	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	2/18/2025/	
4	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	2/18/2025/	
5	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	2/18/2025/	
6	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	2/18/2025/	
7	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	2/18/2025/	
8	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	/	
9	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	2/18/2025/	
10	A-1 3041 FAIRMOUNT SA16AAUTO (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	2/18/2025/	
11	A-32 FAIRMOUNT AT ARLINGTON SA16AAUPO (INTERSECTION)	<input type="checkbox"/>	Sound	2/18/2025/	
12	A-38 FAIRMOUNT AT MARLBORO SA16AAUJM0 (INTERSECTION)	<input type="checkbox"/>	Sound	2/18/2025/	
13	A-35 2393 COVENTRY SA16AAASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	2/18/2025/	
14	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	2/18/2025/	
15	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	2/19/2025/	
16	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>		2/19/2025/	
Unable to access due to construction and water main break					
17	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	2/19/2025/	
18	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Sound	2/18/2025/	
19	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	2/18/2025/	
20	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	2/18/2025/	
21	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEAO	<input type="checkbox"/>	Sound	2/18/2025/	
22	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	2/19/2025/	
23	B-13-HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	2/18/2025/	
24	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	2/18/2025/	
25	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>		2/19/2025/	
Not on overflow sheet					
26	B-15 COVENTRY AND CEDAR SA16ADBHO	<input type="checkbox"/>	Sound	2/18/2025/	
27	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	2/19/2025/	
28	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	2/19/2025/	
29	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	2/19/2025/	

Work Order Detail Report

2/21/2025

9:56 AM

ISO overflow inspections 2-13-2025 0.39'

30	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	2/19/2025/
31	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	2/19/2025/
32	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	2/19/2025/
33	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOQU0	<input type="checkbox"/>	Sound	2/19/2025/
34	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	2/19/2025/
Rope needs replaced				
35	C-55 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	2/19/2025/

Tasks/Resources						
SMCT36 Inspection						
Crew:	Status:					
Supervisor:	UOM:					
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
19356 Manco, Angelo	Hours	12.00	\$333.24		2/18/2025	2/19/2025
39986 O'Brien, Dominick	Hours	12.00	\$247.92		2/18/2025	2/19/2025
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD 350 CREW CAB	Hours	12.00	\$211.80	572 450 ford crew cab	2/18/2025	2/19/2025
9						

			*Actual	*Estimated	*Difference
Projected Complete:	Lock:	<input type="checkbox"/>	WO Duration	15.48	0.00
Repair Type:			Labor Hours	24.00	0.00
Subcontractor:			Labor Costs	\$581.16	\$0.00
Profit Center:			Material Costs	0.00	0.00
			Fluids Costs	0.00	0.00
Quantity:	0.00	Lock:	Equipment Costs	211.80	0.00
Unit of Measure:	Each		Contractor Costs	0.00	0.00
Unit Cost:	\$0.00		Misc. Costs	0.00	0.00
NO Hours:	0.00		Total Costs	\$792.96	\$0.00
			Use Task Info:	True	True

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:		Cell #:
City:		Fax #:		
State:		E-mail:		
Zip:				

Billing Data		*Billing Amount:	Billing Required:
Contact Name:		Date Bill Sent:	Billing Processed:
Invoice Number:		Payment Received:	Imported to Financials:
Incoming Account #:		Payment Method:	

Associated PMs		PM Code and Description	Closed
SSO-02 SSO INSPECTION			<input checked="" type="checkbox"/>

Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	2/18/2025	7:01 AM
Supervisor Notification	Email Queued Successfully!	jjackson	2/18/2025	7:01 AM
Leadworker Notification	Email Queued Successfully!	jjackson	2/18/2025	7:01 AM
Status Change	From New Work Order to Closed In Field	amanco	2/19/2025	1:48 PM

Work Order Detail Report

2/21/2025

SSO overflow inspections 2-13-2025 0.39'

9:56 AM

Rate:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned.	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:	Appointment Date: 2/18/2025 8:00 AM		
Dye Test Results:			
WO User 51:	E Mail:		
Measurement:	Measurement Line 2:		
History:			
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sleeves		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Repair:			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:	Televised:	<input type="checkbox"/>
WO User 59:	WO User 69:	Paid:	<input type="checkbox"/>
WO User 60:	WO User 70:	WO User 104:	<input type="checkbox"/>
WO User 61:	WO User 71:	WO User 105:	<input type="checkbox"/>
WO User 72:	WO User 82:	WO User 106:	<input type="checkbox"/>
WO User 73:	Quantity:		
WO User 74:	WO User 84:		
WO User 75:	WO User 85:		
WO User 76:	WO User 86:		
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 2/18/2025	PM Trigger:	Rec #: 16086

Northwest Ohio Regional Sewer District


Daily precipitation Report

Accumulation in inches

લક્ષ્મી

卷之三

Lake County



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Wednesday, February 26, 2025

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.38	0.38	0.29	0.14	0.05	0.02
Brecksville	0.44	0.43	0.34	0.16	0.06	0.02
Brook Park	0.41	0.41	0.30	0.16	0.06	0.02
Cleveland Industrial Pkwy	0.43	0.43	0.31	0.15	0.06	0.02
Dille Ave PS	0.38	0.38	0.31	0.14	0.05	0.03
Division Ave PS	0.40	0.40	0.31	0.14	0.06	0.03
Easterly WWTP	0.36	0.34	0.24	0.14	0.06	0.03
Independence	0.37	0.37	0.27	0.14	0.05	0.02
James Rhodes HS	0.40	0.40	0.29	0.15	0.06	0.03
Jennings PS	n/a	n/a	n/a	n/a	n/a	n/a
Macedonia	0.44	0.43	0.31	0.15	0.05	0.03
Maple Heights	0.34	0.34	0.26	0.14	0.06	0.03
Mary Street PS	0.39	0.39	0.31	0.14	0.05	0.02
Mayfield Heights	0.47	0.42	0.30	0.13	0.05	0.02
Moreland Hills	0.43	0.42	0.31	0.17	0.06	0.03
North Olmsted	0.42	0.42	0.32	0.14	0.06	0.03
North Royalton	0.43	0.41	0.32	0.17	0.06	0.03
Oakwood	0.45	0.45	0.33	0.17	0.06	0.03
Olmsted Falls	0.41	0.40	0.30	0.16	0.06	0.02
Parma	0.37	0.37	0.28	0.15	0.05	0.02
Ritchfield	0.52	0.51	0.37	0.16	0.07	0.03
Shaker Heights	0.38	0.38	0.29	0.15	0.06	0.03
South Euclid	0.46	0.41	0.29	0.15	0.06	0.02
Southerly WWTC	0.38	0.38	0.28	0.16	0.06	0.02
Strongsville C WWTP	0.39	0.38	0.29	0.16	0.06	0.03
Strongsville Foltz	0.47	0.44	0.32	0.18	0.06	0.03
University Heights	0.38	0.37	0.28	0.13	0.05	0.02
Wade Park	0.39	0.39	0.30	0.15	0.06	0.02
Westerville WWTP	0.37	0.37	0.30	0.15	0.07	0.03
Westlake	0.41	0.41	0.32	0.16	0.06	0.03

Work Order Detail Report

3/3/2025

SSO overflow inspections 2-28-2025 0.38'

8:22 AM

WO Number:	250228-0001	Category:	SSOs
Status:	Closed In Field	Problem:	Storm Response
Status Date:	2/28/2025 2:03 pm	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	2/28/2025 7:30 AM
Lead Worker:	Manco, Angelo	End Date:	2/28/2025 2:30 PM
Priority:	High	Override Notifications	<input type="checkbox"/>
Account #:		Problem	<input type="checkbox"/>
Proj No - Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer

Comments for Crew
Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations

<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>	<u>Address 2</u>
FAIRFAX AT NORTH PARK				
2,220,655.65435414	665,517.24643672		Doan Brook	
NORTH PARK AND COVENTRY				
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH				
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX				
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)				
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND				
2,222,845.06631389	664,689.08536339		Doan Brook	
2,226,440.21168265	664,329.55524255			
2,226,354.79813956	664,409.89202413			
2,226,389.92077273	664,379.07548472			
FAIRMOUNT AT DARTMOOR				
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON				
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)				
2,223,111.44143730	664,794.46048072		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT MARLBORO				
2,221,638.88762389	665,726.15513962		DOAN BROOK - MAIN BRANCH	

Work Order Detail Report

3/3/2025

iso overflow inspections 2-28-2025 0.38'

8:22 AM

FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	LEE RD. & SUPERIOR AVE.
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	
2,224,536.21778722	668,887.44048372	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	

Work Order Detail Report

3/3/2025

:so overflow inspections 2-28-2025 0.38'

8:22 AM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

3/3/2025

ISO overflow inspections 2-28-2025 0.38'

8:22 AM

Work Order Assets

Object Type	System ID 1	System ID 2	Description 1			PM Description	Asset ID	Completed
			Odometer	Hourmeter	Othermeter			
Sewer Control Valve						FAIRFAX AT NORTH PARK		
SSO 431						26		
Sewer Control Valve						NORTH PARK AND COVENTRY		
SSO 114						16		
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35		
Sewer Structure								
SA16AAWB0						3094		
Sewer Control Valve						FAIRMOUNT AT FAIRFAX		
SSO 112						7		
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6		
Sewer Control Valve						3012 NORTH WOODLAND		
SSO 432						14		
Sewer Control Valve								
DB-03						55		
Sewer Control Valve								
DB-01						56		
Sewer Control Valve								
DB-02						57		
Sewer Control Valve						FAIRMOUNT AT DARTMOOR		
CH-04						5		
Sewer Control Valve						FAIRMOUNT AT WELLINGTON		
SSO 110						44		
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33		
Sewer Control Valve						FAIRMOUNT AT MARLBORO		
SSO 116						4		
Sewer Control Valve						FAIRMOUNT AT ARLINGTON		
SSO 111						46		
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37		
Sewer Control Valve						FAIRMOUNT AND COVENTRY		
SSO 124						47		
Sewer Control Valve						SCARBOROUGH AT LAMBERTON		
CH-50						53		
Sewer Control Valve						BRADFORD AND LEE		
SSO 129						11		
Sewer Control Valve						EDDINGTON		
CH-52						2		
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42		
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL		
SSO 122						36		
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34		
Sewer Structure								
SA16ADZB0						1536		
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20		
Sewer Structure								
SA16ADPH0						4446		
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8		
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103						19		
Sewer Control Valve						3003 EUCLID HEIGHTS BLVD		
SSO 104						15		

Work Order Detail Report

3/3/2025

iso overflow inspections 2-28-2025 0.38'

8:22 AM

Sewer Structure	3402
SA16AGMG0	
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	4987
SA16AQD0	
Sewer Structure	3745
SA16AQQC0	
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	1809
SA16APEF0	

Work Order Detail Report

3/3/2025

so overflow inspections 2-28-2025 0.38'

8:22 AM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	2/28/2025/	
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	2/28/2025/	
3	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	2/28/2025/	
4	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	2/28/2025/	
5	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	2/28/2025/	
6	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	2/28/2025/	
7	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	2/28/2025/	
8	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Not Sound	2/28/2025/	
No block (need to reset new block)					
9	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	2/28/2025/	
10	A-1 3041 FAIRMOUNT SA16AAUTO (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	2/28/2025/	
11	A-32 FAIRMOUNT AT ARLINGTON SA16AAUPO (INTERSECTION)	<input type="checkbox"/>	Sound	2/28/2025/	
12	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	2/28/2025/	
13	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	2/28/2025/	
No block (need to reset new block/)					
14	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Not Sound	2/28/2025/	
Reset block					
15	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	2/28/2025/	
16	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Not Sound	2/28/2025/	
Reset block					
17	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Not Sound	2/28/2025/	
Reset block					
18	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Sound	2/28/2025/	
19	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	2/28/2025/	
20	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Not Sound	2/28/2025/	
Reset block					
21	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Not Sound	2/28/2025/	
Reset block					
22	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	2/28/2025/	
23	B-13-HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Not Sound	2/28/2025/	
Reset block					
24	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	/	
25	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>		2/28/2025/	
Not on sso list					

Work Order Detail Report

3/3/2025

8:22 AM

sso overflow inspections 2-28-2025 0.38'

26	B-15 COVENTRY AND CEDAR SA16ADBHQ	<input type="checkbox"/>	Sound	2/28/2025/
27	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	2/28/2025/
28	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Not Sound	2/28/2025/
Water level still high /. Unable to set block				
29	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	2/28/2025/
Reset block				
30	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	2/28/2025/
31	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	2/28/2025/
Need to restrung block				
32	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Not Sound	2/28/2025/
No block / need to reset new block				
33	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	2/28/2025/
34	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Not Sound	2/28/2025/
Water still high in manhole / unable to set block				
35	C-55 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	2/28/2025/

Tasks/Resources

SMCT36 Inspection

Crew:

Supervisor:

Status:

UOM: Each

*Cal'c UC: \$22.90

*Task Cost: \$801.66

Start Dt: 2/28/2025

of Units: 35.00

*Unit Cost: \$0.00

End Dt: 2/28/2025

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
12459 Eathridge, David	Hours	8.00	\$211.20		2/28/2025	2/28/2025
19356 Manco, Angelo	Hours	8.00	\$222.16		2/28/2025	2/28/2025
19356 Manco, Angelo	Hours	5.00	\$138.85		2/28/2025	2/28/2025

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD 350 CREW CAB 9	Hours	8.00	\$141.20	572 ford 450	2/28/2025	2/28/2025
CHFLT55 FORD 350 CREW CAB 9	Hours	5.00	\$88.25		2/28/2025	2/28/2025

Task Comment: sso overflow inspections 2-28-2025 0.38'

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	21.00	0.00	0.00
Subcontractor:		Labor Costs	\$572.21	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	229.45	0.00	0.00
Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
VO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$801.66	\$0.00	\$0.00
		Use Task Info:	True	True	

Work Order Detail Report

3/3/2025

so overflow inspections 2-28-2025 0.38'

8:22 AM

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	Cell #:
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	<input type="checkbox"/>
Invoice Number:		Date Bill Sent:	<input type="checkbox"/>
Incoming Account #:		Payment Received:	<input type="checkbox"/>
		Payment Method:	<input type="checkbox"/>
Imported to Financials: <input type="checkbox"/>			

Associated PMs		PM Code and Description	Closed		
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>		
Item	Tracking	Description	By	Date	Time
Work Order Creation		From Routine Work SSO-02 - SSO INSPECTION	jjackson	2/28/2025	7:22 AM
Supervisor Notification		Email Queued Successfully!	jjackson	2/28/2025	7:22 AM
Leadworker Notification		Email Queued Successfully!	jjackson	2/28/2025	7:23 AM
Status Change		From New Work Order to Closed In Field	amanco	2/28/2025	2:03 PM

Rate:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: <input type="checkbox"/>
Test Performed Through:	Appointment Date: 2/28/2025 8:00 AM	
Dye Test Results:		
NO User 51:		
Measurement:	E Mail:	
History:	Measurement Line 2:	
Manhole Basin Repair:	Pipe Size:	
Material Used:	PVC Tees, Angles, Sled	
Pipe Repair:	WO User 44:	
Street Repair:	WO User 45:	
Grass Repair:	WO User 46:	
Curb Repair:		
Driveway- Sidewalk Repair:		
Construction Crew:		
NO User 39:	OUPS #:	
NO User 40:	WO User 48:	
NO User 41:		
NO User 52:	WO User 62:	
NO User 53:	WO User 63:	
NO User 54:	WO User 64:	
NO User 55:	WO User 65:	
NO User 56:	WO User 66:	
NO User 57:	WO User 67:	
NO User 58:	WO User 68:	
NO User 59:	WO User 69:	
NO User 60:	WO User 70:	
NO User 61:	WO User 71:	

Work Order Detail Report

3/3/2025

iso overflow inspections 2-28-2025 0.38'

8:22 AM

NO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
NO User 73:	Quantity:	Paid:	<input type="checkbox"/>
NO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
NO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
NO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
NO User 92 Date:	WO User 97 Date:		
NO User 93 Date:	WO User 98 Date:		
NO User 94 Date:	WO User 99 Date:		
NO User 95 Date:	WO User 100 Date:		
NO User 96 Date:	WO User 101 Date:		
NO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
NO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
NO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
NO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
NO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
NO Creator: jjackson	WO Creation Date: 2/28/2025	PM Trigger:	Rec #: 16123