




## Daily Precipitation Report Sunday, May 10, 2020

Accumulation in Inches



## Northeast Ohio Regional Sewer District

Daily Precipitation Report  
Sunday, May 10, 2020

<u>Site Location</u>	<u>Peak Accumulation (inches)</u>				
	<u>24-Hour</u>	<u>6-Hour</u>	<u>3-Hour</u>	<u>1-Hour</u>	<u>15-Minute</u>
Beachwood	0.32	0.31	0.26	0.20	0.08
Brecksville	0.34	0.34	0.33	0.30	0.10
Brook Park	0.37	0.36	0.33	0.23	0.09
Cleveland Industrial Pkwy	0.38	0.37	0.29	0.22	0.08
Dille Ave PS	n/a	n/a	n/a	n/a	n/a
Division Ave PS	0.40	0.40	0.29	0.24	0.10
Easterly WWTP	n/a	n/a	n/a	n/a	n/a
Independence	0.36	0.35	0.35	0.30	0.10
James Rhodes HS	0.36	0.35	0.30	0.24	0.09
Jennings PS	0.37	0.36	0.29	0.24	0.09
Macedonia	0.21	0.21	0.21	0.17	0.06
Maple Heights	0.23	0.22	0.21	0.15	0.05
Mary Street PS	0.35	0.34	0.27	0.21	0.09
Mayfield Heights	0.43	0.41	0.33	0.27	0.09
Moreland Hills	0.26	0.25	0.25	0.20	0.07
North Olmsted	0.29	0.29	0.21	0.18	0.08
North Royalton	0.26	0.26	0.26	0.23	0.07
Oakwood	0.20	0.20	0.20	0.17	0.06
Olmsted Falls	0.28	0.28	0.27	0.21	0.08
Parma	0.34	0.33	0.32	0.24	0.08
Richfield	0.28	0.28	0.28	0.23	0.08
Shaker Heights	0.28	0.27	0.23	0.18	0.07
South Euclid	0.40	0.39	0.31	0.23	0.10
Southberry WWTC	0.36	0.35	0.32	0.28	0.10
Strongsville C WWTP	0.27	0.26	0.25	0.22	0.08
Strongsville Foltz	0.26	0.26	0.25	0.23	0.07
University Heights	0.41	0.40	0.30	0.20	0.08
Wade Park	0.35	0.34	0.25	0.18	0.07
Westlake	0.41	0.39	0.32	0.21	0.11

## Work Order Detail Report

5/13/2020

SSO INSPECTION 5-10-2020 0.41 INCHES OF RAIN

4:42 PM

WO Number:	200512-0001	Category:	SSOs
Status:	Complete	Problem:	Excessive Rainfall
Status Date:	5/13/2020 4:41 pm	Main Task:	Inspection

Asset: SSO 102  
 Location: 2225 NOBLE ROAD

Cause:	Assigned By:
Assigned Crew:	Assigned Date: 11/30/2018 7:00 AM
Supervisor: Jackson, Jeff	Start Date: 5/12/2020 8:00 AM
Lead Worker: Claggett, Dwane	End Date: 5/13/2020
Priority: High	Override Notifications
Account #:	Problem <input type="checkbox"/>
Proj No - Acct:	Overdue <input type="checkbox"/>
Project:	Lead Worker <input type="checkbox"/>
Reason:	Task <input type="checkbox"/>
Received By:	Supervisor <input type="checkbox"/>
Inspected By:	Hard Lock WO <input type="checkbox"/>

Location	Comments for Crew
Department: Sewer Collection	RESET BLOCK
Division: Sewer Collection	
Sub-Division:	
Area:	
Sub-Area:	
Owner:	
Location:	
Classification:	

Maintenance Zone: Alternate Zone:

Work Order Locations				
<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>	<u>Address 2</u>
2225 NOBLE ROAD				
2,227,020.20068015	682,910.03907888		NINE MILE CREEK - MAIN BRANCH	
2828 BERKSHIRE, EAST OF COVENTRY				
2,220,768.48319674	670,614.63814481		DUGWAY CREEK - MAIN BRANCH	
3003 EUCLID HEIGHTS BLVD				
2,222,538.05642922	672,458.71614955		DUGWAY CREEK - MAIN BRANCH	
COVENTRY SOUTH OF FAIRMOUNT				
2,220,178.73142348	666,876.97731304		Doan Brook	
COVENTRY/CEDAR				
2,220,516.67923839	669,679.88509305		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON				
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT ARLINGTON				
2,222,127.85875881	665,393.74077822		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX				
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH	
HAMPSHIRE AT EUCLID HTS. BLVD.				
2,218,465.44876081	671,703.91811846		DOAN BROOK - MAIN BRANCH	
HAMPSHIRE LANE AT MAYFIELD (36")				
2,219,354.97683740	672,902.85961822		DUGWAY CREEK - MAIN BRANCH	
FAIRMOUNT AT DARTMOOR				
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT LEE				
2,224,647.69623882	664,467.25017713		Doan Brook	
LEE RD. & SUPERIOR AVE.				
2,224,449.07983814	672,366.92072946		HEIGHT = NA, WIDTH = NA, LENGTH = NA	

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200512-0001

## Work Order Detail Report

5/13/2020

SSO INSPECTION 5-10-2020 0.41 INCHES OF RAIN

4:42 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	
2,223,111.44143730	664,794.46048072 DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	
2,223,053.81655256	664,693.25202172 DOAN BROOK - MAIN BRANCH
2,225,617.27960148	665,510.97315531
2,225,612.24483465	665,508.19560181
2,226,741.98076415	679,430.76519755
2,226,741.35609348	679,432.95121680
2,226,591.76420106	679,420.92761880
2,226,592.54503940	679,418.74159955

## Work Order Detail Report

5/13/2020

SSO INSPECTION 5-10-2020 0.41 INCHES OF RAIN

4:42 PM

### Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>	<u>Description 2</u>	<u>Asset ID</u>	<u>Completed</u>
Sewer Control Valve								2225 NOBLE ROAD		
SSO 102									3	
Sewer Control Valve								2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103									19	
Sewer Control Valve								3003 EUCLID HEIGHTS BLVD		
SSO 104									15	
Sewer Control Valve								COVENTRY SOUTH OF FAIRMOUNT		
SSO 426									13	
Sewer Control Valve								COVENTRY/CEDAR		
SSO 93									27	
Sewer Control Valve								FAIRMOUNT AT WELLINGTON		
SSO 110									44	
Sewer Control Valve								FAIRMOUNT AT ARLINGTON		
SSO 111									46	
Sewer Control Valve								FAIRMOUNT AT FAIRFAX		
SSO 112									7	
Sewer Control Valve								HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91									20	
Sewer Control Valve								HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89									34	
Sewer Control Valve								FAIRMOUNT AT DARTMOOR		
CH-04									5	
Sewer Control Valve								FAIRMOUNT AT LEE		
CH-08									41	
Sewer Control Valve								LEE RD. & SUPERIOR AVE.		
DV-11									9	
Sewer Control Valve								FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87									33	
Sewer Control Valve								FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99									6	
Sewer Structure									2992	
ST16ZBTK0										
Sewer Structure									3851	
SA16AFWE0										
Sewer Structure									4020	
ST16ZJRC0										
Sewer Structure									4987	
SA16AQD0										
Sewer Structure									3745	
SA16AQQC0										
Sewer Structure									4416	
ST16ZJRB0										

## Work Order Detail Report

5/13/2020

SSO INSPECTION 5-10-2020 0.41 INCHES OF RAIN

4:42 PM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	SSO A CH-01 FAIRMOUNT AND NORTH WOODLAND (3041)	<input type="checkbox"/>	Sound	5/12/2020/ 9:09 am	
2	SSO A CH-02 FAIRMOUNT AND NORTH WOODLAND (3026)	<input type="checkbox"/>	Sound	5/13/2020/ 9:01 am	5/13/2020
No overflow					
3	SSO A CH-03 FAIRMOUNT AT WELLINGTON	<input type="checkbox"/>	Sound	5/12/2020/ 9:24 am	
4	SSO A CH-04 FAIRMOUNT AT DARTMOOR	<input type="checkbox"/>	Sound	5/12/2020/ 9:43 am	
5	SSO A CH-32 FAIRMOUNT AT ARLINGTON	<input type="checkbox"/>	Sound	5/12/2020/12:46 pm	
6	SSO A CH-33 FAIRMOUNT AND FAIRFAX (SOUTH SIDE)	<input type="checkbox"/>	Not Sound	5/12/2020/ 9:33 am	
7	SSO A CH-35 2393 COVENTRY W OF FAIRMOUNT	<input type="checkbox"/>	Sound	5/12/2020/ 9:54 am	
8	SSO A CH-36 NORTH PARK AT COVENTRY	<input type="checkbox"/>	Sound	5/12/2020/10:25 am	
9	SSO A CH-37 FAIRFAX AND NORTH PARK	<input type="checkbox"/>	Sound	5/12/2020/ 9:37 am	
10	SSO A CH-38 FAIRMOUNT AT MARLBORO	<input type="checkbox"/>	Sound	5/12/2020/ 9:29 am	
11	SSO A CH-39 3012 NORTH WOODLAND	<input type="checkbox"/>	Sound	5/12/2020/10:30 am	
12	SSO A CH-45 FAIRMOUNT IN THE ISLAND	<input type="checkbox"/>	Sound	5/12/2020/ 9:55 am	
13	SSO A CH-49 FAIRMOUNT EAST OF CHURCH	<input type="checkbox"/>	Sound	5/12/2020/ 9:58 am	
14	SSO A CH-50 SCARBOROUGH AND LAMBERTON	<input type="checkbox"/>	Sound	5/12/2020/12:39 pm	
15	SSO B CH-09 BRADFORD AND LEE	<input type="checkbox"/>	Sound	5/12/2020/12:44 pm	
16	SSO B CH-10 HAMPSHIRE LANE AT MAYFIELD 18"	<input type="checkbox"/>	Sound	5/12/2020/ 1:03 pm	
17	SSO B CH-11 HAMPSHIRE LANE AT MAYFIELD 36"	<input type="checkbox"/>	Sound	5/12/2020/ 1:04 pm	
18	SSO B CH-13 HAMPSHIRE LANE AT EUCLID HTS. BLVD	<input type="checkbox"/>	Sound	5/12/2020/ 1:08 pm	
19	SSO B CH-17 1685 CUMBERLAND	<input type="checkbox"/>	Sound	5/12/2020/ 1:17 pm	
20	SSO B CH-22 2225 NOBLE ROAD	<input type="checkbox"/>	Sound	5/13/2020/12:10 pm	5/13/2020
No overflow					
21	SSO B CH-25 CUMBERLAND AND SOMERTON	<input type="checkbox"/>	Sound	/ 1:15 pm	
22	SSO B CH-26 EUCLID HTS. BLVD. AND CUMBERLAND	<input type="checkbox"/>	Sound	5/12/2020/ 1:25 pm	
23	SSO B CH-27 QUILLIAMS AND RANDOLPH	<input type="checkbox"/>	Sound	5/13/2020/12:15 pm	5/13/2020
No overflow					
24	SSO B CH-28 EUCLID HTS. BLVD. AND LEE RD.	<input type="checkbox"/>	Sound	5/13/2020/10:03 am	5/13/2020
No overflow					
25	SSO B CH-51 AATHERSTONE AND LANGTON	<input type="checkbox"/>	Sound	5/13/2020/12:19 pm	5/13/2020
No overflow					
26	SSO C CH-12 LEE AND SUPERIOR	<input type="checkbox"/>	Sound	5/13/2020/10:00 am	5/13/2020
No overflow					
27	SSO C CH-14 DERBYSHIRE AT EUCLID HTS. BLVD.	<input type="checkbox"/>	Sound	5/13/2020/ 1:07 pm	5/13/2020
No overflow					

## Work Order Detail Report

5/13/2020

SSO INSPECTION 5-10-2020 0.41 INCHES OF RAIN

4:42 PM

28	SSO C CH-15 COVENTRY AND CEDAR Missing block	<input type="checkbox"/>	Sound	5/13/2020/ 1:17 pm	5/13/2020
29	SSO C CH-23 2828 BERKSHIRE EAST OF COVENTRY No overflow	<input type="checkbox"/>	Sound	5/13/2020/ 1:22 pm	5/13/2020
30	SSO C CH-24 3003 EUCLID HTS. BLVD.	<input type="checkbox"/>	Sound	5/12/2020/ 1:14 pm	
31	SSO C CH-30 SOUTH TAYLOR NORTH OF SUPERIOR No overflow	<input type="checkbox"/>	Sound	5/13/2020/ 9:53 am	5/13/2020
32	SSO C CH-42 12537 CEDAR ROAD Overflowed	<input type="checkbox"/>	Sound	5/13/2020/ 1:12 pm	5/13/2020
33	SSO C CH-46 EDGEHILL AT EUCLID HTS, BLVD. No overflow	<input type="checkbox"/>	Sound	5/13/2020/ 1:03 pm	5/13/2020
34	SSO C CH-47 2528 STRATFORD No overflow	<input type="checkbox"/>	Sound	5/13/2020/ 9:40 am	5/13/2020
35	SSO C CH-52 EDDINGTON ROAD NORTH OF AVONDALE No overflow	<input type="checkbox"/>	Sound	5/13/2020/ 12:42 pm	5/13/2020
36	SSO C CH-54 2806 FAIRMOUNT No overflow	<input type="checkbox"/>	Sound	5/13/2020/ 8:53 am	5/13/2020
37	SSO A CH-5 FAIRMOUNT AND SHELBURNE Missing block	<input type="checkbox"/>	Sound	5/13/2020/ 9:16 am	5/13/2020
38	SSO A CH- 6 FAIRMOUNT AT SHELBURNE No overflow	<input type="checkbox"/>	Sound	5/13/2020/ 9:15 am	5/13/2020
39	SSO A CH-07 FAIRMOUNT AT SHELBURNE No overflow	<input type="checkbox"/>	Sound	5/13/2020/ 9:17 am	5/13/2020
40	SSO C CH-50 3593 FENLEY No overflow	<input type="checkbox"/>	Sound	5/13/2020/ 12:29 pm	5/13/2020
41	SSO B CH-57 E MONMOUTH W OF DARTMOOR No overflow	<input type="checkbox"/>	Sound	5/13/2020/ 9:34 am	5/13/2020
42	SSO B CH-58 E MONMOUTH AT EXETER No overflow	<input type="checkbox"/>	Sound	5/13/2020/ 9:27 am	5/13/2020
43	SSO B CH-59 3427 THORNE RD No overflow	<input type="checkbox"/>	Sound	5/13/2020/ 10:14 am	5/13/2020
44	SSO B CH-60 3415 THORNE ROAD No overflow	<input type="checkbox"/>	Sound	5/13/2020/ 10:12 am	5/13/2020
45	SSO C CH-61 2600 HAMPSHIRE ROAD No overflow	<input type="checkbox"/>	Sound	5/13/2020/ 12:51 pm	5/13/2020
46	SSO CH-56 MEADOWBROOK AND LEE Needs more paint	<input type="checkbox"/>	Sound	5/12/2020/ 12:51 pm	5/12/2020

## Work Order Detail Report

5/13/2020

SSO INSPECTION 5-10-2020 0.41 INCHES OF RAIN

4:42 PM

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:	*Cal'c UC: \$13.59	*Task Cost: \$625.12	Start Dt:		
Supervisor:	UOM: Each	# of Units: 46.00	*Unit Cost: \$0.00	End Dt:		
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
27146 Corbo, Joe	Hours	8.00	\$160.48			
29967 Claggett, Dwane	Hours	8.00	\$181.12			
9512 DelZoppo, Michael	Hours	8.00	\$172.32			
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 GMC SAVANA SEWER 7 VAN	Hours	8.00	\$4.00			
CHFLT-56 FORD TRANSIT SEWER 0 VAN	Each	8.00	\$0.00			
CHFLT55 FORD F250 PICK UP 0	Hours	8.00	\$107.20			
Task Comment: 0.40 INCHES OF RAIN						

Projected Complete:		Lock: <input type="checkbox"/>	*Actual	*Estimated	*Difference
Repair Type:			WO Duration	8.00	0.00
Subcontractor:			Labor Hours	24.00	0.00
Profit Center:			Labor Costs	\$513.92	\$0.00
Quantity:	0.00	Lock: <input type="checkbox"/>	Material Costs	0.00	0.00
Unit of Measure:			Fluids Costs	0.00	0.00
*Unit Cost:	\$0.00		Equipment Costs	111.20	0.00
WO Hours:	0.00		Contractor Costs	0.00	0.00
			Misc. Costs	0.00	0.00
			Total Costs	\$625.12	\$0.00
			Use Task Info:	True	True

Billed Party		Billing
Customer ID:	Customer Number:	
Customer Name:	Last Name:	
Address:		
City:	Phone:	Cell #:
State:	Fax #:	
Zip:	E-mail:	
Billing Data		
Contact Name:	*Billing Amount:	Billing Required: <input type="checkbox"/>
Invoice Number:	Date Bill Sent:	Billing Processed: <input type="checkbox"/>
Incoming Account #:	Payment Received:	Imported to Financials: <input type="checkbox"/>
	Payment Method:	

Associated PMs	
PM Code and Description SSO-101 SSO INSPECTION FORM	Closed <input checked="" type="checkbox"/>

\* A 'Hidden' field indicates permission to view the secured field is turned off.

## Work Order Detail Report

5/13/2020

SSO INSPECTION 5-10-2020 0.41 INCHES OF RAIN

4:42 PM

Item	Tracking	Description	By	Date	Time
Work Order Creation		From Routine Work SSO-101 - SSO INSPECTION FORM	jjackson	5/12/2020	7:45 AM
Supervisor Notification		Email Queued Successfully!	jjackson	5/12/2020	7:45 AM
Email Successfully Sent		jjackson@clvhts.com Lucy Work Order Update - Supervisor	BackgroundTaskUser	5/12/2020	7:45 AM
Leadworker Notification		Email Queued Successfully!	jjackson	5/12/2020	7:46 AM
Email Successfully Sent		dclaggett@clvhts.com Lucy Work Order Status Update - Leadworker	BackgroundTaskUser	5/12/2020	7:46 AM
Status Change		From New Work Order to Complete	aferrone	5/13/2020	4:41 PM

Rates:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	WO User 30:	<input type="checkbox"/>
Test Performed Through:	Appointment Date: 5/12/2020	7:30 AM	
Dye Test Results:			
WO User 51:	E Mail:		
Measurement:	WO User 22:		
History:			
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sleds		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Repair:			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	WO User 83:	WO User 103:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200512-0001

## Work Order Detail Report

5/13/2020

SSO INSPECTION 5-10-2020 0.41 INCHES OF RAIN

4:42 PM

WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 5/12/2020	PM Trigger:	Rec #: 5438




## Northeast Ohio Regional Sewer District

### Daily Precipitation Report

Friday, May 15, 2020

Accumulation in inches



**Northeast Ohio Regional Sewer District**

Daily Precipitation Report  
Friday, May 15, 2020

<u>Site Location</u>	<u>Peak Accumulation (inches)</u>				
	<u>24-Hour</u>	<u>6-Hour</u>	<u>3-Hour</u>	<u>1-Hour</u>	<u>15-Minute</u>
Beachwood	1.51	1.25	0.86	0.55	0.23
Brecksville	1.84	1.67	1.45	0.82	0.42
Brook Park	2.80	2.57	2.22	1.51	0.52
Cleveland Industrial Pkwy	2.11	1.96	1.55	1.03	0.39
Dille Ave PS	1.60	1.36	1.03	0.63	0.20
Division Ave PS	1.66	1.36	0.90	0.47	0.22
Easterly WWTP	n/a	n/a	n/a	n/a	n/a
Independence	1.98	1.77	1.35	0.94	0.33
James Rhodes HS	2.10	1.96	1.61	1.17	0.41
Jennings PS	1.95	1.82	1.42	0.98	0.34
Macedonia	2.39	2.17	1.77	1.20	0.70
Maple Heights	1.94	1.73	1.27	0.86	0.34
Mary Street PS	1.63	1.41	1.02	0.64	0.26
Mayfield Heights	1.72	1.16	0.73	0.39	0.19
Moreland Hills	1.37	1.18	0.87	0.58	0.20
North Olmsted	2.83	2.68	2.10	1.42	0.61
North Royalton	1.81	1.66	1.41	0.85	0.50
Oakwood	2.33	2.10	1.46	1.00	0.56
Olmsted Falls	2.86	2.65	2.31	1.57	0.51
Parma	2.21	1.99	1.60	1.06	0.46
Richfield	0.97	0.83	0.50	0.39	0.19
Shaker Heights	1.73	1.58	1.24	0.89	0.33
South Euclid	1.46	1.12	0.80	0.42	0.19
Southerly WWTC	1.93	1.83	1.55	1.15	0.43
Strongsville C WWTP	2.19	2.04	1.56	1.03	0.44
Strongsville Foltz	1.67	1.51	1.14	0.64	0.22
University Heights	1.74	1.20	0.81	0.49	0.17
Wade Park	1.50	1.17	0.81	0.40	0.14
Westlake	1.48	1.38	1.11	0.76	0.36

## Work Order Detail Report

5/18/2020

SSO INSPECTION 5-15-2020 1.75 INCHES OF RAIN

3:25 PM

WO Number: 200518-0005	Category:	SSOs
Status: Complete	Problem:	Storm Response
Status Date: 5/18/2020 3:19 pm	Main Task:	Inspection

Asset: SSO 431	Location: FAIRFAX AT NORTH PARK	Category:	SSOs
Cause: Weather	Assigned By:	Assigned Date:	Start Date: 5/18/2020 8:00 AM
Assigned Crew:	Supervisor: Jackson, Jeff	End Date: 5/18/2020	<u>Override</u> <u>Notifications</u>
Lead Worker: DelZoppo, Michael	Priority: High	Project ID:	Problem <input type="checkbox"/>
Account #:	Proj No - Acct:	Project Name:	Overdue <input type="checkbox"/>
Project:	Reason:	Lead Worker:	Task <input type="checkbox"/>
Received By:		Supervisor:	Supervisor <input type="checkbox"/>
Inspected By:			Hard Lock WO <input type="checkbox"/>

### Request Comments for Work Order

Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

#### Location

Department: Sewer Collection  
Division: Sewer Collection

Comments for Crew  
Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:  
Area:  
Sub-Area:  
Owner:  
Location:  
Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations		
Address	X Coord	Y Coord
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH

**Work Order Detail Report**

5/18/2020

SSO INSPECTION 5-15-2020 1.75 INCHES OF RAIN

3:25 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

**Work Order Detail Report**

5/18/2020

SSO INSPECTION 5-15-2020 1.75 INCHES OF RAIN

3:25 PM

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

## Work Order Detail Report

5/18/2020

SSO INSPECTION 5-15-2020 1.75 INCHES OF RAIN

3:25 PM

Work Order Assets									
<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>	<u>Asset ID</u>	<u>Completed</u>
Sewer Control Valve							FAIRFAX AT NORTH PARK		
SSO 431								26	
Sewer Control Valve							NORTH PARK AND COVENTRY		
SSO 114								16	
Sewer Control Valve							FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121								35	
Sewer Structure									
SA16AAWB0								3094	
Sewer Control Valve							FAIRMOUNT AT FAIRFAX		
SSO 112								7	
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99								6	
Sewer Control Valve							3012 NORTH WOODLAND		
SSO 432								14	
Sewer Control Valve									
DB-03								55	
Sewer Control Valve									
DB-01								56	
Sewer Control Valve									
DB-02								57	
Sewer Control Valve							FAIRMOUNT AT DARTMOOR		
CH-04								5	
Sewer Control Valve							FAIRMOUNT AT WELLINGTON		
SSO 110								44	
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87								33	
Sewer Control Valve							FAIRMOUNT AT MARLBORO		
SSO 116								4	
Sewer Control Valve							FAIRMOUNT AT ARLINGTON		
SSO 111								46	
Sewer Control Valve							FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113								37	
Sewer Control Valve							FAIRMOUNT AND COVENTRY		
SSO 124								47	
Sewer Control Valve							SCARBOROUGH AT LAMBERTON		
CH-50								53	
Sewer Control Valve							BRADFORD AND LEE		
SSO 129								11	
Sewer Control Valve							EDDINGTON		
CH-52								2	
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88								42	
Sewer Control Valve							EAST OVERLOOK AT EDGEHILL		
SSO 122								36	
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89								34	
Sewer Structure									
SA16ADZB0								1536	
Sewer Control Valve							HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91								20	
Sewer Structure									
SA16ADPH0								4446	
Sewer Control Valve							CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120								8	
Sewer Control Valve									
							2828 BERKSHIRE, EAST OF COVENTRY		

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200518-0005

**Work Order Detail Report**

5/18/2020

SSO INSPECTION 5-15-2020 1.75 INCHES OF RAIN

3:25 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQCO	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

## Work Order Detail Report

5/18/2020

SSO INSPECTION 5-15-2020 1.75 INCHES OF RAIN

3:25 PM

Check List		<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0 Overflowed	<input type="checkbox"/>	Sound	5/18/2020/ 8:27 am	5/18/2020
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT) Overflowed	<input type="checkbox"/>	Sound	5/18/2020/ 8:31 am	5/18/2020
3	A-45-FAIRMOUNT ( IN THE ISLAND EAST OF COVENTRY) SA16ACNE0 No overflow	<input type="checkbox"/>	Sound	5/18/2020/ 8:37 am	5/18/2020
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK) No overflow	<input type="checkbox"/>	Sound	5/18/2020/ 8:44 am	5/18/2020
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK) Overflowed	<input type="checkbox"/>	Sound	5/18/2020/ 8:46 am	5/18/2020
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN) No overflow	<input type="checkbox"/>	Sound	5/18/2020/ 8:49 am	5/18/2020
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD) No overflow	<input type="checkbox"/>	Sound	5/18/2020/ 8:52 am	5/18/2020
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE) No overflow	<input type="checkbox"/>	Sound	5/18/2020/ 8:56 am	5/18/2020
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK) Missing block	<input type="checkbox"/>	Sound	5/18/2020/ 8:59 am	5/18/2020
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND) No overflow	<input type="checkbox"/>	Sound	5/18/2020/ 9:01 am	5/18/2020
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN) No overflow	<input type="checkbox"/>	Sound	5/18/2020/ 9:05 am	5/18/2020
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION) No overflow	<input type="checkbox"/>	Sound	5/18/2020/ 9:08 am	5/18/2020
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK) No overflow	<input type="checkbox"/>	Sound	5/18/2020/ 9:10 am	5/18/2020
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION) No overflow	<input type="checkbox"/>	Sound	5/18/2020/ 9:13 am	5/18/2020
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION) No overflow	<input type="checkbox"/>	Sound	5/18/2020/ 9:14 am	5/18/2020
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN) No overflow	<input type="checkbox"/>	Sound	5/18/2020/ 9:19 am	5/18/2020
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION) Manhole cover found flipped over. Could not open.	<input type="checkbox"/>	/		5/18/2020
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION) Overflowed	<input type="checkbox"/>	Sound	5/18/2020/ 9:25 am	5/18/2020

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200518-0005

## Work Order Detail Report

5/18/2020

### SSO INSPECTION 5-15-2020 1.75 INCHES OF RAIN

3:25 PM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	5/18/2020/ 9:28 am	5/18/2020
	No overflow				
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	5/18/2020/ 9:32 am	5/18/2020
	No overflow. Lid needs to be repainted.				
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	5/18/2020/ 9:38 am	5/18/2020
	No overflow. Lid needs to be repainted.				
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Sound	5/18/2020/ 9:41 am	5/18/2020
	No overflow				
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	5/18/2020/ 9:53 am	5/18/2020
	Block missing.				
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	5/18/2020/ 9:56 am	5/18/2020
	No overflow				
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	5/18/2020/ 9:58 am	5/18/2020
	No overflow				
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	5/18/2020/ 9:59 am	5/18/2020
	No overflow. Lid needs to be repainted.				
27	B-13 HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	5/18/2020/10:01 am	5/18/2020
	Overflowed				
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	5/18/2020/10:03 am	5/18/2020
	No overflow				
29	B-14 DERBYSHIRE AT EUCLID HTS. BLVD. SA16ADPH0	<input type="checkbox"/>	Sound	5/18/2020/10:05 am	5/18/2020
	No overflow. Lid needs to be repainted.				
30	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	5/18/2020/10:10 am	5/18/2020
	No overflow.				
31	B-15 COVENTRY AND CEDAR SA16ADBHQ	<input type="checkbox"/>	Sound	5/18/2020/10:13 am	5/18/2020
	Block missing. Lid needs to be repainted.				
32	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	5/18/2020/10:18 am	5/18/2020
	No overflow.				
33	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	5/18/2020/10:24 am	5/18/2020
	No overflow.				
34	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	5/18/2020/10:30 am	5/18/2020
	No overflow. Lid needs to be repainted.				
35	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	5/18/2020/12:13 pm	5/18/2020
	Block missing. Lid needs to be repainted.				
36	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	5/18/2020/12:17 pm	5/18/2020
	No overflow.				
37	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	5/18/2020/12:19 pm	5/18/2020
	Overflowed. Lid needs to be repainted.				
38	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	5/18/2020/12:21 pm	5/18/2020
	No overflow.				
39	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	5/18/2020/12:22 pm	5/18/2020
	No overflow.				

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200518-0005

## Work Order Detail Report

5/18/2020

SSO INSPECTION 5-15-2020 1.75 INCHES OF RAIN

3:25 PM

40	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	5/18/2020/12:24 pm	5/18/2020
No overflow.					
41	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	5/18/2020/12:31 pm	5/18/2020
No overflow. Lid needs to be repainted.					
42	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	5/18/2020/12:33 pm	5/18/2020
No overflow. Lid needs to be repainted.					
43	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	5/18/2020/12:38 pm	5/18/2020
No overflow.					
44	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	5/18/2020/12:42 pm	5/18/2020
No overflow.					
45	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	5/18/2020/12:44 pm	5/18/2020
No overflow.					
46	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	5/18/2020/12:47 pm	5/18/2020
No overflow. Lid needs to be repainted.					

Tasks/Resources					
SWCT26 Inspection					
Crew:	Status:		*Cal'c UC: \$6.08	*Task Cost: \$279.52	Start Dt: 5/18/2020
Supervisor:	UOM:	Each	# of Units: 46.00	*Unit Cost: \$0.00	End Dt:
Employee					
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt
9512 DelZoppo, Michael	Hours	8.00	\$172.32		5/18/2020
Equipment					
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt
CHFLT55 FORD F250 PICK UP 0	Hours	8.00	\$107.20		5/18/2020
Task Comment: SSO INSPECTION 1.74" OF RAIN					

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	8.00	0.00	0.00
Subcontractor:		Labor Costs	\$172.32	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	107.20	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$279.52	\$0.00	\$0.00
		Use Task Info:	True	True	

Billing					
Billed Party			Customer Number:		
Customer ID:			Last Name:		
Customer Name:			Phone:		
Address:			Cell #:		
City:			Fax #:		
State:			E-mail:		
Zip:			Billing Data		
Contact Name:			*Billing Amount:		
Invoice Number:			Date Bill Sent:		
Incoming Account #:			Payment Received:		
			Payment Method:		
			Billing Required: <input type="checkbox"/>		
			Billing Processed: <input type="checkbox"/>		
			Imported to Financials: <input type="checkbox"/>		

## Work Order Detail Report

5/18/2020

SSO INSPECTION 5-15-2020 1.75 INCHES OF RAIN

3:25 PM

Associated PMs		PM Code and Description	Closed	
		SSO-02 SSO INSPECTION	<input checked="" type="checkbox"/>	
<b>Tracking</b>				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	aferrone	5/18/2020	1:00 PM
Supervisor Notification	Email Queued Successfully!	aferrone	5/18/2020	1:00 PM
Email Successfully Sent	jackson@clvths.com Lucy Work Order Update - Supervisor	BackgroundTaskUser	5/18/2020	1:00 PM
Status Change	From New Work Order to Complete	aferrone	5/18/2020	3:19 PM
<b>Rates:</b>	<b>Opened At:</b>		<b>Televised:</b>	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned		Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:		Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:		Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:		Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:		Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:		GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL		WO User 30:	<input type="checkbox"/>
Test Performed Through:	Appointment Date:	5/15/2020		
Dye Test Results:				
WO User 51:				
Measurement:	E Mail:			
History:	WO User 22:			
Manhole Basin Repair:	Pipe Size:			
Material Used:	PVC Tees, Angles, Sled			
Pipe Repair:	WO User 44:			
Street Repair:	WO User 45:			
Grass Repair:	WO User 46:			
Curb Repair:				
Driveway- Sidewalk Re:				
Construction Crew:				
WO User 39:	OUPS #:			
WO User 40:	WO User 48:			
WO User 41:				
WO User 52:	WO User 62:			
WO User 53:	WO User 63:			
WO User 54:	WO User 64:			
WO User 55:	WO User 65:			
WO User 56:	WO User 66:			
WO User 57:	WO User 67:			
WO User 58:	WO User 68:			
WO User 59:	WO User 69:			
WO User 60:	WO User 70:			
WO User 61:	WO User 71:			
WO User 72:	WO User 82:		Televised:	<input type="checkbox"/>
WO User 73:	WO User 83:		WO User 103:	<input type="checkbox"/>
WO User 74:	WO User 84:		WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:		WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:		WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:			
WO User 93 Date:	WO User 98 Date:			
WO User 94 Date:	WO User 99 Date:			
WO User 95 Date:	WO User 100 Date:			
WO User 96 Date:	WO User 101 Date:			

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200518-0005

**Work Order Detail Report**

5/18/2020

SSO INSPECTION 5-15-2020 1.75 INCHES OF RAIN

3:25 PM


WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: aferrone	WO Creation Date: 5/18/2020	PM Trigger:	Rec #: 5461



## Northeast Ohio Regional Sewer District

Daily Precipitation Report  
Friday, May 29, 2020

Accumulation in Inches



## Northeast Ohio Regional Sewer District

Daily Precipitation Report  
Friday, May 29, 2020

<u>Site Location</u>	Peak Accumulation (inches)				
	<u>24-Hour</u>	<u>6-Hour</u>	<u>3-Hour</u>	<u>1-Hour</u>	<u>15-Minute</u>
Beachwood	0.44	0.43	0.40	0.26	0.10
Brecksville	0.40	0.40	0.36	0.31	0.21
Brook Park	0.65	0.65	0.62	0.42	0.29
Cleveland Industrial Pkwy	0.54	0.54	0.52	0.32	0.21
Dillie Ave PS	0.43	0.43	0.41	0.27	0.13
Division Ave PS	0.47	0.47	0.47	0.31	0.16
Easterly WWTP	0.36	0.36	0.35	0.21	0.11
Independence	0.34	0.33	0.30	0.22	0.13
James Rhodes HS	0.40	0.40	0.37	0.20	0.11
Jennings PS	0.53	0.53	0.50	0.33	0.16
Macedonia	0.48	0.47	0.42	0.35	0.25
Maple Heights	0.38	0.38	0.36	0.31	0.17
Mary Street PS	0.54	0.54	0.52	0.36	0.16
Mayfield Heights	0.43	0.43	0.41	0.26	0.10
Moreland Hills	0.38	0.38	0.33	0.27	0.13
North Olmsted	0.50	0.50	0.48	0.32	0.22
North Royalton	0.34	0.34	0.30	0.21	0.16
Oakwood	0.46	0.46	0.41	0.36	0.15
Olmsted Falls	0.60	0.60	0.55	0.36	0.23
Parma	0.47	0.47	0.42	0.25	0.19
Richfield	0.51	0.51	0.43	0.36	0.27
Shaker Heights	0.45	0.45	0.42	0.31	0.13
South Euclid	0.48	0.48	0.47	0.34	0.23
Southerly WWTC	0.48	0.48	0.45	0.31	0.14
Strongsville C WWTP	0.60	0.60	0.54	0.33	0.23
Strongsville Foltz	0.47	0.47	0.43	0.31	0.24
University Heights	0.55	0.55	0.52	0.36	0.19
Wade Park	0.43	0.43	0.42	0.27	0.12
Westlake	0.50	0.50	0.47	0.27	0.14

## Work Order Detail Report

6/4/2020

SSO INSPECTION 5-29-2020 0.55 INCHES OF RAIN

11:07 AM

WO Number:	200603-0002	Category:	SSOs			
Status:	Complete	Problem:	Storm Response			
Status Date:	6/4/2020 11:05 am	Main Task:	Inspection			
Asset:	SSO 431					
Location:	FAIRFAX AT NORTH PARK					
Cause:	Weather	Assigned By:				
Assigned Crew:						
Supervisor:	Jackson, Jeff	Start Date:	6/3/2020 8:00 AM			
Lead Worker:	DelZoppo, Michael	End Date:	6/3/2020			
Priority:	High	Override Notifications	<input type="checkbox"/>			
Account #:						
Proj No - Act:						
Project:	Project ID:	Lead Worker	<input type="checkbox"/>			
Reason:	Project Name:	Task	<input type="checkbox"/>			
Received By:						
Inspected By:						
Request Comments for Work Order						
Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.						

### Location

Department: Sewer Collection  
Division: Sewer Collection  
Sub-Division:  
Area:  
Sub-Area:  
Owner:  
Location:  
Classification:

### Comments for Crew

Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

### Maintenance Zone:

### Alternate Zone:

Work Order Locations			Address 2
<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK			
2,220,655,65435414	665,517,24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873,16674590	666,048,82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364,86097248	666,446,72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920,81917815	666,080,57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053,81655256	664,693,25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845,06631389	664,689,08536339		Doan Brook
2,226,440,21168265	664,329,55524255		
2,226,354,79813956	664,409,89202413		
2,226,389,92077273	664,379,07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149,97508989	664,453,31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969,26550905	664,532,08075613		DOAN BROOK - MAIN BRANCH

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200603-0002

## Work Order Detail Report

6/4/2020

SSO INSPECTION 5-29-2020 0.55 INCHES OF RAIN

11:07 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

**Work Order Detail Report**

6/4/2020

SSO INSPECTION 5-29-2020 0.55 INCHES OF RAIN

11:07 AM

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

## Work Order Detail Report

6/4/2020

SSO INSPECTION 5-29-2020 0.55 INCHES OF RAIN

11:07 AM

Work Order Assets							
<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>Description 2</u>
							<u>PM Description</u>
Sewer Control Valve							FAIRFAX AT NORTH PARK
SSO 431							26
Sewer Control Valve							NORTH PARK AND COVENTRY
SSO 114							16
Sewer Control Valve							FAIRMOUNT SOUTH OF SCARBOROUGH
SSO 121							35
Sewer Structure							
SA16AAWB0							3094
Sewer Control Valve							FAIRMOUNT AT FAIRFAX
SSO 112							7
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (S. SIDE)
SSO 99							6
Sewer Control Valve							3012 NORTH WOODLAND
SSO 432							14
Sewer Control Valve							
DB-03							55
Sewer Control Valve							
DB-01							56
Sewer Control Valve							
DB-02							57
Sewer Control Valve							FAIRMOUNT AT DARTMOOR
CH-04							5
Sewer Control Valve							FAIRMOUNT AT WELLINGTON
SSO 110							44
Sewer Control Valve							FAIRMOUNT AT NORTH WOODLAND (N. SIDE)
SSO 87							33
Sewer Control Valve							FAIRMOUNT AT MARLBORO
SSO 116							4
Sewer Control Valve							FAIRMOUNT AT ARLINGTON
SSO 111							46
Sewer Control Valve							FAIRMOUNT & COVENTRY (SCARBOROUGH)
SSO 113							37
Sewer Control Valve							FAIRMOUNT AND COVENTRY
SSO 124							47
Sewer Control Valve							SCARBOROUGH AT LAMBERTON
CH-50							53
Sewer Control Valve							BRADFORD AND LEE
SSO 129							11
Sewer Control Valve							EDDINGTON
CH-52							2
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (18")
SSO 88							42
Sewer Control Valve							EAST OVERLOOK AT EDGEHILL
SSO 122							36
Sewer Control Valve							HAMPSHIRE LANE AT MAYFIELD (36")
SSO 89							34
Sewer Structure							
SA16ADZB0							1536
Sewer Control Valve							HAMPSHIRE AT EUCLID HTS. BLVD.
SSO 91							20
Sewer Structure							
SA16ADPH0							4446
Sewer Control Valve							CEDAR BTW. FAIRMOUNT/DEMINGTON
SSO 120							8
Sewer Control Valve							2828 BERKSHIRE, EAST OF COVENTRY

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200603-0002

## Work Order Detail Report

6/4/2020

SSO INSPECTION 5-29-2020 0.55 INCHES OF RAIN

11:07 AM

SSO 103	19
Sewer Control Valve SSO 104	3003 EUCLID HEIGHTS BLVD 15
Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior R 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

## Work Order Detail Report

6/4/2020

SSO INSPECTION 5-29-2020 0.55 INCHES OF RAIN

11:07 AM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	6/3/2020/ 8:37 am	
	No overflow				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	6/3/2020/ 8:39 am	6/3/2020
	No overflow				
3	A-45-FAIRMOUNT ( IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	6/3/2020/ 8:50 am	6/3/2020
	No overflow				
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	6/3/2020/ 8:54 am	6/3/2020
	No overflow				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	6/3/2020/ 8:57 am	6/3/2020
	Overflowed				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	6/3/2020/ 9:02 am	6/3/2020
	No overflow				
7	A-2 3040 Fairmount AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	6/3/2020/ 9:12 am	6/3/2020
	No overflow				
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	6/3/2020/ 9:20 am	6/3/2020
	No overflow				
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	6/3/2020/ 9:22 am	6/3/2020
	No overflow				
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	6/3/2020/ 9:23 am	6/3/2020
	No overflow				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	6/3/2020/ 9:30 am	6/3/2020
	No overflow				
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	6/3/2020/ 9:33 am	6/3/2020
	No overflow				
13	A-1 3041 FAIRMOUNT SA16AAUTO (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	6/3/2020/ 9:37 am	6/3/2020
	No overflow				
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	6/3/2020/ 9:39 am	6/3/2020
	No overflow				
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	6/3/2020/ 9:41 am	6/3/2020
	No overflow				
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	6/3/2020/ 9:46 am	6/3/2020
	No overflow				
17	A-35 2393 COVENTRY SA16AAASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	6/3/2020/ 9:49 am	6/3/2020
	Overflowed				
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	6/3/2020/ 9:54 am	6/3/2020
	No overflow				

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200603-0002

## Work Order Detail Report

6/4/2020

SSO INSPECTION 5-29-2020 0.55 INCHES OF RAIN

11:07 AM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	6/3/2020/10:00 am	6/3/2020
	Overflowed				
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	6/3/2020/10:04 am	6/3/2020
	No overflow				
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	6/3/2020/10:06 am	6/3/2020
	No overflow				
22	A-9 BRADFORD AT LEE SA16AFL0 (INTERSECTION)	<input type="checkbox"/>	Sound	6/3/2020/10:11 am	6/3/2020
	Overflowed				
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	6/3/2020/10:21 am	6/3/2020
	No overflow				
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	6/3/2020/10:26 am	6/3/2020
	No overflow				
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	6/3/2020/10:27 am	6/3/2020
	No overflow				
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	6/3/2020/10:29 am	6/3/2020
	No overflow				
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	6/3/2020/10:32 am	6/3/2020
	No overflow				
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	6/3/2020/10:35 am	6/3/2020
	Overflowed				
29	B-14 DERBYSHIRE AT EUCLID HTS. BLVD. SA16ADPH0	<input type="checkbox"/>	Sound	6/3/2020/10:39 am	6/3/2020
	No overflow				
30	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	6/3/2020/10:43 am	6/3/2020
	No overflow				
31	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	6/3/2020/10:46 am	6/3/2020
	No overflow				
32	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	6/3/2020/10:50 am	6/3/2020
	No overflow				
33	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	6/3/2020/10:55 am	
	No overflow				
34	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	6/3/2020/11:02 am	6/3/2020
	Can't locate				
35	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	6/3/2020/11:44 am	6/3/2020
	Overflowed				
36	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	6/3/2020/11:49 am	6/3/2020
	No overflow				
37	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	6/3/2020/11:52 am	
	No overflow				
38	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	6/3/2020/11:54 am	6/3/2020
	No overflow				
39	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	6/3/2020/11:57 am	6/3/2020
	No overflow				

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200603-0002

## Work Order Detail Report

6/4/2020

SSO INSPECTION 5-29-2020 0.55 INCHES OF RAIN

11:07 AM

40	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	6/3/2020/11:59 am	6/3/2020
No overflow					
41	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	6/3/2020/12:11 pm	6/3/2020
No overflow					
42	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	6/3/2020/12:08 pm	6/3/2020
No overflow					
43	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	6/3/2020/12:17 pm	6/3/2020
No overflow					
44	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	6/3/2020/12:21 pm	6/3/2020
No overflow					
45	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	6/3/2020/12:24 pm	6/3/2020
No overflow					
46	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	6/3/2020/12:29 pm	6/3/2020
No overflow					
47		<input type="checkbox"/>	/		
48		<input type="checkbox"/>	/		
49		<input type="checkbox"/>	/		
50		<input type="checkbox"/>	/		

Tasks/Resources						
SWCT27 Inspection						
Crew:	Status:		*Cal'c UC: \$6.08	*Task Cost: \$279.52	Start Dt:	6/2/2020
Supervisor: Ferrone, Anthony		UOM: Each	# of Units: 46.00	*Unit Cost: \$0.00	End Dt:	
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
9512 DelZoppo, Michael	Hours	8.00	\$172.32		6/2/2020	
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT55 FORD F250 PICK UP 0	Hours	8.00	\$107.20		6/2/2020	
Task Comment: EXCESSIVE RAIN 0.55 INCHES						

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	8.00	0.00	0.00
Subcontractor:		Labor Costs	\$172.32	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	107.20	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$279.52	\$0.00	\$0.00
		Use Task Info:	True	True	

## Work Order Detail Report

6/4/2020

SSO INSPECTION 5-29-2020 0.55 INCHES OF RAIN

11:07 AM

Billing				
<b>Billed Party</b>				
<b>Customer ID:</b> <b>Customer Name:</b> <b>Address:</b> <b>City:</b> <b>State:</b> <b>Zip:</b>	<b>Customer Number:</b> <b>Last Name:</b> <b>Phone:</b> <b>Fax #:</b> <b>E-mail:</b>			
<b>Billing Data</b>				
<b>Contact Name:</b> <b>Invoice Number:</b> <b>Incoming Account #:</b>	<b>*Billing Amount:</b> <b>Date Bill Sent:</b> <b>Payment Received:</b> <b>Payment Method:</b>	<b>Billing Required:</b> <input type="checkbox"/> <b>Billing Processed:</b> <input type="checkbox"/> <b>Imported to Financials:</b> <input type="checkbox"/>		
<b>Associated PMs</b>		<b>Closed</b> <input checked="" type="checkbox"/>		
<b>PM Code and Description</b> SSO-02 SSO INSPECTION				
<b>Tracking</b>				
<b>Item</b> Work Order Creation  Supervisor Notification Email Successfully Sent  Status Change	<b>Description</b> From Routine Work SSO-02 - SSO INSPECTION  Email Queued Successfully! jjackson@clvhts.com Lucity Work Order Update - Supervisor  From New Work Order to Complete	<b>By</b> jjackson  jjackson BackgroundTaskUser  aferrone	<b>Date</b> 6/3/2020  6/3/2020 6/3/2020  6/4/2020	<b>Time</b> 7:59 AM  7:59 AM 8:00 AM  11:05 AM
<b>Rates:</b> <b>Received By:</b> <b>Work From:</b> <b>Pipe Size:</b> <b>Pipe Condition:</b> <b>Could Not Open:</b> <b>Additional Repair:</b> <b>Dye Test Reason:</b> <b>Test Performed Through:</b> <b>Dye Test Results:</b> <b>WO User 51:</b> <b>Measurement:</b> <b>History:</b>	<b>Opened At:</b> Pipe Footage Cleaned <b>Gallons Used:</b> WO User 23: WO User 24: WO User 9: User 10: Appointment Date DNL Appointment Date: 6/3/2020 7:30 AM  <b>E Mail:</b> WO User 22:  <b>Pipe Size:</b> PVC Tees, Angles, Slat WO User 44: WO User 45: WO User 46:  <b>OUPS #:</b> WO User 48:			
<b>Manhole Basin Repair:</b> <b>Material Used:</b> <b>Pipe Repair:</b> <b>Street Repair:</b> <b>Grass Repair:</b> <b>Curb Repair:</b> <b>Driveway- Sidewalk Re:</b> <b>Construction Crew:</b> <b>WO User 39:</b> <b>WO User 40:</b> <b>WO User 41:</b>				

\* A 'Hidden' field indicates permission to view the secured field is turned off.

## Work Order Detail Report

6/4/2020

SSO INSPECTION 5-29-2020 0.55 INCHES OF RAIN

11:07 AM

WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	
WO User 72:	WO User 82:	Televised: <input type="checkbox"/>
WO User 73:	WO User 83:	WO User 103: <input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104: <input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105: <input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106: <input type="checkbox"/>

WO User 92 Date:	WO User 97 Date:	
WO User 93 Date:	WO User 98 Date:	
WO User 94 Date:	WO User 99 Date:	
WO User 95 Date:	WO User 100 Date:	
WO User 96 Date:	WO User 101 Date:	
WO User 77:	WO User 87:	WO User 107: <input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108: <input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109: <input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110: <input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111: <input type="checkbox"/>

WO Creator: jjackson WO Creation Date: 6/3/2020 PM Trigger: Rec #: 5530

