




Northeast Ohio Regional Sewer District

Daily Precipitation Report

Wednesday, June 10, 2020

Accumulation in Inches

L a k e E r i e



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Wednesday, June 10, 2020

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.52	0.52	0.52	0.51	0.46	0.34
Brecksville	n/a	n/a	n/a	n/a	n/a	n/a
Brook Park	0.59	0.59	0.59	0.59	0.34	0.17
Cleveland Industrial Pkwy	n/a	n/a	n/a	n/a	n/a	n/a
Dille Ave PS	0.73	0.73	0.73	0.72	0.43	0.17
Division Ave PS	0.52	0.52	0.52	0.52	0.36	0.18
Easterly WWTP	0.82	0.82	0.82	0.80	0.45	0.21
Independence	0.28	0.28	0.28	0.26	0.20	0.10
James Rhodes HS	0.64	0.64	0.64	0.63	0.40	0.15
Jennings PS	0.85	0.85	0.85	0.84	0.51	0.21
Macedonia	0.39	0.39	0.39	0.39	0.32	0.24
Maple Heights	0.35	0.35	0.35	0.34	0.30	0.19
Mary Street PS	0.69	0.69	0.69	0.68	0.42	0.19
Mayfield Heights	0.25	0.25	0.25	0.25	0.20	0.11
Moreland Hills	0.54	0.54	0.54	0.53	0.48	0.34
North Olmsted	0.30	0.30	0.30	0.30	0.17	0.08
North Royalton	n/a	n/a	n/a	n/a	n/a	n/a
Oakwood	0.40	0.40	0.40	0.40	0.35	0.25
Olmsted Falls	0.41	0.41	0.41	0.41	0.23	0.11
Parma	0.66	0.66	0.66	0.66	0.44	0.23
Richfield	0.35	0.35	0.35	0.35	0.33	0.26
Shaker Heights	0.61	0.61	0.61	0.58	0.50	0.28
South Euclid	0.70	0.70	0.70	0.65	0.38	0.24
Southerly WWTC	0.65	0.65	0.65	0.64	0.42	0.27
Strongsville C WWTP	0.64	0.64	0.64	0.63	0.38	0.15
Strongsville Foltz	0.68	0.68	0.68	0.68	0.43	0.18
University Heights	0.62	0.62	0.62	0.58	0.42	0.22
Wade Park	0.75	0.75	0.75	0.73	0.36	0.21
Westlake	0.27	0.27	0.27	0.27	0.17	0.07

Work Order Detail Report

6/12/2020

SSO INSPECTION 6-11-2020 0.62 INCHES OF RAIN

11:39 AM

WO Number: 200612-0001	Category: SSOs
Status: Complete	Problem: Storm Response
Status Date: 6/12/2020 11:38 am	Main Task: Inspection
Asset: SSO 431	
Location: FAIRFAX AT NORTH PARK	
Cause: Weather	Assigned By:
Assigned Crew:	Assigned Date:
Supervisor: Jackson, Jeff	Start Date: 6/12/2020 8:00 AM
Lead Worker: DelZoppo, Michael	End Date: 6/12/2020
Priority: High	<u>Override</u>
Account #:	<u>Notifications</u>
Proj No - Acct:	Problem ☐
Project:	Overdue ☐
Reason:	Lead Worker ☐
Received By:	Task ☐
Inspected By:	Supervisor ☐
	Hard Lock WO ☐

Request Comments for Work Order

Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection
Sub-Division:
Area:
Sub-Area:
Owner:
Location:
Classification:

Comments for Crew

Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

Maintenance Zone: **Alternate Zone:**

Work Order Locations

<u>Address</u>	<u>Address 2</u>
<u>X Coord</u> <u>Y Coord</u> <u>General Location</u>	
FAIRFAX AT NORTH PARK	
2,220,655.65435414 665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY	
2,219,873.16674590 666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH	
2,220,364.86097248 666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX	
2,220,920.81917815 666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	
2,223,053.81655256 664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND	
2,222,845.06631389 664,689.08536339	Doan Brook
2,226,440.21168265 664,329.55524255	
2,226,354.79813956 664,409.89202413	
2,226,389.92077273 664,379.07548472	
FAIRMOUNT AT DARTMOOR	
2,225,149.97508989 664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON	
2,223,969.26550905 664,532.08075613	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

6/12/2020

SSO INSPECTION 6-11-2020 0.62 INCHES OF RAIN

11:39 AM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

6/12/2020

SSO INSPECTION 6-11-2020 0.62 INCHES OF RAIN

11:39 AM

2,224,536.21778722	668,887.44048372
2,226,741.35609348	679,432.95121680
2,226,591.76420106	679,420.92761880
2,227,825.14395215	684,881.15948047

Work Order Detail Report

SSO INSPECTION 6-11-2020 0.62 INCHES OF RAIN

6/12/2020

11:39 AM

Work Order Assets								
Object Type	Description 1		Description 2					
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed	
Sewer Control Valve					FAIRFAX AT NORTH PARK			
SSO 431						26		
Sewer Control Valve					NORTH PARK AND COVENTRY			
SSO 114						16		
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH			
SSO 121						35		
Sewer Structure								
SA16AAWB0						3094		
Sewer Control Valve					FAIRMOUNT AT FAIRFAX			
SSO 112						7		
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
SSO 99						6		
Sewer Control Valve					3012 NORTH WOODLAND			
SSO 432						14		
Sewer Control Valve								
DB-03						55		
Sewer Control Valve								
DB-01						56		
Sewer Control Valve								
DB-02						57		
Sewer Control Valve					FAIRMOUNT AT DARTMOOR			
CH-04						5		
Sewer Control Valve					FAIRMOUNT AT WELLINGTON			
SSO 110						44		
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)			
SSO 87						33		
Sewer Control Valve					FAIRMOUNT AT MARLBORO			
SSO 116						4		
Sewer Control Valve					FAIRMOUNT AT ARLINGTON			
SSO 111						46		
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)			
SSO 113						37		
Sewer Control Valve					FAIRMOUNT AND COVENTRY			
SSO 124						47		
Sewer Control Valve					SCARBOROUGH AT LAMBERTON			
CH-50						53		
Sewer Control Valve					BRADFORD AND LEE			
SSO 129						11		
Sewer Control Valve					EDDINGTON			
CH-52						2		
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")			
SSO 88						42		
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL			
SSO 122						36		
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")			
SSO 89						34		
Sewer Structure								
SA16ADZB0						1536		
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.			
SSO 91						20		
Sewer Structure								
SA16ADPH0						4446		
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON			
SSO 120						8		
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY			

* A 'Hidden' field indicates permission to view the secured field is turned off.

Work Order Detail Report

6/12/2020

SSO INSPECTION 6-11-2020 0.62 INCHES OF RAIN

11:39 AM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

6/12/2020

SSO INSPECTION 6-11-2020 0.62 INCHES OF RAIN

11:39 AM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	6/12/2020/ 7:16 am	6/12/2020
No overflow					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	6/12/2020/ 7:18 am	6/12/2020
No overflow					
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	6/12/2020/ 7:19 am	6/12/2020
No overflow					
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	6/12/2020/ 7:23 am	6/12/2020
No overflow					
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Sound	6/12/2020/ 7:25 am	6/12/2020
No overflow					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	6/12/2020/ 7:28 am	6/12/2020
No overflow					
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	6/12/2020/ 7:29 am	6/12/2020
No overflow					
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	6/12/2020/ 7:32 am	6/12/2020
No overflow					
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	6/12/2020/ 7:33 am	6/12/2020
No overflow					
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	6/12/2020/ 7:35 am	6/12/2020
No overflow					
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	6/12/2020/ 7:38 am	6/12/2020
No overflow					
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	6/12/2020/ 7:40 am	6/12/2020
No overflow					
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	6/12/2020/ 7:41 am	6/12/2020
No overflow					
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Sound	6/12/2020/ 7:44 am	6/12/2020
No overflow					
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	6/12/2020/ 7:45 am	6/12/2020
No overflow					
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	6/12/2020/ 7:47 am	6/12/2020
No overflow					
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	6/12/2020/ 7:50 am	6/12/2020
No overflow					
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Sound	6/12/2020/ 7:53 am	6/12/2020
Overflowed					

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200612-0001

Work Order Detail Report

6/12/2020

SSO INSPECTION 6-11-2020 0.62 INCHES OF RAIN

11:39 AM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	6/12/2020/ 8:00 am	6/12/2020
	No overflow				
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	6/12/2020/ 8:02 am	6/12/2020
	No overflow				
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	6/12/2020/ 8:04 am	6/12/2020
	No overflow				
22	A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	☐	Sound	6/12/2020/ 8:06 am	6/12/2020
	Overflowed				
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	6/12/2020/ 9:00 am	6/12/2020
	No overflow				
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	6/12/2020/ 9:03 am	6/12/2020
	No overflow				
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	6/12/2020/ 9:04 am	6/12/2020
	No overflow				
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	6/12/2020/ 9:06 am	6/12/2020
	Overflowed				
27	B-13 Hampshire Rd. at Euclid Heights Blvd. SA16ADPR0	☐	Sound	6/12/2020/ 9:07 am	6/12/2020
	No overflow				
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	6/12/2020/ 9:09 am	6/12/2020
	Overflowed				
29	B-14 DERBYSHIRE AT EUCLID HTS. BLVD. SA16ADPH0	☐	Sound	6/12/2020/ 9:12 am	6/12/2020
	No overflow				
30	B-42 12537 CEDAR SA16ACZA0	☐	Sound	6/12/2020/ 9:17 am	6/12/2020
	No overflow				
31	B-15 COVENTRY AND CEDAR SA16ADBHO	☐	Sound	6/12/2020/ 9:20 am	6/12/2020
	No overflow				
32	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	6/12/2020/ 9:24 am	6/12/2020
	No overflow				
33	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	6/12/2020/ 9:27 am	6/12/2020
	No overflow				
34	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	6/12/2020/ 9:31 am	6/12/2020
	No overflow				
35	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	6/12/2020/ 8:18 am	6/12/2020
	Overflowed				
36	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Sound	6/12/2020/ 8:22 am	6/12/2020
	No overflow				
37	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Sound	6/12/2020/ 8:24 am	6/12/2020
	Overflowed				
38	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRLO	☐	Sound	6/12/2020/ 8:26 am	6/12/2020
	No overflow				
39	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Sound	6/12/2020/ 8:27 am	6/12/2020
	No overflow				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200612-0001

Work Order Detail Report

6/12/2020

SSO INSPECTION 6-11-2020 0.62 INCHES OF RAIN

11:39 AM

40	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Sound	6/12/2020/ 8:29 am	6/12/2020
No overflow					
41	C-59 3427 THORNE RD SA16AQD0	☐	Sound	6/12/2020/ 8:33 am	6/12/2020
No overflow					
42	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	6/12/2020/ 8:35 am	6/12/2020
No overflow					
43	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	6/12/2020/ 8:40 am	6/12/2020
No overflow					
44	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	6/12/2020/ 8:43 am	6/12/2020
No overflow					
45	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	6/12/2020/ 8:45 am	6/12/2020
No overflow					
46	C-50 3593 FENLEY SA16APEH0	☐	Sound	6/12/2020/ 8:45 am	6/12/2020
No overflow					

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:	*Cal'c UC: \$6.08	*Task Cost: \$279.52	Start Dt: 6/12/2020		
Supervisor:	UOM: Each	# of Units: 46.00	*Unit Cost: \$0.00	End Dt:		
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
9512 DelZoppo, Michael	Hours	8.00	\$172.32		6/12/2020	
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT93 FORD F250 4 X 4 PICK UP 1	Hours	8.00	\$107.20		6/12/2020	
Task Comment: SSO INSPECTIONS 0.62 INCHES OF RAIN						

Projected Complete:	Lock: ☐	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	0.00	0.00	0.00
Subcontractor:		Labor Costs	\$172.32	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity: 0.00	Lock: ☐	Equipment Costs	107.20	0.00	0.00
Unit of Measure: Each		Contractor Costs	0.00	0.00	0.00
*Unit Cost: \$0.00		Misc. Costs	0.00	0.00	0.00
WO Hours: 0.00		Total Costs	\$279.52	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing	
Customer ID:	Customer Number:		
Customer Name:	Last Name:		
Address:	Phone:	Cell #:	
City:	Fax #:		
State:	E-mail:		
Zip:			
Billing Data			
Contact Name:	*Billing Amount:	Billing Required: ☐	
Invoice Number:	Date Bill Sent:	Billing Processed: ☐	
Incoming Account #:	Payment Received:	Imported to Financials: ☐	
	Payment Method:		

Work Order Detail Report

6/12/2020

SSO INSPECTION 6-11-2020 0.62 INCHES OF RAIN

11:39 AM

Associated PMs	
PM Code and Description	Closed
SSO-02 SSO INSPECTION	☒

Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	kbernard	6/12/2020	7:15 AM
Supervisor Notification	Email Queued Successfully!	kbernard	6/12/2020	7:15 AM
Email Successfully Sent	jjackson@clvhts.com Lucity Work Order Update - Supervisor	BackgroundTaskUser	6/12/2020	7:16 AM
Status Change	From New Work Order to Complete	aferrone	6/12/2020	11:38 AM

Rates:	Opened At:	Televised:	☐
Recieved By:	Pipe Footage Cleaned :	Power Rooter:	☐
Work From:	Gallons Used:	Jet:	☐
Pipe Size:	WO User 23:	Gap Vac:	☐
Pipe Condition:	WO User 24:	Dye Test:	☐
Could Not Open:	WO User 9:	Gap Root Cut:	☐
Additional Repair:	User 10:	GIS Correction?:	☐
Dye Test Reason:	Appointment Date DNL	WO User 30:	☐
Test Performed Throug	Appointment Date:		
Dye Test Results:			
WO User 51:			
Measurement:	E Mail:		
History:	WO User 22:		

Manhole Basin Repair:	Pipe Size:
Material Used:	PVC Tees, Angles, Slex
Pipe Repair:	WO User 44:
Street Repair:	WO User 45:
Grass Repair:	WO User 46:
Curb Repair:	
Driveway- Sidewalk Re	
Construction Crew:	
WO User 39:	
WO User 40:	OUPS #:
WO User 41:	WO User 48:

WO User 52:	WO User 62:	
WO User 53:	WO User 63:	
WO User 54:	WO User 64:	
WO User 55:	WO User 65:	
WO User 56:	WO User 66:	
WO User 57:	WO User 67:	
WO User 58:	WO User 68:	
WO User 59:	WO User 69:	
WO User 60:	WO User 70:	
WO User 61:	WO User 71:	
WO User 72:	WO User 82:	Televised: ☐
WO User 73:	WO User 83:	WO User 103: ☐
WO User 74:	WO User 84:	WO User 104: ☐
WO User 75:	WO User 85:	WO User 105: ☐
WO User 76:	WO User 86:	WO User 106: ☐

WO User 92 Date:	WO User 97 Date:
WO User 93 Date:	WO User 98 Date:
WO User 94 Date:	WO User 99 Date:
WO User 95 Date:	WO User 100 Date:
WO User 96 Date:	WO User 101 Date:

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200612-0001

Work Order Detail Report

6/12/2020

SSO INSPECTION 6-11-2020 0.62 INCHES OF RAIN

11:39 AM

WO User 77:

WO User 87:

WO User 107:



WO User 78:

WO User 88:

WO User 108:



WO User 79:

WO User 89:

WO User 109:



WO User 80:

WO User 90:

WO User 110:



WO User 81:

WO User 91:

WO User 111:




WO Creator: kbernard

WO Creation Date: 6/12/2020

PM Trigger:

Rec #: 5552

Daily Precipitation Report
Tuesday, June 23, 2020

Northeast Ohio Regional Sewer District

Daily Precipitation Report

Tuesday, June 23, 2020

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	0.47	0.47	0.43	0.35	0.27	0.16
Brecksville	0.53	0.53	0.47	0.46	0.29	0.21
Brook Park	0.54	0.54	0.48	0.46	0.34	0.17
Cleveland Industrial Pkwy	0.71	0.71	0.64	0.63	0.38	0.19
Dille Ave PS	0.61	0.61	0.59	0.58	0.36	0.21
Division Ave PS	0.86	0.86	0.81	0.80	0.47	0.23
Easterly WWTP	1.11	1.11	1.07	1.06	0.58	0.25
Independence	0.46	0.46	0.41	0.37	0.30	0.17
James Rhodes HS	0.63	0.63	0.61	0.58	0.34	0.17
Jennings PS	0.63	0.63	0.60	0.60	0.33	0.14
Macedonia	0.42	0.41	0.34	0.33	0.23	0.12
Maple Heights	0.61	0.61	0.55	0.52	0.44	0.17
Mary Street PS	0.76	0.76	0.73	0.71	0.42	0.26
Mayfield Heights	0.51	0.51	0.46	0.38	0.31	0.17
Moreland Hills	0.62	0.62	0.53	0.51	0.43	0.18
North Olmsted	0.55	0.55	0.53	0.49	0.31	0.14
North Royalton	0.43	0.43	0.37	0.37	0.34	0.19
Oakwood	0.44	0.43	0.38	0.35	0.26	0.20
Olmsted Falls	0.67	0.67	0.65	0.62	0.40	0.17
Parma	0.39	0.39	0.37	0.36	0.31	0.19
Richfield	0.38	0.38	0.34	0.33	0.27	0.14
Shaker Heights	0.52	0.52	0.49	0.47	0.42	0.21
South Euclid	1.00	1.00	0.95	0.92	0.52	0.27
Southerly WWTC	0.42	0.42	0.40	0.40	0.31	0.19
Strongsville C WWTP	0.58	0.58	0.51	0.50	0.32	0.18
Strongsville Foltz	0.21	0.21	0.17	0.17	0.13	0.07
University Heights	0.77	0.76	0.73	0.71	0.63	0.34
Wade Park	0.75	0.75	0.72	0.71	0.44	0.24
Westlake	0.75	0.75	0.72	0.59	0.43	0.18

Work Order Detail Report

6/24/2020

SSO INSPECTIONS 06-23-2020 0.77 INCHES OF RAIN

4:01 PM

WO Number: 200624-0002	Category: SSOs
Status: Complete	Problem: Excessive Rainfall
Status Date: 6/24/2020 4:00 pm	Main Task: Inspection
Asset: SSO 102	
Location: 2225 NOBLE ROAD	
Cause:	Assigned By:
Assigned Crew:	Assigned Date: 11/30/2018 7:00 AM
Supervisor: Jackson, Jeff	Start Date: 6/24/2020 8:00 AM
Lead Worker: DelZoppo, Michael	End Date: 6/24/2020
Priority: High	<u>Override</u>
Account #:	<u>Notifications</u>
Proj No - Acct:	Problem ☐
Project:	Overdue ☐
Reason:	Lead Worker ☐
Received By:	Task ☐
Inspected By:	Supervisor ☐
	Hard Lock WO ☐

Location

Department: Sewer Collection**Division:** Sewer Collection**Sub-Division:****Area:****Sub-Area:****Owner:****Location:****Classification:****Maintenance Zone:****Alternate Zone:****Comments for Crew**
RESET BLOCK

Work Order Locations

<u>Address</u>		<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
COVENTRY SOUTH OF FAIRMOUNT		
2,220,178.73142348	666,876.97731304	Doan Brook
COVENTRY/CEDAR		
2,220,516.67923839	669,679.88509305	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT LEE		
2,224,647.69623882	664,467.25017713	Doan Brook
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200624-0002

Work Order Detail Report

6/24/2020

SSO INSPECTIONS 06-23-2020 0.77 INCHES OF RAIN

4:01 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
2,225,617.27960148	665,510.97315531	
2,225,612.24483465	665,508.19560181	
2,226,741.98076415	679,430.76519755	
2,226,741.35609348	679,432.95121680	
2,226,591.76420106	679,420.92761880	
2,226,592.54503940	679,418.74159955	

Work Order Detail Report

6/24/2020

SSO INSPECTIONS 06-23-2020 0.77 INCHES OF RAIN

4:01 PM

Work Order Assets							
Object Type		Description 1			Description 2		
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve					2225 NOBLE ROAD		
SSO 102						3	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103						19	
Sewer Control Valve					3003 EUCLID HEIGHTS BLVD		
SSO 104						15	
Sewer Control Valve					COVENTRY SOUTH OF FAIRMOUNT		
SSO 426						13	
Sewer Control Valve					COVENTRY/CEDAR		
SSO 93						27	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT LEE		
CH-08						41	
Sewer Control Valve					LEE RD. & SUPERIOR AVE.		
DV-11						9	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Structure							
ST16ZBTK0						2992	
Sewer Structure							
SA16AFWE0						3851	
Sewer Structure							
ST16ZJRC0						4020	
Sewer Structure							
SA16AQD0						4987	
Sewer Structure							
SA16AQCC0						3745	
Sewer Structure							
ST16ZJRB0						4416	

Work Order Detail Report

6/24/2020

SSO INSPECTIONS 06-23-2020 0.77 INCHES OF RAIN

4:01 PM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	SSO A CH-01 FAIRMOUNT AND NORTH WOODLAND (3041)	☐	Sound	6/24/2020/ 7:50 am	6/24/2020
	No overflow				
2	SSO A CH-02 FAIRMOUNT AND NORTH WOODLAND (3026)	☐	Sound	6/24/2020/ 7:40 am	6/24/2020
	No overflow				
3	SSO A CH-03 FAIRMOUNT AT WELLINGTON	☐	Sound	6/24/2020/ 7:49 am	6/24/2020
	No overflow				
4	SSO A CH-04 FAIRMOUNT AT DARTMOOR	☐	Sound	6/24/2020/ 7:48 am	6/24/2020
	No overflow				
5	SSO A CH-32 FAIRMOUNT AT ARLINGTON	☐	Sound	6/24/2020/ 7:54 am	6/24/2020
	No overflow				
6	SSO A CH-33 FAIRMOUNT AND FAIRFAX (SOUTH SIDE)	☐	Not Sound	6/24/2020/ 7:35 am	6/24/2020
	Overflowed				
7	SSO A CH-35 2393 COVENTRY W OF FAIRMOUNT	☐	Sound	6/24/2020/ 7:59 am	6/24/2020
	No overflow				
8	SSO A CH-36 NORTH PARK AT COVENTRY	☐	Not Sound	6/24/2020/ 7:28 am	6/24/2020
	Overflowed				
9	SSO A CH-37 FAIRFAX AND NORTH PARK	☐	Sound	6/24/2020/ 7:25 am	6/24/2020
	No overflow				
10	SSO A CH-38 FAIRMOUNT AT MARLBORO	☐	Sound	6/24/2020/ 7:55 am	6/24/2020
	No overflow				
11	SSO A CH-39 3012 NORTH WOODLAND	☐	Sound	6/24/2020/ 7:38 am	6/24/2020
	No overflow				
12	SSO A CH-45 FAIRMOUNT IN THE ISLAND	☐	Sound	6/24/2020/ 7:30 am	6/24/2020
	No overflow				
13	SSO A CH-49 FAIRMOUNT EAST OF CHURCH	☐	Sound	6/24/2020/ 7:57 am	6/24/2020
	No overflow				
14	SSO A CH-50 SCARBOROUGH AND LAMBERTON	☐	Not Sound	6/24/2020/ 8:01 am	6/24/2020
	Overflowed				
15	SSO B CH-09 BRADFORD AND LEE	☐	Sound	6/24/2020/ 8:13 am	6/24/2020
	No overflow				
16	SSO B CH-10 HAMPSHIRE LANE AT MAYFIELD 18"	☐	Sound	6/24/2020/ 8:25 am	6/24/2020
	No overflow				
17	SSO B CH-11 HAMPSHIRE LANE AT MAYFIELD 36"	☐	Sound	6/24/2020/ 8:25 am	6/24/2020
	No overflow				
18	SSO B CH-13 HAMPSHIRE LANE AT EUCLID HTS. BLVD	☐	Sound	6/24/2020/ 8:28 am	6/24/2020
	No overflow				
19	SSO B CH-17 1685 CUMBERLAND	☐	Sound	6/24/2020/ 9:05 am	6/24/2020
	No overflow				
20	SSO B CH-22 2225 NOBLE ROAD	☐	Sound	6/24/2020/ 9:18 am	6/24/2020
	No overflow				

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200624-0002

Work Order Detail Report

6/24/2020

SSO INSPECTIONS 06-23-2020 0.77 INCHES OF RAIN

4:01 PM

21	SSO B CH-25 CUMBERLAND AND SOMERTON	☐	Sound	6/24/2020/ 9:04 am	6/24/2020
No overflow					
22	SSO B CH-26 EUCLID HTS. BLVD. AND CUMBERLAND	☐	Sound	6/24/2020/ 9:02 am	6/24/2020
No overflow					
23	SSO B CH-27 QUILLIAMS AND RANDOLPH	☐	Sound	6/24/2020/ 9:20 am	6/24/2020
No overflow					
24	SSO B CH-28 EUCLID HTS. BLVD. AND LEE RD.	☐	Sound	6/24/2020/ 9:01 am	6/24/2020
No overflow					
25	SSO B CH-51 ATHERSTONE AND LANGTON	☐	Sound	6/24/2020/ 9:22 am	6/24/2020
No overflow					
26	SSO C CH-12 LEE AND SUPERIOR	☐	Sound	6/24/2020/ 8:47 am	6/24/2020
No overflow					
27	SSO C CH-14 DERBYSHIRE AT EUCLID HTS. BLVD.	☐	Sound	6/24/2020/ 8:34 am	6/24/2020
No overflow					
28	SSO C CH-15 COVENTRY AND CEDAR	☐	Sound	6/24/2020/ 8:38 am	6/24/2020
No overflow					
29	SSO C CH-23 2828 BERKSHIRE EAST OF COVENTRY	☐	Sound	6/24/2020/ 8:41 am	6/24/2020
No overflow					
30	SSO C CH-24 3003 EUCLID HTS. BLVD.	☐	Sound	6/24/2020/ 8:44 am	6/24/2020
No overflow					
31	SSO C CH-30 SOUTH TAYLOR NORTH OF SUPERIOR	☐	Not Sound	6/24/2020/ 8:53 am	6/24/2020
Overflowed					
32	SSO C CH-42 12537 CEDAR ROAD	☐	Sound	6/24/2020/ 8:30 am	6/24/2020
No overflow					
33	SSO C CH-46 EDGEHILL AT EUCLID HTS. BLVD.	☐	Sound	6/24/2020/ 8:32 am	6/24/2020
No overflow					
34	SSO C CH-47 2528 STRATFORD	☐	Sound	6/24/2020/ 8:07 am	6/24/2020
No overflow					
35	SSO C CH-52 EDDINGTON ROAD NORTH OF AVONDALE	☐	Sound	6/24/2020/ 8:22 am	6/24/2020
No overflow					
36	SSO C CH-54 2806 FAIRMOUNT	☐	Sound	6/24/2020/ 7:34 am	6/24/2020
No overflow					
37	SSO A CH-05 FAIRMOUNT AND SHELBURNE	☐	Sound	6/24/2020/ 7:44 am	6/24/2020
No overflow					
38	SSO A CH- 06 FAIRMOUNT AT SHELBURNE	☐	Sound	6/24/2020/ 7:43 am	6/24/2020
No overflow					
39	SSO A CH-07 FAIRMOUNT AT SHELBURNE	☐	Sound	6/24/2020/ 7:46 am	6/24/2020
No overflow					
40	SSO C CH-50 3593 FENLEY	☐	Sound	6/24/2020/ 9:25 pm	6/24/2020
No overflow					
41	SSO B CH-57 E MONMOUTH W OF DARTMOOR	☐	Sound	6/24/2020/ 8:10 am	6/24/2020
No overflow					

Work Order Detail Report

6/24/2020

SSO INSPECTIONS 06-23-2020 0.77 INCHES OF RAIN

4:01 PM

42	SSO B CH-58 E MONMOUTH AT EXETER	☐	Sound	6/24/2020/ 8:11 am	6/24/2020
No overflow					
43	SSO B CH-59 3427 THORNE RD	☐	Sound	6/24/2020/ 9:11 am	6/24/2020
No overflow					
44	SSO B CH-60 3415 THORNE ROAD	☐	Sound	6/24/2020/ 9:13 am	6/24/2020
No overflow					
45	SSO C CH-61 2600 HAMPSHIRE ROAD	☐	Not Sound	6/24/2020/ 8:27 am	6/24/2020
Overflowed					
46	SSO CH-56 MEADOWBROOK AND LEE	☐	Sound	6/24/2020/ 8:48 am	6/24/2020
No overflow					
47	SSO B CH-46 Edgehill at East Overlook	☐	Not Sound	6/24/2020/ 8:29 am	6/24/2020
Overflowed					
48	SSO B-CH-42 12537 Ceder Road	☐	Sound	6/24/2020/ 8:36 am	6/24/2020
No overflow					

Tasks/Resources

SWCT26 Inspection

Crew:

Status:

*Cal'c UC: \$6.08

*Task Cost: \$279.52

Start Dt:

Supervisor:

UOM: Each

of Units: 46.00

*Unit Cost: \$0.00

End Dt:

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
9512 DelZoppo, Michael	Hours	8.00	\$172.32			

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	8.00	\$107.20			

Task Comment: EXCESSIVE RAINFALL 0.77 INCHES OF RAIN

Projected Complete:

Lock: ☐

Repair Type:

Subcontractor:

Profit Center:

Quantity: 0.00 -

Lock: ☐

Unit of Measure:

*Unit Cost: \$0.00

WO Hours: 0.00

	*Actual	*Estimated	*Difference
WO Duration	0.00	0.00	0.00
Labor Hours	8.00	0.00	0.00
Labor Costs	\$172.32	\$0.00	\$0.00
Material Costs	0.00	0.00	0.00
Fluids Costs	0.00	0.00	0.00
Equipment Costs	107.20	0.00	0.00
Contractor Costs	0.00	0.00	0.00
Misc. Costs	0.00	0.00	0.00
Total Costs	\$279.52	\$0.00	\$0.00
Use Task Info:	True	True	

Billing

Billed Party

Customer ID:
Customer Name:
Address:
City:
State:
Zip:

Customer Number:
Last Name:
Phone:
Fax #:
E-mail:

Cell #:

Billing Data

Contact Name:
Invoice Number:
Incoming Account #:

*Billing Amount:
Date Bill Sent:
Payment Received:
Payment Method:

Billing Required: ☐
Billing Processed: ☐
Imported to Financials: ☐

Work Order Detail Report

6/24/2020

SSO INSPECTIONS 06-23-2020 0.77 INCHES OF RAIN

4:01 PM

Associated PMs**PM Code and Description**

SSO-101 SSO INSPECTION FORM

Closed**Tracking**

<u>Item</u>	<u>Description</u>	<u>By</u>	<u>Date</u>	<u>Time</u>
Work Order Creation	From Routine Work SSO-101 - SSO INSPECTION FORM	jjackson	6/24/2020	12:00 PM
Supervisor Notification	Email Queued Successfully!	jjackson	6/24/2020	12:01 PM
Email Successfully Sent	jjackson@clvhts.com Lucity Work Order Update - Supervisor	BackgroundTaskUser	6/24/2020	12:01 PM
Status Change	From New Work Order to Complete	aferrone	6/24/2020	4:00 PM

Rates:**Recieved By:****Work From:****Pipe Size:****Pipe Condition:****Could Not Open:****Additional Repair:****Dye Test Reason:****Test Performed Throug****Dye Test Results:****WO User 51:****Measurement:****History:****Opened At:****Pipe Footage Cleaned :****Gallons Used:****WO User 23:****WO User 24:****WO User 9:****User 10:****Appointment Date DNL**

Appointment Date: 6/24/2020 7:00 AM

Televised: ☐**Power Rooter:** ☐**Jet:** ☐**Gap Vac:** ☐**Dye Test:** ☐**Gap Root Cut:** ☐**GIS Correction?:** ☐**WO User 30:** ☐**Manhole Basin Repair:****Material Used:****Pipe Repair:****Street Repair:****Grass Repair:****Curb Repair:****Driveway- Sidewalk Re****Construction Crew:****WO User 39:****WO User 40:****WO User 41:****Pipe Size:****PVC Tees, Angles, Slec****WO User 44:****WO User 45:****WO User 46:****OUPS #:****WO User 48:****WO User 52:****WO User 53:****WO User 54:****WO User 55:****WO User 56:****WO User 57:****WO User 58:****WO User 59:****WO User 60:****WO User 61:****WO User 62:****WO User 63:****WO User 64:****WO User 65:****WO User 66:****WO User 67:****WO User 68:****WO User 69:****WO User 70:****WO User 71:****WO User 72:****WO User 73:****WO User 74:****WO User 75:****WO User 76:****WO User 62:****WO User 63:****WO User 64:****WO User 65:****WO User 66:****WO User 67:****WO User 68:****WO User 69:****WO User 70:****WO User 71:****WO User 72:****WO User 73:****WO User 74:****WO User 75:****WO User 76:****Televised:** ☐**WO User 103:** ☐**WO User 104:** ☐**WO User 105:** ☐**WO User 106:** ☐**WO User 92 Date:****WO User 93 Date:****WO User 94 Date:****WO User 95 Date:****WO User 96 Date:****WO User 97 Date:****WO User 98 Date:****WO User 99 Date:****WO User 100 Date:****WO User 101 Date:**

Work Order Detail Report

6/24/2020

SSO INSPECTIONS 06-23-2020 0.77 INCHES OF RAIN

4:01 PM

WO User 77:	WO User 87:	WO User 107:	☐
WO User 78:	WO User 88:	WO User 108:	☐
WO User 79:	WO User 89:	WO User 109:	☐
WO User 80:	WO User 90:	WO User 110:	☐
WO User 81:	WO User 91:	WO User 111:	☐
WO Creator: jjackson	WO Creation Date: 6/24/2020	PM Trigger:	Rec #: 5589