




**Northeast Ohio  
Regional Sewer District**

**Daily Precipitation Report  
Saturday, July 11, 2020**

Accumulation in Inches



## Northeast Ohio Regional Sewer District

Daily Precipitation Report  
Saturday, July 11, 2020

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	3.55	2.79	1.85	1.45	0.86
Brecksville	0.30	0.20	0.15	0.09	0.05
Brook Park	0.36	0.34	0.26	0.16	0.08
Cleveland Industrial Pkwy	0.83	0.80	0.71	0.36	0.26
Dille Ave PS	1.71	1.57	0.98	0.59	0.39
Division Ave PS	1.34	1.30	0.71	0.69	0.51
Easternly WWTP	2.43	2.18	1.30	1.25	0.82
Independence	0.66	0.46	0.29	0.19	0.13
James Rhodes HS	0.87	0.80	0.66	0.33	0.23
Jennings PS	1.15	1.02	0.80	0.43	0.31
Macedonia	0.46	0.37	0.23	0.16	0.11
Maple Heights	1.75	1.55	0.80	0.57	0.44
Mary Street PS	1.68	1.48	0.86	0.62	0.44
Mayfield Heights	2.11	1.77	1.19	0.82	0.39
Moreland Hills	2.18	1.74	1.48	0.88	0.51
North Olmsted	0.82	0.69	0.60	0.38	0.20
North Royalton	0.59	0.54	0.38	0.23	0.14
Oakwood	1.26	0.97	0.71	0.42	0.23
Olmsted Falls	1.22	1.11	1.04	0.85	0.55
Parma	0.44	0.37	0.26	0.17	0.11
Richfield	0.62	0.59	0.39	0.28	0.14
Shaker Heights	2.88	2.40	1.39	0.89	0.50
South Euclid	2.84	2.53	1.43	1.10	0.65
Southerly WWTC	1.11	1.05	0.78	0.53	0.34
Strongsville C WWTP	0.60	0.52	0.35	0.17	0.10
Strongsville Foltz	1.09	0.99	0.82	0.63	0.25
University Heights	n/a	n/a	n/a	n/a	n/a
V Wade Park	2.01	1.67	1.03	0.72	0.42
Westlake	0.24	0.24	0.22	0.21	0.13

## Work Order Detail Report

7/16/2020

SSO INSPECTIONS 7-11-2020 N/A RAIN FALL

2:32 PM

WO Number:	200715-0002	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	7/16/2020 2:31 pm	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather		
Assigned Crew:			
Supervisor:	Jackson, Jeff	Assigned By:	
Lead Worker:	Cardarella, Joe	Assigned Date:	
Priority:	High	Start Date:	7/15/2020 8:00 AM
Account #:		End Date:	7/16/2020
Proj No - Acct:		Project ID:	<input type="checkbox"/> Override Notifications
Project:		Project Name:	<input type="checkbox"/> Problem <input type="checkbox"/> Overdue <input type="checkbox"/> Lead Worker <input type="checkbox"/> Task <input type="checkbox"/> Supervisor <input type="checkbox"/> Hard Lock WO
Reason:			
Received By:			
Inspected By:			

### Request Comments for Work Order

Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

#### Location

Department: Sewer Collection  
Division: Sewer Collection

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

#### Work Order Locations

<u>Address</u>	<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>	<u>Address 2</u>
FAIRFAX AT NORTH PARK				
2,220,655.65435414	665,517.24643672		Doan Brook	
NORTH PARK AND COVENTRY				
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT SOUTH OF SCARBOROUGH				
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT FAIRFAX				
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)				
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH	
3012 NORTH WOODLAND				
2,222,845.06631389	664,689.08536339		Doan Brook	
2,226,440.21168265	664,329.55524255			
2,226,354.79813956	664,409.89202413			
2,226,389.92077273	664,379.07548472			
FAIRMOUNT AT DARTMOOR				
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH	
FAIRMOUNT AT WELLINGTON				
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH	

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200715-0002

## Work Order Detail Report

7/16/2020

SSO INSPECTIONS 7-11-2020 N/A RAIN FALL

2:32 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481	672,922.02624655	EAST OVERLOOK AT EDGEHILL
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	LEE RD. & SUPERIOR AVE.
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

## Work Order Detail Report

7/16/2020

SSO INSPECTIONS 7-11-2020 N/A RAIN FALL

2:32 PM

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

## Work Order Detail Report

7/16/2020

SSO INSPECTIONS 7-11-2020 N/A RAIN FALL

2:32 PM

Work Order Assets									
Object Type	System ID 1	System ID 2	Description 1	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve	SSO 431						FAIRFAX AT NORTH PARK		26
Sewer Control Valve	SSO 114						NORTH PARK AND COVENTRY		16
Sewer Control Valve	SSO 121						FAIRMOUNT SOUTH OF SCARBOROUGH		35
Sewer Structure	SA16AAWB0								3094
Sewer Control Valve	SSO 112						FAIRMOUNT AT FAIRFAX		7
Sewer Control Valve	SSO 99						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		6
Sewer Control Valve	SSO 432						3012 NORTH WOODLAND		14
Sewer Control Valve	DB-03								55
Sewer Control Valve	DB-01								56
Sewer Control Valve	DB-02								57
Sewer Control Valve	CH-04						FAIRMOUNT AT DARTMOOR		5
Sewer Control Valve	SSO 110						FAIRMOUNT AT WELLINGTON		44
Sewer Control Valve	SSO 87						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		33
Sewer Control Valve	SSO 116						FAIRMOUNT AT MARLBORO		4
Sewer Control Valve	SSO 111						FAIRMOUNT AT ARLINGTON		46
Sewer Control Valve	SSO 113						FAIRMOUNT & COVENTRY (SCARBOROUGH)		37
Sewer Control Valve	SSO 124						FAIRMOUNT AND COVENTRY		47
Sewer Control Valve	CH-50						SCARBOROUGH AT LAMBERTON		53
Sewer Control Valve	SSO 129						BRADFORD AND LEE		11
Sewer Control Valve	CH-52						EDDINGTON		2
Sewer Control Valve	SSO 88						HAMPSHIRE LANE AT MAYFIELD (18")		42
Sewer Control Valve	SSO 122						EAST OVERLOOK AT EDGEHILL		36
Sewer Control Valve	SSO 89						HAMPSHIRE LANE AT MAYFIELD (36")		34
Sewer Structure	SA16ADZB0								1536
Sewer Control Valve	SSO 91						HAMPSHIRE AT EUCLID HTS. BLVD.		20
Sewer Structure	SA16ADPH0								4446
Sewer Control Valve	SSO 120						CEDAR BTW. FAIRMOUNT/DEMINGTON		8
Sewer Control Valve							2828 BERKSHIRE, EAST OF COVENTRY		

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200715-0002

## Work Order Detail Report

7/16/2020

SSO INSPECTIONS 7-11-2020 N/A RAIN FALL

2:32 PM

SSO 103	19
Sewer Control Valve SSO 104	3003 EUCLID HEIGHTS BLVD 15
Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior R 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

## Work Order Detail Report

7/16/2020

SSO INSPECTIONS 7-11-2020 N/A RAIN FALL

2:32 PM

Check List		<u>Completed</u>	<u>Condition</u>	<u>Completion Date/Time</u>	<u>Est Completion Date</u>
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	7/15/2020/ 1:46 pm	
	Reset block				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Not Sound	7/15/2020/ 1:51 pm	
	Reset block				
3	A-45-FAIRMOUNT ( IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	7/15/2020/ 1:27 pm	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	7/15/2020/ 1:33 pm	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	7/15/2020/ 1:38 pm	
	Can't put back need 2 people				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	7/16/2020/ 9:05 am	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	7/16/2020/ 9:02 am	
8	A-6 FAIRMOUNT AT SHELBOURNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	7/16/2020/ 8:50 am	
9	A-5 FAIRMOUNT AT SHELBOURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	7/16/2020/ 8:56 am	
10	A-7 FAIRMOUNT AT SHELBOURNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	7/16/2020/ 8:52 am	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	7/15/2020/ 2:12 pm	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/16/2020/ 9:34 am	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	7/16/2020/ 9:17 am	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/16/2020/ 9:21 am	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/16/2020/ 9:25 am	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	7/16/2020/ 9:42 am	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/15/2020/ 1:21 pm	
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Not Sound	7/15/2020/ 1:15 pm	
	Reset block				
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	7/15/2020/ 1:05 pm	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	7/15/2020/12:51 pm	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	7/15/2020/12:55 pm	
22	A-9 BRADFORD AT LEE SA16AFL0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	7/15/2020/12:43 pm	
	Reset block				
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	7/15/2020/ 9:16 am	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	7/15/2020/ 9:24 am	

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200715-0002

## Work Order Detail Report

7/16/2020

SSO INSPECTIONS 7-11-2020 N/A RAIN FALL

2:32 PM

25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	7/15/2020/ 9:28 am
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	7/15/2020/ 9:31 am
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO	<input type="checkbox"/>	Not Sound	7/15/2020/ 9:39 am
Reset block				
28	B-46 EDGEHILL AT E OVERLOOK SA16AEFP0	<input type="checkbox"/>	Not Sound	7/15/2020/ 9:55 am
No block				
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	7/16/2020/ 8:01 am
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	7/16/2020/ 9:47 am
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	7/15/2020/10:34 am
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	7/15/2020/10:00 am
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	7/15/2020/10:41 am
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	7/15/2020/ 2:23 pm
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Not Sound	7/15/2020/12:33 pm
Reset block				
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	7/15/2020/12:23 pm
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Not Sound	7/15/2020/10:07 am
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	7/15/2020/10:13 am
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	7/15/2020/10:20 am
40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	7/15/2020/ 8:59 am
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	7/15/2020/ 8:55 am
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	7/15/2020/ 8:44 am
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	7/15/2020/ 8:10 am
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	7/15/2020/ 8:30 am
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Not Sound	7/15/2020/ 8:21 am
Reset block				

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:	UOM:	*Cal'c UC:	*Task Cost:	Start Dt:	End Dt:
Supervisor:	UOM:	Each	# of Units:	\$559.04	*Unit Cost:	\$0.00
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	16.00	\$344.64			
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	16.00	\$214.40			

Task Comment: SSO INSPECTIONS N/A BUT SURROUNDING AREAS WERE 2.88-3.55" OF RAIN

## Work Order Detail Report

7/16/2020

SSO INSPECTIONS 7-11-2020 N/A RAIN FALL

2:32 PM

		Lock: <input type="checkbox"/>	*Actual	*Estimated	*Difference
Projected Complete:		WO Duration	8.00	0.00	0.00
Repair Type:		Labor Hours	16.00	0.00	0.00
Subcontractor:		Labor Costs	\$344.64	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	214.40	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$559.04	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:	Cell #:	
City:		Fax #:		
State:		E-mail:		
Billing Data				
Contact Name:		*Billing Amount:	Billing Required: <input type="checkbox"/>	
Invoice Number:		Date Bill Sent:	Billing Processed: <input type="checkbox"/>	
Incoming Account #:		Payment Received:	Imported to Financials: <input type="checkbox"/>	
		Payment Method:		

Associated PMs				
PM Code	and Description	Closed <input checked="" type="checkbox"/>		
SSO-02	SSO INSPECTION			

Tracking					
Item	Description	By	Date	Time	
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	7/15/2020	7:35 AM	
Supervisor Notification	Email Queued Successfully!	jjackson	7/15/2020	7:35 AM	
Email Successfully Sent	jackson@clvhts.com Lucy Work Order	BackgroundTaskUser	7/15/2020	7:35 AM	
Status Change	Update - Supervisor				
	From New Work Order to Complete	aferrone	7/16/2020	2:31 PM	

Rates:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	WO User 30: <input type="checkbox"/>
Test Performed Through:	Appointment Date: 7/15/2020	7:30 AM
Dye Test Results:		
WO User 51:	E Mail:	
Measurement:	WO User 22:	
History:		

## Work Order Detail Report

7/16/2020

SSO INSPECTIONS 7-11-2020 N/A RAIN FALL

2:32 PM


Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sled		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:			
WO User 40:	OUPS #:		
WO User 41:	WO User 48:		
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	WO User 83:	WO User 103:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 7/15/2020	PM Trigger:	Rec #: 5648



## Daily Precipitation Report

Sunday, July 19, 2020

Accumulation in Inches



**Northeast Ohio Regional Sewer District**

Daily Precipitation Report  
Sunday, July 19, 2020

<b>Site Location</b>	<b>Peak Accumulation (Inches)</b>				
	<b>24-Hour</b>	<b>6-Hour</b>	<b>3-Hour</b>	<b>1-Hour</b>	<b>15-Minute</b>
Beachwood	0.55	0.55	0.55	0.55	0.31
Brecksville	n/a	n/a	n/a	n/a	0.21
Brook Park	0.26	0.26	0.26	0.26	n/a
Cleveland Industrial Pkwy	0.62	0.62	0.62	0.62	0.17
Dille Ave PS	0.36	0.36	0.36	0.36	0.47
Division Ave PS	0.25	0.25	0.22	0.22	0.28
Easterly WWTP	0.54	0.54	0.30	0.30	0.19
Independence	0.31	0.31	0.31	0.30	0.26
James Rhodes HS	0.63	0.63	0.63	0.63	0.29
Jennings PS	0.72	0.72	0.72	0.72	0.51
Macedonia	0.61	0.61	0.55	0.55	0.24
Maple Heights	0.36	0.36	0.34	0.34	0.31
Mary Street PS	0.30	0.30	0.30	0.30	0.62
Mayfield Heights	0.16	0.16	0.16	0.16	0.13
Moreland Hills	0.41	0.41	0.40	0.40	0.36
North Olmsted	0.26	0.26	0.26	0.26	0.26
North Royalton	0.66	0.66	0.66	0.66	0.58
Oakwood	0.27	0.27	0.27	0.26	0.24
Olmsted Falls	0.18	0.18	0.18	0.18	0.16
Parma	0.16	0.16	0.16	0.16	0.06
Richfield	n/a	n/a	n/a	n/a	n/a
Shaker Heights	0.55	0.55	0.55	0.55	0.19
South Euclid	0.21	0.21	0.14	0.14	0.06
Southerly WWTC	0.35	0.35	0.35	0.35	0.12
Strongsville C WWTP	0.18	0.18	0.18	0.18	0.11
Strongsville Foltz	0.54	0.54	0.53	0.52	0.42
University Heights	0.38	0.38	0.38	0.38	0.36
Wade Park	0.40	0.40	0.30	0.30	0.27
Westlake	0.37	0.37	0.37	0.37	0.23

## Work Order Detail Report

7/22/2020

SSO INSPECTION 7-19-2020

3:16 PM

WO Number:	200721-0001	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	7/22/2020 3:15 pm	Main Task:	Inspection

Asset:	SSO 431	Location:	FAIRFAX AT NORTH PARK	
Cause:	Weather	Assigned By:		
Assigned Crew:		Assigned Date:		
Supervisor:	Jackson, Jeff	Start Date:		Override
Lead Worker:	Cardarella, Joe	End Date:	7/22/2020	Notifications
Priority:	High	Problem	<input type="checkbox"/>	
Account #:		Overdue	<input type="checkbox"/>	
Proj No - Acct:		Lead Worker	<input type="checkbox"/>	
Project:		Project ID:		Task
Reason:		Project Name:		Supervisor
Received By:				Hard Lock WO
Inspected By:				<input type="checkbox"/>

### Request Comments for Work Order

Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

#### Location

Department: Sewer Collection  
Division: Sewer Collection

Comments for Crew  
Inspect all (46) SSO's when rainfall is one quarter (1/4")  
inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
Address	X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339		Doan Brook
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH

## Work Order Detail Report

7/22/2020

SSO INSPECTION 7-19-2020

3:16 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	MONMOUTH, EAST OF DARTMOOR
2,225,152.08663423	665,499.19660404	DOAN BROOK BRADFORD AND LEE
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH EDDINGTON
2,221,299.08384156	674,932.84604380	HAMPSHIRE LANE AT MAYFIELD (18")
2,219,348.17140481	672,922.02624655	EAST OVERLOOK AT EDGEHILL
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH HAMPSHIRE LANE AT MAYFIELD (36")
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH CEDAR BTW. FAIRMOUNT/DEMINGTON
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH 2828 BERKSHIRE, EAST OF COVENTRY
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH 3003 EUCLID HEIGHTS BLVD
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH South Taylor between Antisdale Ave and Superior Rd
2,227,113.30810548	671,276.67684697	LEE RD. & SUPERIOR AVE.
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA EUCLID HEIGHTS BLVD AND LEE
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH EUCLID HEIGHTS BLVD/CUMBERLAND
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH 1685 CUMBERLAND
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH CUMBERLAND/SOMERTON
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH QUILLIAMS, N. OF RANDOLF
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH LANGTON AND AATHERSTONE
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

---

**Work Order Detail Report**

7/22/2020

SSO INSPECTION 7-19-2020

3:16 PM

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

## Work Order Detail Report

SSO INSPECTION 7-19-2020

7/22/2020

3:16 PM

### Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Description 2</u>	<u>Asset ID</u>	<u>Completed</u>
			<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>
Sewer Control Valve						FAIRFAX AT NORTH PARK
SSO 431						26
Sewer Control Valve						NORTH PARK AND COVENTRY
SSO 114						16
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH
SSO 121						35
Sewer Structure						
SA16AAWB0						3094
Sewer Control Valve						FAIRMOUNT AT FAIRFAX
SSO 112						7
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)
SSO 99						6
Sewer Control Valve						3012 NORTH WOODLAND
SSO 432						14
Sewer Control Valve						
DB-03						55
Sewer Control Valve						
DB-01						56
Sewer Control Valve						
DB-02						57
Sewer Control Valve						FAIRMOUNT AT DARTMOOR
CH-04						5
Sewer Control Valve						FAIRMOUNT AT WELLINGTON
SSO 110						44
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)
SSO 87						33
Sewer Control Valve						FAIRMOUNT AT MARLBORO
SSO 116						4
Sewer Control Valve						FAIRMOUNT AT ARLINGTON
SSO 111						46
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)
SSO 113						37
Sewer Control Valve						FAIRMOUNT AND COVENTRY
SSO 124						47
Sewer Control Valve						SCARBOROUGH AT LAMBERTON
CH-50						53
Sewer Control Valve						BRADFORD AND LEE
SSO 129						11
Sewer Control Valve						EDDINGTON
CH-52						2
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")
SSO 88						42
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL
SSO 122						36
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")
SSO 89						34
Sewer Structure						
SA16ADZB0						1536
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.
SSO 91						20
Sewer Structure						
SA16ADPH0						4446
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON
SSO 120						8
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY

\* A 'Hidden' field indicates permission to view the secured field is turned off.

## Work Order Detail Report

7/22/2020

SSO INSPECTION 7-19-2020

3:16 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQCO	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND AHERSTON
CH-51	54
Sewer Structure	
SA16APEF0	1809

## Work Order Detail Report

7/22/2020

SSO INSPECTION 7-19-2020

3:16 PM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	7/22/2020/ 8:37 am	
Reset block					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	7/22/2020/ 8:49 am	
3	A-45-FAIRMOUNT ( IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	7/22/2020/ 9:16 am	
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	7/22/2020/ 9:21 am	
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Not Sound	7/22/2020/ 8:29 am	
Reset block					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	7/21/2020/ 1:17 pm	
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	7/21/2020/ 1:13 pm	
8	A-6 FAIRMOUNT AT SHELBOURNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	7/21/2020/12:52 pm	
9	A-5 FAIRMOUNT AT SHELBOURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	7/21/2020/12:59 pm	
10	A-7 FAIRMOUNT AT SHELBOURNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	7/21/2020/12:56 pm	
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	7/21/2020/12:43 pm	
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/21/2020/ 1:24 pm	
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	7/21/2020/ 1:33 pm	
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/22/2020/ 8:09 am	
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/22/2020/ 8:17 am	
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	7/22/2020/ 9:26 am	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	7/21/2020/ 2:22 pm	
Reset block					
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	7/21/2020/ 1:58 pm	
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	7/21/2020/ 1:40 pm	
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	7/21/2020/12:34 pm	
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	7/21/2020/12:37 pm	
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	7/21/2020/12:26 pm	
Reset block					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	7/21/2020/ 8:44 am	
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	7/21/2020/ 8:53 am	
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	7/21/2020/ 8:54 am	

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200721-0001

## Work Order Detail Report

7/22/2020

SSO INSPECTION 7-19-2020

3:16 PM

26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	7/21/2020/ 9:03 am
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPRO	<input type="checkbox"/>	Sound	7/21/2020/ 9:06 am
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Not Sound	7/21/2020/ 9:29 am
	String not long enough			
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	7/21/2020/ 9:35 am
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	7/21/2020/ 9:38 am
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	7/21/2020/ 9:43 am
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	7/21/2020/ 9:50 am
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	7/21/2020/10:33 am
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Not Sound	7/21/2020/10:43 am
	Reset block			
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	7/21/2020/10:25 am
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Not Sound	7/21/2020/10:19 am
	Reset block			
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	7/21/2020/ 9:56 am
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Not Sound	7/21/2020/10:01 am
	Block gone			
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	7/21/2020/10:08 am
40	C-59 3427 THORNE RD SA16AQKD0	<input type="checkbox"/>	Sound	7/21/2020/ 8:34 am
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	7/21/2020/ 8:31 am
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	7/21/2020/ 8:26 am
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	7/21/2020/ 8:03 am
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	7/21/2020/ 8:16 am
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Not Sound	7/21/2020/ 8:09 am
	Reset block			

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:		*Cal'c UC: \$8.71	*Task Cost: \$391.90	Start Dt:	
Supervisor:	UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:	
Employee						
Resource	UOM		Units	*Total Cost	Alt Description	Start Dt
22394 Cardarella, Joe	Hours		10.00	\$215.40		End Dt
Equipment						
Resource	UOM		Units	*Total Cost	Alt Description	Start Dt
CHFLT55 FORD 350 CREW CAB	Hours		10.00	\$176.50		End Dt
9						
Task Comment: SSO INSPECTION 0.38 INCHES OF RAIN						

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200721-0001

## Work Order Detail Report

7/22/2020

SSO INSPECTION 7-19-2020

3:16 PM

			*Actual	*Estimated	*Difference
Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	0.00	0.00	0.00
Repair Type:		Labor Hours	10.00	0.00	0.00
Subcontractor:		Labor Costs	\$215.40	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity:	0.00	Equipment Costs	176.50	0.00	0.00
Unit of Measure:	Each	Contractor Costs	0.00	0.00	0.00
*Unit Cost:	\$0.00	Misc. Costs	0.00	0.00	0.00
WO Hours:	0.00	Total Costs	\$391.90	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing	
Customer ID:	Customer Number:		
Customer Name:	Last Name:		
Address:			
City:	Phone:	Cell #:	
State:	Fax #:		
Zip:	E-mail:		
Billing Data			
Contact Name:	*Billing Amount:		Billing Required: <input type="checkbox"/>
Invoice Number:	Date Bill Sent:		Billing Processed: <input type="checkbox"/>
Incoming Account #:	Payment Received:		Imported to Financials: <input type="checkbox"/>
	Payment Method:		

Associated PMs				
PM Code and Description				
SSO-02 SSO INSPECTION		Closed <input checked="" type="checkbox"/>		

Tracking				
Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	7/21/2020	7:22 AM
Supervisor Notification	Email Queued Successfully!	jjackson	7/21/2020	7:22 AM
Email Successfully Sent	jjackson@clvhts.com Lucy Work Order	BackgroundTaskUser	7/21/2020	7:22 AM
Status Change	Update - Supervisor			
	From New Work Order to Complete	aferrone	7/22/2020	3:15 PM

Rates:	Opened At:	Televised: <input type="checkbox"/>
Received By:	Pipe Footage Cleaned,	Power Rooter: <input type="checkbox"/>
Work From:	Gallons Used:	Jet: <input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac: <input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test: <input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut: <input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?: <input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	WO User 30: <input type="checkbox"/>
Test Performed Through:	Appointment Date: 7/21/2020	7:00 AM
Dye Test Results:	E Mail:	
WO User 51:	WO User 22:	
Measurement:		
History:		


## Work Order Detail Report

SSO INSPECTION 7-19-2020

7/22/2020

3:16 PM

Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sleds		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Repair:			
Construction Crew:			
WO User 39:	OUPS #:		
WO User 40:	WO User 48:		
WO User 41:			
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
WO User 73:	WO User 83:	WO User 103:	<input type="checkbox"/>
WO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
WO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
WO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
WO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
WO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
WO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
WO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>
WO Creator: jjackson	WO Creation Date: 7/21/2020	PM Trigger:	Rec #: 5665



## Northeast Ohio Regional Sewer District

Daily Precipitation Report

Monday, July 27, 2020

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	1.11	1.09	1.05	0.69	0.42
Brecksville	1.21	1.21	1.21	1.08	0.72
Brook Park	0.78	0.77	0.74	0.52	0.32
Cleveland Industrial Pkwy	1.46	1.46	1.43	1.09	0.91
Dille Ave PS	0.81	0.81	0.76	0.44	0.35
Division Ave PS	0.73	0.72	0.56	0.36	0.28
Easterly WWTP	0.11	0.11	0.10	0.08	0.04
Independence	1.13	1.13	1.13	1.07	0.52
James Rhodes HS	1.06	1.06	1.05	0.67	0.51
Jennings PS	0.97	0.96	0.94	0.57	0.45
Macedonia	0.26	0.25	0.23	0.18	0.13
Maple Heights	1.36	1.36	1.36	0.87	0.59
May Street PS	0.93	0.92	0.85	0.45	0.35
Mayfield Heights	0.33	0.32	0.19	0.12	0.08
Moreland Hills	0.62	0.62	0.62	0.46	0.25
North Olmsted	n/a	n/a	n/a	n/a	n/a
North Royalton	0.84	0.84	0.84	0.59	0.33
Oakwood	2.04	2.04	2.04	2.01	0.99
Olmsted Falls	0.50	0.50	0.49	0.39	0.25
Parma	0.60	0.60	0.60	0.47	0.27
Richfield	0.04	0.04	0.03	0.03	0.03
Shaker Heights	0.98	0.97	0.96	0.54	0.44
South Euclid	0.23	0.23	0.14	0.11	0.07
Southerly WWTC	0.96	0.96	0.94	0.49	0.44
Strongsville C WWTP	0.39	0.39	0.30	0.16	0.08
Strongsville Foltz	0.53	0.53	0.44	0.34	0.20
University Heights	0.49	0.47	0.46	0.28	0.21
Wade Park	0.49	0.48	0.42	0.25	0.17
Westlake	1.27	1.27	1.15	0.63	0.49

## Work Order Detail Report

7/29/2020

SSO INSPECTION 7-27-2020 0.49 INCHES OF RAIN

2:21 PM

WO Number:	200729-0004	Category:	SSOs
Status:	Complete	Problem:	Storm Response
Status Date:	7/29/2020 2:20 pm	Main Task:	Inspection

Asset:	SSO 431	Location:	FAIRFAX AT NORTH PARK	
Cause:	Weather	Assigned By:		
Assigned Crew:		Assigned Date:		
Supervisor:	Jackson, Jeff	Start Date:	7/29/2020 8:00 AM	Override
Lead Worker:	DelZoppo, Michael	End Date:	7/29/2020	Notifications
Priority:	High			
Account #:				Problem <input type="checkbox"/>
Proj No - Acct:				Overdue <input type="checkbox"/>
Project:		Project ID:		Lead Worker <input type="checkbox"/>
Reason:		Project Name:		Task <input type="checkbox"/>
Received By:				Supervisor <input type="checkbox"/>
Inspected By:				Hard Lock WO <input type="checkbox"/>

### Request Comments for Work Order

Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

#### Location

Department: Sewer Collection  
Division: Sewer Collection

Comments for Crew  
Inspect all (46) SSO's when rainfall is one quarter (1/4") inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations			Address 2
Address	X Coord	Y Coord	General Location
FAIRFAX AT NORTH PARK			
2,220,655.65435414	665,517.24643672		Doan Brook
NORTH PARK AND COVENTRY			
2,219,873.16674590	666,048.82312946		DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH			
2,220,364.86097248	666,446.72325230		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX			
2,220,920.81917815	666,080.57995571		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)			
2,223,053.81655256	664,693.25202172		DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND			
2,222,845.06631389	664,689.08536339		Doan Brook
2,226,440.21168265	664,329.55524255		
2,226,354.79813956	664,409.89202413		
2,226,389.92077273	664,379.07548472		
FAIRMOUNT AT DARTMOOR			
2,225,149.97508989	664,453.31024438		DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON			
2,223,969.26550905	664,532.08075613		DOAN BROOK - MAIN BRANCH

## Work Order Detail Report

7/29/2020

SSO INSPECTION 7-27-2020 0.49 INCHES OF RAIN

2:21 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200729-0004

**Work Order Detail Report**

7/29/2020

SSO INSPECTION 7-27-2020 0.49 INCHES OF RAIN

2:21 PM

2,224,536.21778722	668,887.44048372
--------------------	------------------

2,226,741.35609348	679,432.95121680
--------------------	------------------

2,226,591.76420106	679,420.92761880
--------------------	------------------

2,227,825.14395215	684,881.15948047
--------------------	------------------

## Work Order Detail Report

7/29/2020

SSO INSPECTION 7-27-2020 0.49 INCHES OF RAIN

2:21 PM

### Work Order Assets

<u>Object Type</u>	<u>System ID 1</u>	<u>System ID 2</u>	<u>Description 1</u>	<u>Odometer</u>	<u>Hourmeter</u>	<u>Othermeter</u>	<u>PM Description</u>	<u>Asset ID</u>	<u>Completed</u>
Sewer Control Valve	SSO 431						FAIRFAX AT NORTH PARK		26
Sewer Control Valve	SSO 114						NORTH PARK AND COVENTRY		16
Sewer Control Valve	SSO 121						FAIRMOUNT SOUTH OF SCARBOROUGH		35
Sewer Structure	SA16AAWB0								3094
Sewer Control Valve	SSO 112						FAIRMOUNT AT FAIRFAX		7
Sewer Control Valve	SSO 99						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		6
Sewer Control Valve	SSO 432						3012 NORTH WOODLAND		14
Sewer Control Valve	DB-03								55
Sewer Control Valve	DB-01								56
Sewer Control Valve	DB-02								57
Sewer Control Valve	CH-04						FAIRMOUNT AT DARTMOOR		5
Sewer Control Valve	SSO 110						FAIRMOUNT AT WELLINGTON		44
Sewer Control Valve	SSO 87						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		33
Sewer Control Valve	SSO 116						FAIRMOUNT AT MARLBORO		4
Sewer Control Valve	SSO 111						FAIRMOUNT AT ARLINGTON		46
Sewer Control Valve	SSO 113						FAIRMOUNT & COVENTRY (SCARBOROUGH)		37
Sewer Control Valve	SSO 124						FAIRMOUNT AND COVENTRY		47
Sewer Control Valve	CH-50						SCARBOROUGH AT LAMBERTON		53
Sewer Control Valve	SSO 129						BRADFORD AND LEE		11
Sewer Control Valve	CH-52						EDDINGTON		2
Sewer Control Valve	SSO 88						HAMPSHIRE LANE AT MAYFIELD (18")		42
Sewer Control Valve	SSO 122						EAST OVERLOOK AT EDGEHILL		36
Sewer Control Valve	SSO 89						HAMPSHIRE LANE AT MAYFIELD (36")		34
Sewer Structure	SA16ADZB0								1536
Sewer Control Valve	SSO 91						HAMPSHIRE AT EUCLID HTS. BLVD.		20
Sewer Structure	SA16ADPH0								4446
Sewer Control Valve	SSO 120						CEDAR BTW. FAIRMOUNT/DEMINGTON		8
Sewer Control Valve							2828 BERKSHIRE, EAST OF COVENTRY		

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200729-0004

## Work Order Detail Report

7/29/2020

SSO INSPECTION 7-27-2020 0.49 INCHES OF RAIN

2:21 PM

SSO 103	19
Sewer Control Valve SSO 104	3003 EUCLID HEIGHTS BLVD 15
Sewer Structure SA16AGMG0	3402
Sewer Control Valve CH-30	South Taylor between Antisdale Ave and Superior R 52
Sewer Control Valve DV-11	LEE RD. & SUPERIOR AVE. 9
Sewer Control Valve SSO 108	EUCLID HEIGHTS BLVD AND LEE 22
Sewer Control Valve SSO 106	EUCLID HEIGHTS BLVD/CUMBERLAND 43
Sewer Control Valve SSO 95	1685 CUMBERLAND 18
Sewer Control Valve SSO 105	CUMBERLAND/SOMERTON 30
Sewer Structure SA16AQGD0	4987
Sewer Structure SA16AQQC0	3745
Sewer Control Valve SSO 102	2225 NOBLE ROAD 3
Sewer Control Valve SSO 107	QUILLIAMS, N. OF RANDOLF 38
Sewer Control Valve CH-51	LANGTON AND AHERSTONE 54
Sewer Structure SA16APEF0	1809

## Work Order Detail Report

7/29/2020

SSO INSPECTION 7-27-2020 0.49 INCHES OF RAIN

2:21 PM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Sound	7/29/2020/ 8:07 am	7/29/2020
	No overflow				
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	7/29/2020/ 8:10 am	7/29/2020
	No overflow				
3	A-45-FAIRMOUNT ( IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	<input type="checkbox"/>	Sound	7/29/2020/ 8:12 am	7/29/2020
	No overflow				
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	<input type="checkbox"/>	Sound	7/29/2020/ 8:15 am	7/29/2020
	No overflow				
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	7/29/2020/ 8:37 am	7/29/2020
	No overflow				
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	7/29/2020/ 8:39 am	7/29/2020
	No overflow				
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	7/29/2020/ 8:41 am	7/29/2020
	No overflow				
8	A-6 FAIRMOUNT AT SHELBYNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	7/29/2020/ 8:44 am	7/29/2020
	No overflow				
9	A-5 FAIRMOUNT AT SHELBYNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	7/29/2020/ 8:45 am	7/29/2020
	No overflow				
10	A-7 FAIRMOUNT AT SHELBYNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	7/29/2020/ 8:47 am	7/29/2020
	No overflow				
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	7/29/2020/ 8:48 am	7/29/2020
	No overflow				
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/29/2020/ 8:50 am	7/29/2020
	No overflow				
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	7/29/2020/ 8:51 am	7/29/2020
	No overflow				
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/29/2020/ 8:52 am	7/29/2020
	No overflow				
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/29/2020/ 8:53 am	7/29/2020
	No overflow				
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	<input type="checkbox"/>	Sound	7/29/2020/ 8:54 am	7/29/2020
	No overflow				
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/29/2020/ 8:56 am	7/29/2020
	No overflow				
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Sound	7/29/2020/ 8:58 am	7/29/2020
	No overflow				

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200729-0004

## Work Order Detail Report

7/29/2020

SSO INSPECTION 7-27-2020 0.49 INCHES OF RAIN

2:21 PM

19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	7/29/2020/ 9:03 am	7/29/2020
No overflow					
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	7/29/2020/ 9:05 am	7/29/2020
No overflow					
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	7/29/2020/ 9:06 am	7/29/2020
No overflow					
22	A-9 BRADFORD AT LEE SA16AFL0 (INTERSECTION)	<input type="checkbox"/>	Sound	7/29/2020/ 9:08 am	7/29/2020
Overflowed					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Sound	7/29/2020/ 9:19 am	7/29/2020
No overflow					
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	7/29/2020/ 9:21 am	7/29/2020
No overflow					
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	7/29/2020/ 9:22 am	7/29/2020
No overflow					
26	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	7/29/2020/ 9:23 am	7/29/2020
No overflow					
27	B-13 Hampshire AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	7/29/2020/ 9:25 am	7/29/2020
No overflow					
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	7/29/2020/ 9:26 am	7/29/2020
No overflow					
29	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	7/29/2020/ 9:31 am	7/29/2020
No overflow					
30	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	7/29/2020/ 9:33 am	7/29/2020
Overflowed					
31	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	7/29/2020/ 9:36 am	7/29/2020
No overflow					
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	<input type="checkbox"/>	Sound	7/29/2020/ 9:38 am	7/29/2020
No overflow					
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	<input type="checkbox"/>	Sound	7/29/2020/ 9:43 am	7/29/2020
No overflow					
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	7/29/2020/ 9:48 am	7/29/2020
Overflowed					
35	C-12 LEE AND SUPERIOR SA16AGTJ0	<input type="checkbox"/>	Sound	7/29/2020/ 9:51 am	7/29/2020
No overflow					
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	<input type="checkbox"/>	Sound	7/29/2020/ 9:53 am	7/29/2020
No overflow					
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	<input type="checkbox"/>	Sound	7/29/2020/ 9:54 am	7/29/2020
No overflow					
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	<input type="checkbox"/>	Sound	7/29/2020/ 9:55 am	7/29/2020
Missing block					
39	C-17 1685 CUMBERLAND RD SA16AQIQB0	<input type="checkbox"/>	Sound	7/29/2020/ 9:57 am	7/29/2020
Overflowed					

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200729-0004

## Work Order Detail Report

7/29/2020

SSO INSPECTION 7-27-2020 0.49 INCHES OF RAIN

2:21 PM

40	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	7/29/2020/10:02 am	7/29/2020
No overflow					
41	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	7/29/2020/10:03 am	7/29/2020
No overflow					
42	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	7/29/2020/10:06 am	7/29/2020
No overflow					
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	7/29/2020/10:09 am	7/29/2020
No overflow					
44	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Sound	7/29/2020/10:10 am	7/29/2020
No overflow					
45	C-50 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Sound	7/29/2020/10:13 am	7/29/2020
No overflow					

Tasks/Resources					
SWCT26 Inspection					
Crew:	Status:		*Cal'c UC: \$6.21	*Task Cost: \$279.52	Start Dt: 7/29/2020
Supervisor:	UOM:	Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt:
Employee					
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt
9512 DelZoppo, Michael	Hours	8.00	\$172.32		7/29/2020
Equipment					
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt
CHFLT50 FORD F250 CREW CAB	Hours	8.00	\$107.20		7/29/2020
5					
Task Comment: EXCESSIVE RAINFALL 7-27-2020 0.49"					

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
Repair Type:		Labor Hours	0.00	0.00	0.00
Subcontractor:		Labor Costs	\$172.32	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
Quantity:	0.00	Fluids Costs	0.00	0.00	0.00
Unit of Measure:	Each	Equipment Costs	107.20	0.00	0.00
*Unit Cost:	\$0.00	Contractor Costs	0.00	0.00	0.00
WO Hours:	0.00	Misc. Costs	0.00	0.00	0.00
		Total Costs	\$279.52	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing		
Customer ID:		Customer Number:		
Customer Name:		Last Name:		
Address:		Phone:		Cell #:
City:		Fax #:		
State:		E-mail:		
Zip:				
Billing Data		*Billing Amount:	Billing Required: <input type="checkbox"/>	
Contact Name:		Date Bill Sent:	Billing Processed: <input type="checkbox"/>	
Invoice Number:		Payment Received:	Imported to Financials: <input type="checkbox"/>	
Incoming Account #:		Payment Method:		

Associated PMs		Closed <input checked="" type="checkbox"/>
PM Code and Description	SSO-02 SSO INSPECTION	

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200729-0004

## Work Order Detail Report

7/29/2020

SSO INSPECTION 7-27-2020 0.49 INCHES OF RAIN

2:21 PM

Tracking					
Item	Description	By	Date	Time	
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	kbernard	7/29/2020	12:55 PM	
Supervisor Notification	Email Queued Successfully!	kbernard	7/29/2020	12:55 PM	
Email Successfully Sent	jjackson@clvhts.com Lucyty Work Order Update - Supervisor	BackgroundTaskUser	7/29/2020	12:56 PM	
Status Change	From New Work Order to Complete	aferrone	7/29/2020	2:20 PM	
Rates:	Opened At:		Televised:	<input type="checkbox"/>	
Received By:	Pipe Footage Cleaned		Power Rooter:	<input type="checkbox"/>	
Work From:	Gallons Used:		Jet:	<input type="checkbox"/>	
Pipe Size:	WO User 23:		Gap Vac:	<input type="checkbox"/>	
Pipe Condition:	WO User 24:		Dye Test:	<input type="checkbox"/>	
Could Not Open:	WO User 9:		Gap Root Cut:	<input type="checkbox"/>	
Additional Repair:	User 10:		GIS Correction?:	<input type="checkbox"/>	
Dye Test Reason:	Appointment Date DNL		WO User 30:	<input type="checkbox"/>	
Test Performed Through:	Appointment Date:	7/29/2020	7:30 AM		
Dye Test Results:					
WO User 51:	E Mail:				
Measurement:	WO User 22:				
History:					
Manhole Basin Repair:	Pipe Size:				
Material Used:	PVC Tees, Angles, Slect				
Pipe Repair:	WO User 44:				
Street Repair:	WO User 45:				
Grass Repair:	WO User 46:				
Curb Repair:					
Driveway- Sidewalk Re					
Construction Crew:					
WO User 39:	OUPS #:				
WO User 40:	WO User 48:				
WO User 41:					
WO User 52:	WO User 62:				
WO User 53:	WO User 63:				
WO User 54:	WO User 64:				
WO User 55:	WO User 65:				
WO User 56:	WO User 66:				
WO User 57:	WO User 67:				
WO User 58:	WO User 68:				
WO User 59:	WO User 69:				
WO User 60:	WO User 70:				
WO User 61:	WO User 71:				
WO User 72:	WO User 82:		Televised:	<input type="checkbox"/>	
WO User 73:	Quantity:		Paid:	<input type="checkbox"/>	
WO User 74:	WO User 84:		WO User 104:	<input type="checkbox"/>	
WO User 75:	WO User 85:		WO User 105:	<input type="checkbox"/>	
WO User 76:	WO User 86:		WO User 106:	<input type="checkbox"/>	
WO User 92 Date:	WO User 97 Date:				
WO User 93 Date:	WO User 98 Date:				
WO User 94 Date:	WO User 99 Date:				
WO User 95 Date:	WO User 100 Date:				
WO User 96 Date:	WO User 101 Date:				

\* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 200729-0004

## Work Order Detail Report

7/29/2020

SSO INSPECTION 7-27-2020 0.49 INCHES OF RAIN

2:21 PM

WO User 77:

WO User 87:

WO User 107:

WO User 78:

WO User 88:

WO User 108:

WO User 79:

WO User 89:

WO User 109:

WO User 80:

WO User 90:

WO User 110:

WO User 81:

WO User 91:

WO User 111:

WO Creator: kbernard

WO Creation Date: 7/29/2020

PM Trigger:

Rec #: 5697