



Law Department

August 15, 2022

Via U.S. Mail and E-Mail: vezner.kris@epa.gov and Berger.Jake@epa.gov

Kris P. Vezner, Esq.
Associate Regional Counsel
U.S. Environmental Protection Agency
Region 5 (C-14J)
77 West Jackson Blvd.
Chicago, IL 60604

and

Jake Berger
Physical Scientist
Water Enforcement & Compliance Assurance Branch
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Mail Code ECW-15J
Chicago, IL 60604

Re: July 2022 Overflow Monitoring Reports
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through July 31, 2022, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,

A handwritten signature in blue ink, appearing to read "William R. Hanna".

William R. Hanna
Director of Law

Enclosures

Overflow Monitoring Update
August 15, 2022


cc: Thomas Benson, Esq., EPA Attorney
James Vinch, Esq., EPA Attorney
James Zimny, EPA Engineer
U.S. EPA Region 5 Water Enforcement Branch
Mark Klingenstein, Environmental Engineer
Erm Gomes, Ohio EPA
Allison Cycyk, Ohio EPA
Casey Galligan, Ohio EPA
David Brumbaugh, Ohio EPA
Bill Fischbein, Ohio EPA
Kahlil Seren, Mayor
Collette Clinkscale, Director of Public Works
Steve Barker, Public Relations
Anthony Ferrone, Utilities Commissioner
Kevin Vander Tuig, P.E. (Outside Engineer)
Mathew St. Pierre, (Outside Engineer)
Dan Porter (Outside Engineer)
Cindy Biacofsky (Outside Engineer)
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)



Daily Precipitation Report

Tuesday, July 5, 2022

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Tuesday, July 5, 2022


Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.82	0.82	0.82	0.47	0.32
Brecksville	0.37	0.37	0.34	0.22	0.10
Brook Park	0.28	0.28	0.28	0.18	0.07
Cleveland Industrial Pkwy	0.47	0.47	0.47	0.24	0.22
Dille Ave PS	0.65	0.64	0.64	0.31	0.25
Division Ave PS	0.52	0.52	0.52	0.25	0.22
Easterly WWTP	0.76	0.76	0.76	0.46	0.26
Independence	0.42	0.42	0.40	0.19	0.18
James Rhodes HS	0.46	0.46	0.46	0.23	0.21
Jennings PS	0.42	0.42	0.42	0.24	0.14
Macedonia	0.43	0.43	0.38	0.20	0.14
Maple Heights	0.46	0.46	0.46	0.23	0.18
Mary Street PS	0.63	0.63	0.63	0.31	0.28
Mayfield Heights	0.67	0.67	0.66	0.44	0.27
Moreland Hills	0.55	0.55	0.55	0.35	0.27
North Olmsted	0.26	0.26	0.26	0.15	0.08
North Royalton	0.31	0.31	0.31	0.26	0.12
Oakwood	0.57	0.57	0.57	0.27	0.25
Olmsted Falls	0.19	0.19	0.19	0.13	0.05
Parma	0.36	0.36	0.36	0.19	0.15
Richfield	1.33	0.85	0.85	0.85	0.62
Shaker Heights	0.55	0.55	0.55	0.29	0.19
South Euclid	0.71	0.71	0.71	0.42	0.28
Southerly WWTC	0.54	0.54	0.54	0.26	0.23
Strongsville C WWTP	0.28	0.28	0.28	0.20	0.08
Strongsville Foltz	0.29	0.28	0.28	0.26	0.12
University Heights	0.79	0.79	0.79	0.48	0.33
Wade Park	0.64	0.64	0.64	0.42	0.29
Westerly WWTP	0.45	0.45	0.45	0.23	0.18
Westlake	0.31	0.31	0.30	0.20	0.07



Daily Precipitation Report

Friday, July 1, 2022

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Friday, July 1, 2022

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.80	0.80	0.72	0.44	0.19
Brecksville	0.54	0.53	0.52	0.39	0.17
Brook Park	0.31	0.31	0.31	0.25	0.13
Cleveland Industrial Pkwy	0.42	0.42	0.42	0.31	0.17
Dille Ave PS	0.45	0.45	0.45	0.31	0.12
Division Ave PS	0.51	0.51	0.50	0.28	0.13
Easterly WWTP	0.46	0.46	0.46	0.26	0.14
Independence	0.42	0.42	0.42	0.26	0.12
James Rhodes HS	0.39	0.39	0.38	0.26	0.12
Jennings PS	0.47	0.46	0.44	0.30	0.12
Macedonia	0.51	0.51	0.50	0.27	0.16
Maple Heights	0.68	0.68	0.67	0.45	0.25
Mary Street PS	0.46	0.46	0.46	0.33	0.11
Mayfield Heights	0.71	0.70	0.63	0.41	0.17
Moreland Hills	0.76	0.75	0.73	0.35	0.16
North Olmsted	0.34	0.34	0.34	0.26	0.12
North Royalton	0.49	0.49	0.49	0.35	0.20
Oakwood	0.48	0.47	0.43	0.24	0.13
Olmsted Falls	0.25	0.25	0.24	0.20	0.11
Parma	0.41	0.41	0.41	0.32	0.19
Richfield	0.52	0.52	0.52	0.36	0.19
Shaker Heights	0.79	0.78	0.73	0.45	0.18
South Euclid	0.69	0.69	0.68	0.42	0.17
Southerly WWTC	0.66	0.66	0.65	0.48	0.24
Strongsville CWWTP	0.30	0.30	0.29	0.18	0.07
Strongsville Foltz	0.49	0.49	0.48	0.43	0.30
University Heights	0.82	0.82	0.72	0.46	0.22
Wade Park	0.54	0.54	0.53	0.33	0.13
Westerly WWTP	0.36	0.36	0.35	0.21	0.09
Westlake	0.51	0.50	0.49	0.38	0.22

Work Order Detail Report

7/11/2022

1:48 PM

SSO INSPECTION 7-1-2022 (.82) & 7-5-2022 (.79)

WO Number: 220708-0001		Category:	SSOs	
Status: Complete		Problem:	Storm Response	
Status Date: 7/11/2022 1:47 pm		Main Task:	Inspection	
Asset: SSO 431				
Location: FAIRFAX AT NORTH PARK				
Cause:	Weather		Assigned By:	
Assigned Crew:			Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date: 7/7/2022	7:45 AM	<u>Override</u>
Lead Worker:	Cardarella, Joe	End Date: 7/8/2022	3:27 PM	<u>Notifications</u>
Priority:	High			
Account #:				
Proj No - Acct:		Project ID:		
Project:		Project Name:		
Reason:				
Received By:				
Inspected By:				

- Problem ☐
- Overdue ☐
- Lead Worker ☐
- Task ☐
- Supervisor ☐
- Hard Lock WO ☐

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection
Sub-Division:
Area:
Sub-Area:
Owner:
Location:
Classification:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Maintenance Zone: **Alternate Zone:**

Work Order Locations

<u>Address</u>	<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>
<u>General Location</u>	
FAIRFAX AT NORTH PARK	
2,220,655.65435414	665,517.24643672
NORTH PARK AND COVENTRY	Doan Brook
2,219,873.16674590	666,048.82312946
FAIRMOUNT SOUTH OF SCARBOROUGH	DOAN BROOK - MAIN BRANCH
2,220,364.86097248	666,446.72325230
FAIRMOUNT AT FAIRFAX	DOAN BROOK - MAIN BRANCH
2,220,920.81917815	666,080.57995571
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	DOAN BROOK - MAIN BRANCH
2,223,053.81655256	664,693.25202172
3012 NORTH WOODLAND	DOAN BROOK - MAIN BRANCH
2,222,845.06631389	664,689.08536339
	Doan Brook
2,226,440.21168265	664,329.55524255
2,226,354.79813956	664,409.89202413
2,226,389.92077273	664,379.07548472
FAIRMOUNT AT DARTMOOR	
2,225,149.97508989	664,453.31024438
FAIRMOUNT AT WELLINGTON	DOAN BROOK - MAIN BRANCH
2,223,969.26550905	664,532.08075613
	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

7/11/2022

1:48 PM

SSO INSPECTION 7-1-2022 (.82) & 7-5-2022 (.79)

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

7/11/2022

SSO INSPECTION 7-1-2022 (.82) & 7-5-2022 (.79)

1:48 PM

2,224,536.21778722	668,887.44048372
2,226,741.35609348	679,432.95121680
2,226,591.76420106	679,420.92761880
2,227,825.14395215	684,881.15948047

Work Order Detail Report

SSO INSPECTION 7-1-2022 (.82) & 7-5-2022 (.79)

7/11/2022

1:48 PM

Work Order Assets		Description 1			Description 2		Asset ID	Completed
Object Type	System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description		
Sewer Control Valve	SSO 431					FAIRFAX AT NORTH PARK	26	
Sewer Control Valve	SSO 114					NORTH PARK AND COVENTRY	16	
Sewer Control Valve	SSO 121					FAIRMOUNT SOUTH OF SCARBOROUGH	35	
Sewer Structure	SA16AAWB0						3094	
Sewer Control Valve	SSO 112					FAIRMOUNT AT FAIRFAX	7	
Sewer Control Valve	SSO 99					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	6	
Sewer Control Valve	SSO 432					3012 NORTH WOODLAND	14	
Sewer Control Valve	DB-03						55	
Sewer Control Valve	DB-01						56	
Sewer Control Valve	DB-02						57	
Sewer Control Valve	CH-04					FAIRMOUNT AT DARTMOOR	5	
Sewer Control Valve	SSO 110					FAIRMOUNT AT WELLINGTON	44	
Sewer Control Valve	SSO 87					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)	33	
Sewer Control Valve	SSO 116					FAIRMOUNT AT MARLBORO	4	
Sewer Control Valve	SSO 111					FAIRMOUNT AT ARLINGTON	46	
Sewer Control Valve	SSO 113					FAIRMOUNT & COVENTRY (SCARBOROUGH)	37	
Sewer Control Valve	SSO 124					FAIRMOUNT AND COVENTRY	47	
Sewer Control Valve	CH-50					SCARBOROUGH AT LAMBERTON	53	
Sewer Control Valve	SSO 129					BRADFORD AND LEE	11	
Sewer Control Valve	CH-52					EDDINGTON	2	
Sewer Control Valve	SSO 88					HAMPSHIRE LANE AT MAYFIELD (18")	42	
Sewer Control Valve	SSO 122					EAST OVERLOOK AT EDGEHILL	36	
Sewer Control Valve	SSO 89					HAMPSHIRE LANE AT MAYFIELD (36")	34	
Sewer Structure	SA16ADZB0						1536	
Sewer Control Valve	SSO 91					HAMPSHIRE AT EUCLID HTS. BLVD.	20	
Sewer Structure	SA16ADPH0						4446	
Sewer Control Valve	SSO 120					CEDAR BTW. FAIRMOUNT/DEMINGTON	8	
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY		

Work Order Detail Report

7/11/2022

1:48 PM

SSO INSPECTION 7-1-2022 (.82) & 7-5-2022 (.79)

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	3402
SA16AGMG0	South Taylor between Antisdale Ave and Superior R
Sewer Control Valve	52
CH-30	LEE RD. & SUPERIOR AVE.
Sewer Control Valve	9
DV-11	EUCLID HEIGHTS BLVD AND LEE
Sewer Control Valve	22
SSO 108	EUCLID HEIGHTS BLVD/CUMBERLAND
Sewer Control Valve	43
SSO 106	1685 CUMBERLAND
Sewer Control Valve	18
SSO 95	CUMBERLAND/SOMERTON
Sewer Control Valve	30
SSO 105	
Sewer Structure	4987
SA16AQD0	
Sewer Structure	3745
SA16AQQC0	2225 NOBLE ROAD
Sewer Control Valve	3
SSO 102	QUILLIAMS, N. OF RANDOLF
Sewer Control Valve	38
SSO 107	LANGTON AND ATHERSTONE
Sewer Control Valve	54
CH-51	
Sewer Structure	1809
SA16APEF0	

Work Order Detail Report

SSO INSPECTION 7-1-2022 (.82) & 7-5-2022 (.79)

7/11/2022

1:48 PM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Sound	7/8/2022/ 2:30 pm	7/8/2022
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	7/8/2022/ 2:33 pm	7/8/2022
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	7/8/2022/ 2:34 pm	7/8/2022
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	7/8/2022/ 2:34 pm	7/8/2022
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Not Sound	7/8/2022/ 2:35 pm	7/8/2022
Reset					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	7/8/2022/ 2:36 pm	7/8/2022
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	7/8/2022/ 2:36 pm	7/8/2022
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	7/8/2022/ 2:37 pm	7/8/2022
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	7/8/2022/ 2:37 pm	7/8/2022
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	7/8/2022/ 2:38 pm	7/8/2022
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	7/8/2022/ 2:38 pm	7/8/2022
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	7/8/2022/ 2:39 pm	7/8/2022
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	7/8/2022/ 2:47 pm	7/8/2022
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Not Sound	7/8/2022/ 2:40 pm	7/8/2022
No block					
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	7/8/2022/ 2:46 pm	7/8/2022
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	7/8/2022/ 2:45 pm	7/8/2022
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Sound	7/8/2022/ 2:44 pm	7/8/2022
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Not Sound	7/8/2022/ 2:44 pm	7/8/2022
Reset					
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	7/8/2022/ 2:43 pm	7/8/2022
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Sound	7/8/2022/ 2:42 pm	7/8/2022
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	7/8/2022/ 2:42 pm	7/8/2022
22	A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	☐	Not Sound	7/8/2022/ 2:41 pm	7/8/2022
No block					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	7/8/2022/ 2:50 pm	7/8/2022
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	7/8/2022/ 2:51 pm	7/8/2022
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	7/8/2022/ 2:51 pm	7/8/2022

* A 'Hidden' field indicates permission to view the secured field is turned off.

Work Order Detail Report

7/11/2022

1:48 PM

SSO INSPECTION 7-1-2022 (.82) & 7-5-2022 (.79)

26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	7/8/2022/ 2:52 pm	7/8/2022
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Not Sound	7/8/2022/ 2:52 pm	7/8/2022
Reset					
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	7/8/2022/ 2:53 pm	7/8/2022
29	B-42 12537 CEDAR SA16ACZA0	☐	Sound	7/8/2022/ 2:54 pm	7/8/2022
30	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	7/8/2022/ 2:54 pm	7/8/2022
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	/ 2:55 pm	7/8/2022
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	7/8/2022/ 2:55 pm	7/8/2022
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	7/8/2022/ 2:55 pm	7/8/2022
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Not Sound	7/8/2022/10:15 am	7/8/2022
Reset					
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Not Sound	7/8/2022/ 9:14 pm	7/8/2022
Can't reset surcharging					
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Not Sound	7/8/2022/ 9:31 pm	7/8/2022
Reset					
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Not Sound	/ 9:43 am	
Reset					
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Sound	7/8/2022/ 9:00 am	7/8/2022
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Not Sound	7/8/2022/ 9:31 am	7/8/2022
Reset					
40	C-59 3427 THORNE RD SA16AQQD0	☐	Sound	7/8/2022/ 7:56 am	7/8/2022
41	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	7/8/2022/ 8:04 am	7/8/2022
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	7/8/2022/ 8:14 am	7/8/2022
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	7/8/2022/ 8:23 am	7/8/2022
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	/ 8:33 am	
45	C-50 3593 FENLEY SA16APEH0	☐	Sound	7/8/2022/ 8:45 am	7/8/2022

Tasks/Resources

SWCT26 Inspection

Crew:

Status:

*Cal'c UC: \$12.42

*Task Cost: \$559.04

Start Dt: 7/7/2022

Supervisor:

UOM: Each

of Units: 45.00

*Unit Cost: \$0.00

End Dt: 7/8/2022

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	16.00	\$344.64		7/7/2022	7/8/2022

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	16.00	\$214.40		7/7/2022	7/8/2022

Task Comment: SSO INSPECTION 0.82 7-1-22 AND 0.79 7-5-2022

Work Order Detail Report

SSO INSPECTION 7-1-2022 (.82) & 7-5-2022 (.79)

7/11/2022

1:48 PM

			<u>*Actual</u>	<u>*Estimated</u>	<u>*Difference</u>
Projected Complete:	Lock: ☐	WO Duration	15.70	0.00	0.00
Repair Type:		Labor Hours	16.00	0.00	0.00
Subcontractor:		Labor Costs	\$344.64	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity:	0.00	Equipment Costs	214.40	0.00	0.00
Unit of Measure:	Each	Contractor Costs	0.00	0.00	0.00
*Unit Cost:	\$0.00	Misc. Costs	0.00	0.00	0.00
WO Hours:	0.00	Total Costs	\$559.04	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing	
Customer ID:		Customer Number:	
Customer Name:		Last Name:	
Address:		Phone:	Cell #:
City:		Fax #:	
State:		E-mail:	
Zip:			
Billing Data			
Contact Name:		*Billing Amount:	Billing Required: ☐
Invoice Number:		Date Bill Sent:	Billing Processed: ☐
Incoming Account #:		Payment Received:	Imported to Financials: ☐
		Payment Method:	

Associated PMs		Closed
<u>PM Code and Description</u>		☒
SSO-02 SSO INSPECTION		

Item	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jjackson	7/8/2022	2:06 PM
Supervisor Notification	Email Queued Successfully!	jjackson	7/8/2022	2:06 PM
Status Change	From New Work Order to Complete	aferrone	7/11/2022	1:47 PM

Rate:	Opened At:	Televised: ☐
Recieved By:	Pipe Footage Cleaned	Power Rooter: ☐
Work From:	Gallons Used:	Jet: ☐
Pipe Size:	WO User 23:	Gap Vac: ☐
Pipe Condition:	WO User 24:	Dye Test: ☐
Could Not Open:	WO User 9:	Gap Root Cut: ☐
Additional Repair:	User 10:	GIS Correction?: ☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction: ☐
Test Performed Throug	Appointment Date: 7/8/2022 8:00 AM	
Dye Test Results:		
WO User 51:		
Measurement:	E Mail:	
History:	Measurement Line 2:	

Work Order Detail Report

7/11/2022

SSO INSPECTION 7-1-2022 (.82) & 7-5-2022 (.79)

1:48 PM

Manhole Basin Repair:

Material Used:

Pipe Repair:

Street Repair:

Grass Repair:

Curb Repair:

Driveway- Sidewalk Re

Construction Crew:

WO User 39:

WO User 40:

WO User 41:

Pipe Size:

PVC Tees, Angles, Slec

WO User 44:

WO User 45:

WO User 46:

OUPS #:

WO User 48:

WO User 52:

WO User 53:

WO User 54:

WO User 55:

WO User 56:

WO User 57:

WO User 58:

WO User 59:

WO User 60:

WO User 61:

WO User 72:

WO User 73:

WO User 74:

WO User 75:

WO User 76:

WO User 62:

WO User 63:

WO User 64:

WO User 65:

WO User 66:

WO User 67:

WO User 68:

WO User 69:

WO User 70:

WO User 71:

WO User 82:

Quantity:

WO User 84:

WO User 85:

WO User 86:

Televised:

☐

Paid:

☐

WO User 104:

☐

WO User 105:

☐

WO User 106:

☐

WO User 92 Date:

WO User 93 Date:

WO User 94 Date:

WO User 95 Date:

WO User 96 Date:

WO User 97 Date:

WO User 98 Date:

WO User 99 Date:

WO User 100 Date:

WO User 101 Date:

WO User 77:

WO User 78:

WO User 79:

WO User 80:

WO User 81:

WO User 87:

WO User 88:

WO User 89:

WO User 90:

WO User 91:

WO User 107:

☐

WO User 108:

☐

WO User 109:

☐

WO User 110:

☐

WO User 111:

☐

WO Creator: jjackson

WO Creation Date: 7/8/2022

PM Trigger:


Rec #: 12898



**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Monday, July 18, 2022
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Monday, July 18, 2022

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	1.11	0.63	0.63	0.35	0.15
Brecksville	0.32	0.18	0.14	0.12	0.07
Brook Park	0.77	0.61	0.61	0.51	0.19
Cleveland Industrial Pkwy	0.70	0.36	0.36	0.31	0.12
Dille Ave PS	1.61	0.91	0.90	0.68	0.30
Division Ave PS	1.26	0.85	0.85	0.59	0.29
Easterly WWTP	0.96	0.49	0.46	0.37	0.16
Independence	0.88	0.52	0.52	0.49	0.30
James Rhodes HS	1.38	0.82	0.81	0.63	0.28
Jennings PS	1.39	0.89	0.89	0.70	0.37
Macedonia	0.47	0.27	0.27	0.25	0.16
Maple Heights	0.77	0.56	0.56	0.50	0.25
Mary Street PS	1.50	0.76	0.76	0.52	0.24
Mayfield Heights	0.97	0.64	0.58	0.49	0.23
Moreland Hills	1.17	0.85	0.85	0.52	0.20
North Olmsted	n/a	n/a	n/a	n/a	n/a
North Royalton	0.49	0.32	0.31	0.23	0.09
Oakwood	0.50	0.25	0.24	0.19	0.12
Olmsted Falls	0.41	0.30	0.30	0.25	0.15
Parma	0.86	0.65	0.64	0.48	0.23
Richfield	0.40	0.25	0.23	0.22	0.11
Shaker Heights	1.45	0.89	0.89	0.57	0.31
South Euclid	2.17	1.37	1.35	1.07	0.43
Southerly WWTP	0.98	0.60	0.60	0.43	0.21
Strongsville C WWTP	0.94	0.74	0.72	0.56	0.21
Strongsville Foltz	0.79	0.68	0.68	0.52	0.24
University Heights	1.45	0.86	0.84	0.54	0.24
Wade Park	1.52	1.03	1.01	0.81	0.38
Westerly WWTP	0.82	0.59	0.59	0.43	0.24
Westlake	0.29	0.22	0.22	0.21	0.10




**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Sunday, July 17, 2022

Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Sunday, July 17, 2022

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.99	0.93	0.82	0.67	0.28
Brecksville	0.94	0.79	0.73	0.65	0.28
Brook Park	1.21	1.09	0.92	0.78	0.41
Cleveland Industrial Pkwy	1.24	1.12	0.91	0.78	0.41
Dille Ave PS	1.24	1.12	1.01	0.87	0.44
Division Ave PS	1.17	1.01	0.79	0.68	0.35
Easterly WWTP	1.12	1.01	0.90	0.80	0.44
Independence	1.03	0.90	0.80	0.69	0.37
James Rhodes HS	1.32	1.22	1.10	0.92	0.50
Jennings PS	1.39	1.26	1.15	1.00	0.49
Macedonia	1.03	0.92	0.82	0.65	0.26
Maple Heights	1.10	1.03	0.95	0.80	0.34
Mary Street PS	1.27	1.12	0.99	0.85	0.44
Mayfield Heights	1.08	1.03	0.93	0.75	0.44
Moreland Hills	1.09	1.03	0.91	0.77	0.31
North Olmsted	1.27	0.99	0.65	0.51	0.20
North Royalton	1.06	0.90	0.82	0.72	0.41
Oakwood	0.92	0.85	0.79	0.67	0.25
Olmsted Falls	1.19	0.95	0.81	0.64	0.33
Parma	1.35	1.21	1.07	0.99	0.55
Richfield	1.00	0.86	0.73	0.56	0.25
Shaker Heights	0.98	0.89	0.75	0.58	0.26
South Euclid	0.94	0.90	0.78	0.64	0.33
Southerly WWTC	1.02	0.91	0.78	0.69	0.34
Strongsville C WWTP	1.11	0.95	0.85	0.76	0.41
Strongsville Foltz	1.04	0.84	0.74	0.70	0.38
University Heights	0.90	0.85	0.72	0.57	0.27
Wade Park	1.06	1.00	0.88	0.77	0.42
Westerly WWTP	0.99	0.85	0.67	0.57	0.31
Westlake	1.39	0.99	0.60	0.40	0.20

Work Order Detail Report

7/20/2022

SSO INSPECTION 7-18-2022 1.45 INCHES OF RAIN

2:58 PM

WO Number: 220718-0001 Category: SSOs
Status: Complete Problem: Storm Response
Status Date: 7/20/2022 2:57 pm Main Task: Inspection

Asset: SSO 431
Location: FAIRFAX AT NORTH PARK

Cause: Weather

Assigned Crew:

Supervisor: Jackson, Jeff
Lead Worker: Cardarella, Joe
Priority: High

Account #:

Proj No - Acct:

Project:

Reason:

Received By:

Inspected By:

Assigned By:

Assigned Date:

Start Date: 7/19/2022 12:55 PM

End Date: 7/20/2022 2:47 PM

OverrideNotificationsProblem ☐Overdue ☐Lead Worker ☐Task ☐Supervisor ☐Hard Lock WO ☐

Project ID:

Project Name:

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection

Division: Sewer Collection

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Work Order Locations

<u>Address</u>	<u>Address 2</u>
<u>X Coord</u>	<u>Y Coord</u>
<u>General Location</u>	
FAIRFAX AT NORTH PARK	
2,220,655.65435414	665,517.24643672
NORTH PARK AND COVENTRY	Doan Brook
2,219,873.16674590	666,048.82312946
FAIRMOUNT SOUTH OF SCARBOROUGH	DOAN BROOK - MAIN BRANCH
2,220,364.86097248	666,446.72325230
FAIRMOUNT AT FAIRFAX	DOAN BROOK - MAIN BRANCH
2,220,920.81917815	666,080.57995571
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	DOAN BROOK - MAIN BRANCH
2,223,053.81655256	664,693.25202172
3012 NORTH WOODLAND	DOAN BROOK - MAIN BRANCH
2,222,845.06631389	664,689.08536339
	Doan Brook
2,226,440.21168265	664,329.55524255
2,226,354.79813956	664,409.89202413
2,226,389.92077273	664,379.07548472
FAIRMOUNT AT DARTMOOR	
2,225,149.97508989	664,453.31024438
FAIRMOUNT AT WELLINGTON	DOAN BROOK - MAIN BRANCH
2,223,969.26550905	664,532.08075613
	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

7/20/2022

SSO INSPECTION 7-18-2022 1.45 INCHES OF RAIN

2:58 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

7/20/2022

SSO INSPECTION 7-18-2022 1.45 INCHES OF RAIN

2:58 PM

2,224,536.21778722	668,887.44048372
2,226,741.35609348	679,432.95121680
2,226,591.76420106	679,420.92761880
2,227,825.14395215	684,881.15948047

Work Order Detail Report

7/20/2022

SSO INSPECTION 7-18-2022 1.45 INCHES OF RAIN

2:58 PM

Work Order Assets							
Object Type	Description 1		Description 2				
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve					FAIRFAX AT NORTH PARK		
SSO 431						26	
Sewer Control Valve					NORTH PARK AND COVENTRY		
SSO 114						16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Control Valve					3012 NORTH WOODLAND		
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO		
SSO 116						4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY		
SSO 124						47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON		
CH-50						53	
Sewer Control Valve					BRADFORD AND LEE		
SSO 129						11	
Sewer Control Valve					EDDINGTON		
CH-52						2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL		
SSO 122						36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		

Work Order Detail Report

7/20/2022

SSO INSPECTION 7-18-2022 1.45 INCHES OF RAIN

2:58 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

7/20/2022

SSO INSPECTION 7-18-2022 1.45 INCHES OF RAIN

2:58 PM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Not Sound	7/20/2022/ 8:34 am	7/20/2022
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Sound	7/20/2022/ 8:41 am	7/20/2022
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	7/20/2022/ 7:59 am	7/20/2022
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	7/20/2022/ 8:06 am	7/20/2022
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Not Sound	7/20/2022/ 8:21 am	7/20/2022
Reset					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Not Sound	7/20/2022/ 9:42 am	7/20/2022
Reset					
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	7/20/2022/ 9:46 am	7/20/2022
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	7/20/2022/10:11 am	7/20/2022
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Sound	7/20/2022/10:04 am	7/20/2022
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Sound	7/20/2022/ 9:55 am	7/20/2022
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	7/19/2022/12:59 pm	7/19/2022
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	7/19/2022/ 1:09 pm	7/19/2022
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	7/20/2022/ 1:05 pm	7/20/2022
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Not Sound	7/20/2022/12:57 pm	7/20/2022
Board gone needs to be replaced					
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	7/20/2022/ 1:04 pm	7/20/2022
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	7/20/2022/ 1:10 pm	7/20/2022
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Not Sound	7/20/2022/ 9:30 am	7/20/2022
Reset					
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Not Sound	7/19/2022/ 1:18 pm	7/19/2022
Reset					
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	7/20/2022/ 8:50 am	7/20/2022
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Not Sound	7/19/2022/12:42 pm	7/19/2022
Board missing					
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Sound	7/19/2022/12:46 pm	7/19/2022
22	A-9 BRADFORD AT LEE SA16AFL0 (INTERSECTION)	☐	Sound	7/19/2022/12:36 pm	7/19/2022
Has meter in it					
23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	7/19/2022/ 9:24 am	7/19/2022

Work Order Detail Report

7/20/2022

SSO INSPECTION 7-18-2022 1.45 INCHES OF RAIN

2:58 PM

24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	7/19/2022/ 9:35 am	7/19/2022
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	7/19/2022/ 9:37 am	7/19/2022
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	7/19/2022/ 9:51 am	7/19/2022
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Not Sound	7/19/2022/ 9:58 am	7/19/2022
Reset					
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Sound	7/19/2022/10:02 am	7/19/2022
29	B-42 12537 CEDAR SA16ACZA0	☐	Sound	7/20/2022/12:37 pm	7/20/2022
30	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Not Sound	7/20/2022/12:43 pm	7/20/2022
Reset					
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	7/19/2022/10:18 am	7/19/2022
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	7/19/2022/10:22 am	7/19/2022
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	7/20/2022/12:29 pm	7/20/2022
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Sound	7/20/2022/10:17 am	7/20/2022
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Not Sound	7/19/2022/ 8:44 am	7/19/2022
Surcharging					
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Not Sound	7/20/2022/10:30 am	7/20/2022
Reset					
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Sound	7/19/2022/ 8:56 am	7/19/2022
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Not Sound	7/19/2022/ 9:06 am	7/19/2022
Reset					
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Not Sound	7/19/2022/ 9:13 am	7/19/2022
Board missing					
40	C-59 3427 THORNE RD SA16AQD0	☐	Sound	7/19/2022/ 7:45 am	7/19/2022
41	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	7/19/2022/ 7:46 am	7/19/2022
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Sound	7/19/2022/ 7:54 am	7/19/2022
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Sound	7/19/2022/ 8:11 am	7/19/2022
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Sound	7/19/2022/ 8:19 am	7/19/2022
45	C-50 3593 FENLEY SA16APEH0	☐	Not Sound	7/19/2022/ 8:24 am	7/19/2022
Reset					

Work Order Detail Report

7/20/2022

SSO INSPECTION 7-18-2022 1.45 INCHES OF RAIN

2:58 PM

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:	*Cal'c UC: \$9.32	*Task Cost: \$419.28	Start Dt: 7/19/2022		
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 7/20/2022		
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	12.00	\$258.48		7/19/2022	7/20/2022
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	12.00	\$160.80		7/19/2022	7/20/2022
Task Comment: SSO INSPECTION1.45 INCHES OF RAIN						

Projected Complete:	Lock: ☐	WO Duration	<u>*Actual</u>	<u>*Estimated</u>	<u>*Difference</u>
Repair Type:		Labor Hours	9.87	0.00	0.00
Subcontractor:		Labor Costs	12.00	0.00	0.00
Profit Center:		Labor Costs	\$258.48	\$0.00	\$0.00
		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity: 0.00	Lock: ☐	Equipment Costs	160.80	0.00	0.00
Unit of Measure: Each		Contractor Costs	0.00	0.00	0.00
*Unit Cost: \$0.00		Misc. Costs	0.00	0.00	0.00
WO Hours: 0.00		Total Costs	\$419.28	\$0.00	\$0.00
		Use Task Info:	True	True	

Billing Party		Billing	
Customer ID:	Customer Number:		
Customer Name:	Last Name:		
Address:	Phone:	Cell #:	
City:	Fax #:		
State:	E-mail:		
Zip:			
Billing Data			
Contact Name:	*Billing Amount:	Billing Required: ☐	
Invoice Number:	Date Bill Sent:	Billing Processed: ☐	
Incoming Account #:	Payment Received:	Imported to Financials: ☐	
	Payment Method:		

Associated PMs	PM Code and Description	Closed
	SSO-02 SSO INSPECTION	☒

Tracking	Item	Description	By	Date	Time
Work Order Creation		From Routine Work SSO-02 - SSO INSPECTION	aferrone	7/18/2022	12:43 PM
Supervisor Notification		Email Queued Successfully!	aferrone	7/18/2022	12:43 PM
Status Change		From New Work Order to Complete	aferrone	7/20/2022	2:57 PM

Work Order Detail Report

7/20/2022


SSO INSPECTION 7-18-2022 1.45 INCHES OF RAIN

2:58 PM

Rate:	Opened At:	Televised:	☐
Recieved By:	Pipe Footage Cleaned :	Power Rooter:	☐
Work From:	Gallons Used:	Jet:	☐
Pipe Size:	WO User 23:	Gap Vac:	☐
Pipe Condition:	WO User 24:	Dye Test:	☐
Could Not Open:	WO User 9:	Gap Root Cut:	☐
Additional Repair:	User 10:	GIS Correction?:	☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	☐
Test Performed Throug	Appointment Date:		
Dye Test Results:			
WO User 51:			
Measurement:	E Mail:		
History:	Measurement Line 2:		
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Slec		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:			
WO User 40:	OUPS #:		
WO User 41:	WO User 48:		
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	☐
WO User 73:	Quantity:	Paid:	☐
WO User 74:	WO User 84:	WO User 104:	☐
WO User 75:	WO User 85:	WO User 105:	☐
WO User 76:	WO User 86:	WO User 106:	☐
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	☐
WO User 78:	WO User 88:	WO User 108:	☐
WO User 79:	WO User 89:	WO User 109:	☐
WO User 80:	WO User 90:	WO User 110:	☐
WO User 81:	WO User 91:	WO User 111:	☐
WO Creator: aferrone	WO Creation Date: 7/18/2022	PM Trigger:	Rec #: 12921



Daily Precipitation Report
Sunday, July 24, 2022
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Sunday, July 24, 2022

Site Location	Peak Accumulation (inches)					
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute	5-Minute
Beachwood	1.29	1.29	1.29	1.28	0.78	0.38
Brecksville	0.03	0.02	0.02	0.02	0.01	0.01
Brook Park	0.71	0.71	0.71	0.69	0.49	0.25
Cleveland Industrial Pkwy	0.65	0.65	0.65	0.63	0.40	0.23
Dille Ave PS	1.07	1.07	1.07	1.06	0.44	0.22
Division Ave PS	0.98	0.98	0.98	0.96	0.49	0.31
Easterly WWTP	0.04	0.04	0.04	0.04	0.03	0.02
Independence	0.39	0.20	0.20	0.20	0.20	0.10
James Rhodes HS	0.90	0.90	0.90	0.89	0.73	0.39
Jennings PS	0.88	0.88	0.88	0.84	0.69	0.36
Macedonia	0.01	0.01	0.01	0.01	0.01	0.01
Maple Heights	0.46	0.41	0.41	0.41	0.25	0.20
Mary Street PS	1.19	1.19	1.19	1.16	0.61	0.33
Mayfield Heights	0.99	0.99	0.99	0.98	0.44	0.27
Moreland Hills	0.38	0.38	0.38	0.38	0.38	0.21
North Olmsted	1.00	1.00	1.00	0.90	0.50	0.26
North Royalton	0.21	0.17	0.17	0.17	0.17	0.14
Oakwood	0.12	0.10	0.10	0.10	0.09	0.06
Olmsted Falls	0.57	0.54	0.54	0.53	0.47	0.35
Parma	0.41	0.41	0.41	0.41	0.33	0.19
Richfield	0.14	0.13	0.13	0.10	0.05	0.02
Shaker Heights	0.90	0.90	0.90	0.89	0.64	0.30
South Euclid	0.85	0.84	0.84	0.84	0.53	0.23
Southerly WWTC	0.62	0.59	0.59	0.59	0.47	0.19
Strongsville C WWTP	0.47	0.45	0.45	0.45	0.41	0.25
Strongsville Foltz	0.52	0.37	0.37	0.37	0.37	0.20
University Heights	1.24	1.24	1.24	1.23	0.53	0.25
Wade Park	0.91	0.91	0.91	0.90	0.56	0.24
Westerly WWTP	0.67	0.67	0.67	0.66	0.36	0.20
Westlake	0.72	0.72	0.72	0.60	0.42	0.26

Work Order Detail Report

7/27/2022

SSO INSPECTION 7-24-2022 1.24 INCHES OF RAIN

4:18 PM

WO Number: 220727-0001	Category: SSOs	
Status: Complete	Problem: Storm Response	
Status Date: 7/27/2022 4:17 pm	Main Task: Inspection	
Asset: SSO 431		
Location: FAIRFAX AT NORTH PARK		
Cause: Weather	Assigned By:	
Assigned Crew:	Assigned Date:	
Supervisor: Jackson, Jeff	Start Date: 7/27/2022 7:15 AM	Override
Lead Worker: Cardarella, Joe	End Date: 7/27/2022 3:15 PM	Notifications
Priority: High		Problem ☐
Account #:		Overdue ☐
Proj No - Acct:	Project ID:	Lead Worker ☐
Project:	Project Name:	Task ☐
Reason:		Supervisor ☐
Received By:		Hard Lock WO ☐
Inspected By:		

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer Collection
Sub-Division:
Area:
Sub-Area:
Owner:
Location:
Classification:

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Maintenance Zone:

Alternate Zone:

Work Order Locations

Address	Address 2
X Coord	Y Coord
General Location	
FAIRFAX AT NORTH PARK	
2,220,655.65435414	665,517.24643672
NORTH PARK AND COVENTRY	Doan Brook
2,219,873.16674590	666,048.82312946
FAIRMOUNT SOUTH OF SCARBOROUGH	DOAN BROOK - MAIN BRANCH
2,220,364.86097248	666,446.72325230
FAIRMOUNT AT FAIRFAX	DOAN BROOK - MAIN BRANCH
2,220,920.81917815	666,080.57995571
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)	DOAN BROOK - MAIN BRANCH
2,223,053.81655256	664,693.25202172
3012 NORTH WOODLAND	DOAN BROOK - MAIN BRANCH
2,222,845.06631389	664,689.08536339
	Doan Brook
2,226,440.21168265	664,329.55524255
2,226,354.79813956	664,409.89202413
2,226,389.92077273	664,379.07548472
FAIRMOUNT AT DARTMOOR	
2,225,149.97508989	664,453.31024438
FAIRMOUNT AT WELLINGTON	DOAN BROOK - MAIN BRANCH
2,223,969.26550905	664,532.08075613
	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

7/27/2022

SSO INSPECTION 7-24-2022 1.24 INCHES OF RAIN

4:18 PM

FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON		
2,222,127.85875881	665,393.74077822	DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)		
2,220,278.63411081	667,231.62916280	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY		
2,220,419.37169023	666,567.10752596	DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON		
2,221,598.28993607	666,996.61322863	
MONMOUTH, EAST OF DARTMOOR		
2,225,152.08663423	665,499.19660404	DOAN BROOK
BRADFORD AND LEE		
2,224,643.84191582	665,970.39907372	DOAN BROOK - MAIN BRANCH
EDDINGTON		
2,221,299.08384156	674,932.84604380	
HAMPSHIRE LANE AT MAYFIELD (18")		
2,219,348.17140481	672,922.02624655	DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL		
2,218,479.60588473	671,538.70289771	DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")		
2,219,354.97683740	672,902.85961822	DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD		
HAMPSHIRE AT EUCLID HTS. BLVD.		
2,218,465.44876081	671,703.91811846	DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON		
2,218,036.25112839	669,668.09115338	DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY		
2,220,768.48319674	670,614.63814481	DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD		
2,222,538.05642922	672,458.71614955	DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd		
2,227,113.30810548	671,276.67684697	
LEE RD. & SUPERIOR AVE.		
2,224,449.07983814	672,366.92072946	HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE		
2,224,196.49208874	673,102.72798488	DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND		
2,223,890.24106081	672,984.80925746	DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND		
2,223,414.40769489	674,158.55920655	DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON		
2,223,678.60992239	673,517.13791722	DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD		
2225 NOBLE ROAD		
2,227,020.20068015	682,910.03907888	NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF		
2,229,594.65878581	682,393.53289405	NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE		
2,228,126.76638040	684,188.23206055	
2,220,777.89623564	666,181.72575080	
2,218,501.67473823	671,997.54581206	
2,216,759.55453481	670,474.59347738	

Work Order Detail Report

7/27/2022

SSO INSPECTION 7-24-2022 1.24 INCHES OF RAIN

4:18 PM

2,224,536.21778722	668,887.44048372
2,226,741.35609348	679,432.95121680
2,226,591.76420106	679,420.92761880
2,227,825.14395215	684,881.15948047

Work Order Detail Report

7/27/2022

SSO INSPECTION 7-24-2022 1.24 INCHES OF RAIN

4:18 PM

Work Order Assets							
Object Type	Description 1		Description 2				
System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve					FAIRFAX AT NORTH PARK		
SSO 431						26	
Sewer Control Valve					NORTH PARK AND COVENTRY		
SSO 114						16	
Sewer Control Valve					FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35	
Sewer Structure							
SA16AAWB0						3094	
Sewer Control Valve					FAIRMOUNT AT FAIRFAX		
SSO 112						7	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6	
Sewer Control Valve					3012 NORTH WOODLAND		
SSO 432						14	
Sewer Control Valve							
DB-03						55	
Sewer Control Valve							
DB-01						56	
Sewer Control Valve							
DB-02						57	
Sewer Control Valve					FAIRMOUNT AT DARTMOOR		
CH-04						5	
Sewer Control Valve					FAIRMOUNT AT WELLINGTON		
SSO 110						44	
Sewer Control Valve					FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33	
Sewer Control Valve					FAIRMOUNT AT MARLBORO		
SSO 116						4	
Sewer Control Valve					FAIRMOUNT AT ARLINGTON		
SSO 111						46	
Sewer Control Valve					FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37	
Sewer Control Valve					FAIRMOUNT AND COVENTRY		
SSO 124						47	
Sewer Control Valve					SCARBOROUGH AT LAMBERTON		
CH-50						53	
Sewer Control Valve					BRADFORD AND LEE		
SSO 129						11	
Sewer Control Valve					EDDINGTON		
CH-52						2	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42	
Sewer Control Valve					EAST OVERLOOK AT EDGEHILL		
SSO 122						36	
Sewer Control Valve					HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34	
Sewer Structure							
SA16ADZB0						1536	
Sewer Control Valve					HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20	
Sewer Structure							
SA16ADPH0						4446	
Sewer Control Valve					CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8	
Sewer Control Valve					2828 BERKSHIRE, EAST OF COVENTRY		

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220727-0001

Work Order Detail Report

7/27/2022

SSO INSPECTION 7-24-2022 1.24 INCHES OF RAIN

4:18 PM

SSO 103	19
Sewer Control Valve	3003 EUCLID HEIGHTS BLVD
SSO 104	15
Sewer Structure	
SA16AGMG0	3402
Sewer Control Valve	South Taylor between Antisdale Ave and Superior R
CH-30	52
Sewer Control Valve	LEE RD. & SUPERIOR AVE.
DV-11	9
Sewer Control Valve	EUCLID HEIGHTS BLVD AND LEE
SSO 108	22
Sewer Control Valve	EUCLID HEIGHTS BLVD/CUMBERLAND
SSO 106	43
Sewer Control Valve	1685 CUMBERLAND
SSO 95	18
Sewer Control Valve	CUMBERLAND/SOMERTON
SSO 105	30
Sewer Structure	
SA16AQQD0	4987
Sewer Structure	
SA16AQQC0	3745
Sewer Control Valve	2225 NOBLE ROAD
SSO 102	3
Sewer Control Valve	QUILLIAMS, N. OF RANDOLF
SSO 107	38
Sewer Control Valve	LANGTON AND ATHERSTONE
CH-51	54
Sewer Structure	
SA16APEF0	1809

Work Order Detail Report

SSO INSPECTION 7-24-2022 1.24 INCHES OF RAIN

7/27/2022

4:18 PM

Check List					
	Item	Completed	Condition	Completion Date/Time	Est Completion Date
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	☐	Not Sound	7/27/2022/ 7:45 am	7/27/2022
Reset					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	☐	Not Sound	7/27/2022/ 7:45 am	7/27/2022
Reset					
3	A-45-FAIRMOUNT (IN THE ISLAND EAST OF COVENTRY) SA16ACNE0	☐	Sound	7/27/2022/ 7:46 am	7/27/2022
4	A-54-2806 FAIRMOUNT SA16AAWB0 (TREE LAWN BY SIDEWALK)	☐	Sound	7/27/2022/ 7:46 am	7/27/2022
5	A-33-FAIRMOUNT AT FAIRFAX SA16AAWC0 (SW CORNER IN THE SIDEWALK)	☐	Not Sound	7/27/2022/ 8:10 am	7/27/2022
Reset					
6	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	☐	Sound	7/27/2022/ 8:10 am	7/27/2022
7	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	☐	Sound	7/27/2022/ 8:11 am	7/27/2022
8	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	☐	Sound	7/27/2022/ 8:11 am	7/27/2022
9	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	☐	Not Sound	7/27/2022/ 8:12 am	7/27/2022
Reset					
10	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	☐	Not Sound	7/27/2022/ 8:12 am	7/27/2022
Reset					
11	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	☐	Sound	7/27/2022/ 8:13 am	7/27/2022
12	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	☐	Sound	7/27/2022/ 8:13 am	7/27/2022
13	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	☐	Sound	7/27/2022/ 8:14 am	7/27/2022
14	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	☐	Not Sound	7/27/2022/ 8:14 am	7/27/2022
No block					
15	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	☐	Sound	7/27/2022/ 8:15 am	7/27/2022
16	A-49 2757 FAIRMOUNT SA16AAUC0 (EAST OF CHURCH IN TREE LAWN)	☐	Sound	7/27/2022/ 8:15 am	
17	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	☐	Not Sound	7/27/2022/ 8:16 am	7/27/2022
Reset					
18	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	☐	Not Sound	7/27/2022/ 8:16 am	7/27/2022
Reset					
19	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	☐	Sound	7/27/2022/ 8:17 am	7/27/2022
20	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	☐	Not Sound	7/27/2022/ 8:17 am	7/27/2022
No block					
21	A-58 E MONMOUTH AT EXETER (INTERSECTION)	☐	Not Sound	7/27/2022/ 8:18 am	7/27/2022
22	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	☐	Not Sound	7/27/2022/ 8:18 am	7/27/2022
No block meter in manhole					

* A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 220727-0001

Work Order Detail Report

7/27/2022

SSO INSPECTION 7-24-2022 1.24 INCHES OF RAIN

4:18 PM

23	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	☐	Sound	7/27/2022/ 8:19 am	7/27/2022
24	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	☐	Sound	7/27/2022/ 8:25 am	7/27/2022
25	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	☐	Sound	7/27/2022/ 8:25 am	
26	B-61 2600 HAMPSHIRE SA16ADZB0	☐	Sound	7/27/2022/ 8:39 am	7/27/2022
27	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	☐	Not Sound	7/27/2022/ 8:44 am	7/27/2022
Reset					
28	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	☐	Not Sound	7/27/2022/ 8:47 am	7/27/2022
Reset					
29	B-42 12537 CEDAR SA16ACZA0	☐	Sound	7/27/2022/10:06 am	7/27/2022
30	B-15 COVENTRY AND CEDAR SA16ADBH0	☐	Sound	7/27/2022/10:18 am	7/27/2022
31	B-23 2828 BERKSHIRE SA16AETA0	☐	Sound	7/27/2022/ 9:01 am	7/27/2022
32	B-24 3003 EUCLID HTS. BLVD. ST16AALB0	☐	Sound	7/27/2022/ 9:12 am	7/27/2022
33	B-56 LEE AND MEADOWBROOK SA16AGMG0	☐	Sound	7/27/2022/ 9:25 am	7/27/2022
34	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	☐	Not Sound	/10:01 am	7/27/2022
35	C-12 LEE AND SUPERIOR SA16AGTJ0	☐	Not Sound	7/27/2022/ 9:18 am	7/27/2022
Can't reset surcharging					
36	C-28 EUCLID HTS. BLVD AND LEE RD SA16AGTE0	☐	Not Sound	7/27/2022/ 9:18 am	7/27/2022
Reset					
37	C-26 EUCLID HTS BLVD AND CUMBERLAND SA16AIRL0	☐	Sound	7/27/2022/ 8:30 am	7/27/2022
38	C-25 CUMBERLAND AND SOMERTON SA16AISA0	☐	Not Sound	7/27/2022/ 8:30 am	7/27/2022
Reset					
39	C-17 1685 CUMBERLAND RD SA16AQIB0	☐	Not Sound	7/27/2022/ 8:29 am	7/27/2022
Needs block					
40	C-59 3427 THORNE RD SA16AQQD0	☐	Not Sound	7/27/2022/ 8:28 am	7/27/2022
Reset					
41	C-60 3415 THORNE RD SA16AQQC0	☐	Sound	7/27/2022/ 8:28 am	7/27/2022
42	C-22 2225 NOBLE RD ST16ZLHB0	☐	Not Sound	7/27/2022/ 8:28 am	7/27/2022
Reset					
43	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	☐	Not Sound	7/27/2022/ 8:27 am	7/27/2022
Reset					
44	C-51 ATHERSTONE AND LANGTON SA16AOKA0	☐	Not Sound	7/27/2022/ 8:26 am	7/27/2022
Needs block					
45	C-50 3593 FENLEY SA16APEH0	☐	Sound	7/27/2022/ 7:44 am	7/27/2022

Work Order Detail Report

SSO INSPECTION 7-24-2022 1.24 INCHES OF RAIN

7/27/2022

4:18 PM

Tasks/Resources						
SWCT26 Inspection						
Crew:	Status:	*Cal'c UC: \$6.21	*Task Cost: \$279.52	Start Dt: 7/27/2022		
Supervisor:	UOM: Each	# of Units: 45.00	*Unit Cost: \$0.00	End Dt: 7/27/2022		
Employee						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	8.00	\$172.32		7/27/2022	7/27/2022
Equipment						
Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	8.00	\$107.20		7/27/2022	7/27/2022
Task Comment: SSO INSPECTIONS 0.85 INCHES OF RAIN						

Projected Complete:	Lock: ☐	WO Duration	<u>*Actual</u>	<u>*Estimated</u>	<u>*Difference</u>
Repair Type:		Labor Hours	8.00	0.00	0.00
Subcontractor:		Labor Costs	\$172.32	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity: 0.00	Lock: ☐	Equipment Costs	107.20	0.00	0.00
Unit of Measure: Each		Contractor Costs	0.00	0.00	0.00
*Unit Cost: \$0.00		Misc. Costs	0.00	0.00	0.00
WO Hours: 0.00		Total Costs	\$279.52	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party		Billing	
Customer ID:	Customer Number:		
Customer Name:	Last Name:		
Address:			
City:	Phone:	Cell #:	
State:	Fax #:		
Zip:	E-mail:		
Billing Data			
Contact Name:	*Billing Amount:	Billing Required: ☐	
Invoice Number:	Date Bill Sent:	Billing Processed: ☐	
Incoming Account #:	Payment Received:	Imported to Financials: ☐	
	Payment Method:		

Associated PMs	
<u>PM Code and Description</u>	<u>Closed</u>
SSO-02 SSO INSPECTION	☒

Tracking	Item	Description	By	Date	Time
Work Order Creation		From Routine Work SSO-02 - SSO INSPECTION	jjackson	7/27/2022	7:17 AM
Supervisor Notification		Email Queued Successfully!	jjackson	7/27/2022	7:17 AM
Status Change		From New Work Order to Complete	aferrone	7/27/2022	4:17 PM

Work Order Detail Report

7/27/2022

SSO INSPECTION 7-24-2022 1.24 INCHES OF RAIN

4:18 PM

Rate:	Opened At:	Televised:	☐
Received By:	Pipe Footage Cleaned:	Power Rooter:	☐
Work From:	Gallons Used:	Jet:	☐
Pipe Size:	WO User 23:	Gap Vac:	☐
Pipe Condition:	WO User 24:	Dye Test:	☐
Could Not Open:	WO User 9:	Gap Root Cut:	☐
Additional Repair:	User 10:	GIS Correction?:	☐
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	☐
Test Performed Throug	Appointment Date: 7/27/2022 7:30 AM		
Dye Test Results:			
WO User 51:			
Measurement:	E Mail:		
History:	Measurement Line 2:		
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Slex		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Re			
Construction Crew:			
WO User 39:			
WO User 40:	OUPS #:		
WO User 41:	WO User 48:		
WO User 52:	WO User 62:		
WO User 53:	WO User 63:		
WO User 54:	WO User 64:		
WO User 55:	WO User 65:		
WO User 56:	WO User 66:		
WO User 57:	WO User 67:		
WO User 58:	WO User 68:		
WO User 59:	WO User 69:		
WO User 60:	WO User 70:		
WO User 61:	WO User 71:		
WO User 72:	WO User 82:	Televised:	☐
WO User 73:	Quantity:	Paid:	☐
WO User 74:	WO User 84:	WO User 104:	☐
WO User 75:	WO User 85:	WO User 105:	☐
WO User 76:	WO User 86:	WO User 106:	☐
WO User 92 Date:	WO User 97 Date:		
WO User 93 Date:	WO User 98 Date:		
WO User 94 Date:	WO User 99 Date:		
WO User 95 Date:	WO User 100 Date:		
WO User 96 Date:	WO User 101 Date:		
WO User 77:	WO User 87:	WO User 107:	☐
WO User 78:	WO User 88:	WO User 108:	☐
WO User 79:	WO User 89:	WO User 109:	☐
WO User 80:	WO User 90:	WO User 110:	☐
WO User 81:	WO User 91:	WO User 111:	☐
WO Creator: jjackson	WO Creation Date: 7/27/2022	PM Trigger:	Rec #: 12966