

CITY OF
CLEVELAND
HEIGHTS
LAW DEPARTMENT

March 12, 2024

Via E-Mail: vezner.kris@epa.gov and Berger.Jake@epa.gov

Kris P. Vezner, Esq.
Associate Regional Counsel
U.S. Environmental Protection Agency
Region 5 (C-14J)
77 West Jackson Blvd.
Chicago, IL 60604

and

Jake Berger
Physical Scientist
Water Enforcement & Compliance Assurance Branch
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Mail Code ECW-15J
Chicago, IL 60604


Re: February 2024 Overflow Monitoring Reports
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through February 29, 2024, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,




William R. Hanna
Director of Law

Enclosures

cc: Thomas Benson, Esq., EPA Attorney
James Vinch, Esq., EPA Attorney
James Zimny, EPA Engineer
U.S. EPA Region 5 Water Enforcement Branch
Mark Klingenstein, Environmental Engineer
Erm Gomes, Ohio EPA
Allison Cycyk, Ohio EPA
Casey Galligan, Ohio EPA
David Brumbaugh, Ohio EPA
Bill Fischbein, Ohio EPA
Kahlil Seren, Mayor
Collette Clinkscale, Director of Public Works
Steve Barker, Public Relations
Anthony Ferrone, Utilities Commissioner
Kevin Vander Tuig, P.E. (Outside Engineer)
Mathew St. Pierre, (Outside Engineer)
Dan Porter (Outside Engineer)
Cindy Biacofsky (Outside Engineer)
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

**Northwest Ohio
Regional Sewer District**

Daily Precipitation Report
Thursday, February 22, 2024
Accumulation in Inches



Northeast Ohio Regional Sewer District

Daily Precipitation Report

Thursday, February 22, 2024

Site Location	Peak Accumulation (inches)				
	24-Hour	6-Hour	3-Hour	1-Hour	15-Minute
Beachwood	0.69	0.48	0.34	0.17	0.06
Brecksville	0.57	0.29	0.17	0.08	0.04
Brook Park	0.52	0.40	0.26	0.13	0.05
Cleveland Industrial Pkwy	0.55	0.42	0.28	0.15	0.05
Dille Ave PS	0.55	0.41	0.27	0.14	0.05
Division Ave PS	0.67	0.47	0.31	0.18	0.07
Easterly WWTP	0.58	0.42	0.29	0.18	0.06
Independence	0.53	0.36	0.24	0.10	0.04
James Rhodes HS	0.57	0.44	0.31	0.17	0.06
Jennings PS	0.62	0.47	0.33	0.16	0.06
Macedonia	0.53	0.28	0.17	0.10	0.04
Maple Heights	n/a	n/a	n/a	n/a	n/a
Mary Street PS	0.63	0.45	0.30	0.16	0.06
Mayfield Heights	n/a	n/a	n/a	n/a	n/a
Moreland Hills	0.62	0.43	0.30	0.14	0.05
North Olmsted	0.57	0.39	0.27	0.13	0.05
North Royalton	0.52	0.29	0.16	0.08	0.03
Oakwood	0.46	0.28	0.17	0.08	0.03
Olmsted Falls	0.51	0.37	0.24	0.12	0.04
Parma	0.55	0.40	0.27	0.12	0.05
Richfield	0.50	0.25	0.14	0.08	0.03
Shaker Heights	0.68	0.48	0.35	0.15	0.05
South Euclid	0.66	0.45	0.31	0.14	0.04
Southerly WWTC	0.62	0.47	0.34	0.17	0.06
Strongsville C WWTP	0.55	0.36	0.22	0.11	0.05
Strongsville Foltz	0.51	0.30	0.18	0.09	0.04
University Heights	0.67	0.48	0.33	0.15	0.05
Wade Park	0.64	0.43	0.29	0.15	0.06
Westerly WWTP	0.62	0.43	0.29	0.17	0.06
Westlake	0.63	0.41	0.29	0.17	0.07

Category:	SSOs	Priority:	High
Problem:	Storm Response	Crew:	
Cause:	Weather	Supervisor:	Jackson, Jeff
Main Task:	Inspection	Status:	Complete
Work Order Start Date/Time:	2/22/2024 8:00 AM	Work Order End Date/Time:	2/22/2024 2:30 PM

Location (s)

FAIRFAX AT NORTH PARK
Doan Brook
NORTH PARK AND COVENTRY
DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH
DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX
DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)
DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND
Doan Brook

FAIRMOUNT AT DARTMOOR
DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON
DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)
DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO
DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT ARLINGTON
DOAN BROOK - MAIN BRANCH
FAIRMOUNT & COVENTRY (SCARBOROUGH)
DOAN BROOK - MAIN BRANCH
FAIRMOUNT AND COVENTRY
DOAN BROOK - MAIN BRANCH
SCARBOROUGH AT LAMBERTON
MONMOUTH, EAST OF DARTMOOR
DOAN BROOK
BRADFORD AND LEE
DOAN BROOK - MAIN BRANCH
EDDINGTON
HAMPSHIRE LANE AT MAYFIELD (18")
DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL
DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")
DUGWAY CREEK - MAIN BRANCH
2600 HAMPSHIRE RD
HAMPSHIRE AT EUCLID HTS. BLVD.
DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON
DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY
DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD
DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd
LEE RD. & SUPERIOR AVE.
HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE
DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND
DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND

CUMBERLAND/SOMERTON
DUGWAY CREEK - MAIN BRANCH
2225 NOBLE RD
2225 NOBLE ROAD
NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF
NINE MILE CREEK - MAIN BRANCH
LANGTON AND ATHERSTONE

Comments from Request

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Comments for Crew

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

CHECKLIST

<u>Comp.</u>	<u>Item</u>	<u>Condition</u>
☒	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	Sound
☒	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	Sound
☒	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	Sound
☒	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	Sound
☒	A-6 FAIRMOUNT AT SHELBURNE ST16ZBJK0 (WEST BOUND LANE)	Sound
☒	A-5 FAIRMOUNT AT SHELBURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	Sound
☒	A-7 FAIRMOUNT AT SHELBURNE SA16AAVH0 (EAST BOUND)	Sound
☒	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	Sound
☒	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	Sound
☒	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	Sound
☒	A-32 FAIRMOUNT AT ARLINGTON SA16AAUP0 (INTERSECTION)	Sound
☒	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	Sound
☒	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	Sound
☒	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	Sound
☒	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	Sound
☒	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	Sound
☒	A-58 E MONMOUTH AT EXETER (INTERSECTION)	Sound
☒	A-9 BRADFORD AT LEE SA16AFLLO (INTERSECTION)	Sound
☒	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	Sound
☒	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	Sound
☒	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	Sound
☒	B-61 2600 HAMPSHIRE SA16ADZB0	Sound
☒	HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	Sound
☒	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	Sound
☐	B-42 12537 CEDAR SA16ACZA0	
☒	B-15 COVENTRY AND CEDAR SA16ADBH0	Sound
☒	B-23 2828 BERKSHIRE SA16AETA0	Sound
☒	B-56 LEE AND MEADOWBROOK SA16AGMG0	Sound
☒	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	Sound
☒	C-59 3427 THORNE RD SA16AQQD0	Sound
☒	C-60 3415 THORNE RD SA16AQQC0	Sound
☒	C-22 2225 NOBLE RD ST16ZLHB0	Sound
☒	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	Sound
☒	C-51 ATHERSTONE AND LANGTON SA16AOKA0	Sound
☒	C-50 3593 FENLEY SA16APEH0	Not Sound

Task Code: SMCT36

Task Description: Inspection

Employee Number	Employee Name	Time Type				Units
		Reg	OT	Normal	Type	
40151	Mc Coy, Sam	0.00	0.00	5.00	REGULAR TIME	Hours

Equipment Code	Equipment Description	Units
CHFLT550	FORD F250 PICK UP	5.00

Material Code	Material Description	Units

Fluid Code	Fluid Description	Units