

CITY OF
**CLEVELAND
HEIGHTS** 
LAW DEPARTMENT

November 25, 2024

Via E-Mail: vezner.kris@epa.gov and Berger.Jake@epa.gov

Kris P. Vezner, Esq.
Associate Regional Counsel
U.S. Environmental Protection Agency
Region 5 (C-14J)
77 West Jackson Blvd.
Chicago, IL 60604

and

Jake Berger
Physical Scientist
Water Enforcement & Compliance Assurance Branch
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Mail Code ECW-15J
Chicago, IL 60604


Re: October 2024 Overflow Monitoring Reports
City of Cleveland Heights, Ohio

Dear Mr. Vezner and Mr. Berger:

Please find enclosed the Overflow Monitoring Reports for inspections performed through October 31, 2024, as well as the Sanitary Sewer Overflow spreadsheet.

Please contact Director of Public Works Collette Clinkscale or me with any questions.

Very truly yours,


William R. Hanna
Director of Law

Enclosures


cc: Thomas Benson, Esq., EPA Attorney
James Vinch, Esq., EPA Attorney
James Zimny, EPA Engineer
U.S. EPA Region 5 Water Enforcement Branch
Mark Klingenstein, Environmental Engineer
Erm Gomes, Ohio EPA
Allison Cycyk, Ohio EPA
Casey Galligan, Ohio EPA
David Brumbaugh, Ohio EPA
Bill Fischbein, Ohio EPA
Kahlil Seren, Mayor
Collette Clinkscale, Director of Public Works
Steve Barker, Public Relations
Anthony Ferrone, Utilities Commissioner
Kevin Vander Tuig, P.E. (Outside Engineer)
Sarah Fuller, (Outside Engineer)
Dan Porter (Outside Engineer)
Cindy Biacofsky (Outside Engineer)
Louis L. McMahon, McMahon DeGulis LLP (Outside Legal Counsel)

**Northeast Ohio
Regional Sewer District**

Daily Precipitation Report

Sunday, October 13, 2024

Accumulation in Inches



Work Order Detail Report

10/16/2024

SSO overflow inspections 10-13-2024 1.2'

9:38 AM

WO Number:	241015-0001	Category:	SSOs
Status:	New Work Order	Problem:	Storm Response
Status Date:	10/15/2024 7:18 am	Main Task:	Inspection
Asset:	SSO 431		
Location:	FAIRFAX AT NORTH PARK		
Cause:	Weather	Assigned By:	
Assigned Crew:		Assigned Date:	
Supervisor:	Jackson, Jeff	Start Date:	10/15/2024 8:00 AM
Lead Worker:	Cardarella, Joe	End Date:	10/15/2024 1:30 PM
Priority:	High	Override Notifications	
Account #:		Problem	<input type="checkbox"/>
Proj No - Acct:		Overdue	<input type="checkbox"/>
Project:		Lead Worker	<input type="checkbox"/>
Reason:		Task	<input type="checkbox"/>
Received By:		Supervisor	<input type="checkbox"/>
Inspected By:		Hard Lock WO	<input type="checkbox"/>

Request Comments for Work Order

Inspect all (45) SSO's when rainfall is one quarter (1/4") inch or higher.

Location

Department: Sewer Collection
Division: Sewer

Comments for Crew
Inspect all (45) SSO's when rainfall is one quarter (1/4")
inch or higher.

Sub-Division:

Area:

Sub-Area:

Owner:

Location:

Classification:

Maintenance Zone:

Alternate Zone:

Work Order Locations

<u>Address</u>	<u>Address 2</u>	
<u>X Coord</u>	<u>Y Coord</u>	<u>General Location</u>
FAIRFAX AT NORTH PARK		
2,220,655.65435414	665,517.24643672	Doan Brook
NORTH PARK AND COVENTRY		
2,219,873.16674590	666,048.82312946	DOAN BROOK - MAIN BRANCH
FAIRMOUNT SOUTH OF SCARBOROUGH		
2,220,364.86097248	666,446.72325230	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT FAIRFAX		
2,220,920.81917815	666,080.57995571	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
2,223,053.81655256	664,693.25202172	DOAN BROOK - MAIN BRANCH
3012 NORTH WOODLAND		
2,222,845.06631389	664,689.08536339	Doan Brook
2,226,440.21168265	664,329.55524255	
2,226,354.79813956	664,409.89202413	
2,226,389.92077273	664,379.07548472	
FAIRMOUNT AT DARTMOOR		
2,225,149.97508989	664,453.31024438	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT WELLINGTON		
2,223,969.26550905	664,532.08075613	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
2,223,111.44143730	664,794.46048072	DOAN BROOK - MAIN BRANCH
FAIRMOUNT AT MARLBORO		
2,221,638.88762389	665,726.15513962	DOAN BROOK - MAIN BRANCH

Work Order Detail Report

10/16/2024

9:38 AM

iso overflow inspections 10-13-2024 1.2'

FAIRMOUNT AT ARLINGTON

2,222,127.85875881 665,393.74077822 DOAN BROOK - MAIN BRANCH

FAIRMOUNT & COVENTRY (SCARBOROUGH)

2,220,278.63411081 667,231.62916280 DOAN BROOK - MAIN BRANCH

FAIRMOUNT AND COVENTRY

2,220,419.37169023 666,567.10752596 DOAN BROOK - MAIN BRANCH

SCARBOROUGH AT LAMBERTON

2,221,598.28993607 666,996.61322863

MONMOUTH, EAST OF DARTMOOR

2,225,152.08663423 665,499.19660404 DOAN BROOK

BRADFORD AND LEE

2,224,643.84191582 665,970.39907372 DOAN BROOK - MAIN BRANCH
EDDINGTON

2,221,299.08384156 674,932.84604380
HAMPSHIRE LANE AT MAYFIELD (18")

2,219,348.17140481 672,922.02624655 DUGWAY CREEK - MAIN BRANCH
EAST OVERLOOK AT EDGEHILL

2,218,479.60588473 671,538.70289771 DOAN BROOK - MAIN BRANCH
HAMPSHIRE LANE AT MAYFIELD (36")

2,219,354.97683740 672,902.85961822 DUGWAY CREEK - MAIN BRANCH

2600 HAMPSHIRE RD

HAMPSHIRE AT EUCLID HTS. BLVD.

2,218,465.44876081 671,703.91811846 DOAN BROOK - MAIN BRANCH
CEDAR BTW. FAIRMOUNT/DEMINGTON

2,218,036.25112839 669,668.09115338 DOAN BROOK - MAIN BRANCH
2828 BERKSHIRE, EAST OF COVENTRY

2,220,768.48319674 670,614.63814481 DUGWAY CREEK - MAIN BRANCH
3003 EUCLID HEIGHTS BLVD

2,222,538.05642922 672,458.71614955 DUGWAY CREEK - MAIN BRANCH
South Taylor between Antisdale Ave and Superior Rd

2,227,113.30810548 671,276.67684697
LEE RD. & SUPERIOR AVE.

2,224,449.07983814 672,366.92072946 HEIGHT = NA, WIDTH = NA, LENGTH = NA
EUCLID HEIGHTS BLVD AND LEE

2,224,196.49208874 673,102.72798488 DUGWAY CREEK - MAIN BRANCH
EUCLID HEIGHTS BLVD/CUMBERLAND

2,223,890.24106081 672,984.80925746 DUGWAY CREEK - MAIN BRANCH
1685 CUMBERLAND

2,223,414.40769489 674,158.55920655 DUGWAY CREEK - MAIN BRANCH
CUMBERLAND/SOMERTON

2,223,678.60992239 673,517.13791722 DUGWAY CREEK - MAIN BRANCH

2225 NOBLE RD

2225 NOBLE ROAD

2,227,020.20068015 682,910.03907888 NINE MILE CREEK - MAIN BRANCH
QUILLIAMS, N. OF RANDOLF

2,229,594.65878581 682,393.53289405 NINE MILE CREEK - MAIN BRANCH
LANGTON AND AHERSTONE

2,228,126.76638040 684,188.23206055

2,220,777.89623564 666,181.72575080

2,218,501.67473823 671,997.54581206

2,216,759.55453481 670,474.59347738

2,224,536.21778722 668,887.44048372

2,226,741.35609348 679,432.95121680

2,226,591.76420106 679,420.92761880

Work Order Detail Report

10/16/2024

iso overflow inspections 10-13-2024 1.2'

9:38 AM

2,227,825.14395215 684,881.15948047

Work Order Detail Report

10/16/2024

ISO overflow inspections 10-13-2024 1.2'

9:38 AM

Work Order Assets		Description 1			Description 2			
Object Type	System ID 1	System ID 2	Odometer	Hourmeter	Othermeter	PM Description	Asset ID	Completed
Sewer Control Valve						FAIRFAX AT NORTH PARK		
SSO 431						26		
Sewer Control Valve						NORTH PARK AND COVENTRY		
SSO 114						16		
Sewer Control Valve						FAIRMOUNT SOUTH OF SCARBOROUGH		
SSO 121						35		
Sewer Structure								
SA16AAWB0						3094		
Sewer Control Valve						FAIRMOUNT AT FAIRFAX		
SSO 112						7		
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (S. SIDE)		
SSO 99						6		
Sewer Control Valve						3012 NORTH WOODLAND		
SSO 432						14		
Sewer Control Valve								
DB-03						55		
Sewer Control Valve								
DB-01						56		
Sewer Control Valve								
DB-02						57		
Sewer Control Valve						FAIRMOUNT AT DARTMOOR		
CH-04						5		
Sewer Control Valve						FAIRMOUNT AT WELLINGTON		
SSO 110						44		
Sewer Control Valve						FAIRMOUNT AT NORTH WOODLAND (N. SIDE)		
SSO 87						33		
Sewer Control Valve						FAIRMOUNT AT MARLBORO		
SSO 116						4		
Sewer Control Valve						FAIRMOUNT AT ARLINGTON		
SSO 111						46		
Sewer Control Valve						FAIRMOUNT & COVENTRY (SCARBOROUGH)		
SSO 113						37		
Sewer Control Valve						FAIRMOUNT AND COVENTRY		
SSO 124						47		
Sewer Control Valve						SCARBOROUGH AT LAMBERTON		
CH-50						53		
Sewer Control Valve						BRADFORD AND LEE		
SSO 129						11		
Sewer Control Valve						EDDINGTON		
CH-52						2		
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (18")		
SSO 88						42		
Sewer Control Valve						EAST OVERLOOK AT EDGEHILL		
SSO 122						36		
Sewer Control Valve						HAMPSHIRE LANE AT MAYFIELD (36")		
SSO 89						34		
Sewer Structure								
SA16ADZB0						1536		
Sewer Control Valve						HAMPSHIRE AT EUCLID HTS. BLVD.		
SSO 91						20		
Sewer Structure								
SA16ADPH0						4446		
Sewer Control Valve						CEDAR BTW. FAIRMOUNT/DEMINGTON		
SSO 120						8		
Sewer Control Valve						2828 BERKSHIRE, EAST OF COVENTRY		
SSO 103						19		
Sewer Control Valve						3003 EUCLID HEIGHTS BLVD		
SSO 104						15		

Work Order Detail Report

10/16/2024

SSO overflow inspections 10-13-2024 1.2'

9:38 AM

Sewer Structure		
SA16AGMG0	3402	
Sewer Control Valve		
CH-30	52	South Taylor between Antisdale Ave and Superior F
Sewer Control Valve		
DV-11	9	LEE RD. & SUPERIOR AVE.
Sewer Control Valve		
SSO 108	22	EUCLID HEIGHTS BLVD AND LEE
Sewer Control Valve		
SSO 106	43	EUCLID HEIGHTS BLVD/CUMBERLAND
Sewer Control Valve		
SSO 95	18	1685 CUMBERLAND
Sewer Control Valve		
SSO 105	30	CUMBERLAND/SOMERTON
Sewer Structure		
SA16AQQD0	4987	
Sewer Structure		
SA16AQQC0	3745	
Sewer Control Valve		
SSO 102	3	2225 NOBLE ROAD
Sewer Control Valve		
SSO 107	38	QUILLIAMS, N. OF RANDOLF
Sewer Control Valve		
CH-51	54	LANGTON AND AHERSTONE
Sewer Structure		
SA16APEF0	1809	

Work Order Detail Report

10/16/2024

iso overflow inspections 10-13-2024 1.2'

9:38 AM

Check List		Completed	Condition	Completion Date/Time	Est Completion Date
	<u>Item</u>				
1	A-37-FAIRFAX AT NORTH PARK SA16ACPG0	<input type="checkbox"/>	Not Sound	10/15/2024/ 1:30 pm	10/15/2024
Reset					
2	A-36-NORTH PARK AT COVENTRY SA16ACNB0 (IN MEDIAN-CEMENT)	<input type="checkbox"/>	Sound	10/15/2024/ 1:30 pm	10/15/2024
3	A-39-3012 NORTH WOODLAND SA16AAWM5 (TREE LAWN)	<input type="checkbox"/>	Sound	10/15/2024/ 1:30 pm	10/15/2024
4	A-2 FAIRMOUNT AT NORTH WOODLAND SA16AAWK0(MIDDLE OF THE ROAD)	<input type="checkbox"/>	Sound	10/15/2024/ 1:31 pm	10/15/2024
5	A-6 FAIRMOUNT AT SHELBOURNE ST16ZBJK0 (WEST BOUND LANE)	<input type="checkbox"/>	Sound	10/15/2024/ 1:31 pm	10/15/2024
6	A-5 FAIRMOUNT AT SHELBOURNE SA16AAXB0(ON THE SE CORNER IN THE SIDEWALK)	<input type="checkbox"/>	Sound	10/15/2024/ 1:31 pm	10/15/2024
7	A-7 FAIRMOUNT AT SHELBOURNE SA16AAVH0 (EAST BOUND)	<input type="checkbox"/>	Sound	10/15/2024/ 1:32 pm	10/15/2024
8	A-4 FAIRMOUNT AT DARTMOOR SA16AAVB0(NW CORNER IN THE GRASS BY STOP SIGN)	<input type="checkbox"/>	Sound	10/15/2024/ 1:33 pm	10/15/2024
9	A-3 FAIRMOUNT AT WELLINGTON SA16AAUW0 (INTERSECTION)	<input type="checkbox"/>	Sound	10/15/2024/ 1:33 pm	10/15/2024
10	A-1 3041 FAIRMOUNT SA16AAUT0 (TREE LAWN NEAR SIDEWALK)	<input type="checkbox"/>	Sound	10/15/2024/ 1:33 pm	10/15/2024
11	A-32 FAIRMOUNT AT ARLINGTON SA16AAUPO (INTERSECTION)	<input type="checkbox"/>	Sound	10/15/2024/ 1:34 pm	10/15/2024
12	A-38 FAIRMOUNT AT MARLBORO SA16AAUM0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	10/15/2024/ 1:34 pm	10/15/2024
Reset					
13	A-35 2393 COVENTRY SA16AASK0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	10/15/2024/ 1:35 pm	10/15/2024
NR					
14	A-50 SCARBOROUGH AND LAMBERTON SA16AANE5 (INTERSECTION)	<input type="checkbox"/>	Not Sound	10/15/2024/ 1:35 pm	10/15/2024
Reset					
15	A-47 2528 STRATFORD SA16ACDB5 (INTERSECTION)	<input type="checkbox"/>	Sound	10/15/2024/ 1:36 pm	10/15/2024
16	A-57 E MONMOUTH SA16AFWA5 WEST OF (DARTMOOR NEAR LEE)	<input type="checkbox"/>	Sound	10/15/2024/ 1:37 pm	10/15/2024
17	A-58 E MONMOUTH AT EXETER (INTERSECTION)	<input type="checkbox"/>	Sound	10/15/2024/ 1:36 pm	10/15/2024
18	A-9 BRADFORD AT LEE SA16AFLL0 (INTERSECTION)	<input type="checkbox"/>	Not Sound	10/15/2024/ 1:36 pm	10/15/2024
Reset					
19	B-52 EDDINGTON NORTH OF AVONDALE SA16AHVE0	<input type="checkbox"/>	Not Sound	10/15/2024/ 1:37 pm	
NR					
20	B-10 HAMPSHIRE LANE AT MAYFIELD SA16BACB0	<input type="checkbox"/>	Sound	10/15/2024/ 1:38 pm	10/15/2024
21	B-11 HAMPSHIRE LANE AT MAYFIELD SA16AEEA0	<input type="checkbox"/>	Sound	10/15/2024/ 1:38 pm	10/15/2024
22	B-61 2600 HAMPSHIRE SA16ADZB0	<input type="checkbox"/>	Sound	10/15/2024/ 1:38 pm	10/15/2024
23	B-13-HAMPSHIRE AT EUCLID HTS. BLVD. SA16ADPR0	<input type="checkbox"/>	Sound	10/15/2024/ 1:39 pm	10/15/2024
24	B-46 EDGEHILL AT E OVERLOOK SA16AEPF0	<input type="checkbox"/>	Sound	10/15/2024/ 1:39 pm	10/15/2024
25	B-42 12537 CEDAR SA16ACZA0	<input type="checkbox"/>	Sound	10/15/2024/ 1:40 pm	10/15/2024
26	B-15 COVENTRY AND CEDAR SA16ADBH0	<input type="checkbox"/>	Sound	10/15/2024/ 1:40 pm	10/15/2024
27	B-23 2828 BERKSHIRE SA16AETA0	<input type="checkbox"/>	Sound	10/15/2024/ 1:40 pm	10/15/2024

A 'Hidden' field indicates permission to view the secured field is turned off.

WO#: 241015-0001

Work Order Detail Report

10/16/2024

9:38 AM

sso overflow inspections 10-13-2024 1.2'

28	B-56 LEE AND MEADOWBROOK SA16AGM00	<input type="checkbox"/>	Sound	10/15/2024/ 1:41 pm	10/15/2024
29	C-30 S TAYLOR NORTH OF SUPERIOR SA16AIVF0	<input type="checkbox"/>	Sound	10/15/2024/ 1:41 pm	10/15/2024
30	C-59 3427 THORNE RD SA16AQQD0	<input type="checkbox"/>	Sound	10/15/2024/ 1:41 pm	10/15/2024
31	C-60 3415 THORNE RD SA16AQQC0	<input type="checkbox"/>	Sound	10/15/2024/ 1:42 pm	10/15/2024
32	C-22 2225 NOBLE RD ST16ZLHB0	<input type="checkbox"/>	Sound	10/15/2024/ 1:42 pm	10/15/2024
33	C-27 QUILLIAMS NORTH OF RANDOLPH SA16AOUQ0	<input type="checkbox"/>	Sound	10/15/2024/ 1:42 pm	10/15/2024
34	C-51 AHERSTONE AND LANGTON SA16AOKA0	<input type="checkbox"/>	Not Sound	10/15/2024/ 1:43 pm	10/15/2024
Still surchargeing					
35	C-55 3593 FENLEY SA16APEH0	<input type="checkbox"/>	Not Sound	10/15/2024/ 1:43 pm	10/15/2024
Reset					

Tasks/Resources

SMCT36 Inspection

Crew:	Status:	*Cal'c UC: \$5.51	*Task Cost: \$192.90	Start Dt: 10/15/2024
Supervisor:	UOM: Each	# of Units: 35.00	*Unit Cost: \$0.00	End Dt: 10/15/2024

Employee

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
22394 Cardarella, Joe	Hours	5.00	\$125.90		10/15/2024	10/15/2024

Equipment

Resource	UOM	Units	*Total Cost	Alt Description	Start Dt	End Dt
CHFLT50 FORD F250 CREW CAB 5	Hours	5.00	\$67.00		10/15/2024	10/15/2024

Task Comment: sso overflow inspections 10-13-2024 1.02'

Projected Complete:	Lock: <input type="checkbox"/>	WO Duration	*Actual	*Estimated	*Difference
			5.50	0.00	0.00
Repair Type:		Labor Hours	5.00	0.00	0.00
Subcontractor:		Labor Costs	\$125.90	\$0.00	\$0.00
Profit Center:		Material Costs	0.00	0.00	0.00
		Fluids Costs	0.00	0.00	0.00
Quantity:	0.00	Equipment Costs	67.00	0.00	0.00
Jnt of Measure:	Each	Contractor Costs	0.00	0.00	0.00
Unit Cost:	\$0.00	Misc. Costs	0.00	0.00	0.00
NO Hours:	0.00	Total Costs	\$192.90	\$0.00	\$0.00
		Use Task Info:	True	True	

Billed Party

Customer ID:	Customer Number:
Customer Name:	Last Name:
Address:	
City:	Phone:
State:	Fax #:
Zip:	E-mail:

Billing Data

Contact Name:	*Billing Amount:	Billing Required: <input type="checkbox"/>
Invoice Number:	Date Bill Sent:	Billing Processed: <input type="checkbox"/>
Incoming Account #:	Payment Received:	Imported to Financials: <input type="checkbox"/>
	Payment Method:	

Associated PMs

PM Code and Description
SSO-02 SSO INSPECTION

Closed

Work Order Detail Report

10/16/2024

ISO overflow inspections 10-13-2024 1.2'

9:38 AM

Tracking	Description	By	Date	Time
Work Order Creation	From Routine Work SSO-02 - SSO INSPECTION	jackson	10/15/2024	7:18 AM
Supervisor Notification	Email Queued Successfully!	jackson	10/15/2024	7:18 AM

Rate:	Opened At:	Televised:	<input type="checkbox"/>
Received By:	Pipe Footage Cleaned	Power Rooter:	<input type="checkbox"/>
Work From:	Gallons Used:	Jet:	<input type="checkbox"/>
Pipe Size:	WO User 23:	Gap Vac:	<input type="checkbox"/>
Pipe Condition:	WO User 24:	Dye Test:	<input type="checkbox"/>
Could Not Open:	WO User 9:	Gap Root Cut:	<input type="checkbox"/>
Additional Repair:	User 10:	GIS Correction?:	<input type="checkbox"/>
Dye Test Reason:	Appointment Date DNL	Test Tee Correction:	<input type="checkbox"/>
Test Performed Through:	Appointment Date: 10/15/2024 8:00 AM		
Dye Test Results:			
NO User 51:	E Mail:		
Measurement:	Measurement Line 2:		
History:			
Manhole Basin Repair:	Pipe Size:		
Material Used:	PVC Tees, Angles, Sockets		
Pipe Repair:	WO User 44:		
Street Repair:	WO User 45:		
Grass Repair:	WO User 46:		
Curb Repair:			
Driveway- Sidewalk Repair:			
Construction Crew:			
NO User 39:	OUPS #:		
NO User 40:	WO User 48:		
NO User 41:			
NO User 52:	WO User 62:		
NO User 53:	WO User 63:		
NO User 54:	WO User 64:		
NO User 55:	WO User 65:		
NO User 56:	WO User 66:		
NO User 57:	WO User 67:		
NO User 58:	WO User 68:		
NO User 59:	WO User 69:		
NO User 60:	WO User 70:		
NO User 61:	WO User 71:		
NO User 72:	WO User 82:	Televised:	<input type="checkbox"/>
NO User 73:	Quantity:	Paid:	<input type="checkbox"/>
NO User 74:	WO User 84:	WO User 104:	<input type="checkbox"/>
NO User 75:	WO User 85:	WO User 105:	<input type="checkbox"/>
NO User 76:	WO User 86:	WO User 106:	<input type="checkbox"/>

NO User 92 Date:	WO User 97 Date:		
NO User 93 Date:	WO User 98 Date:		
NO User 94 Date:	WO User 99 Date:		
NO User 95 Date:	WO User 100 Date:		
NO User 96 Date:	WO User 101 Date:		
NO User 77:	WO User 87:	WO User 107:	<input type="checkbox"/>
NO User 78:	WO User 88:	WO User 108:	<input type="checkbox"/>
NO User 79:	WO User 89:	WO User 109:	<input type="checkbox"/>
NO User 80:	WO User 90:	WO User 110:	<input type="checkbox"/>
NO User 81:	WO User 91:	WO User 111:	<input type="checkbox"/>

NO Creator: jackson

WO Creation Date: 10/15/2024 PM Trigger:

Rec #: 15866